

ASS. REC. BY:

REF: CS/FCI19011336/kvd3p2

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Henry K90

of FCI

Date/Time: 26.6.19 4.18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 5599R

Insured: SHA 8180K

at Workshop m/s Transcab

Tel: 62876666

of M 2 AMT Street 63

Policy No:

Claim No: D19004173MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26.6.19 4.30p.m.

Person Contacted:

Amanda

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 8180K: CC3/AIG15016962/H1m3n2 D.O.A. 05/10/2015

SHD 5599R: CC3/CTI16004598/Ky63p2 D.O.A. 08/03/2016

28/6/19

Email preli revised to FCI

ASSIGNMENT

From:

Date:

27.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 5599R

at Workshop m/s

Trans-cab

of

NO 2 Amr street 63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 5599R

Yr Regn:

12 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C.

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

38892

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU003077142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / BY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

25/6/19

D.O.A.

27/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt older rim

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/6/19 \$1091.64 (Red 5102.75, 827)

RECEIVED 28 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/6 - typist

Days Of Repair:

1

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

350

Report Format :

CWS

Lump Sum / I.B.I: (\$

1091.64



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004173MFSH

Our ref: CS/FCI19011336/Kvd3

Date : 28/6/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5599R


We thank for your instruction on 26/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/6/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,194.39
Revised Estimate Amount	: S\$1,091.64
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s door mirror



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-06-2019	Our Ref No. D19004173MFSH
Accident Date	25-06-2019	Claim Type. Third Party
Insured Vehicle	SHA8180K	Third Party Vehicle. SHD5599R
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 28 June 2019 11:29 AM
To: Ng Wai Yin; calvin.er@transcab.com.sg
Cc: SUR; jasminetan@transcab.com.sg
Subject: SHD 5599R-DOA: 25/6/2019
Attachments: MARKING.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Final fig \$1091.64 @ 1 working day

Please forward us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 28 June 2019 11:24 AM
To: SUR; 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'
Subject: RE: SURVEY ASSESSMENT - D19004173MFSH/1, SHD 5599R
Attachments: SHD 5599R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 5599R
Date of survey: 27/6/2019
Number of days : 1 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 28 June 2019 11:19 AM
To: SUR <sur@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19004173MFSH/1

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 26 June, 2019 4:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004173MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5599R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B78189
Chassis No.:	JTDKB3FU003077142
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	04 Dec 2018
First Registration Date:	04 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2026
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	03 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
Total Rebate Amount:	\$28,330.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Jun 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 5599R**AAD1906-225**

Not Withheld
Resumy Bypaint
@1091.64

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 5599R

JTDKB3FU003077142

TOYOTA

PRIUS

25.6.19

FIRST CAPITAL

4/12/2018

PART

- | | | PART |
|---|---|-------------------------------------|
| 1 | 1 | RIGHT SIDE VIEW MIRROR |
| 2 | 1 | FRONT DOOR OUTER MOULDING RH |
| 3 | 1 | HANDLE ASSY, FRONT DOOR, OUTSIDE RH |
| 4 | 1 | PANEL SUB-ASSY, FRONT DOOR, RH |
| 5 | 1 | PANEL, FRONT DOOR, OUTER RH |

LIST

\$	<i>Bro</i>	1,275.52	<i>✓</i>
\$	<i>SL</i>	188.60	<i>✓</i>
\$	<i>SL</i>	383.40	<i>✓</i>
\$	<i>SL</i>	1,264.00	<i>✓</i>
\$	<i>SL</i>	361.00	<i>✓</i>
TOTAL	\$	3,472.52	
25%	\$	868.13	
	\$	2,604.39	

Special Nett

- | | | |
|---|---|--------------------------------|
| 1 | 1 | FRONT DOOR STICKER 'TRANS-CAB' |
|---|---|--------------------------------|

\$	<i>nn</i>	80.00	<i>X</i>
TOTAL	\$	80.00	

TOTAL PARTS	\$	2,684.39
--------------------	-----------	-----------------

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$		1,500.00	<i>601</i>
----	--	----------	------------

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of Parts,
 Adjust And Realign The Same

\$		1,500.00	<i>601</i>
----	--	----------	------------

To Rust-Proofing Of The Affected Areas.

\$	<i>nn</i>	170.00	<i>X</i>
----	-----------	--------	----------

To transfer of Right Door fittings, attachments and
 perform water seepage test.

\$	<i>nn</i>	170.00	<i>X</i>
----	-----------	--------	----------

To Check Electrical Lighting Concerned.

\$		170.00	<i>151</i>
----	--	--------	------------

TOTAL	\$	3,510.00
--------------	-----------	-----------------

Trans-cab Auto Services Pte Ltd

AAD1906-225

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5599R

Over All Total \$ 6,194.39

(PART-BY-PART) Repair Days

~~5~~ DAYS
1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011336/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8180K	Veh. Inspected	SHD 5599R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004173MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	26/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU003077142	Colour	M.P.WHITE / RED	
Odometer	38892	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	4 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	4 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	3 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2019	Inspection Date	27/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5599R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RIGHT SIDE VIEW MIRROR	BROKEN	1,275.52	1,275.52
1	FRONT DOOR OUTER MOULDING RH	SERVICEABLE	188.60	-
1	HANDLE ASSY,FRONT DOOR,OUTSIDE RH	SERVICEABLE	383.40	-
1	PANEL SUB-ASSY,FRONT DOOR,RH	TO REPAIR SEE LABOUR	1,264.00	-
1	PANEL,FRONT DOOR,OUTER,RH	SERVICEABLE	361.00	-
	LESS 25% DISCOUNT		-868.13	-318.88
			2,604.39	956.64
SPECIAL NETT ITEMS				
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
			80.00	-
LABOUR				
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,500.00	60.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,FRONT DOOR,RH.		1,500.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF RIGHT DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
			3,510.00	135.00
GRAND TOTAL			6,194.39	1,091.64
RECOMMENDED COST OF REPAIRS				1,091.64

Report Ref No. CS/FC19011336/Kvd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.