(08/11/13)

ASS. REC. BY:

REF ASM (AXA)

ASSIGNMENT

From: Date: 26.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 3077Z

at Workshop m/s Esteem Performance

of 385 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $ 8llc

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp''

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLM 3077Z Yr Regn: 03 / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Prius (A) c.c 1798

Colour M.P. White A/C: Insured / Std / NI / NA

Sp.Reading 119086 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FU303554064

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: Rovelo 195/65R15

R: Pir

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	9 mm
L/Bal.	7 mm	L/Bal.	8 mm
D.O.A.	24/6/19	D.O.I.	26/6/19

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL