(08/11/13)

ASS. REC. BY: Rasul | REF ASM (AXA) | 54686

COBXPRY: 2029

ASSIGNMENT

From: | Date: 26.6. 2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 7723H

at Workshop m/s Mova

of 15 Fan Yoong Road

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $ 62K

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp''

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLX 7723H | Yr Regn: 2009 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: B.M.W 320I A 2.0L | c.c 1998

Colour WHITE | A/C: Insured / Std / NI / NA

Sp.Reading – | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAPG56 00DNL225.41

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	24/06/19	D.O.I.	26/06/19

Survey held at Mova (FY)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL