

ASS. REC. BY:

REF: CS3/C7119011388/6cd3

Special Instruction:

Surveyor: GA**ASSIGNMENT (Office)**From (Person): Irene Tay of CTI Date/Time: 24.6.19 4.01p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 65603 Insured: GBD 8482Uat Workshop m/s AF motorworks Tel: 63849931of 66 kate Butil Ave 6 Arc @ BPolicy No: DMCXSN30549618022 Claim No: SIVM191202798C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16.6.19
(Client's Record)CA / REV / REP. / REV 24 HRS my' H.O.D. Endorsement: _____Date/Time: 27.6.19 12.1p.m Person Contacted: Jia Yun Vehicle IN/OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|-----------------------------------|
| | <u>SKW 65603 - X</u> |
| | <u>GBD 8482U - X</u> |
| | <u>Dismantle: 26/6/2019</u> |
| | <u>After repair: 28/6/2019</u> |
| | |
| | |

PRS
Gad.

REF:

CTI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s

AF Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No:

SKW6560J

Yr Regn:

11 Nov 2015

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry 2.5

C.C

2494

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

82/51

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053 AK 500 40/0074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

25-06-19

Survey held at

w/s

upm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 4000 - \$ 5000

21/6/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

PRS

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 24 Jun 2019 | | 01 Jul 2019 16:16 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

| CLAIM SUBFOLDER DETAILS | [Created by insurer] |
|---|-----------------------------|
| Insured: | |
| Main Claimant: | TAY LENG WHATT |
| Vehicle Reg. No.: | SKW6560J |
| Date of Loss: | 16/06/2019 11:00 - :59 |
| Claim Type: | TP / SNM19D202798C02 |
| Policy/Cover Note No.: | DMCVSN30549618022 |
| Vehicle Reg. No. (Insured): | GBD8482U |
| Policy No. (Claimant): | |
| Excess: | S\$0.00 |
| Repairer: Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB, 417895 Kaki Bukit - Tel: | |
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/07/2019] | |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT |

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 24 June 2019 4:01 PM
To: JyL; assignments
Cc: 'Max'; admin@afmotorworkz.com; kenhow@singnet.com.sg
Subject: RE: OUR REF : SNM19D202798/TAYHP - Our Ref: SKW6560J, Your Insured Car: GBD8482U

Dear AF MOTORWORKZ,

As spoken, you are not using our panel surveyor.

Hence, we will proceed to appoint LKK to survey.

Aside to LKK,

Please proceed to liaise with AF MOTORWORKZ to survey.

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: JyL [<mailto:jiayun.lee@advlawllc.com>]
Sent: Monday, 24 June, 2019 12:08 PM
To: Lim Shu Min <shumin.lim@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Cc: 'Max' <max@advlawllc.com>; admin@afmotorworkz.com; kenhow@singnet.com.sg
Subject: RE: OUR REF : SNM19D202798/TAYHP - Our Ref: SKW6560J, Your Insured Car: GBD8482U

Good Afternoon

Any update regarding this?

Dear Sir/ Ms,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES.

We act for who has been instructed with motorcar no. **SKW6560J** with instructions to repair the same.
Accident on : 16/06/2019 @ 11:10 HRS, AT BLK 404B FERNVALE LANE LOADING/ UNLOADING BAY

Please be informed that the said vehicle can be inspected at:-

Venue : AF MOTORWORKZ
66 KAKI BUKIT AVENUE 6
Ark @ KB
SINGAPORE 417895

Contact No : 63849931

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening weekend and public holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Best Regards

Jia Yun

ADVANCE
ADVANCE LAW LLC

430 Lorong 6 Toa Payoh #11-01 OrangeTee Building Singapore 319402
Tel: (65)6323 5488 | Fax: (65)6258 5521

STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

From: Lim Shu Min <shumin.lim@sg.cntaiping.com>

Sent: Friday, June 21, 2019 2:57 PM

To: JyL <jiajun.lee@advlawllc.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Cc: 'Max' <max@advlawllc.com>; admin@afmotorworkz.com; kenhow@singnet.com.sg

Subject: OUR REF : SNM19D202798/TAYHP - Our Ref: SKW6560J, Your Insured Car: GBD8482U

Dear Irene,

Please conduct PRS SKW6560J soonest possible.

File with Officer-In-Charge – Irene Tay – 63896192.

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: JyL [<mailto:jiayun.lee@advlawllc.com>]

Sent: Friday, 21 June, 2019 11:08 AM

To: DL-CLAIMS <claims@sg.cntaiping.com>

Cc: 'Max' <max@advlawllc.com>; admin@afmotorworkz.com; kenhow@singnet.com.sg

Subject: Our Ref: SKW6560J, Your Insured Car: GBD8482U

Dear Sir/ Ms,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES.

We act for who has been instructed with motorcar no. **SKW6560J** with instructions to repair the same.

Accident on : 16/06/2019 @ 11:10 HRS, AT BLK 404B FERNVALE LANE LOADING/ UNLOADING BAY

Please be informed that the said vehicle can be inspected at:-

Venue : AF MOTORWORKZ
66 KAKI BUKIT AVENUE 6
Ark @ KB
SINGAPORE 417895

Contact No : 63849931

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening weekend and public holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Best Regards

Jia Yun



430 Lorong 6 Toa Payoh #11-01 OrangeTee Building Singapore 319402
Tel: (65)6323 5488 | Fax: (65)6258 5521

STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MSME19078817 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 17/06/2019 16:16
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 17/06/2019 16:16 |
| Date Of Accident | 16/06/2019 11:10 |
| Exact Location Of Accident | BLK 404B FERNVALE LANE LOADING/ UNLOADING BAY |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKW6560J |
| Insured/Policyholder | |
| Name Of Registered Owner | TAY LENG WHATT |
| NRIC No | S0488993B |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96654252 |
| Alternative Phone No | OFFICE-96654252 |

Vehicle Particulars

| | |
|--|---------------|
| Manufacturer | TOYOTA |
| Model | CAMRY-2.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 2100436690-03 |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | TAY LENG WHATT |
| NRIC No | S0488993B |
| Date Of Birth | 18/12/1951 |
| Occupation | INDOOR |
| Date Of Driving Pass | 23/06/1970 |
| Driving Experience | 48 YEARS AND 11 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96654252 |
| Fax Number | |
| Contact Number | OFFICE-96654252 |
| Email Address | NOEMAIL |

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAY LEE YEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKW6560J

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer police report No: T/20190616/2058

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

17/6/19

11:55am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GUSTING (Singapore) Pte Ltd

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190616/2058

2 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20190616/2058

CONTINUATION OF REPORT

| Details of Vehicle Insurance | | | | |
|------------------------------|--------------------------------------|---------------|------------|-------------|
| Vehicle No. | Insurance Company | Insurance No. | Effective | Expiry Date |
| SKW6560J | AIG ASIA PACIFIC INSURANCE PTE. LTD. | 2100436690-03 | 11/11/2018 | 10/11/2019 |

| Details of Person Involved | | | | |
|-----------------------------------|-------------------------------------|--|--|---|
| Any Pedestrian Involved: No | | | | |
| No. of Pedestrians Injured: NIL | | | Use of Pedestrian Crossing: NA | |
| Driver | | | | |
| Name | JACKIE NG CHEE KANG | | ID No. | NIL |
| Related Vehicle | GBD8482U (Van) | | Contact No. | 96530343 |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | | Degree of Injury | NIL |
| Driver | | | | |
| Name | TAY LENG WHATT | | ID No. | S0488993B |
| Related Vehicle | SKW6560J (Car) | | Contact No. | 96654252 |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date | Class: 2B,2A,2,3 Date of Expiry: NIL |
| Date Treatment | NIL | | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | | Degree of Injury | NIL |
| Passenger | | | | |
| Name | TAY LEE YEN | | ID No. | S8735300A |
| Related Vehicle | SKW6560J (Car) | | Contact No. | 96876203 |
| Hospital/Clinic | SENGKANG GENERAL HOSPITAL PTE. LTD. | | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | 16/06/2019 | | Date Discharge | 16/06/2019 |
| No. of Days granted Medical Leave | 02 | | Degree of Injury | NIL |

Sketch Plan #6 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20190616/2058

4 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20190616/2058

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MUHAMMAD ISA BIN MD RASHID

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/06/2019 15:20

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

**SINGAPORE
POLICE FORCE**

Authentication Stamp

NP168

SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|---------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 8993B |
| Vehicle Details | |
| Vehicle No.: | SKW6560J |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 27 Jun 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | CAMRY 2.5 AUTO |
| Primary Colour: | Grey |
| Manufacturing Year: | 2015 |
| Engine No.: | 2ARU271124 |
| Chassis No.: | MR053AK5004010074 |
| Maximum Power Output: | 133.0 kW (178 bhp) |
| Open Market Value: | \$28,170.00 |
| Original Registration Date: | 11 Nov 2015 |
| First Registration Date: | 11 Nov 2015 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$31,438.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 10 Nov 2025 |
| PARF Rebate Amount: | \$23,578.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 10 Nov 2025 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$58,190.00 |
| COE Rebate Amount: | \$37,077.00 |
| Total Rebate Amount: | \$60,655.00 |

The information contained herein is correct as at 27 Jun 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 24 Jun 2019 | | 01 Jul 2019 16:16 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | -, Co. Reg. No.: - | | |
| Main Claimant: | TAY LENG WHATT | | |
| Vehicle Reg. No.: | SKW6560J | Date of Loss: | 16/06/2019 11:00 - :59 [43 Months and 5 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / SNM19D202798C02 | Policy/Cover Note No.: | DMCVSN30549618022 |
| Vehicle Reg. No. (Insured): | GBD8482U | Policy No. (Claimant): | |
| | | Excess: | S\$0.00 |
| Repairer: | Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB, 417895 Kaki Bukit - Tel: | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/07/2019] | | |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |




































Claim Documents














































***SKW6560J (SNM19D202798C02)**
[GBD8482U]

TP
TAY LENG WHATT
Jun 16 2019 11:00AM
[-]
Af Motorworkz Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

| Photos/Images | | | 3 per page | |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 36 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 08/07/19 12:05 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 08/07/19 12:05 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 08/07/19 12:06 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19011388/GCD3S2

Date: 11/07/2019

REFERENCE

| | | | |
|-----------------------|---|----------------------|-------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSN30549618022 |
| Claimant Vehicle No : | SKW6560J | Insured Vehicle No : | GBD8482U |
| Date of Loss: | 16/06/2019 | Nature of Claim: | TP |
| | | Claim No: | SNM19D202798C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SKW6560J | Engine No: | 2ARU271124 |
| Make & Model: | TOYOTA CAMRY, 2.5 (A) | Chassis No: | MR053AK5004010074 |
| Reg. Date: | 11/11/2015 (Man. Year: 2015) | Odometer: | 82151 km |
| Colour: | Grey | | |
| Engine Capacity: | 2494 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 215/55R17 | Rear Tyre Size: | 215/55R17 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 01/07/2019 | |
| Date Inspected: | 25/06/2019 | Inspected At: Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB Singapore 417895 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/11/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 11 Jul 2019) |
| Parts: | 143 | TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKW6560J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >