

22/03/2002

ASS. REC. BY:

REF: CS3/MS1G/19011396/R1cd302 Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)From (Person): Irene Tan Get Ing of MS1G Date/Time: 27.6.19 11.44 AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 2702 Z Insured: YN 3852Tat Workshop m/s Empire Image Tel: 9742 5441of No 4 Pandan Loop (Bik 1 / Bik E)Policy No: B29045132MKF Claim No: 597556

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 24.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 27.6.19 1.06 PM Person Contacted: Kenny H.O.D. Endorsement: \_\_\_\_\_Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>YN 3852T : X</u>
	<u>SKC 2702 Z : X</u>
	<u>After repair: 5/7/2019</u>
	<u>Dismantle: 2/7/2019</u>

## ASSIGNMENT

From: Date: 1.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 2702Zat Workshop m/s Empire Imageof NO 4 Pandan Loop (B1K / B1K 1)

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 26K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKC 2702Z Yr Regn: Aug / 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.C. 1591Colour: BLU A/C: Insured / Std / NI / NASp. Reading: 147241 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMH541CMCH217564

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17R: 215/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/06/19D.O.I. 01/07/19

Survey held at

EMPIRE IMAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ESTIMATE RANGE OF REPAIR - (4K - 5K) / 5 days

24/7/2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 5Resurvey No. of Trip: 2

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee.

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I: (\$ )

120

11

131

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iris Auth'd	Status
Main	25 Jun 2019 16:01		27 Jun 2019 11:44 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>YHS (SINGAPORE) PTE LTD, Co. Reg. No.: 199401863Z</b>								
Main Claimant:	<b>CHAN PENG, ID: S7021492Z</b>								
Vehicle Reg. No.:	<b>SKC2702Z</b>	Date of Loss:	24/06/2019 10:00 - :59 [94 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 597556</b>	Policy/Cover Note No.:	B29095132MKF (Comprehensive) Coverage: 01/09/2018 - 31/07/2019						
Vehicle Reg. No. (Insured):	<b>YN3852T</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:</b>								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]</b>								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/06/2019]</b>								
Driver/Custodian (Insured):	<b>ZHANG DONGYAN ( / Male) , NRIC: G6620693P Email:</b>								
Adj Asg. Remarks:	<b>on WP. Liab: dispute, TP disagree on SJE - assign LKK. Contact: Mr Kenny Lim @ 9742 5441 / 6777 5453</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1492Z
<b>Vehicle Details</b>	
Vehicle No.:	SKC2702Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jul 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	G4FGBU281095
Chassis No.:	KMHDH41CMCU217564
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$13,572.00
Original Registration Date:	08 Aug 2011
First Registration Date:	08 Aug 2011
Transfer Count:	2
Actual ARF Paid:	\$13,572.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2021
PARF Rebate Amount:	\$8,143.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$48,801.00
COE Rebate Amount:	\$10,153.00
<b>Total Rebate Amount:</b>	<b>\$18,296.00</b>

The information contained herein is correct as at 08 Jul 2019

OK

26000  
18,296  
-----  
7704  
=====

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/06/2019 12:58
Date Of Accident	24/06/2019 10:05
Exact Location Of Accident	N0. 9 KAKI BUKIT RD 1 EUNOS TECHNOLINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC2702Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHAN PENG
NRIC No	S7021492Z
Email Address	MARKCHAN73@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94876233
Alternative Phone No	OFFICE-94876233

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105718899
Cover Note Number	

### Driver

Name of Driver	CHAN PENG
NRIC No	S7021492Z
Date Of Birth	15/06/1970
Occupation	OUTDOOR
Date Of Driving Pass	02/02/1988
Driving Experience	31 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94876233
Fax Number	
Contact Number	OFFICE-94876233
EEmail Address	MARKCHAN73@HOTMAIL.COM

Address	BLK 89 DAWSON RD #35-04
Postcode	142089
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSSENGER GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLANS


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN3852T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on the left lane at Eunros Tehnolink  
 No 9 Kaki Bukit Rd 1 toward the exit of the  
 car park. Vehicle 'B' YN3852T was stationary on the  
 right lane. AS I drove near toward the exit and  
 about to pass Vehicle YN3852T, Vehicle YN3852T  
 made a sudden left turn and cut in to my lane  
 hitting the right front <sup>side</sup> portion of my vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:




**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




  
Policyholder's Signature  
Date & Time:


\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan #2 Pg. 1






This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	31/01/2013



# Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on the left lane at Eunros Tehnolink  
 No 9 Kaki Bukit Rd 1 toward the exit of the  
 car park. Vehicle 'B' YN3852T was stationary on the  
 right lane. As I drove near toward the exit and  
 about to pass Vehicle YN3852T, Vehicle YN3852T  
 made a sudden left turn and cut in to my lane  
 hitting the right front <sup>side</sup> portion of my vehicle

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan #2 Pg. 1





This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	31/01/2013



### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2019 16:01		27 Jun 2019 11:44 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>YHS (SINGAPORE) PTE LTD</b> , Co. Reg. No.: 199401863Z								
Main Claimant:	<b>CHAN PENG</b> , ID: S7021492Z								
Vehicle Reg. No.:	<b>SKC2702Z</b>	Date of Loss:	24/06/2019 10:00 - :59 [94 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 597556</b>	Policy/Cover Note No.:	B29095132MKF (Comprehensive) Coverage: 01/09/2018 - 31/07/2019						
Vehicle Reg. No. (Insured):	<b>YN3852T</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Empire Image (HQ)</b> NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Imm.Advice due 28/06/2019]								
Driver/Custodian (Insured):	ZHANG DONGYAN ( / Male) , NRIC: G6620693P Email:								
Adj Asg. Remarks:	on WP. Liab: dispute. TP disagree on SJE - assign LKK. Contact: Mr Kenny Lim @ 9742 5441 / 6777 5453								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKC2702Z (597556)  
 [YN3852T]  
 TP  
 CHAN PENG  
 Jun 24 2019 10:00AM  
 [YHS (SINGAPORE) PTE LTD]  
 Empire Image

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/07/19 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	09/07/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	09/07/19 17:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	09/07/19 17:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	09/07/19 17:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	09/07/19 17:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	09/07/19 17:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/06/19 16:02	OI YN3852T E-FILE REPORT	 Load PDF	
2	25/06/19 16:02	TP SKC2702Z E-FILE REPORT	 Load PDF	
3	27/06/19 11:05	Disagree on SJE & workshop details	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19011396/R1CD3E2

Date: 29/07/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29095132MKF

Claimant Vehicle No : SKC2702Z

Insured Vehicle No : YN3852T

Date of Loss: 24/06/2019

Nature of Claim: TP

Claim No: 597556

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKC2702Z

Make &amp; Model: HYUNDAI ELANTRA, 1.6 (A)

Reg. Date: 08/08/2011 (Man. Year: 2011)

Colour: Blue

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (\$\$): Market Value/New Car Price

Engine No: G4FGBU281095

Chassis No: KMHDH41CMCU217564

Odometer: 147241 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 27/06/2019

Date Inspected: 01/07/2019 Inspected At:

Empire Image (HQ)  
NO 4 PANDAN LOOP (BLK 1/ BLK K)  
Singapore 128222

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 29 Jul 2019)

**Parts:** 143      HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKC2702Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >