



QUOTATION

Customer :

NO. : 34328

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
CHINA TAIPING INSURANCE (S) PTE LTD

*not added
all
1 day
27/6/19
take the other 117... plus*

DATE : 21/06/2019
CLAIM NO. : 11367
POLICY NO. : AVFMSB0000591904
FROM : RAYMOND

VEHICLE NO. : FBL2268U
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL LH (BLACK) P/N: 57615	REPLACE	1.00	\$82.00	82.00 X
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00 X
3	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	3.00	\$35.00	105.00
4	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	35.00 X
5	MUDGUARD FRONT (BLACK) P/N: 49723	REPLACE	1.00	\$98.00	98.00 X
6	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$119.00	119.00
7	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	\$18.00	18.00 X
8	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00 X
9	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK ONCE REPAIR DONE.	*	2.00	\$35.00	70.00 X
10	VISOR P/N: 43130	REPLACE	1.00	\$30.00	30.00 X

SUB TOTAL \$764.00
GST @ 7 % \$53.48
GRAND TOTAL \$817.48



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

