

ASS. REC. BY:

REF: CS3/A2G19011404/R1cd302

S.veup: R05U

ASSIGNMENT (Office)

From (Person):

chin lee Yiney

of

AIG

Date/Time:

27/6/19 @ 12:16pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 9652L

Insured:

SKX 9519F

at Workshop no:

Equator Brotherhood

Tel:

90113391

of

25 Kaki Bukit Rd 4 #

Policy No:

Claim No:

12603308188G

Sum Insured:

Excess:

Make of Veh:

D.O.A

27/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1243pm 27/6/19

Person Contacted:

willie

Vehicle:

IN/OUT

Date/Time	Action/Instruction
	Vehicle (X)
	SKX 9519F - X
	FBN 9652L - X
	Dismantle: 27/6/2019
	After repair: 9/7/2019

Signature: PRM
PRS


REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBN 9652L
at Workshop m/s KAUSTUK BROTHERHOOD
of 25, KAKI BUKIT RD 4 # 08-79
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBN 9652L Yr Regn: Jan / 19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: YAMAHA C.C. : 125
Colour: MULTI A/C: Insured / Std / NI / NA
Sp. Reading: 05761 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: LWB JCTH A9H1012490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 80/90-18
R: 90/90-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or IRC

Front Rear
R/Bal. 3 mm R/Bal. 3 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 27/06/19

Survey held at Equator

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I. (\$) _____

180

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	29 May 2019 Edit Reg		09 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	WONG CHIEN KHOON, ID: S8140841F		
Main Claimant:	MUHAMMAD HADIL BIN KAMALI, ID: S9508007C		
Vehicle Reg. No.:	FBN9652L	Date of Loss:	27/05/2019 00:00 - :59
Claim Type:	TP / 1260330818SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 31/12/2018 - 30/12/2019
Vehicle Reg. No. (Insured):	SKX9519E	Policy No. (Claimant):	
		Excess:	
Repairer:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/07/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (10/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/27/2019 12:16:30 PM

Hi LKK,

Kindly assist to survey today, bike in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Sophia Tan [mailto:sophia.tan@advlawllc.com]

Sent: Tuesday, June 25, 2019 5:31 PM

To: Hor, Yinrul

Subject: [EXTERNAL] RE: PRI NOTICE - SKX 9519E

This message is from an external sender; be cautious with links and attachments.

Dear Yinrul

Your insured vehicle : SKX 9519E

D.O.A – 27.5.19

Rdgs

Sophia Tan

Advance Law LLC

From: Sophia Tan <sophia.tan@advlawllc.com>

Sent: Tuesday, June 25, 2019 5:07 PM

To: 'yinrul.hor@aig.com' <yinrul.hor@aig.com>

Subject: PRI NOTICE

Dear Yinrul

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We act for **EQUATOR BROTHERHOOD** who has been instructed with motorcar no. **FBN 9652L** with instructions to repair the same.

Please be informed that the said vehicle can be inspected at:-

Venue :	EQUATOR BROTHERHOOD 25 Kaki Bukit Road
----------------	---

#03-79
Singapore 417800

Contact: Willie
90113391

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Best Regards,
Sophia Tan



430 Lorong 6 Toa Payoh #11-01 OrangeTee Building Singapore 319402
Tel: (65)6323 5488 | Fax: (65)6258 5521

STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBN9652L		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	GLR1251WH		
Chassis No. :	LWBJC74A9H1012490		
Propellant :	Petrol		
Engine No. :	JC74E5012636		
Engine Capacity :	125 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	286 kg		
Unladen Weight :	128 kg		
Year Of Manufacture :	2018		
Original Registration Date :	10 Jan 2019		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$3,789.00		
COE Expiry Date :	09 Jan 2029		
Road Tax Expiry Date :	09 Jan 2020		
Inspection Due Date :	09 Jan 2022		
Intended Transfer Date :	15 Jul 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8007C
Vehicle Details	
Vehicle No.:	FBN9652L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	GLR1251WH
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	JC74E5012636
Chassis No.:	LWBJC74A9H1012490
Maximum Power Output:	-
Open Market Value:	\$2,092.00
Original Registration Date:	10 Jan 2019
First Registration Date:	10 Jan 2019
Transfer Count:	1
Actual ARF Paid:	\$314.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jan 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,789.00
COE Rebate Amount:	\$3,593.00
Total Rebate Amount:	\$3,593.00

The information contained herein is correct as at 15 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2019 09:49
Date Of Accident	27/05/2019 17:20
Exact Location Of Accident	JUNCTION OF BEDOK NORTH AVE 1 & BEDOK NORTH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN9652L
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD HAIDIL BIN KAMALI
NRIC No	S9508007C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91824822
Alternative Phone No	OTHERS-91824822

Vehicle Particulars

Manufacturer	HONDA
Model	GLR 125 IWH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MUHAMMAD HAIDIL BIN KAMALI
NRIC No	S9508007C
Date Of Birth	08/03/1995
Occupation	OUTDOOR
Date Of Driving Pass	13/08/2015
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91824822
Fax Number	(LOCAL) +65-91824822
Contact Number	OTHERS-91824822
EMail Address	NOEMAIL

Address	BLK 615 BEDOK RESERVIOR ROAD #05-1220
Postcode	470615
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX9519E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number FBH5458P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD HAIDIL BIN KAMALI
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBN9652L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan Pg. 1



VEHICLE A: FOM 9652L
 VEHICLE B: SKX 9519 E
 VEHICLE C: FOM 5458 P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE AND TIME, I VEHICLE A FOM 9652L
 AND VEHICLE C FOM 5458 P WERE TRAVELLING STRAIGHT
 ON THE STATED VENUE, WE SAW A PMD FELL ON TO
 THE GROUND SO WIF STOPPED ON THE SIDE OF THE ROAD.
 MOMENTS LATER, VEHICLE B SKX 9519 E HIT ON TO
 VEHICLE C AND MY VEHICLE. I WISH TO STATE MY
 VEHICLE WAS STATIONARY AT THE POINT OF TIME.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/PPN No.:


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 3



POLICE FORCE



T/20190527/7041

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190527/7041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/05/2019 21:08		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MUHAMMAD HAIDIL BIN KAMALI			Address: APT BLK 615 BEDOK RESERVOIR ROAD #05-1220 SINGAPORE 470615		
ID Type / ID No.: NRIC NO / S9508007C			Contact No.: Home/Office:		Mobile: 91824822
Nationality: SINGAPORE CITIZEN			Email: haidil_raul@hotmail.com		
Sex: Male	Age: 24	Date of Birth: 08/03/1995	Type of Informant: Rider		
Race: Javanese			Language: English		Institution / School Name:
Occupation: Lift Technician			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident					
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 27/05/2019 17:20	Type of Location: Straight Road	
Location: BEDOK NORTH AVENUE 1					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH5458P	Motorcycle				Seriously Damaged	0
FBN9652L	Motorcycle	HONDA	GLR1251W H	White	Slightly Damaged	0
SKX9519E	Car				Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



SINGAPORE
POLICE FORCE



T/20190527/7041

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190527/7041

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBN9652L	TENET SOMPO INSURANCE PTE. LTD.	D19MTMC0100043 2	11/01/2019	10/01/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD HAIDIL BIN KAMALI	ID No.	S9508007C
Related Vehicle	FBN9652L (Motorcycle)	Contact No.	91824822
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	27/05/2019	Date Discharge	27/05/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

ON 27/05/2019 AT ABOUT 17:20HR, I WAS RIDING ALONG BEDOK NORTH AVENUE 1. I SLOWED DOWN AND SUDDENLY FELT AN IMPACT ON MY MOTORCYCLE'S REAR PORTION. I THEN REALISED I WAS INVOLVED IN A CHAIN COLLISION OF 3 VEHICLES.

I WISH TO STATE THAT I HAVE VIDEO FOOTAGE OF THE ACCIDENT BUT DO NOT WISH FOR IT TO BE DISCLOSED TO ANY THIRD PARTY FOR VIEWING.

I THEN SEEK MEDICAL ATTENTION AT KL TAY CLINIC & SURGERY AND WAS GIVEN 2 DAYS MC.



**SINGAPORE
POLICE FORCE**



T/20190527/7041

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190527/7041

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65472076

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
27/05/2019 21:08

Classification Of Case:

Co. Reg. No. 19805-HMC

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D19MTMC01000432
 Insured : MUHAMMAD HAIDIL BIN KAMALI
 Motor Vehicle (Regn No.) : FBN9652L
 Cover : Third Party, Fire & Theft
 Policy Commencement Date : 11 JANUARY 2019 13:19
 Policy Expiry Date : 10 JANUARY 2020 23:59
 Maximum Liability (Section I) : Market value at time of loss
 Excess* : \$300 - Section I
 Named Driver 1 : MUHAMMAD HAIDIL BIN KAMALI
 HIRE PURCHASE OWNER : GLOBAL MOTOR PTE LTD

This Bike Is Still Under Hire Purchase
 GLOBAL MOTOR PTE
 No Add rider, Renewal Term
 Or Lay Up Is Allowed

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*
 MUHAMMAD HAIDIL BIN KAMALI

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle and has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or

Limitations As To Use

Use only for social, domestic and pleasure purposes and
 (a) by the Insured in person in connection with his business or profession or
 (b) in connection with the Insured's business or profession

The Policy does not cover

- (i) Use for hire or reward
- (ii) Use for racing pacemaking, reliability trial or speed-testing
- (iii) Use for the carriage of goods (other than samples) in connection with any trade or business
- (iv) Use for any purpose in connection with the Motor Trade

Accident Reporting


It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Vehicle within 24 hours of the accident or by the next working day thereof.

For list of Accident Reporting Centres, please visit our website at www.sompo.com.sg or call our Emergency Hotline:


We hereby certify that the Policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Transport Act, 1987 (Malaysia); and (2) the policy terms, conditions and exceptions of the Motorcycle Policy (Ref: MCY-AT)

Sompo Insurance Singapore Pte. Ltd.

Stallak









Vehicle No: FBN 9652L

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	CNT	✓	
3001	995065	Front Tyre	CNT	✓	60
3002	995095	Front Rim	DD	✓	
3003	994872	Front Tyre Rim Spoke	CNT	✓	
3004	991771	Front Fender Wheel Guard	CNT	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	CNT	✓	
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	CNT	✓	
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror LH & RH	CNT	✓	
3019	995245	Front LH Signal Lamp	CNT	✓	
3020	995246	Front RH Signal Lamp	CNT	✓	
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit	CNT	✓	
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip	REC	✓	
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	BR	✓	
3035	992293	Hand Brake Lever	CNT	✓	
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing LH	CNT	✓	
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			
		Fuel Tank Garnish LH	CNT	✓	

[illegible]

004749 CORN

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 Edit Reg		27 Jun 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	WONG CHIEN KHOON , ID: S8140841F								
Main Claimant:	MUHAMMAD HADIL BIN KAMALI , ID: S9508007C								
Vehicle Reg. No.:	FBN9652L	Date of Loss:	27/05/2019 00:00 - :59 [4 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1260330818SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 31/12/2018 - 30/12/2019						
Vehicle Reg. No. (Insured):	SKX9519E	Policy No. (Claimant):							
		Excess:							
Repairer:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (10/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN9652L (1260330818SG)
[SKX9519E]




































TP



















































MUHAMMAD HADIL BIN KAMALI





























May 27 2019 12:00AM

[WONG CHIEN KHOON]

Equator Brotherhood

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser		
Photos/Images												3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print		
1	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
2	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
3	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
4	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
5	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
6	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
7	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
8	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
9	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
10	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
11	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
12	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
13	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
14	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
15	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
16	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
17	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
18	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
19	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
20	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
21	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
22	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
23	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
24	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
25	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
26	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
27	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
28	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
29	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
30	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
31	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
32	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
33	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
34	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
35	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
36	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	
37	09/07/19 13:05	General View											Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
59	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
60	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
61	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
62	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
63	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
64	09/07/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
65	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	09/07/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	15/07/19 19:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/07/19 11:39	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011404/R1CD3E2

Date: 18/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBN9652L

Insured Vehicle No : SKX9519E

Date of Loss: 27/05/2019

Nature of Claim: TP

Claim No: 1260330818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN9652L**

Make & Model: HONDA GLH125, 125cc

Engine No: JC74E5012636

Reg. Date: 10/01/2019 (Man. Year: 2018)

Chassis No: LWBJC74A9H1012490

Colour: Multi-colour

Odometer: 5761 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-18 Rear Tyre Size: 90/90-18
Front Left Side: IRC 3 mm Rear Left Side: IRC 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/06/2019

Date Inspected: 27/06/2019 Inspected At:

Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-79 synergy @ kb
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRONT TYRE (60%)	Cut	0.00 F	*- F
3	1		*FRONT RIM	Dented	0.00 F	*- F
4	1		*FRONT TYRE RIM SPOKE	Cut	0.00 F	*- F
5	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
6	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
7	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
8	1		*FRONT WING MIRROR LH & RH	Cut	0.00 F	*- F
9	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
10	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
11	1		*ERP UNIT	Cut	0.00 F	*- F
12	1		*HANDLE BAR	Bent	0.00 F	*- F
13	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
14	1		*CLUTCH LEVER	Broken	0.00 F	*- F
15	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
16	1		*REAR FAIRING LH	Cut	0.00 F	*- F
17	1		*FUEL TANK GARNISH LH	Cut	0.00 F	*- F
18	1		*FRONT FOOT REST LH	Torn	0.00 F	*- F
19	1		*REAR FOOT REST LH	Torn	0.00 F	*- F
20	1		*REAR FENDER WHEEL GUARD	Torn	0.00 F	*- F
21	1		*REAR LH SIGNAL LAMP	Cut	0.00 F	*- F
22	1		*REAR TAILLAMP	Cracked	0.00 F	*- F
23	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
24	1		*REAR BOX	Cut	0.00 F	*- F
25	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
26	1		*TAILBOARD	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >