

ASS. REG. BY:

Mr. Jim

REF:

ALG

ASSIGNMENT

Vic

From:

Date:

28/6/19

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKD 6572A

at Workshop m/s

Team Autopro

of

160 Lin Ming Drive # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKD 6572A

Yr Regn:

/

Type

☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi TT Coupe 2.0 C.C. 1984

Colour

Metallic grey

A/C:

Insured / Std / NI / NA

Sp. Reading

85646

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TRUZZE 8J2C1004568

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 245/40/18

R: 245/40/18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

25/6/19

D.O.I.

28/6/19

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Vehicle sold - unable to secure LTA owner's detail
	5444W
	HS 4700/2 @ 6 days repair Team Lin 22/11/19
	Team Lin 5/7/19

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + PS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SKD 6572A**

Model : Audi TT

Year :

Chassis No :

After-Paint:

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 1,968.00	\$ ✓ 1,968.00
2	Rear bumper clips	1	\$ 55.00	\$ RPT X 55.00
3	Rear bumper retainer	2	\$ 133.00	\$ ✓ 266.00
4	Rear fender rh	1	\$ 893.50	\$ -893.50
5	Rear fender quarter glass moulding	1	\$ 188.50	\$ ✓ 188.50
6	Door rh	1	\$ 2,655.00	\$ -2,655.00
7	Side mirror rh	1	\$ 385.30	\$ -385.30
8	Rear shock absorber	1	\$ 382.00	\$ -382.00
9	Rear upper arm rh	1	\$ 675.00	\$ 675.00
10	Rear center arm rh	1	\$ 683.60	\$ 683.60
11	Rear lower arm	1	\$ 684.00	\$ -684.00
12	Rear wheel knuckle arm	1	\$ 1,690.00	\$ 991.25 1,690.00
13	Rear wheel knuckle arm bearing	1	\$ 252.00	\$ ✓ 252.00
Parts Sub Total :				\$ 3365.75 10,777.90
5% Discount				\$ 182.79 538.90
PARTS TOTAL :				\$ 3472.96 10,239.01

DDV
RPT X
NECV
RX
NECV
RX
NDX
NNX
DDV
NECV

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ -60.00
2	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
3	Front 18" alloy Rim local repair	1	\$ 600.00	\$ 300.00 600.00
SPECIAL NETT TOTAL :				\$ 330.00 710.00

NNX
NECV
NECV

Nos.	LABOUR	S\$
1	R&R reverse sensor	\$ 60.00 80.00
2	R&R rear fender quarter glass rh	\$ -80.00
3	R&R oil tank	\$ 150.00
4	R&R undercarriage	\$ 100.00 250.00
5	4 wheels alignment	\$ 60.00 80.00
6	Panel beat	\$ 1000.00 1,600.00
7	Rust proofing	\$ 60.00 -150.00
8	Spray painting	\$ 800.00 1,400.00
LABOUR TOTAL :		\$ 2080.00 3,790.00

NNX

LABOUR TOTAL :

PARTS TOTAL : \$ 3472.96 10,239.01
SPECIAL NETT TOTAL : \$ 330.00 710.00
LABOUR TOTAL : \$ 2080.00 3,790.00
GRAND TOTAL : \$ 14,739.01

5882.96

1176.60

4706.37

@ 20 %

HS 4700/2 TGTim lim 22/11/19

Survey on 28/6/19
TGTim lim
Lump Sum repair
Repair days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: