

(08/11/13)

ASS. REC. BY:

REF

A2G

ASSIGNMENT

From:

Date:

1-7-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMG 2016B

at Workshop m/s

Optima MK2

of

9A Seangoon Miah Ave 5

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Moring

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

1-B.1%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

rep

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMG 2016B

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Noah

C.C.

1797

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

74300

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

BWR80

0324338

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MCT / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

23/6/19

D.O.I.

17/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

(NOT FINALISE/AMOUNT WITHOUT CHECK ITEMS)

P/P (\$2,726.53 / RED \$ 860.01/ 24%)

CHECK ITEMS: \$150

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)