

ASS. REC. BY:

REF: CS3/1AIG19011439/R1cd307 Special Instruction:

Surveyor: RASU

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time: 27.6.19 3.45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 5465 Z

Insured:

SLU 9359D

at Workshop m/s

AK9 Auto PC LTD

Tel:

81880754

of

25 Kaki Bukit Road 4 Surveyor @ KB #05-36

Policy No:

1800016612

Claim No:

0858656789SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/06/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

27.6.19 3.54pm

Person Contacted:

Rachu!

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLU 9359D X
	SJH 5465Z X
	Dismantle: 4/7/2019.

Date/Time

Signature

Person

REF:

92268

LOG XPRY: 2023/11/24

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJH 54652at Workshop m/s AKA AUTOof 25, KAKABUKIT RD, #02-36Insured: AKA

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 24K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJH 54652 Yr Regn: 2008 / AULType: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA AIRWAVE / SNA c.c. 1496Colour: GREEN A/C: Insured / Std / NI / NASp.Reading: 262323 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 9311300893

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt orBrake: in order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/06/19 D.O.I. 27/06/19

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO G3A

Repair limit 9k

RANGE OF REPAIR COST - (6k - 8k)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 12

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I. (\$) _____

180

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2019 Edit Reg		09 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	GOH THENG WEE, ID: S7501639E			
Main Claimant:	NEO ENG TAI, ID: S0189226F			
Vehicle Reg. No.:	SJH5465Z	Date of Loss:	25/06/2019 20:00 - :59	
Claim Type:	TP / 0858656789SG	Policy/Cover Note No.:	1800016612 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLU9359D	Policy No. (Claimant):		
		Excess:		
Repairer:	Aka Auto (HQ) 25 Kaki Bukit Road 4, #05-58, Synergy@KB, 417800 Kaki Bukit - Tel: 81880754			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/07/2019]			


ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (10/07/2019): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU9359D AND SJH5465Z ON 25/06/2019

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: Thursday, 27 June, 2019 3:45:05 PM
Attachments:  SJH5465Z NOA.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel: +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

AKA AUTO PTE LTD
25 KAKI BUKIT ROAD 4
SYNERGY@KB #05-36, #05-37
SINGAPORE 417800

Date: 26/6/2019

To AIG
Motor Claims Department

78 Shenton Way,
#07-16 AIG Building, Singapore 0791208

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no SJH5465Z and vehicle(s) no. SLU9359D and SJX6113Z had taken place at / along Eu Tong Sen Street on date 25/6/2019 at time 8.30pm.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call Rachel 81880754 to arrange.

Yours sincerely,
Rachel

PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9226F
Vehicle Details	
Vehicle No.:	SJH5465Z
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	L15A5200927
Chassis No.:	GJ11300893
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,069.00
Original Registration Date:	13 Aug 2008
First Registration Date:	13 Aug 2008
Transfer Count:	0
Actual ARF Paid:	\$14,069.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$14,102.00
Total Rebate Amount:	\$14,102.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Jun 2019

OK

24,000

14,102

9898

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/06/2019 16:47
Date Of Accident	25/06/2019 20:30
Exact Location Of Accident	EU TONG SEN STREET
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJH5465Z
Insured/Policyholder	
Name Of Registered Owner	NEO ENG TAI
NRIC No	S0189226F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96435091
Alternative Phone No	OFFICE-96435091
Vehicle Particulars	
Manufacturer	HONDA
Model	AIRWAVE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP307930
Cover Note Number	
Driver - Particulars	
Name of Driver	NEO SOON CHEN TERRY
NRIC No	S8604191Z
Date Of Birth	09/02/1986
Occupation	INDOOR
Date Of Driving Pass	04/10/2005
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96153041
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 239 HOUGANG ST 22 #07-01
Postcode	530239
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CARYNN LEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190626/2000.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU9359D
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	GOH THENG WEE
NRIC/Passport Number	
Contact Number	96232505
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJX6113Z

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NEO SOON CHEN TERRY

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJH5465Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A = SJH546S-2

B = SLU9359D

C = SJX6113Z




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on Eu tong Sen street on 25/6/2019 about 830pm. Approaching a traffic junction, the traffic light turned red and my car came to a complete stop.


Out of a sudden vehicle SLU9359D collided onto the rear of my vehicle causing me to inch forward and collided to vehicle SJX6113Z

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPORTING CENTRE PERSONNEL'S SIGNATURE



**SINGAPORE
POLICE FORCE**



T/20190626/2000

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20190626/2000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/06/2019 00:17		Vide Report No.:		Station Diary No.: 10	
Informant's Particulars					
Name of Informant: NEO SOON CHEN, TERRY			Address: APT BLK 239 HOUGANG STREET 22 #07-01 SINGAPORE 530239		
ID Type / ID No.: NRIC NO / S8604191Z			Contact No.: Home/Office: Mobile: 96153041		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 09/02/1986	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: ACCOUNTING MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/06/2019 20:30	Type of Location:
Location: Along Road 1 EU TONG SEN STREET Along Eu Tong Sen Street's traffic junction.				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH5465Z	Car				Seriously Damaged	1
SJX6113Z	Car					0
SLU9359D	Car					0



**SINGAPORE
POLICE FORCE**



T/20190626/2000

2 of 3

Report No. T/20190626/2000

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Brief Details.

On 25/06/2019 at about 2030hrs, I was travelling in my vehicle (SJH 5465Z) along Eu Tong Sen Street and everything was in order. After reaching the traffic junction, the traffic light turned red and my vehicle came to a complete stop and there was another vehicle (SJX 6113Z) in front of me.

A short while later, I felt an impact at the rear of my vehicle. It was when I realized that I was involved in a traffic accident after the vehicle (SLU 9359D) from the rear came and collided onto me. Due to the impact of the accident, I suffered some head injuries and was given three days medical certificate from the doctor. Furthermore, my vehicle suffered dents from the front and rear of the bumper and my wife whom was with me at the point of time did not suffer any injuries.

I am lodging this report for record and insurance purposes.

Details of the driver for SLU 9359D
Goh Theng Wee
S7501639E
Contact number: 9623 2505



**SINGAPORE
POLICE FORCE**



T/20190626/2000

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20190626/2000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 1 ONG YU HAN

Signature Of Interpreter:
Not applicable




Officer In Charge Of Case:
TP / AEIT /
SI MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Authentication Stamp
NP168

Signature Of Informant:


Date/Time:
26/06/2019 00:17

Classification Of Case:



Accident Sketch Plan Pg. 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8604191Z



Name
NEO SOON CHEN, TERRY



族名
梁 順 程

Race
CHINESE

Date of birth
09-02-1989

Sex
M

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE




Class 3 Motor Cars < 3500 kg with < 7 passengers; exclusive of the cab; and a two motor vehicles < 3500 kg

Valid from 01 Feb 2011 to 01 Sep 2015

DR 1000071

860412



NRID No. S8604191Z



Date of issue
16-12-2011

Address
APT BLK 299 HOUGANG STREET 22
#07-01
SINGAPORE 530239

YOU ARE CURRENTLY DRIVING A CLASS 3 MOTOR CAR WITH 7 SEATS


Class 3 Motor Cars < 3500 kg with < 7 passengers; exclusive of the cab; and a two motor vehicles < 3500 kg

Valid from 01 Feb 2011 to 01 Sep 2015

NR 428A

License No. S8604191Z





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form X1

CERTIFICATE NUMBER : MP307930

Type of Coverage : Comprehensive

Own Damage Excess : SGD600.00

Sum Insured : Market Value

Windscreen Excess : SGD100.00

- | | |
|--|--------------|
| 1. Index Mark and Registration Number of Vehicle | SJH5465Z |
| Chassis Number of Vehicle | GJ11300893 |
| 2. Name of Policyholder | NEO, ENG TAI |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 13 Aug 2018 |
| 4. Date of Expiry of Insurance | 12 Aug 2019 |
| 5. Persons or Classes of Persons entitled to drive* | |
| 01. NEO, ENG TAI | 02. N/A |
| 03. N/A | 04. N/A |
| 05. N/A | 06. N/A |

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.

This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

Hire Purchase Company : N/A

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.

Issue on: 05 Aug 2018

MOTOR CAR (Frt)

Front Portion

Vehicle No: **5JH5465Z**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	DD	✓	
1002	991887	Frt Number Plate Base	CRA	✓	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD	✓	
1005	992341	Frt Bumper Clips	WEC	✓	6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS	✓	
1008	991433	Frt Bumper Reinforcement	DD	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper and Tow Eye Cover	MIS	✓	
1013	991363	Frt Bumper Grille	CRA	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	MIS	✓	
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA	✓	
1022	991328	Frt Grille Emblem	MIS	✓	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT	✓	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA	✓	
1030	991821	Frt RH Headlamp Assy	CRA	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BUC	✓	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	BT	✓	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge	BT	✓	2
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BT	✓	
1043	990122	Air Con Fan Assy	BT	✓	
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	✓	
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)	DD	✓	
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	DD	✓	
1053	992738	Radiator Cowling	CRA	✓	
1054	992742	Radiator Fan Assy	CRA	✓	
1055	992745	Radiator Fan Clutch	CRA	✓	
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct	CRA	✓	
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990039	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	CRA	✓	
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992232	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

24/7/2019

MOTORCAR (Rear)

25/2

Rear Portion

NAC	INC	Item	CON	ACQ	Q
1137	993626	Rear Number Plate	DD	✓	
1138	993627	Rear Number Plate Base	DIS	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CRA	2	
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	MEC	6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	2	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	Short	DM	✓
1159	993327	Rear End Panel	BUC	✓	
1160	993339	Rear End Panel Top Garnish	CRA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BUC	✓	
1182	991328	Tailgate Emblem	MEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding Handle	DIS	✓	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp LH & RH	CRA	2	
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	MEC	✓	
1196	994607	Tailgate Glass Sealant	MEC	✓	
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	DIS	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA	✓	

Vehicle No

SJH 5465Z

NAC	INC	Item	CON	ACQ	Q
1202	993784	Spare Tyre Board	CRA	✓	
1203	994328	Spare Tyre Panel	BUC	✓	
1204	995065	Spare Tyre Panel Insulator	MEC	✓	
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover	ONT	✓	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	CRA	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Rear View Camera			
		LH Taillamp Lower Garnish	CRA	✓	

24/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2019 Edit Reg		27 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: GOH THENG WEE , ID: S7501639E									
Main Claimant: NEO ENG TAI , ID: S0189226F									
Vehicle Reg. No.: SJH5465Z		Date of Loss: 25/06/2019 20:00 - :59 [130 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0858656789SG		Policy/Cover Note No.: 1800016612 (Comprehensive)							
Vehicle Reg. No. (Insured): SLU9359D		Policy No. (Claimant):							
		Excess:							
Repairer: Aka Auto (HQ) 25 Kaki Bukit Road 4, #05-58, Synergy@KB, 417800 Kaki Bukit - Tel: 81880754									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (10/07/2019): TP GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJH5465Z (0858656789SG)
[SLU9359D]
TP
NEO ENG TAI
Jun 25 2019 8:00PM
[GOH THENG WEE]
Aka Auto

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print	
1	10/07/19 13:41	Accident Statement From:OD - Reg. No: SLU9359D, Claimant: GOH THENG WEE										Load HTM		
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
2	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
3	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
4	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
5	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
6	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
7	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
8	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
9	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
10	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
11	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
12	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
13	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
14	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
15	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
16	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
17	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
18	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
19	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
20	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
21	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
22	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
23	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
24	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
25	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
26	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
27	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
28	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
29	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
30	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
31	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
32	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	
33	09/07/19 12:59	General View										Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
34	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
35	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
36	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
37	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
38	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
39	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
40	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
41	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
42	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
43	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
44	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
45	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
46	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
47	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
48	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
49	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
50	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
51	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
52	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
53	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
54	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
55	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
56	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
57	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
58	09/07/19 12:59	General View		Load JPG <input checked="" type="checkbox"/>
59	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
60	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
61	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
62	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
63	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
64	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
65	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
66	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
67	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
68	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
69	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
70	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
71	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
72	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
73	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
74	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
75	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
76	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
77	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
78	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
79	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
80	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
81	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
82	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
83	09/07/19 13:00	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
134	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	09/07/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011439/R1CD3E2

Date: 31/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800016612

Claimant Vehicle No : SJH5465Z

Insured Vehicle No : SLU9359D

Date of Loss: 25/06/2019

Nature of Claim: TP

Claim No: 0858656789SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJH5465Z**

Make & Model: HONDA AIRWAVE, 1.5 M (A)

Engine No: L15A5200927

Reg. Date: 13/08/2008 (Man. Year: 2008)

Chassis No: GJ11300893

Colour: Grey

Odometer: 262323 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/06/2019

Date Inspected: 27/06/2019 Inspected At:

25 Kaki Bukit Road 4 Synergy @ KB #05-36

Repairer : Aka Auto (HQ)

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Dented	0.00 F	*-F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*-F
3	1		*FRT BUMPER	Dented	0.00 F	*-F
4	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
5	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
6	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*-F
7	1		*FRT BUMPER TOW EYE COVER	Missing	0.00 F	*-F
8	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*-F
9	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*-F
10	1		*FRT GRILLE	Cracked	0.00 F	*-F
11	1		*FRT GRILLE EMBLEM	Missing	0.00 F	*-F
12	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
13	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
14	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*-F
15	1		*BONNET	Buckled	0.00 F	*-F
16	1		*BONNET LOCK	Bent	0.00 F	*-F
17	1		*BONNET INSULATOR	* Check	0.00 F	*-F
18	2		*BONNET HINGE	Bent	0.00 F	*-F
19	1		*BONNET RUBBER	* Check	0.00 F	*-F
20	1		*AIR CON CONDENSER	Bent	0.00 F	*-F
21	1		*AIR CON FAN ASSY	Cut	0.00 F	*-F
22	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	Bent	0.00 F	*-F
23	1		*AIR CON SUCTION HOSE	* Check	0.00 F	*-F
24	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Dented	0.00 F	*-F
25	1		*AIR CON LIQUID PIPE	* Check	0.00 F	*-F
26	1		*RADIATOR	Dented	0.00 F	*-F
27	1		*RADIATOR COWLING	Cracked	0.00 F	*-F
28	1		*RADIATOR FAN ASSY	Cut	0.00 F	*-F
29	1		*AIR DUCT	Cracked	0.00 F	*-F
30	1		*ENGINE UNDER COVER	Cracked	0.00 F	*-F
31	1		*REAR NUMBER PLATE	Dented	0.00 F	*-F
32	1		*REAR NUMBER PLATE BASE	Distorted	0.00 F	*-F
33	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*-F
34	1		*REAR BUMPER	Dented	0.00 F	*-F
35	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
36	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
37	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*-F
38	1		*REVERSE SENSOR	Shorted / Damaged	0.00 F	*-F
39	1		*REAR END PANEL	Buckled	0.00 F	*-F
40	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*-F
41	1		*REAR LH TAILLAMP	Cracked	0.00 F	*-F
42	1		*REAR RH TAILLAMP	Cracked	0.00 F	*-F
43	1		*TAILGATE	Buckled	0.00 F	*-F
44	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
45	1		*TAILGATE OUTER HANDLE	* Check	0.00 F	*-F
46	1		*TAILGATE INNER HANDLE	Cut	0.00 F	*-F
47	1		*TAILGATE GARNISH	Distorted	0.00 F	*-F
48	2		*TAILGATE LAMP LH & RH	Cracked	0.00 F	*-F
49	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
51	1		*TAILGATE LOCK	Bent	0.00 F	*- F
52	1		*TAILGATE RUBBER	Distorted	0.00 F	*- F
53	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
54	1		*SPARE TYRE BOARD	Cracked	0.00 F	*- F
55	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
56	1		*SPARE TYRE PANEL INSULATOR	Necessary	0.00 F	*- F
57	1		*SPARE TYRE COVER	Cut	0.00 F	*- F
58	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*- F
59	1		*REVERSE CAMERA	* Check	0.00 F	*- F
60	1		*LH TAILLAMP LOWER GARNISH	Cracked	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >