

A.S. REC. BY:

REF:

CS3/ALG19011481/Mcd307

Special Instruction:

Surveyor: Taufiq

menemen

ASSIGNMENT (Office)

From (Person): Chin Lee Yiney

of

ALG

Date/Time: 8/7/19 @ 4.43pm

Estimated Cost:

Bill to:

OD/PT/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SAN 567A

Insured:

SJR 79954

at Workshop m/s

platinum workz

Tel:

98528570

of

53 ubi Ave 1 #01-25

Policy No:

1700090773

Claim No:

148073866686

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

9/7/19

H.O.D. Endorsement:

Date/Time:

520pm @ 8/7/19

Person Contacted:

Gorden

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate / ✓
	SAN 567A - X
	SJR 79954 - X
	Diamond: 9/7/2019
	After repair: 11/7/2019

ASS. REC. BY: *Tough*

REF AIG

ASSIGNMENT

From: Date: 9.7.19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGN 567A
at Workshop m/s *Plah num work 2*
of 53 Ubi Ave 1 #01-23

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 12.00 p.m. Owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAG Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *my*

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGN 567A Yr Regn: May 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 c.c. 1595

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 30552 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 205042R390273

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size: F: 225/60 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Continental*

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at *Plah num work 2*Des. of Damages: Frt *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no GUA

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: *DAR*

Lump Sum / I.B.I. (\$))

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

180

11


191

PRI

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2019		08 Jul 2019 00:00				Pending for Survey Report
	Edit Reg		Edit Adj Rpt				Cancel Case

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp_clmheader&caseid=842114&extid=309567&CFID=5782... 1/2

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR7995U AND SGN567A ON 30/06/2019

From: Chin, Lee-Ying
To: assignments, Admin A
Cc:
Sent: 7/8/2019 4:43:05 PM
Attachments:  GIA.PDF

Hi LKK,

Owner will leave vehicle tonight, please arrange survey tomorrow.

Thanks.

Best Regards

Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Li Ping [mailto:Prs.pd@slawch.com]

Sent: Tuesday, July 02, 2019 2:37 PM

To: Hor, Yinrul

Cc: 'Platinum Werkz'

Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR7995U AND SGN567A ON 30/06/2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly take note we have some changer for the contact person, we would like to change under **Gordan (HP:98528570)**.

Regards

Li Ping

Did: 6909 5194

11 Keng Cheow Street #02-03 Riverside Piazza Singapore 059608



SL LAW CHAMBERS

This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

From: Li Ping [mailto:Prs.pd@slawch.com]

Sent: Tuesday, July 02, 2019 2:27 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; 'Platinum Werkz'

Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR7995U AND SGN567A ON 30/06/2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear Sir/Mdm,

ACCIDENT INVOLVING SGN567A & SJR7995U ALONG CTE TOWARDS AMK AVE 5 ON 30/06/2019 @ 12:40

We refer to your letter dated 2 July 2019 confirming your intention to conduct a pre-repair survey on our client's vehicle **SGN567A**.

We have instructions to reject your surveyor and propose to engage **Winson Goh from WG Appraisal Services**.

Please be informed that said vehicle can be inspected at:

Workshop: Platinumwerkz
Address: 53 Ubi Avenue 1 #01-25 (Paya Ubi Industrial Park) Singapore 408934
Contact Person: YS (HP: 9238 9179)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence

For Surveyor: To initial after Completion

1st Inspection

Appointed surveyor
(Name & Signature)

Date & Time

2nd Inspection

Appointed surveyor
(Name & Signature)

Date & Time

3rd Inspection

Appointed surveyor
(Name & Signature)

Date & Time

Regards

Li Ping

Did: 6909 5194

11 Keng Cheow Street #02-03 Riverside Piazza Singapore 059608



SL LAW CHAMBERS

This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	606B
Vehicle Details	
Vehicle No.:	SGN567A
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	27491031362939
Chassis No.:	WDD2050402R390273
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$36,478.00
Original Registration Date:	23 May 2018
First Registration Date:	23 May 2018
Transfer Count:	0
Actual ARF Paid:	\$43,070.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2028
PARF Rebate Amount:	\$32,302.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,605.00
COE Rebate Amount:	\$32,914.00
Total Rebate Amount:	\$65,216.00

The information contained herein is correct as at 21 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/07/2019 15:40
Date Of Accident	30/06/2019 12:40
Exact Location Of Accident	CTE TWDS AMK AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN567A
Insured/Policyholder	
Name Of Registered Owner	OH BENG HUA
NRIC No	S1643606B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93862390
Alternative Phone No	OFFICE-93862390

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180 AVANTGARDE (R17 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29084374QMY
Cover Note Number	

Driver

Name of Driver	CHRISTINA OH SHIIN CHENG
NRIC No	S1560626F
Date Of Birth	11/07/1962
Occupation	OUTDOOR
Date Of Driving Pass	28/05/2004
Driving Experience	15 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-93862390
Fax Number	
Contact Number	OFFICE-93862390
EMail Address	NOEMAIL

Address	BLK 320 HOUGANG AVENUE 5 #04-04
Postcode	530320
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7995U
Vehicle Make/Model/Colour	MAZDA 3 sedan 1.5
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	XU WEI MING
NRIC/Passport Number	S8534744F
Contact Number	92392855
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHRISTINA OH SHIIN CHENG
------	--------------------------

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SGN567A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:


Accident Sketch Plan

Vehicle A: SHN 507A

Vehicle B: SJR 7995U

CRD 011 1000 0000

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was the driver of vehicle A and my vehicle was stationary, waiting to exit highway 411 at a red light. I felt an impact coming from the back and I realised I was hit by vehicle B from the rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRCC PIN No.:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CRA	✓	1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side	CUT	✓	1
1145	993103	Rear Bumper Tow Cover	R/H	✓	1
1146	992341	Rear Bumper Clips	N/C	✓	1 set
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	R/H	✓	1
1149	993045	Rear Bumper Reinforcement	B+	✓	1
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad	Lower Garnish	✓	1
1155	993026	Rear Bumper Moulding	chrome	✓	1
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	outer R/H	✓	1
1159	993327	Rear End Panel	DD	✓	1
1160	993339	Rear End Panel Top Garnish	CRA	✓	1
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	1
1167	993853	Rear RH Taillamp Garnish	CRA	✓	1
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	1
1171	991328	Bootlid Emblem	NEC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SGN 567A

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993471	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI












































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2019 Edit Reg		08 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	XU WEIMING , ID: S8534744F								
Main Claimant:	OH BENG HUA , ID: S1643606B								
Vehicle Reg. No.:	SGN567A	Date of Loss:	30/06/2019 12:00 - :59 [13 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1480738666SG	Policy/Cover Note No.:	1700090772 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJR7995U	Policy No. (Claimant):							
		Excess:							
Repairer:	Platinumwerkz (HQ) 53 Ubi Avenue 1 #01-25 (Paya Ubi Industrial Park), 408934 Ubi - Tel: 88261413								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/07/2019]								
Claimant's Solicitor:	SI Law Chamber - Tel: 6909 5194								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (09/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGN567A (1480738666SG)
[SJR7995U]
TP
OH BENG HUA
Jun 30 2019 12:00PM
[XU WEIMING]
Platinumwerkz

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
2	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
3	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
4	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
5	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
6	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
7	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
8	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
9	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
10	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
11	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
12	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
13	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
14	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
15	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
16	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
17	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
18	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
19	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
20	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
21	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
22	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
23	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
24	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
25	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
26	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
27	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
28	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
29	21/08/19 09:50	General View										Load JPG	<input checked="" type="checkbox"/>	
30	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
31	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
32	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
33	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
34	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
35	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
36	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
37	21/08/19 09:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	21/08/19 09:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/07/19 10:19	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011481/T1CD3E2

Date: 21/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700090772
Claimant Vehicle No : SGN567A **Insured Vehicle No :** SJR7995U
 Date of Loss: 30/06/2019 Nature of Claim: TP Claim No: 1480738666SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN567A**
 Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491031362939
 Reg. Date: 23/05/2018 (Man. Year: 2018) Chassis No: WDD2050402R390273
 Colour: White Odometer: 30552 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/07/2019
 Date Inspected: 09/07/2019 Inspected At: Platinumwerkz (HQ)
 53 Ubi Avenue 1 #01-25 (Paya Ubi Industrial Park)
 Singapore 408934
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	0.00 F	*- F
2	1		*REAR BUMPER SIDE	Cut	0.00 F	*- F
3	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER R/H	Cracked	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER LOWER GARNISH	Scratched	0.00 F	*- F
7	1		*REAR BUMPER MOULDING CHROME	Scratched	0.00 F	*- F
8	1		*REVERSE SENSOR OUTER R/H	Shorted	0.00 F	*- F
9	1		*REAR END PANEL	Dented	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR RH TAILLAMP GARNISH	Crumpled	0.00 F	*- F
13	1		*BOOTLID	Repair	0.00 F	*- F
14	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
15	1		*BOOTLID RUBBER	Dented	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >