

22/03/2003

ASS. REC. BY:

REF: CS3/SM019011487/ECd302

Special Instruction:

Surveyor: Steve ASSIGNMENT (Office)

From (Person): Hwang shiang yi of SMD Date/Time: 26.6.19 12:21 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBF 8461U Insured: FBD 70C

at Workshop m/s Chuk Kong Motor Tel: 63295205

of Block 1, 387B Woodland Road Yew Tee

Policy No: DIB MTRK 01005151 Claim No: CMTD 1903078

Sum Insured: Excess:

Make of Veh: D.O.A. 26.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26.6.19 1:00 PM Person Contacted: Wai kg Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBD 70C NBA/INC14004396/34 D.O.A. 06/03/2014
	FBF 8461U: X
	Dismantle: 28/6/2019

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBF 84614 M Regn: 15/12/11
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha F2 16 CC: 153
Colour: Red A/C: Insured / Std / NI /
Sp. Reading: 99999 T/Rwlin: Insured / Std / NI
Eng/No: ME 121C 079 B 2012 895
Ci/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 100/70 R17
R: 130/70 R17
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 Rear: 6
R/Bal. _____ mm R/Bal. _____
L/Bal. _____ mm L/Bal. _____
D.O.A. 26/6/19 D.O.I. 28/6/19
Survey held at Chek Kong Mtr
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to co

Date / Time Action / Instruction

MV- 3K

Range + Days
23K-3K, 3 days

9/7/2019

Date/Time: File Pass to? ☐ : Prel. Report
4) ☐ : Final Report

Date/Time: File Return to?

2)

Report Format: PRE
Lump Sum / I.B.B. (%)

Days Of Repair: 3
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation
3 + R5 24
Photos
Collection

100
60
11
171

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jun 2019		28 Jun 2019 12:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAY CHEE MENG, ID: S7725757H, Tel: +6597993047, Email: cheemeng.tay@gmail.com		
Main Claimant:	MESKUM BIN JOE, ID: S1727168G		
Vehicle Reg. No.:	FBF8461U	Date of Loss:	26/06/2019 14:00 - :59
Claim Type:	TP / CMTD1903078	Policy/Cover Note No.:	D18MTMC01005151 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBD70C	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2019]		
Driver/Custodian (Insured):	TAY CHEE MENG (41 / Male), NRIC: S7725757H, Tel: +6597993047 Email: cheemeng.tay@gmail.com		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Lee Wee Ka <weeka@gohjpwong.com>
Sent: Friday, 28 June 2019 12:28 PM
To: Teo, Grace
Cc: admin-d@lkkauto.com; assignments@lkkauto.com; Hwang, Shiang Yi; Ye, Yong Kang Melvin
Subject: Re: CMTD1903078/SYH - LKK/ FBD70C & FBF8461U ACC ON 26.06.19 \ Yr Ref: GTW.ACC.6070.19

Dear Mdm

Our client's motorcycle FBF 8461U is now at Chek Kong Motor Pte Ltd at Block 1, 387B Woodlands Road, Yew Tee Industrial Estate Singapore 677948 (Tel: 6769 8793 - Mr Lionel)

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days. Kindly advise your surveyor to liaise with the workshop directly to conduct the post-repair inspection.

Kindly extend to us a copy of your surveyor's pre-repair inspection report once the report has been completed

Lee Wee Ka
for and on behalf of Goh Teck Wee
Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.
You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, Jun 28, 2019 at 12:18 PM Teo, Grace <grace.teo@sompo.com.sg> wrote:
Our Reference: CMTD1903078/SYH
Your Reference GTW.ACC.6070.19

Without Prejudice
EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Date: 28/06/2019

Attention:
M/S GOH JP & WONG LLC

Dear Wee Ka,

ACCIDENT INVOLVING FBD70C & FBF8461U ON 26.06.2019

We refer to your email of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

Kindly provide us the address of location and contact for our motor surveyor to conduct the pre-repair survey.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Lee Wee Ka [<mailto:weeka@gohjpwong.com>]

Sent: Friday, June 28, 2019 11:49 AM

To: Teo, Grace

Cc: Hwang, Shiang Yi; Ye, Yong Kang Melvin

Subject: Re: CMTD1903078/SYH - PRI/ FBD70C & FBF8461U ACC ON 26.06.19 \ Yr Ref: GTW.ACC.6070.19

Dear Mdm

We are not agreeable to your proposed motor surveyors.

Our list of proposed Single Joint Expert ("SJE") as follows:-

1. Dylan Lee of Lee Appraisal Services
2. Jayson Liaw Leong San of Pro-Option Services
3. Seah Kwang Boon of Absolute Appraisal Services

4. Oh Han Cheong of Oh Appraisal
5. Bok Jee Tan of Prudent Adjustors Services
6. Fong Kok Heng Stanley of Automax Survey
7. Sebastian Lim Yong Tian of Constant Appraiser Services
8. Lek Boon Hwee of Auto Performance Appraisal
9. Louis S C Ng Cae Amimi of Prestige Appraiser Services
10. Richard Wong Ah Kow of R W Automotive Appraiser Services

Kindly let us hear from you soonest.

Lee Wee Ka
for and on behalf of Goh Teck Wee

Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, Jun 28, 2019 at 11:04 AM Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1903078/SYH

Your Reference GTW.ACC.6070.19

Without Prejudice

EMAIL ONLY

Date: 28/06/2019

Attention:

M/S GOH JP & WONG LLC

Dear Wee Ka,

ACCIDENT INVOLVING FBD70C & FBF8461U ON 26.06.2019

We refer to your Notice of Accident dated 25/06/2019.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Lee Wee Ka [mailto:weeka@gohjpwong.com]
Sent: Friday, June 28, 2019 9:03 AM
To: Claims - Motor Survey
Subject: pre repair inspection notice - Our Ref: GTW.ACC.6070.19

Dear Sir/Mdm

NOTIFICATION OF ACCIDENT
SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FBF 8461U & FBD 70C ON 26.6.2019
ALONG DUNEARN ROAD

We enclosed herewith the pre repair inspection notice dated 28th June 2019 for your attention.

Lee Wee Ka

for and on behalf of Goh Teck Wee
Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and

notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7168G
Vehicle Details	
Vehicle No.:	FBF8461U
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	FZ 16
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	21C7012902
Chassis No.:	ME121C079B2012895
Maximum Power Output:	-
Open Market Value:	\$2,112.00
Original Registration Date:	15 Dec 2011
First Registration Date:	15 Dec 2011
Transfer Count:	3
Actual ARF Paid:	\$317.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,902.00
COE Rebate Amount:	\$466.00
Total Rebate Amount:	\$466.00

The information contained herein is correct as at 01 Jul 2019

OK



(7)

model

Yamaha FZ16

Type

Any

Price From

Any

Price To

Any

Class


Any

more search options

Q SEARCH

VIEW ALL (LISTING/USED BIKES/LISTING)

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/12960/)



REG \$4500

Reg: 02/10/2012

Type: Street Bikes

153cc

-

Engine in tip top condition. Good fuel consumption. Great beginner bike. Stock pipe will be given. Price Negotiable. View to believe.

Posted on: 08/06/2019

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-12960/)

BIKE GADGETS


Plates for Sale (/listing/motorcycle/golden-number-plate-for-sale/)

Installation Calculator (/installment_calculator/)

Instant Insurance Quote (/motorcycle-insurance/landing/)

Bounty (/bounty/)

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/12952/)



REG \$7200

Reg: 08/07/2015

Type: Street Bikes

149cc

58000km

Black And Gold Colour 2015 Yamaha Fz16 Ver. 2. Bike is Well Maintained. Servicing Every 1500km. Aesthetics: 7/10 (Paint Chips On Rims, Scratches From A Stationary Drop). Functionality: 9/10. ...

Posted on: 08/06/2019

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/12952/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/12845/)



REG \$4700

Reg: 06/12/2013

Type: Street Bikes

153cc

45729km

Yamaha FZ16 with electric start and kick start for Sale. Selling because under utilized and driving car. Viewing at Punggol. WhatsApp for more details. Price negotiable.

Posted on: 28/05/2019

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/12845/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 ST (/listing/usedbike/yamaha-yamaha-fz16-st/12823/)



REG \$6500

Reg: 01/04/2014

Type: Street Bikes

153cc

23000km

2014 Yamaha Fz16 ST. Coe Renewable. Still in Very Good Condition. Road Tax Already Renewed Until March 2020. Recently Changed Battery And Bike Chain. Viewing At Marling Mt And Woodlands ...

Posted on: 27/05/2019

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/12823/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/12800/)



REG \$5500

Reg: 28/07/2011

Type: Street Bikes

153cc

97510km

Selling a reliable workhorse. It serve me well. Currently still under hire purchase. Bike in good condition. Only the Meter LCD abt faded and right side sticker need to change due to fall ...

Posted on: 24/05/2019

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/12800/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/12723/)



REG \$3500

Reg: 29/11/2011

Type: Street Bikes

153cc

1km

Bike is in good condition. Well maintained. Full cash only. Able to nego due the led speedometer.

Posted on: 17/05/2019

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/12723/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 ST (/listing/usedbike/yamaha-yamaha-fz16-st/10250/)



REG \$4500

Reg: 11/05/2015

Type: Street Bikes

153cc

89970km

Posted on: -

FIND AD

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/10250/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 ST (/listing/usedbike/yamaha-yamaha-fz16-st/12092/)



REG \$4500

Reg: 05/07/2012

Type: Street Bikes

153cc

20000km

FZ16ST with COE till 4 July 2022. Comes with: 15k Oil Filter, 2k Rectifier. Price negotiable.

Posted on: -

FIND AD

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/12092/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/10836/)



REG \$4500

Reg: 07/02/2013

Type: Street Bikes

153cc

95000km

Selling my bike because I have bought a CB400. This bike has serves me for 6 years without any major problem. Maintenance such as clutch broken, brake pads, etc are normal maintenance whic...

Posted on: -

FIND AD

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/10836/)


COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 (/listing/usedbike/yamaha-yamaha-fz16/7811/)



REG \$4500

Reg: 12/02/2014

Type: Street Bikes

153cc

-

Red Yamaha FZ16. COE till 2024. Vehicle is in very good condition. Only used to go my office. Am planning to buy for us selling this bike. Please contact for viewing if you are interested.

Posted on: -

FIND AD

DIRECT SELLER

COMPARE

DETAILS (/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/7811/)

COE RESULTS

Rd 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000



0/

Bike model	Type	Price From	Price To	Class
Yamaha FZ16	Any	Any	Any	Any

WIDE SEARCH OPTIMIZED

QL SEARCH VIEW ALL (LISTING/USED/BIKES/USING/USING)

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/12902/)

 **\$4900** Reg: 14/11/2012 Type: Street Bikes 153cc

Visit United Cycles! Trade In/Loan Available! Price Hags For Sincere Buyers! Call Now!

Posted on: 01/07/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/12902/)

COMPARE

BIKE GADGETS

Number Plates for Sale (listing/motorcycle/golden-number-plate-for-sale/)

Installation Calculator (listing/installment_calculator/)

Instant Insurance Quote (listing/motorcycle-insurance/landing/)

Routry (Bounty/)

Yamaha FZ16 (listing/usedbike/yamaha-yamaha-fz16/12880/)

 **\$5800** Reg: 13/02/2014 Type: Street Bikes 153cc

Trade In/Loan of vehicle available. Interested buyers are welcome to reg. Come visit Albert Motor Supply.

Posted on: 28/04/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/12880/)

COMPARE

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/12689/)

 **\$4888** Reg: 18/05/2013 Type: Street Bikes 153cc

Well maintained bike. Showroom condition.

Posted on: 14/06/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/12689/)

COMPARE

COE RESULTS

Reg 2, 19 Jun 2019

COE Bidding of Motorcycles

CAT D \$3000

Yamaha FZ16 (listing/usedbike/yamaha-yamaha-fz16-st/12938/)

 **\$5999** Reg: 03/12/2014 Type: Street Bikes 153cc 45000km

Very Well Taken Care Of. Spent A Lot To Take Care Of This Bike. Only 3 Owners. Overall Bike Condition 9.5/10. Severely Under Utilize Because I Have A Daily Driven Car. This Bike Is Mainly...

Posted on: 06/04/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/12938/)

COMPARE

See the list of used bikes for sale

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/12517/)

 **\$5200** Reg: 20/06/2013 Type: Street Bikes 153cc 64000km


Paint to point work horse. Accident free. Scratches on the exhaust cover. Fuel efficient. Fuel tank can go up to 500km. Bike serviced every 2500 km; engine oil, spark plug, oil filter items...

Posted on: 02/06/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/12517/)

COMPARE

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/11917/)

 **\$4500** Reg: 04/10/2013 Type: Street Bikes 153cc 70000km

Bike outlook converted to FZ16. Bike fully paid.

Posted on: 15/05/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/11917/)

COMPARE

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/13210/)

 **\$5500** Reg: 03/12/2014 Type: Street Bikes 153cc 50800km

Letting Go My Beloved FZ16ST. Religiously Maintained At Least Once A Month. Very Fuel Efficient. 1-1.5 Weeks Only Pump Once With Daily Commute To And Fro. Everything Is Stock Accessories. Like I...

Posted on: 27/06/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/13210/)

COMPARE

Yamaha FZ16 (listing/usedbike/yamaha-yamaha-fz16/13047/)

 **\$5000** Reg: 29/05/2012 Type: Street Bikes 153cc 13000km


2012 Yamaha FZ16. Well Taken Care Bike. Servicing has Been Done Consistently. Good Bike For Beginner's As The Fuel Consumption Is Not That Much. Full Tank Is 12L. Plus Reserve. Road Tax 18L.

Posted on: 15/06/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/13047/)

COMPARE

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/13032/)

 **\$4300** Reg: 02/09/2018 Type: Street Bikes 153cc 78000km

Sep 2013 FZ16ST for sale. Changing To A Bigger Bike. Bike Used Mainly To Go Work To And Fro. Recently Serviced One Way Starter And Normal Servicing (Eng Oil And Oil Filter). Bike Never Give A...

Posted on: 16/06/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/13032/)

COMPARE

Yamaha FZ16 ST (listing/usedbike/yamaha-yamaha-fz16-st/13030/)

 **\$3800** Reg: 25/04/2012 Type: Street Bikes 153cc 98000km

Yamaha Fazer FZ16ST. Replaced Forks And SU Unit In 2018 May-June.

Posted on: 14/06/2019

DETAILS > (LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16-ST/13030/)

COMPARE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/06/2019 17:22
Date Of Accident	26/06/2019 15:00
Exact Location Of Accident	ALONG BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBF8461U
Insured/Policyholder	
Name Of Registered Owner	MESKUM BIN JOE
NRIC No	S1727168G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87881810
Alternative Phone No	OTHERS-87881810
Vehicle Particulars	
Manufacturer	YAMAHA
Model	FZ16
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	AN3166099
Cover Note Number	
Driver	
Name of Driver	MESKUM BIN JOE
NRIC No	S1727168G
Date Of Birth	29/12/1965
Occupation	INDOOR
Date Of Driving Pass	27/04/2000
Driving Experience	19 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87881810
Fax Number	
Contact Number	OTHERS-87881810
Email Address	NOEMAIL

Address	BLK 418 FAJAR ROAD #08-431
Postcode	670418
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG
Police Station Address	ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	NIZAM (SAFETY OFFICER)
Phone Number	
Email Address	93842964

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBD70C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TAY CHEE MENG
NRIC/Passport Number	S7725757H
Contact Number	97993047

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MESKUM BIN JOE

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBF8461U

Were seat belts worn? NO

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

26.6.2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26-6-2019 about 3PM, I was riding my motor cycle (FBF84614) along bukit timah road and there was construction work on my right. When one of the construction worker display a signage to asking to stop to let cement truck come out from the construction site, I immediately stopped my motor cycle and after a few second one motorcycle (FBF 70C) hit me from the back caused my bike to fell down and he stopped in front of me. Both of us skitted out motorcycle to a safe spot to exchange particulars. After the incident I felt my right leg and hip suffered pain.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

26.6.2019

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.



































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jun 2019		28 Jun 2019 12:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case





















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAY CHEE MENG , ID: S7725757H, Tel: +6597993047, Email: cheemeng.tay@gmail.com									
Main Claimant: MESKUM BIN JOE , ID: S1727168G									
Vehicle Reg. No.: FBF8461U		Date of Loss: 26/06/2019 14:00 - :59 [90 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1903078		Policy/Cover Note No.: D18MTMC01005151 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): FBD70C		Policy No. (Claimant):							
		Excess:							
Repairer: Chek Kong Motor Pte Ltd (HQ) BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL ESTATE, 677948 Woodlands - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang YI - 6329 5205]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 09/07/2019]									
Driver/Custodian (Insured): TAY CHEE MENG (41 / Male) , NRIC: S7725757H, Tel: +6597993047 Email: cheemeng.tay@gmail.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBF8461U (CMTD1903078)**
[FBD70C]
TP
MESKUM BIN JOE
Jun 26 2019 2:00PM
[TAY CHEE MENG]
Chek Kong Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/19 12:20	Accident Statement From: SC - Reg. No: FBD70C, Claimant: TAY CHEE MENG	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/07/19 09:39	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
34	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
35	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
36	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
37	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
38	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
39	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
40	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
41	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
42	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
43	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
44	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
45	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
46	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
47	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
48	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
49	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
50	01/07/19 09:39	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
51	01/07/19 09:39	Chassis Number		Load JPG <input checked="" type="checkbox"/>
52	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
53	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
54	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
55	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
56	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
57	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
58	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
59	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
60	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
61	01/07/19 09:39	General View		Load JPG <input checked="" type="checkbox"/>
62	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
63	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
64	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
65	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
66	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
67	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
68	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
69	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
70	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
71	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
72	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
73	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
74	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
75	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
76	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
77	01/07/19 09:39	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
78	01/07/19 09:40	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
79	01/07/19 09:40	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
80	01/07/19 09:40	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
81	01/07/19 09:40	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
82	01/07/19 09:40	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
83	01/07/19 09:40	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
84	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
85	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
86	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
87	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
88	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
89	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
90	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
91	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
92	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
93	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
94	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
95	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
96	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
97	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
98	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
99	01/07/19 09:40	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/19 10:49	Pre-Repair Survey+PR	 Load PDF	
2	28/06/19 10:51	Third Party E-filed GIA report(M)	 Load PDF	
3	28/06/19 12:20	Pre-Repair Survey - ASSIGN LKK	 Load PDF	
4	28/06/19 14:11	Pre-Repair Survey - Chek Kong Motor Pte Ltd	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19011487/ECD3E2

Date: 11/07/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01005151

Claimant Vehicle
No : FBF8461U

Insured Vehicle No : FBD70C

Date of Loss: 26/06/2019

Nature of Claim: TP

Claim No: CMTD1903078

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBF8461U

Make & Model: YAMAHA FZ16, 153cc (M)

Engine No: 21C7012902

Reg. Date: 15/12/2011 (Man. Year: 2011)

Chassis No: ME121C079B2012895

Colour: Red

Odometer: 99999 km

Engine Capacity: 153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/70 R17

Rear Tyre Size: 130/70 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/06/2019

Date Inspected: 28/06/2019 Inspected At:

Chek Kong Motor Pte Ltd (HQ)
BLK 1 387B WOODLANDS ROAD, YEW
TEE INDUSTIRL ESTATE
Singapore 677948

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,300.00 -\$3,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Jul 2019)	
Parts:	N/A	YAMAHA FZ16 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF8461U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >