

TROCKING ASS. REC. BY:		REF: CS/SMO19011491/NVd302		Special Instructions:	
Surveyor: NAZ		ASSIGNMENT (Office)			
From (Person): Ruth Chua Eut Tjing		of SMO		Date/Time: 28.6.19 14:03 p.m.	
Estimated Cost:		Bill to:			
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS					
To Inspect Vehicle No: FBW 50484		Insured:			
at Workshop n/a Bike Production		Tel: 62995177			
of 610 Serangoon Road					
Policy No: D18MTMCD/006709		Claim No: CMTD1902910			
Sum Insured:		Excess: 600			
Make of Veh:		D.O.A. 13.6.2019			
(Client's Record)		2.7.2019			
CA / REV / REP. / REV 24 HRS		H.O.D. Endorsement:			
Date/Time: 28.6.19 2.17pm		Person Contacted: Wendy		Vehicle IN OUT	

Date/Time	Action/Instruction (✓) Estimate
	FBW 50484: CS/SMO19011491/NVd302
3/7/19	Revert via merimen
4/7/19	Recd approved \$3559 from Ruth via merimen
4/7/19	Informed Mr Kwan c/A on LS repair ex \$600 by email

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: ☒
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **9K**
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **wp**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **FBN 5048H** Yr Regn: **19 OCT 2018**
 Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **YAMAHA** XABRE cc **150CC**
 Colour: **MULTICOLOURED** A/C: Insured / Std / Nil / ☒ NA
 Sp Reading: **21,073** T/Radio: Insured / Std / Nil / ☒ NA
 Eng/No: _____
 C/No: **MH3 R437104K0-25671**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / ☒ STD A/Rim or
 Tyre Size: F: **110/70 R17**
 R: **130/70R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **EXATO**

Front: _____ Rear: _____
 R/Bal: **5** mm R/Bal: **5** mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: **13/6/19** D.O.I: **3/7/19**
 Survey held at **BIKE PRODUCTION**
 Des. of Damages: ☒ Fr / ☒ Rear / ☐ O/S / ☒ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: **20/7/19** Action / Instruction: **FINALIZED LUMP SUM REPAIR @ 3,000 BEFORE EXCESS / 3 REPAIR DAY**
(Red 3031.90, 5000)

RECEIVED 22 JUL 2019

Date/Time, File Path to: ☐ : Prelt. Report

to: ☐ : Final Report

Date/Time, File Path to:

20/7 - typist

Report Format: **mainmen**

Lump Sum / Tech: **3000/-**

Days Of Repair: **3**

Resurvey No. of Trip: **2**

Add Fee: ☐ : Site Insp (5)
☐ : Interview (5)
☐ : Tech Insp (5)
☐ : Night Insp (5)

Survey Fee:

Transportation:

2.1.11.11

Field:

11

261

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019		28 Jun 2019 14:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MALIEKIE BIN ROSLE, ID: S9249179Z, Tel: +6587801819, Email: malik.rosle92@hotmail.com								
Vehicle Reg. No.:	FBN5048H	Date of Loss:	13/06/2019 11:00 - :59						
Claim Type:	OD / CMTD1902910	Policy/Cover Note No.:	D18MTMC01006709 (Comprehensive)						
		Excess:							
Repairer:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2019]								
Driver/Custodian:	MALIEKIE BIN ROSLE (26 / Male) , NRIC: S9249179Z, Tel: +6587801819 Email: malik.rosle92@hotmail.com								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***FBN5048H (CMTD1902910)**

OD

Jun 13 2019 11:00AM

[MALIEKIE BIN ROSLE]

Bike Production Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 22/07/2019 09:27 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3000.00) - FBN5048H - Claim Handler: Ruth Chua Gek Tiang

Approved:3000.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte, Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 22 Jul 2019

Preliminary Advice

Vehicle No	: FBN5048H	Accident Date	: 13/06/2019
Make	: YAMAHA XABRE	Policy No.	: D18MTMC01006709
Assignment Date	: 28/06/2019	Excess	: S\$600.00
Date of Inspection	: 3/7/2019	Est. Duration of Repair	: 3
Inspection At	: BIKE PRODUCTION PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,231.90 (incl.supplementary \$611.00)
Revised Amount (LUMP SUM)	:S\$	3,000.00 (incl.supplementary \$611.00)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,000.00
COE / PARF Rebate	:S\$	3,670.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,330.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 July 2019 11:29 AM
To: Sbk E; SUR
Subject: FBN 5048H-DOA: 13/6/2019

Dear Mr Kwan,

As instructed by our client , please proceed to repair the **insured vehicle FBN 5048H on Lump Sum Repair, (Excess S600/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***FBN5048H (CMTD1902910)**

OD

Jun 13 2019 11:00AM

[MALIEKIE BIN ROSLE]

Bike Production Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 04/07/2019 08:36 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3559.00) - FBN5048H - Claim Handler: Ruth Chua Gek Tiang

Approved:3559.00.

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 28 June 2019 1:55 PM
To: sbk5643e@yahoo.com; Chua, Gek Tiang Ruth; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin
Subject: CMTD1902910/RUC - OD(LKK) FBN5048H ACC ON 13.06.19

Our Ref: CMTD1902910/RUC

Hi Kwan,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Ruth Chua** is the handler of this case who can be contacted at 63295 153.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Authorisation and excess (if applicable) will be further advised upon survey

Aside to **LKK AUTO**,

Please assist to conduct motor survey on **Own Damage** basis.

Please submit with your report via Merimen upon completion of survey to my colleague, Ms. Ruth for authorisation

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited.
If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

-----Original Message-----

From: sbk5643e@yahoo.com <sbk5643e@yahoo.com>

Sent: Friday, 28 June, 2019 11:15 AM

To: claimsreport <claimsreport@sompo.com.sg>

Subject: RE: OD CLAIM FBN5048H

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. The address is 610, Serangoon Road S(218216).
Thank you very much for your attention.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Ruth Chua Gek Tiang	Date:	03 Jul 2019
-------	---------------------	-------	-------------

Preliminary Advice

Vehicle No	: FBN5048H	Accident Date	: 13/06/2019
Make	: YAMAHA XABRE	Policy No.	: D18MTMC01006709
Assignment Date	: 28/06/2019	Excess	: S\$600.00
Date of Inspection	: 3/7/2019	Est. Duration of Repair	: 3
Inspection At	: BIKE PRODUCTION PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,620.90
Revised Amount	:S\$	2,929.00
Check Items (Estimated)	:S\$	630.00
Total	:S\$	3,559.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,000.00
COE / PARF Rebate	:S\$	3,670.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,330.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9179Z
Vehicle Details	
Vehicle No.:	FBN5048H
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	XABRE TFX150
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	G3G8E0034687
Chassis No.:	MH3RG3710HK025671
Maximum Power Output:	-
Open Market Value:	\$2,633.00
Original Registration Date:	19 Oct 2018
First Registration Date:	19 Oct 2018
Transfer Count:	1
Actual ARF Paid:	\$395.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$3,670.00
Total Rebate Amount:	\$3,670.00

The information contained herein is correct as at 03 Jul 2019

OK

Enquire Transfer Fee

Vehicle No.:	FBN5048H
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	XABRE TFX150
Chassis No.:	MH3RG3710HK025671
Propellant:	Petrol
Engine No.:	G3G8E0034687
Engine Capacity:	150 cc
Maximum Power Output:	-
Maximum Laden Weight:	285 kg
Unladen Weight:	135 kg
Year Of Manufacture:	2017
Original Registration Date:	19 Oct 2018
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$3,951.00
COE Expiry Date:	18 Oct 2028
Road Tax Expiry Date:	18 Oct 2019
Inspection Due Date:	18 Oct 2021
Intended Transfer Date:	03 Jul 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/06/2019 12:24
Date Of Accident	13/06/2019 11:30
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN5048H
Insured/Policyholder	
Name Of Registered Owner	MALIEKIE BIN ROSLE
NRIC No	S9249179Z
Email Address	MALIK.ROSLE92@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-87801819
Alternative Phone No	OFFICE-87801819

Vehicle Particulars

Manufacturer	YAMAHA
Model	XABRE-150CC TFX150

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTMC01006709
Cover Note Number	

Driver

Name of Driver	MALIEKIE BIN ROSLE
NRIC No	S9249179Z
Date Of Birth	08/12/1992
Occupation	OUTDOOR
Date Of Driving Pass	30/04/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87801819
Fax Number	
Contact Number	OFFICE-87801819
EMail Address	MALIK.ROSLE92@HOTMAIL.COM

Address	BLK 56 LENGKOK BAHRU #03-467
Postcode	150056
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	LIGHT RAINS
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB9823C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name:

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBN5048H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS RIDING MY BIKE AT THE FIRST CHANG WHEN SUDDENLY RED TAXI ILLEGALLY U-TURN AND I DIDN'T MANAGED TO BRKE ON TIME AND HIT THE SIDE OF THE TAXI.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 14 June 2019

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN5048H

Chassis No.: MH3RG3710HK025671

Engine No.: G3G8E0034687

OCT 2018

Qty	Description	Estimate
1 pc	Front fender	130 \$160.00 / SCR
1 pc	Front fender decals	\$45.00 / - SCR
1 pc	Left front fog lamp (154)	\$105.00 / BT
1 pc	Front wheel axle	\$75.00 X JVL ?
1 pc	Front left fork assy	\$500.00
1 pc	Left front signal	\$75.00 / BR
1 pc	Fork bridge	\$195.00 X JVL
1 pc	Steering stem underbracket	\$295.00 X JVL
2 pcs	Steering stem bearing @ \$38.00	\$76.00 X JVL
1 pc	Left view mirror	\$55.00 / SCR
1 pc	IU bracket	25 \$45.00 / BT
1 pc	Clutch lever	\$75.00 / SCR
1 pc	Left balancer	\$45.00 / MIS
1 pc	Handle bar	\$145.00 X JVL
2 pcs	Front windshield	\$70.00 / CRK
1 pc	Front cowl silver left	\$125.00 / SCR
1 pc	Gear pedal assy	\$270.00 / BR
1 pc	Left tank decals	\$95.00 / - SCR
1 pc	Fuel tank left cover	\$295.00 / SCR
1 pc	Left centre cover	\$105.00 X JVL
1 pc	Front left footrest	\$65.00 / SCR
1 pc	Front left footrest holder	\$145.00 / SCR
1 pc	Left rear footrest	\$65.00 X JVL
1 pc	Left rear footrest holder	\$145.00 X JVL / CUT
1 pc	Swing arm assy	\$390.00
1 pc	Rear fender	\$85.00 X JVL
1 pc	Splash guard	\$175.00 X JVL
		\$3,921.00
Less discount 10%		\$392.10
		\$3,528.90
Special nett items		
1 pc	ERP IU	\$157.00 X working
1 pc	Box bracket	\$155.00 / SCR
1 pc	Metal top case	\$390.00 / MIS
1 pc	Rear number plate	\$40.00 X JVL
1)	Towing charges	\$90.00 80
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$200.00 100 350
	To knock, straighten chassis & body	
3)	balancing	\$380.00 100
	To remove/refit, replace (if damage) check and	
4)	straighten front fork tubes.	\$180.00 ?

- | | | |
|----|---|--------------|
| 5) | To remove/refit, replace (if damage) check and balance front sport rim. | \$180.00 XNN |
| 6) | Spray painting | \$250.00 XNN |

Total Estimate

\$5,620.90

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

492 LK
217/19 1530

L/S

3 DAYS

AFTER REPAIR PHOTOS.

[Handwritten signature]
3/7/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

00

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 14 June 2019

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN5048H

Chassis No.: MH3RG3710HK025671

Engine No.: G3G8E0034687

OCT 2018

Qty	Description	Estimate
1 pc	Front fender	130 \$100.00 / SCR
1 pc	Front fender decals	45 \$45.00 / 105.00 SCR
1 pc	Left front fog lamp (15W)	\$105.00 / BT
1 pc	Front wheel axle	\$75.00 X SVL
1 pc	Front left fork assy	400 \$500.00 150.00 ? / SCR
1 pc	Left front signal	40 \$75.00 / BR
1 pc	Fork bridge	\$105.00 X SVL
1 pc	Steering stem underbracket	\$295.00 X SVL
2 pcs	Steering stem bearing @ \$38.00	\$76.00 X SVL
1 pc	Left view mirror	\$55.00 / SCR
1 pc	IU bracket	25 \$45.00 / BT
1 pc	Clutch lever	50 \$75.00 / SCR
1 pc	Left balancer	\$45.00 / MIS
1 pc	Handle bar	120 \$145.00 X SVL / BT
2 pcs	Front windshield	50 \$70.00 / BRK
1 pc	Front cowling silver left	\$125.00 / SCR
1 pc	Gear pedal assy	250 \$270.00 / BR
1 pc	Left tank decals	\$95.00 / 105.00 SCR
1 pc	Fuel tank left cover	250 \$295.00 / SCR
1 pc	Left centre cover	\$105.00 X SVL
1 pc	Front left footrest	\$65.00 / SCR
1 pc	Front left footrest holder	\$145.00 / SCR
1 pc	Left rear footrest	\$65.00 X SVL
1 pc	Left rear footrest holder	\$145.00 X SVL
1 pc	Swing arm assy	\$390.00 X SVL / CUT
1 pc	Rear fender	\$85.00 X SVL
1 pc	Splash guard	\$175.00 X SVL
		2,900
	Less discount 10%	\$3,921.00
		\$392.10
		\$3,528.90
Special nett items		
1 pc	ERP IU	\$157.00 X 155.00 SVL
1 pc	Box bracket	\$155.00 / SCR
1 pc	Metal top case	\$390.00 / MIS
1 pc	Rear number plate	30 \$40.00 X SVL / BR
1)	Towing charges	655 \$90.00 80
	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$200.00 100.00 350
2)	To knock, straighten chassis & body balancing	\$380.00 X SVL 100
3)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 X SVL ? / 50

- 5) To remove/refit, replace (if damage) check and balance front sport rim.
- 6) Spray painting

~~\$180.00~~ XNN

~~\$250.00~~ XNN

Total Estimate

\$5,620.90

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

PAZ LKK
21/7/19 1530

L1S

3 DAYS

AFTER REPAIR PHOTOS.

PARTS \$2,900
LESS 10% \$2,610
SINERT 655
LABOUR \$ 500

TOTAL \$3,765

LESS LIS 20% \$3,012

LIS TOTAL \$3,000

BEFORE EXCESS 1/3 REPAIR DAYS

- 5) To remove/refit, replace (if damage) check and balance front sport rim.
- 6) Spray painting

~~\$180.00~~ XNN

~~\$250.00~~ XNN

500

Total Estimate

\$5,620.90

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

PAY LEE

21/7/19 1530

L1s

3 DAYS

AFTER REPAIR PHOTOS.

~~1231.90~~

661.90

PARTS \$2,900

LESS 10% \$2,610

SINET 655

LABOUR \$ 500

TOTAL \$3,765

LESS L1s 20% \$3,012

L1s TOTAL \$3,000

BEFORE EXCESS . 13 REPAIR DAYS

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 14 June 2019

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN5048H

Chassis No.: MH3RG3710HK025671

Engine No.: G3G8E0034687

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Headlamp cover	\$105.00 / SCR
1 pc	Side stand	\$75.00 / SCR
1 pc	Brake pump assy	150 \$250.00 / BR
		<hr/>
		\$430.00
	Less discount 10%	\$43.00
		<hr/>
		\$387.00
	<u>Special nett items</u>	
1 pc	Left tube	\$35.00 X NN
		<hr/>
	Total Estimate	\$422.00

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 14 June 2019

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN5048H

Chassis No.: MH3RG3710HK025671

Engine No.: G3G8E0034687

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left side cover	150 \$175.00 / CRK
1 pc	Number plate holder	\$35.00 / BT
		<hr/>
		\$210.00
	Less discount 10%	\$21.00
		<hr/>
		\$189.00
	<u>Special nett items</u>	
	Total Estimate	<hr/>
		\$189.00

Note: The above estimate is subjected to the prevailing GST of 7%


For Bike Production Pte Ltd

Veron Chen (LKKAUTO)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Sunday, 14 July 2019 6:45 PM
To: Naz (LKKAUTO)
Cc: Veron Chen (LKKAUTO); SUR
Subject: Re: FBN 5048H FINALIZATION (OD)

Dear Naz,

Good Day. I agree to the lump sum repair of \$3,000.00 before excess and GST. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Thursday, July 11, 2019, 5:56:17 PM GMT+8, Naz (LKKAUTO) <Naz@lkkauto.com> wrote:

Dear Mr Kwan,

Please acknowledge the Lump Sum Repair \$3,000 / 3 Repair Days before excess, subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216
Tel: 6392 2555 Fax: 6297 5400

TAX INVOICE

Co. Registration No. 200007407G
GST Reg. No: 200007407G
GST Inclusive

No: 6036

Name : SOMPO INSURANCE SINGAPORE PTE LTD Date : 15/7/19
Address : 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SE 048623
I/C No : _____ Occupation : _____ DOB : _____
Tel : (T)6461 6555 (F) 6221 3302 Driving Licence : _____

Particulars		Amount
Reg. No : <u>FBN5048H</u>	Selling Price	\$ 2,568
Make & Model : <u>YAMAHA XABRE TFX150</u>	+ Insurance	\$ 0
Engine No : <u>G3G8E0034687</u>	+ Retention	\$ 0
Chassis No : <u>MH3RG3710HK025671</u>	TOTAL PRICE	\$ 2,568
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire-Theft <input type="checkbox"/> Third Party Only		
Colour : <u>BLACK</u>	LUMP SUM REPAIRS Downpayment	\$ 3,000
	LESS EXCESS	\$ 600
Loan Amount _____ Interest rates _____ p.a.		\$ 2,400
Terms : (_____ Monthly Instalments of \$ _____ GST 7%)		\$ 168
N/R : _____ TEL : _____		\$ 2,568
GTR : _____ TEL : _____		
COE NO : _____	TR	

Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid.
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have fullrights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For Bike Production Pte Ltd

I accept the above terms and conditions

Maliekie Bin Rosle
Blk 56 Lengkok Bahru
#03-467
Singapore 150056

Date: 11/7/2019

To: Mr Kwan Say Hwee
Bike Production Pte Ltd
610, Serangoon Road
Singapore 218216

Dear Sir,

**RE: AKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION
OF YAMAHA XABRE TFX150 VEHICLE NO.: FBN5048H**

I, Maliekie Bin Rosle, NRIC No.: S9249179Z, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above mentioned vehicle on 11/7/19 at 1700H.

Thank you very much for your attention.

Yours faithfully,


Maliekie Bin Rosle

...CLAIM SUBFOLDER...(Pending for Survey Report)
















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jun 2019		28 Jun 2019 14:03 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case



Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MALIEKIE BIN ROSLE , ID: S9249179Z, Tel: +6587801819, Email: malik.rosle92@hotmail.com									
Vehicle Reg. No.: FBN5048H		Date of Loss: 13/06/2019 11:00 - :59 [7 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / CMTD1902910		Policy/Cover Note No.: D18MTMC01006709 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 09/07/2019]									
Driver/Custodian: MALIEKIE BIN ROSLE (26 / Male) , NRIC: S9249179Z, Tel: +6587801819 Email: malik.rosle92@hotmail.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> SOMPO_SG (22/07/2019): Alert - Adj Mandate Approved (S\$3000.00) - FBN5048H - Claim Handler: Ruth Chua G... SOMPO_SG (04/07/2019): Alert - Adj Mandate Approved (S\$3559.00) - FBN5048H - Claim Handler: Ruth Chua G... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




*FBN5048H (CMTD1902910)
 OD
 Jun 13 2019 11:00AM
 [MALIEKIE BIN ROSLE]
 Bike Production Pte Ltd














Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/07/19 17:39	Adjuster Immediate Advice		Load HTM	
2	22/07/19 08:55	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
2	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
3	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
4	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
5	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
6	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
7	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
8	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
9	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
10	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
11	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
12	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
13	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
14	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
15	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
16	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
17	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
18	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
19	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
20	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
21	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
22	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
23	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
24	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
25	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
26	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
27	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
28	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
29	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
30	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
31	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
32	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
33	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>
34	03/07/19 14:22	General View		Load JPG	<input checked="" type="checkbox"/>


Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/07/19 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/07/19 13:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/07/19 13:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	20/07/19 13:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	20/07/19 13:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	20/07/19 13:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	20/07/19 13:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	20/07/19 13:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/19 12:29	OD Survey - SAS	 Load PDF	
2	28/06/19 12:29	OD Survey - ESTIMATE	 Load JPG	<input checked="" type="checkbox"/>
3	28/06/19 12:29	OD Survey - ESTIMATE	 Load JPG	<input checked="" type="checkbox"/>
4	28/06/19 14:02	OD Survey - ASSIGN LKK	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/07/19 08:56	SUPPLEMENTARY	 Load PDF	
2	22/07/19 14:50	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	17/06/19 17:25	Accident Statement	 Load HTM	
2	24/06/19 14:31	Addendum Sheet	 Load TIF	
3	24/06/19 15:00	Accident Statement Addm. #1	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	17/06/19 16:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 16:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 16:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	17/06/19 16:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	17/06/19 17:01	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19011491/NVD3E2

Date: 23/07/2019

REFERENCE

Insured/Claimant: MALIEKIE BIN ROSLE Policy No: D18MTMC01006709
Date of Loss: 13/06/2019 Nature of Claim: OD Claim No: CMTD1902910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN5048H**
Make & Model: YAMAHA XABRE, 150cc TFX150 Engine No: G3G8E0034687
Reg. Date: 19/10/2018 (Man. Year: 2017) Chassis No: MH3RG3710HK025671
Colour: Multi-colour Odometer: 21073 km
Engine Capacity: 150 cc
Market Value/New Car Price: S\$9,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 130/70 R17
Front Left Side: EXATO 5 mm Rear Left Side: EXATO 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,881.90	3,185.00	1,696.90	34.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	580.00	1,200.00	67.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,661.90	3,765.00	2,896.90	43.48
Approved Total (Overridden) (S\$)		3,000.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,061.90	2,400.00	3,661.90	60.41
+ GST 7.00/7.00% (S\$)	424.33	168.00	256.33	60.41
Nett Amount (S\$)	6,486.23	2,568.00	3,918.23	60.41

INSPECTION

Date of Assignment: 28/06/2019

Date Inspected: 03/07/2019 Inspected At:

Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jul 2019)	
Parts:	N/A	YAMAHA XABRE 150cc TFX150 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN5048H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Scratched	160.00 FL	*130.00 FL
2	1		*FRONT FENDER DECALS	Scratched	45.00 FL	*45.00 FL
3	1		*SET LEFT FRONT FOG LAMP	Bent	105.00 FL	*105.00 FL
4	1		*FRONT WHEEL AXLE	Serviceable	75.00 FL	*- FL
5	1		*FRONT LEFT FORK ASSY	Scratched	500.00 FL	*400.00 FL
6	1		*LEFT FRONT SIGNAL	Broken	75.00 FL	*40.00 FL
7	1		*FORK BRIDGE	Serviceable	195.00 FL	*- FL
8	1		*STEERING STEM UNDERBRACKET	Serviceable	295.00 FL	*- FL
9	2		*STEERING STEM BEARING	Serviceable	76.00 FL	*- FL
10	1		*LEFT VIEW MIRROR	Scratched	55.00 FL	*55.00 FL
11	1		*IU BRACKET	Bent	45.00 FL	*25.00 FL
12	1		*CLUTCH LEVER	Scratched	75.00 FL	*50.00 FL
13	1		*LEFT BALANCER	Missing	45.00 FL	*45.00 FL
14	1		*HANDLE BAR	Bent	145.00 FL	*120.00 FL
15	2		*FRONT WINDSHIELD	Cracked	70.00 FL	*50.00 FL
16	1		*FRONT COWLING SILVER LEFT	Scratched	125.00 FL	*125.00 FL
17	1		*GEAR PEDAL ASSY	Broken	270.00 FL	*250.00 FL
18	1		*LEFT TANK DECALS	Scratched	95.00 FL	*95.00 FL
19	1		*FUEL TANK LEFT COVER	Scratched	295.00 FL	*250.00 FL
20	1		*LEFT CENTRE COVER	Serviceable	105.00 FL	*- FL
21	1		*FRONT LEFT FOOTREST	Scratched	65.00 FL	*65.00 FL
22	1		*FRONT LEFT FOOTREST HOLDER	Scratched	145.00 FL	*145.00 FL
23	1		*LEFT REAR FOOTREST	Serviceable	65.00 FL	*- FL
24	1		*LEFT REAR FOOTREST HOLDER	Serviceable	145.00 FL	*- FL
25	1		*SWING ARM ASSY	Cut	390.00 FL	*390.00 FL
26	1		*REAR FENDER	Serviceable	85.00 FL	*- FL
27	1		*ERP IU	Serviceable	157.00 FS	*- FS
28	1		*BOX BRACKET	Scratched	155.00 FS	*155.00 FS
29	1		*METAL TOP CASE	Missing	390.00 FS	*390.00 FS
30	1		*REAR NUMBER PLATE	Broken	40.00 FS	*30.00 FS
31	1		*HEADLAMP COVER	Scratched	105.00 FL	*105.00 FL
32	1		*SIDE STAND	Scratched	75.00 FL	*75.00 FL
33	1		*BRAKE PUMP ASSY	Broken	250.00 FL	*150.00 FL
34	1		*LEFT TUBE	Not Necessary	35.00 FS	*- FS
35	1		*LEFT SIDE COVER	Cracked	175.00 FL	*150.00 FL
36	1		*NUMBER PLATE HOLDER	Bent	35.00 FL	*35.00 FL
37	1		*SPASH GUARD	Serviceable	175.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 5,338.00 3,475.00

- List Item Discount on L Items 10.00/10.00% (\$\$) 456.10 290.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					4,881.90	3,185.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	90.00	80.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	700.00	350.00
3	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	100.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	50.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND BALANCE FRONT SPORT RIM	New	180.00	0.00
6	SPRAY PAINTING	New	250.00	0.00
Gross Labour Cost (\$\$)			1,780.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >