

ASS. REC. BY: Marimer Surveyor: Steve REF: CS3 / AIG 19011500 / Ecd307 Special Instruction: _____

ASSIGNMENT (Office)

From (Person): Chin Lee Ying of AIG Date/Time: 28/6/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 2059A Insured: SFS 1831R

at Workshop in/s SAT Motor Tel: 98599677

of 24 Dehu Lane 12.

Policy No: 5109931450 Claim No: 0960342524SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 28/6. Person Contacted: Jessie H.O.D. Endorsement: _____

Vehicle IN / OUT

Date/Time	Action/Instruction	
	<u>SFS 1831R : NA / INC 19011334 / 24</u>	<u>D.O.A: 25/06/2019</u>
	<u>SLX 2059A NA / INC 19011334 / 24</u>	<u>D.O.A: 25/06/2019</u>

Warrant *Sten*

REF: *A10*

ASSIGNMENT

From _____ Date: _____
Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/s: _____
at _____
Insured _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Report)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *6* days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SLX 2059A* Vi Regn: *6/1/16*
Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *Mercedes benz CLA180* cc: *1595*
Colour: *White* A/C Insured / Std / NI /
Sp. Reading: *42753* T/Ratio: Insured / Std / NI
Eng/No: _____
Ci/No: *W001173422N300555*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Locked / Burnt or
Brake: In order / Jammed / Locked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *225/45R17*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: *7* Rear: *7*
R/Bal. *7* mm R/Bal. *7*
L/Bal. *7* mm L/Bal. *7*
D.O.A. *25/6/19* D.O.I. *28/6/19*
Survey held at *SAT msh*
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to co

Date / Time / Action / Instruction

MV-199K

Date/Time, File Pass to: ☐ : Prel. Report
4) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format: *DAR*

Lump Sum / L.B. (3)

Days Of Repair: *6*
Resurvey No. of Trip: *3*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation
3 + R: 3
Photos
Index

180
11
101

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2019 Edit Reg		28 Jun 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	CHIN SIN BENG, ID: S2511698D								
Main Claimant:	FARISS HAIQEL BIN MOHAMED HAMRAN, ID: S9106412Z								
Vehicle Reg. No.:	SLX2059	Date of Loss:	25/06/2019 00:00 - :59						
Claim Type:	TP / 0960342524SG	Policy/Cover Note No.:	5109931450 (Comprehensive) Coverage: 29/08/2018 - 28/08/2019						
Vehicle Reg. No. (Insured):	SFS1831R	Policy No. (Claimant):							
		Excess:							
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/07/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (01/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFS1831R AND SLX2059A ON 25/06/2019

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/28/2019 11:17:46 AM
Attachments:  [GIA report.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in SAT Motor, 24 Defu Lane 12, (S) 539131.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Li Ping [mailto:Prs.pd@slawch.com]
Sent: Thursday, June 27, 2019 4:51 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; 'Platinum Werkz'
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFS1831R AND SLX2059A ON 25/06/2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear Sir/Mdm,

Currently we have some changer, we would like to engage this person Lim Chang Liang from Alin Automotive Appraisers.

ACCIDENT INVOLVING SLX2059A & SFS1831R ALONG COMMONWEALTH AVE WEST ON 25/06/2019 @ 22:05

We refer to your letter dated **27 June 2019** confirming your intention to conduct a pre-repair survey on our client's vehicle **SLX2059A**.

We have instructions to reject your surveyor and propose to engage **Lim Chang Liang from Alin Automotive Appraisers..**

Please be informed that said vehicle can be inspected at:

Workshop: Platinumwerkz
Address: 53 Ubi Avenue 1 #01-25 (Paya Ubi Industrial Park) Singapore 408934
Contact Person: Yong Sheng (HP: 9238 9179)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence.

Regards
Li Ping

Did: 6909 5194
11 Keng Cheow Street #02-03 Riverside Piazza Singapore 059608

1st Inspection
Appointed surveyor
(Name & Siganature)
Date & Time

2nd Inspection
Appointed surveyor
(Name & Siganature)
Date & Time

3rd Inspection
Appointed surveyor
(Name & Siganature)
Date & Time

To: Prs.pd@slawch.com

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@wahnin.Tong@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFS1831R AND SLX2059A ON 25/06/2019



[More info](#)

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6412Z
Vehicle Details	
Vehicle No.:	SLX2059A
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 (R18 BI)
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	27091030832136
Chassis No.:	WDD1173422N300555
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,046.00
Original Registration Date:	06 Jan 2016
First Registration Date:	06 Jan 2016
Transfer Count:	2
Actual ARF Paid:	\$26,265.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2026
PARF Rebate Amount:	\$19,698.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$36,068.00
Total Rebate Amount:	\$55,766.00

The information contained herein is correct as at 01 Jul 2019

OK



mercedes cla 180

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼

Advanced
Search

Home » Used Cars » ST Carz Pte Ltd » Mercedes-Benz CLA-Class CLA180

Mercedes-Benz CLA-Class CLA180

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

ST CARZ

Price \$104,800**Depreciation** ⑦ \$13,280 /yr
View models with similar depre**Reg Date** 30-May-2016
(6yrs 10mths 28days COE left)**Mileage** 60,000 km (19.4k /yr)**Manufactured** ⑦ 2015**Road Tax** ⑦ \$740 /yr**Transmission** Auto**Dereg Value** ⑦ \$50,579 as of today (change)**OMV** ⑦ \$27,820**COE** ⑦ \$45,000**ARF** ⑦ \$25,948**Engine Cap** 1,595 cc**Power** 90.0 kW (120 bhp)**Curb Weight** ⑦ 1,430 kg**No. of Owners** ⑦ 1**Type of Vehicle** Luxury Sedan**Features**

Powerful And Responsive 1.6L 4 Cylinders Inline Turbocharged Engine, 120 BHP, 7G-DCT Auto Transmission, Paddle Shift, Traction Control, LED Daylights. View specs of the Mercedes-Benz CLA-Class (2013)

Accessories

Sports Rims And Sports Leather Seats, Reverse Camera, Bluetooth And Factory Fitted Audio System, Comes With Navigation.

Description

Fully Maintained By C&C, 1 Owner Unit! Original Paintwork With All Wear And Tear Replaced By Agent! High Trade In For Your Used Car, Approval Rate! 100% Accident Free, Kindly Call Or Whatsapp Us For Viewing Appointment Before It's Sold!

Category

PARF Car

Status


Avi Compare



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2019 16:25
Date Of Accident	25/06/2019 22:05
Exact Location Of Accident	COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX2059A
Insured/Policyholder	
Name Of Registered Owner	FARISS HAIQEL BIN MOHAMED HAMRAN
NRIC No	S9106412Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94509697
Alternative Phone No	OFFICE-94509697

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180 (R18 BI)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109931450
Cover Note Number	

Driver

Name of Driver	FARISS HAIQEL BIN MOHAMED HAMRAN
NRIC No	S9106412Z
Date Of Birth	21/02/1991
Occupation	INDOOR
Date Of Driving Pass	02/01/2014
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94509697
Fax Number	
Contact Number	OFFICE-94509697
EEmail Address	NOEMAIL

Address	BLK 693 JURONG WEST CENTRAL 1 #03-99
Postcode	640693
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHAN KOK KIONG (CHEN GUOQIANG) GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFS1831R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	FARISS HAIQEL BIN MOHAMED HAMRAN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLX2059A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	CHAN KOK KIONG (CHEN GUOQIANG)
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLX2059A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be located outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person(s)' Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

A-SLX2031A
B-SFS1831R

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/6/19 at around 2205hr I was at Commonwealth Ave west
stationary wait for the traffic light to turn green,
Suddenly I heard a loud bang and felt a great impact
from behind my car. I got down and see, car B-SFS1831R
had collided into the back of my car causing damage to
my whole rear side of my car

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

CONDITIONS
(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
(4) Not Consistent (NC)

Aug 2005

Rear Portion

Vehicle No:

SLX 2059A

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	UN	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	CUT	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RA	✓	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler Chrome	UR	✓	
1158	994023	Reverse Sensor	OR	✓	2
1159	993327	Rear End Panel	OR	✓	
1160	993339	Rear End Panel Top Garnish	OR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	OR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	OR	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	OT	✓	
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Bumper Under Cover

OT ✓

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe	CUT	✓	
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Driver's Seat Belt			
		Passenger Seat Belt			
		Rear Seat Belt			

8/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2019 Edit Reg		28 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHIN SIN BENG , ID: S2511698D								
Main Claimant:	FARISS HAIQEL BIN MOHAMED HAMRAN , ID: S9106412Z								
Vehicle Reg. No.:	SLX2059A	Date of Loss:	25/06/2019 00:00 - :59 [41 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0960342524SG	Policy/Cover Note No.:	5109931450 (Comprehensive) Coverage: 29/08/2018 - 28/08/2019						
Vehicle Reg. No. (Insured):	SFS1831R	Policy No. (Claimant):							
		Excess:							
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (01/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX2059A (0960342524SG)

[SFS1831R]






































TP



















































FARISS HAIQEL BIN MOHAMED HAMRAN

Jun 25 2019 12:00AM

[CHIN SIN BENG]

Sat Motors

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		v
Photos/Images															3 per page		v	✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	01/07/19 09:32	General View														Load JPG	✓		
2	01/07/19 09:32	General View														Load JPG	✓		
3	01/07/19 09:32	General View														Load JPG	✓		
4	01/07/19 09:32	General View														Load JPG	✓		
5	01/07/19 09:32	General View														Load JPG	✓		
6	01/07/19 09:32	Odometer Reading														Load JPG	✓		
7	01/07/19 09:32	Chassis Number														Load JPG	✓		
8	01/07/19 09:32	General View														Load JPG	✓		
9	01/07/19 09:32	General View														Load JPG	✓		
10	01/07/19 09:32	General View														Load JPG	✓		
11	01/07/19 09:32	General View														Load JPG	✓		
12	01/07/19 09:32	General View														Load JPG	✓		
13	01/07/19 09:32	General View														Load JPG	✓		
14	01/07/19 09:32	General View														Load JPG	✓		
15	01/07/19 09:32	General View														Load JPG	✓		
16	01/07/19 09:32	General View														Load JPG	✓		
17	01/07/19 09:32	General View														Load JPG	✓		
18	01/07/19 09:32	General View														Load JPG	✓		
19	01/07/19 09:32	General View														Load JPG	✓		
20	01/07/19 09:32	General View														Load JPG	✓		
21	01/07/19 09:32	General View														Load JPG	✓		
22	01/07/19 09:32	General View														Load JPG	✓		
23	01/07/19 09:32	General View														Load JPG	✓		
24	01/07/19 09:32	General View														Load JPG	✓		
25	01/07/19 09:32	General View														Load JPG	✓		
26	01/07/19 09:32	General View														Load JPG	✓		
27	01/07/19 09:32	General View														Load JPG	✓		
28	01/07/19 09:32	General View														Load JPG	✓		
29	01/07/19 09:32	General View														Load JPG	✓		
30	01/07/19 09:32	General View														Load JPG	✓		
31	01/07/19 09:32	General View														Load JPG	✓		
32	01/07/19 09:32	General View														Load JPG	✓		
33	01/07/19 09:32	General View														Load JPG	✓		
34	08/07/19 12:57	Photographs of Damaged Parts														Load JPG	✓		
35	08/07/19 12:57	Photographs of Damaged Parts														Load JPG	✓		
36	08/07/19 12:57	Photographs of Damaged Parts														Load JPG	✓		
37	08/07/19 12:57	Photographs of Damaged Parts														Load JPG	✓		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	08/07/19 12:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	08/07/19 12:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	08/07/19 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	08/07/19 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	08/07/19 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
91	08/07/19 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
92	08/07/19 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
93	08/07/19 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/07/19 10:26	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011500/GCD3E2

Date: 15/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 5109931450
 Claimant Vehicle No: SLX2059A Insured Vehicle No: SFS1831R
 Date of Loss: 25/06/2019 Nature of Claim: TP Claim No: 0960342524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX2059A
 Make & Model: MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A) Engine No: 27091030832136
 Reg. Date: 06/01/2016 (Man. Year: 2015) Chassis No: WDD1173422N300555
 Colour: White Odometer: 42753 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
 Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/06/2019
 Date Inspected: 28/06/2019 Inspected At: Sat Motors (HQ)
 24 Defu Lane 12
 Singapore 539131
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Cut	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
7	1		*REAR BUMPER LOWER CHROME	Broken	0.00 F	*- F
8	2		*REVERSE SENSOR	Broken	0.00 F	*- F
9	1		*REAR END PANEL	Dented	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
12	1		*BOOTLID	Dented	0.00 F	*- F
13	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*BOOTLID LOCK	Bent	0.00 F	*- F
15	1		*BUMPER UNDER COVER	Bent	0.00 F	*- F
16	1		*REAR EXHAUST CHROME PIPE	Cut	0.00 F	*- F
17	1		*DRIVERS SEAT BELT	* Check	0.00 F	*- F
18	1		*FRT PASSENGER SEAT BELT	* Check	0.00 F	*- F
19	1		*RR PASSENGER SEAT BELT	* Check	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >