

22/03/2002

ASS. REC. BY:

REF: CS/MSG19011508/K1vd302

Special Instruction:

Survivor: Kalin

ASSIGNMENT (Office)

From (Person): Jasmine Lok Khy Kwai of MSG

Date/Time: 28.6.19 16.13 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6208T

Insured: SMJ 9564Z

at Workshop m/s Premier Automotive

Tel: 65446687

of 22 Chang South Ave 2 #01-02

Policy No: 291205168M7

Claim No: 598092

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28.6.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 28.6.19 4.44 p.m.

Person Contacted: Mr Chuq

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMJ 9564Z: X

SHC 6208T: CC3/LPC17020670/K1mh3n2 D.O.A: 27/11/2012

12/7/19

@ 1142am Mr Chuq will check

24/7/19

Submit preli report

22/7/19

Recd email from Vincent TP withdraw claim

(08/11/13)

Surveyor: Kalvin

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 6208T Yr Regn: 10 Oct / 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima C.C. 1.685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 460/26 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNA KM414 MES4 69130Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 26/6/14 D.O.I. 10/7/14Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No Damage Found</u>
	<u>11/7/14 @ 932am Jasmine said as not reported yet</u>
	<u>No visible damage, not consistent</u>
	<u>RECEIVED 24 JUL 2019</u>

Date/Time, File Pass to?

☒ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 24/7 - typist

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 150

Transportation: \_\_\_\_\_

S + RS: \_\_\_\_\_ SI

Photos

Others 11TOTAL 161

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**...CLAIM SUBFOLDER...(New Assignment)**

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2019		28 Jun 2019 16:13 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

Show All

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>QIAN ZHONGYAO</b> , ID: S2765521A		
Main Claimant:	<b>PREMIER TAXIS PTE LTD</b> , Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	<b>SHC6208T</b>	Date of Loss:	26/06/2019 23:00 - :59 [56 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 598092</b>	Policy/Cover Note No.:	29120516QMY (Comprehensive) Coverage: 26/03/2019 - 25/03/2020
Vehicle Reg. No. (Insured):	<b>SMJ9564Z</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Premier Automotive Services Pte Ltd (Changi)</b> 23 Changi South Ave 2 #01-02, 486443 Changi - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 29/06/2019]</b>		
Adj Asg. Remarks:	on WP. Liab: dispute (OI NR) TP agree on SJE - assign LKK. Contact: Mr Chua @ 65446689		

## ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)

## Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAUTO)

---

**From:** Vincent Chua <vincent.chua@premiertaxi.com>  
**Sent:** Monday, 22 July 2019 3:00 PM  
**To:** SUR  
**Cc:** Goh Wee Dek; Liew Hai Leong  
**Subject:** RE: Pre-inspection/Accident involving SHC6208T and SMJ9564Z (MSIG) on 26.06.19 (NR case)

Dear Veron,

Good day to you.

We refer to the vehicles mentioned above.

As spoken on the phone, LKK surveyor Calvin proceeded down to inspect the vehicle on the 10<sup>th</sup> July 2019 and assessed the vehicle to have suffered from no damages.

As such, we will proceed to withdraw our claim from the third party.

Hope the above clarifies.

Thank you for your time.



Regards

Vincent Chua  
Operations Assistant  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

---

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

---

**From:** Nabilah Rasol [mailto:nabilah\_rasol@sg.msigg-asia.com]  
**Sent:** Friday, 28 June, 2019 10:58 AM  
**To:** Vincent Chua <vincent.chua@premiertaxi.com>  
**Cc:** Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>; Jasmine Lok Kheng Kwei <jasmine\_lok@sg.msigg-asia.com>  
**Subject:** RE: Pre-inspection/Accident involving SHC6208T and SMJ9564Z (MSIG) on 26.06.19 (NR case)

Hi Vincent,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Please note that our insured has yet to report the accident.

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Vincent Chua [<mailto:vincent.chua@premiertaxi.com>]

**Sent:** Friday, 28 June, 2019 10:40 AM

**To:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>

**Cc:** Goh Wee Dek <[weedek.goh@premiertaxi.com](mailto:weedek.goh@premiertaxi.com)>; Liew Hai Leong <[haileong.liew@premiertaxi.com](mailto:haileong.liew@premiertaxi.com)>;  
Jasmine Lok Kheng Kwei <[jasmine\\_lok@sg.msig-asia.com](mailto:jasmine_lok@sg.msig-asia.com)>

**Subject:** RE: Pre-inspection/Accident involving SHC6208T and SMJ9564Z (MSIG) on 26.06.19 (NR case)

---

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

---

Dear Nabilah,

We refer to the email below.

We would like to appoint **"LKK Auto Consultants" as the SJE for this PRS.**

**\*Vehicle not yet available for survey\***

Kindly arrange for survey first.

Thank you.

Regards

Vincent Chua

Operations Assistant

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443

Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511

Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

---

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

**From:** Nabilah Rasol [mailto:nabilah\_rasol@sg.msig-asia.com]  
**Sent:** Friday, 28 June, 2019 10:28 AM  
**To:** Vincent Chua <vincent.chua@premiertaxi.com>  
**Cc:** Jasmine Lok Kheng Kwei <jasmine\_lok@sg.msig-asia.com>  
**Subject:** RE: Pre-inspection/Accident involving SHC6208T and SMJ9564Z (MSIG) on 26.06.19 (NR case)

Hi Vincent,

We refer to your email dated 27/06/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

\*This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

- (a) **\*Fast lane settlement is not applicable for cases that liability is in dispute\***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Moving forward, please email your survey request to [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Thank you

Have a great week ahead!

**Nabilah Rasol (Ms)**  
Admin Officer, Claims Services (Motor)  
Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Vincent Chua [<mailto:vincent.chua@premiertaxi.com>]

**Sent:** Thursday, 27 June 2019 3:12 PM

**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>

**Cc:** Goh Wee Dek <[weedek.goh@premiertaxi.com](mailto:weedek.goh@premiertaxi.com)>; Liew Hai Leong <[haileong.liew@premiertaxi.com](mailto:haileong.liew@premiertaxi.com)>

**Subject:** Pre-inspection/Accident involving SHC6208T and SMJ9564Z on 26.06.19

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear all,

We refer to the vehicles mentioned above.

Vehicle to be Surveyed: SHC6208T

Insured Vehicle: SMJ9564Z

Date of Accident: 26/06/2019

Name of Workshop: Premier Automotive Services Pte Ltd

Address of Survey Location: 23 Changi South Avenue 2, #01-02, S (486443)

Name of Contact Person: Mr Chua

Contact Number: 65446689

Email Address of Contact Person: [vincent.chua@premiertaxi.com](mailto:vincent.chua@premiertaxi.com)

**\*Vehicle not yet available for survey\***

Kindly arrange for survey first.

Kindly send us your panel surveyor list and arrange for survey.

Thank you.

Regards

Vincent Chua  
Operations Assistant  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	10 Oct 2014 / 09:09:34	Receipt No.:	AACCK001-AX239-141010-000003
Asset Type:	Vehicle	Transaction Amount:	\$63,191.00
Asset ID:	SHC6208T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141010090934851198		

Vehicle No.:	SHC6208T
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)

---

Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	10 Oct 2014
Original Registration Date:	10 Oct 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5469130
Engine No.:	D4FDDH309741
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4

---

Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver

---

Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,613.00
Minimum PARF Benefit:	\$7,267.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	10 Oct 2014 09:09:34
COE No.:	2014101001001197M
COE Expiry Date:	09 Oct 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$50,938.00
Lifespan Expiry Date:	09 Oct 2022
Owner ID Type:	Company

---



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/06/2019 13:47
Date Of Accident	26/06/2019 23:15
Exact Location Of Accident	HAVELOCK ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC6208T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

### Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	

### Driver

Name of Driver	SAHLAN BIN SANI
NRIC No	S8225936H
Date Of Birth	16/08/1982
Occupation	OUTDOOR
Date Of Driving Pass	05/07/2005
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90064459
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 470A #05-408 FERNVALE LINK
Postcode	791470
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

VEH. A - NO PAX VEH. B - 2 PAX

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMJ9564Z
Vehicle Make/Model/Colour	TOYOTA HARRIER/WHITE
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	WANG XU HAI
NRIC/Passport Number	S9474723F
Contact Number	98265595
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT LEFT PORTION
No. Of Passenger (Including Driver)	3

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



27 JUN 2019

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


X *[Signature]*  
38225936 H  
d SHC 6208T

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Signature]*

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A. SHC 6208T

B. SMJ 9564Z

*[The remaining lines of the form are crossed out with a diagonal line.]*

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

Q 38225936H

27 JUN 2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

*[Handwritten signature]*

Describe Circumstance of the Accident.

ON 26/06/2019 @ 2315HRS, I WAS DRIVING MY TAXI ( SHC 6208 T ), TRAVELLING ALONG HAVELOCK ROAD IN LANE 4.

WHILE I WAS MOVING STRAIGHT AHEAD – WITHIN MY LANE, SUDDENLY VEHICLE B ( SMJ 9564Z – TOYOTA HARRIER/WHITE ) WHICH WAS INITIALLY IN LANE 2, FAILED TO KEEP FOR PROPER LOOK OUT – HAD ENCROACHED ONTO MY PATH ON MY RIGHT ABRUPTLY.

AS SUCH, THE FRONT LEFT OF VEHICLE B COLLIDED ONTO THE RIGHT PORTION OF MY TAXI – WHILE HE WAS FILTERING INTO LANE 4.


DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE RIGHT PORTION & VEHICLE B HAD DAMAGE ON THE FRONT LEFT PORTION.



NO INJURY INVOLVED.

NO PASSENGERS ONBOARD MY TAXI & VEHICLE B HAD 2 PASSENGERS ONBOARD.

\*VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



 5822593611  
Driver's Signature & NRIC Number  
@ 1:57:51 PM  
(attended by )

# Premier Automotive Services Pte Ltd

**#01-02, 23 Changi Sth Ave 2  
486443**

Claim Reference:  
Assessment number: 010239  
Version: 1810  
Date calculated: 10/07/2019 1:18 PM

**Full Report**  
**Registration: SHC6208T**  
**Printed: 10/07/2019 1:19 PM**

## Summary Information

### Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	26/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

## Vehicle Details

### Vehicle

Manufacturer:	KIA
Model:	OPTIMA (TF)
Sub Model:	2 LUXE
Model Sheet Number:	28 36 38
Registration:	SHC6208T
VIN number:	
Odometer:	

**Premier Automotive Services Pte  
Ltd**  
**#01-02, 23 Changi Sth Ave 2**  
**486443**

Claim Reference:  
Assessment number: 010239  
Version: 1810  
Date calculated: 10/07/2019 1:18 PM

Full Report  
Registration: SHC6208T  
Printed: 10/07/2019 1:19 PM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
Date of Inspection:

**Damage Areas**

All ☐  
Underbody ☐



**Labour**

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
66300R00)	R + R RIGHT FRONT WING (BUMPER REMOVED)		5.0	25.00
86512R00 ZAX	R + R FRONT BUMPER		3.0	15.00
76000R00	RENEW R/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		16.0	80.00
76000RF0)	R + R R/F DOOR HINGE/S		4.0	20.00
87755R00	R + R R/SILL TRIM		3.0	15.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>3.10</b>	<b>31.0</b>	<b>155.00</b>
<b>Total of Labour</b>				<b>155.00</b>

**Premier Automotive Services Pte Ltd**  
**#01-02, 23 Changi Sth Ave 2**  
**486443**

Claim Reference:  
 Assessment number: 010239

Version: 1810

Date calculated: 10/07/2019 1:18 PM

Full Report  
 Registration: SHC6208T  
 Printed: 10/07/2019 1:19 PM

**Paint**

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING		15.0	

**Paint Material Per Part**

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06

**Labour Cost - Paint**

	50.00 SGD/h	Hrs	WU	Price SGD
Factor				
Time Paint			15.0	
Preparation Main Work Metal		0.70	7.0	35.00
<b>Total</b>	<b>10 WU/h</b>	<b>2.20</b>	<b>22.0</b>	<b>110.00</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	35.06
Material-constant Metal	18.10
<b>Total</b>	<b>53.16</b>

**Spare Parts**

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
1482	RIGHT FRONT DOOR	760042T000		761.00
1488	R/F UPPER DOOR HINGE	793203K000		34.00
1496	R/F LOWER DOOR HINGE	793203K000		34.00
1688	R/F DOOR RR MOULDING	863732T000		0.00
1692	R/F UPP DOOR MLDG	828602T000		0.00
f: OEM Parts				<b>Savings 0.00</b>
n: Non-OEM Parts				<b>Subtotal 829.00</b>
u: Used parts				<b>Subtotal Discount(+35.00%) -290.15</b>
				<b>Total 538.85</b>



**Premier Automotive Services Pte Ltd**  
**#01-02, 23 Changi Sth Ave 2**  
**486443**

Claim Reference:  
 Assessment number: 010239  
 Version: 1810  
 Date calculated: 10/07/2019 1:18 PM


Full Report  
 Registration: SHC6208T  
 Printed: 10/07/2019 1:19 PM

**Extras**

Code	Description	Price SGD
1000	LH door stickers	100.00*
	<b>Total Extras</b>	<b>100.00</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>	829.00	
Total Discount(+35.00%)	-290.15	
<b>Total Parts</b>		<b>538.85</b>
<b>Labour Time Base 10 WU/h</b>		
Total 31.0 WU X 50.00 SGD/h	155.00	
<b>Total of Labour</b>		<b>155.00</b>
<b>Total Of Extras</b>		<b>100.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 22.0 WU X 50.00 SGD/h		
Material Cost		
<b>Total Paint Including Material</b>		<b>163.16</b>
<b>Repair Cost Excludes GST</b>		<b>957.01</b>
GST (+7.0%)		66.99
<b>Repair Cost Included GST</b>		<b>1,024.00</b>



**Comments**

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

*Kahin 10/7/19*  
*10/7/19 165h*  
*Time of survey, no Damage found*

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2019		28 Jun 2019 16:13 <a href="#">Edit Adj Rpt</a>	<b>S\$957.01</b> <a href="#">Edit Estimates</a>	<b>S\$957.01</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>QIAN ZHONGYAO</b> , ID: S2765521A								
Main Claimant:	<b>PREMIER TAXIS PTE LTD</b> , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	<b>SHC6208T</b>	Date of Loss:	26/06/2019 23:00 - :59 [56 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 598092</b>	Policy/Cover Note No.:	29120516QMY (Comprehensive) Coverage: 26/03/2019 - 25/03/2020						
Vehicle Reg. No. (Insured):	<b>SMJ9564Z</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Premier Automotive Services Pte Ltd (Changi)</b> 23 Changi South Ave 2 #01-02, 486443 Changi - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Imm.Advice due 29/06/2019]								
Adj Asg. Remarks:	on WP, Liab: dispute (OI NR) TP agree on SJE - assign LKK. Contact: Mr Chua @ 65446689								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SHC6208T (598092)**  
**[SMJ9564Z]**  
**TP**  
**PREMIER TAXIS PTE LTD**  
**Jun 26 2019 11:00PM**  
**[QIAN ZHONGYAO]**  
**Premier Automotive Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/07/19 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/19 10:04	TP SHC6208T E-FILE REPORT	 Load PDF	
2	28/06/19 10:04	PRI from Premier Automotive Services	 Load PDF	
3	28/06/19 10:59	TP agree on SJE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/19 09:14	EMAIL FROM PREMIER AUTOMOTIVE	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011508/K1VD3E2

Date: 25/07/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29120516QMY

Claimant Vehicle No : SHC6208T

Insured Vehicle No : SMJ9564Z

Date of Loss: 26/06/2019

Nature of Claim: TP

Claim No: 598092

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC6208T

Make &amp; Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH309741

Reg. Date: 10/10/2014 (Man. Year: 2013)

Chassis No: KNAGM414ME5469130

Colour: Silver

Odometer: 460126 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Maxxis 7 mm

Rear Left Side: Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	638.85	638.85	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	318.16	318.16	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>957.01</b>	<b>957.01</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>66.99</b>	<b>66.99</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>1,024.00</b>	<b>1,024.00</b>	<b>0.00</b>	<b>0.00</b>

## INSPECTION

Date of Assignment: 28/06/2019

Date Inspected: 10/07/2019 Inspected At:

Premier Automotive Services Pte Ltd  
(Changi)  
23 Changi South Ave 2 #01-02  
Singapore 486443

Estimated Period of Repair: 0.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2019)
<b>Parts:</b>	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC6208T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT DOOR	No Visible Damage	761.00 FL	*761.00 FL
2	1		*R/F UPPER DOOR HINGE	No Visible Damage	34.00 FL	*34.00 FL
3	1		*R/F LOWER DOOR HINGE	No Visible Damage	34.00 FL	*34.00 FL
4	1		*R/F DOOR RR MOULDING (NPA)	No Visible Damage	0.00 FL	*- FL
5	1		*R/F UPP DOOR MLDG (NPA)	No Visible Damage	0.00 FL	*- FL
6	1		*LH DOOR STICKERS	No Visible Damage	100.00 FS	*100.00 FS
					<b>Sub Total (S\$)</b>	<b>929.00 929.00</b>
					<b>- List Item Discount on L Items 35.00/35.00% (S\$)</b>	<b>290.15 290.15</b>
					<b>Total Parts (S\$)</b>	<b>638.85 638.85</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	31.0 WU X 50.00 SGD/H	New	155.00	155.00
2	LABOUR COST 22.0 WU X 50.00 SGD/H	New	110.00	110.00
3	MATERIAL COST	New	53.16	53.16
Gross Labour Cost (S\$)			<b>318.16</b>	<b>318.16</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >