

ASS. REC. BY:

REF: CS3/AIG190115091 Kcd3²⁷

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chin Lee Yung of AIG Date/Time: 28/6/2019

Estimated Cost: _____ Bill to: _____

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: 8JS 9026Z Insured: SML 2845Zat Workshop m/s Kien Cheong Tel: 81259406 Kellyof Blk A Sin Ming Ind Est #01-26Policy No: 1900098589 Claim No: 9272408963SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 28/6 Person Contacted: Kelly Vehicle IN OUT

Date/Time	Action/Instruction
	<u>Cheng! X</u>
	<u>SML 2845Z X</u>
	<u>8JS 9026Z X</u>
	<u>After repair: 2/7/2019</u>

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STS 90267 Yr Regn: Nov 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alicia c.c. 1896Colour: Red A/C: Insured / Std / NI / NASp. Reading: 299503 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: N 8 T 260 3030021Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / SRIm / STD A/Rim orTyre Size: F: Journey 205/55R16R: Nil

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

Rear

R/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 25/6/19D.O.L. 28/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ File pass to
no estimate

MV: 27000PV: 812980NV: 14020 11000

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - St

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$Report Format: DAR

Lump Sum / I.B.I.: (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2019 Edit Reg		08 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DENNIS QUAH YONG HUI, ID: S9041329E			
Main Claimant:	DRIVE NOW LEASING PTE LTD			
Vehicle Reg. No.:	SJS9026Z	Date of Loss:	25/06/2019 18:00 - :59	
Claim Type:	TP / 9272408963SG	Policy/Cover Note No.:	1900098589 (Comprehensive)	
Vehicle Reg. No. (Insured):	SML2845Z	Policy No. (Claimant):		
		Excess:		
Repairer:	Kien Cheong Automotive (HQ) BLK 9 SIN MING INDUSTRIAL ESTATE #01-26, 575644 Sin Ming - Tel: 81259406			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/07/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (09/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/28/2019 9:10:56 AM
Attachments:  tmpBDC8.tif

Hi LKK,

Kindly assist to survey after 10.30am today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]

Sent: Thursday, June 27, 2019 10:21 AM

To: Hor, Yinrul

Subject: [EXTERNAL] ACCIDENT INVOLVING SJS9026Z AND SML2845Z ON 25 JUNE 2016

This message is from an external sender; be cautious with links and attachments.

Your ref: SML2845Z

Our ref: JEQ/SJS9026Z/KLY

Dear Viviane,

We refer to your email today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Constant Appraiser Services;
2. Perfect Automobile Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Autoprobe Consultants;
5. VP Appraisal Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Oh Appraisal Services;
10. Impact Analysis Consultant.

Kenneth

Please be informed that if the above mentioned surveyors is not ageeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

KIEN CHEONG AUTOMOTIVE
Blk 9 Sin Ming Industrial Estate
#01-26
Singapore 575644
Tel:8125 9406
Person In Charge: Ms Kelly Tay

* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Fax : (65) 6536 5368 (Litigation & Conveyancing)

Email : claims@juseq.com.sg

website : www.juseq.com.sg

Our Ref: JEQ/SJS9026Z/KLY (zi)

Your Ref: SML2845Z

26 June 2019

DENNIS QUAH YONG HUI
502D Yishun Street 51 #03-458
Singapore 764502

By Post Only

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore

By Fax: 6835 7416 Only

Dear Sir

ACCIDENT INVOLVING SJS9026Z & SML2845ZZ ON 25.06.2019

We act for the owner of vehicle no. SJS9026Z.

We hereby notify you of a road traffic accident on 25 June 2019 at about 1806 hrs, at slip road of Scotts Road towards Orchard Road involving our client's vehicle and vehicle registration no. SML2845Z driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2019 16:56
Date Of Accident	25/06/2019 18:05
Exact Location Of Accident	SLIP ROAD SCOTTS RD TOWARDS ORCHARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9026Z
Insured/Policyholder	
Name Of Registered Owner	DRIVE NOW LEASING PTE LTD
Co Reg No	NA
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91705790
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALLION 1.5A
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	SD18V13974/VPZ/R00
Cover Note Number	

Driver

Name of Driver	TENG YONG HUA
NRIC No	S2175997Z
Date Of Birth	20/02/1959
Occupation	OUTDOOR
Date Of Driving Pass	02/05/1980
Driving Experience	39 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91705790
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 120 POTONG PASIR AVENUE 1 #02-802
Postcode	350120
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NA GENDER: : MALE
Passenger 2	NAME: : NA GENDER: : FEMALE
Passenger 3	NAME: : NA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML2845Z	Kia Stonic
Vehicle Make/Model/Colour		
Details Of Properties		
Vehicle Category	PRIVATE CAR	
Name of Driver	JANET	
NRIC/Passport Number		

Contact Number

98239573

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was stopped my vehicle (A) along the slip Road of Scotts Road with 3 passengers. Suddenly the vehicle (B) unable to stop her car and hit onto rear portion of my vehicle (A)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

DRIVE NOW LEASING PTE LTD
Reg No: 2018283224

Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8322H
Vehicle Details	
Vehicle No.:	SJS9026Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	1NZD133069
Chassis No.:	NZT2603030021
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,582.00
Original Registration Date:	24 Nov 2008
First Registration Date:	24 Nov 2008
Transfer Count:	5
Actual ARF Paid:	\$14,582.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$12,980.00
Total Rebate Amount:	\$12,980.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Jul 2019

DOA: 25/6/2019

OK

COE: 23/11/2023

Remaining months of COE : 4 years 4 months 29 days (52.9 months)
from accident date

Depri: \$6300 (yearly) \$525 (monthly)

52.9 months x \$525 = \$27772 (market value) \$27000

MV: \$27000

PV: \$12980

NV: \$14020 \$14000



(COE)

Full Loan Available! New Paintworks. Option For 5 Years COE At \$31800! The Gear Box And Engine Still In Excellent State. No Further Repairs Needed. Original Paintwork. Flexible Loan And Trade In Are Welcome. Please Contact Our Friendly Sales Consultant For An View...

PREMIUM AD

SmartCars Boutique Pte Ltd

Posted: 13-Jul-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.8A (COE till 05/2029) \$58,800 \$5,980 /yr 12-May-2009 1,797 cc 207,000 km Sedan Available

Low Risk Purchase, An Ideal Choice For Daily Commute. Call Our Sales Consultants For A Viewing Today!

PREMIUM AD

Inchape Pre-Owned

Posted: 13-Jul-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 01/2023) \$21,800 \$6,230 /yr 14-Jan-2008 1,495 cc - Sedan Available

Sleek Black On Black Allion. Well Known For Its Fuel Efficiency And No Major Repairs Required. Loan/Trade In Available, Call To Scrutinize.

Posted: 12-Jul-2019 Tags: 2008 Toyota Allion, 2008 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota




Toyota Allion 1.5A (New 5-yr COE) \$34,888 \$6,970 /yr 30-Jun-2009 1,496 cc - Sedan Available

Free 1 Servicing Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Trade In Welcome! Priced Lowest In The Market Yet Comes With Accessories! Well Maintained, Excellent Condition! Don't...

JDM Cars

Posted: 11-Jul-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota

ADVERTISING



Toyota Allion 1.5A (COE till 04/2029) \$47,800 \$4,880 /yr 07-May-2009 1,496 cc 109,000 km Sedan Available

Elegant New Pearl White Paintwork! Meticulously Well Maintained By Previous Owner With No Further Repair Needed. Guaranteed Accident Free! Very Low Mileage Done! We Provide Various Flexible Loan! All Trade In Are Welcome. Please Contact Our Friendly Sales...

Creative Auto

Posted: 10-Jul-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 07/2023) \$27,000 \$6,740 /yr 18-Jul-2008 1,496 cc 130,000 km Sedan Available

Loan Available Up To \$27k. Viewing By Appointment Only.

PREMIUM AD

Allmotoring.sg

Posted: 09-Jul-2019 Tags: 2008 Toyota Allion, 2008 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 04/2024) \$30,800 \$6,420 /yr 25-May-2009 1,496 cc 98,000 km Sedan Available

Well Maintained, Super Low Genuine Mileage Done, No Repair Needed.

DIRECT OWNER

Posted: 07-Jul-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 06/2023) \$25,800 \$6,570 /yr 18-Jun-2008 1,496 cc 200,500 km Sedan Available

Consignment Code: A171. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

CONSIGNMENT

Posted: 01-Jul-2019 Tags: 2008 Toyota Allion, 2008 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota

Toyota Allion 1.5A (COE till /2024) \$31,800 \$7,060 /yr 14-Jan-2009 1,496 cc 93,000 km Sedan Available

aintained, Super Low Genuine Mileage Done. Well Maintained, Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months

PREMIUM AD

Compare

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	N/C	6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	LH	2	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DD		
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish	CRA		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	R	
1171	991328	Bootlid Emblem	NEC	3	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber	TN	3	
1179	990382	Bootlid Hinge	BT	R	
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJS 9026Z

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		BOOTLID PROTECTOR	RR	3	

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2019 Edit Reg		28 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	DENNIS QUAH YONG HUI , ID: S9041329E		
Main Claimant:	DRIVE NOW LEASING PTE LTD		
Vehicle Reg. No.:	SJS9026Z	Date of Loss:	25/06/2019 18:00 - :59 [127 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9272408963SG	Policy/Cover Note No.:	1900098589 (Comprehensive)
Vehicle Reg. No. (Insured):	SML2845Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Kien Cheong Automotive (HQ) BLK 9 SIN MING INDUSTRIAL ESTATE #01-26, 575644 Sin Ming - Tel: 81259406		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (09/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJS9026Z (9272408963SG)**
[SML2845Z]






TP

DRIVE NOW LEASING PTE LTD

Jun 25 2019 6:00PM

[DENNIS QUAH YONG HUI]

Kien Cheong Automotive

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/07/19 10:02	Accident Statement From: SC - Reg. No: SML2845Z, Claimant: DENNIS QUAH YONG HUI	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/07/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19011509/KCD3S2
Date: 25/07/2019**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900098589
Claimant Vehicle No :	SJS9026Z	Insured Vehicle No :	SML2845Z
Date of Loss:	25/06/2019	Nature of Claim:	TP
		Claim No:	9272408963SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS9026Z	Engine No:	1NZD133069
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603030021
Reg. Date:	24/11/2008 (Man. Year: 2008)	Odometer:	299503 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Journey 8 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Journey 8 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/06/2019	
Date Inspected:	28/06/2019	Inspected At: Kien Cheong Automotive (HQ) BLK 9 SIN MING INDUSTRIAL ESTATE #01-26 Singapore 575644
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1		*REAR BUMPER REFLECTOR LH	Cracked	0.00 F	*- F
5	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*BOOTLID	Repair	0.00 F	*- F
10	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
11	1		*BOOTLID LOCK	*Check	0.00 F	*- F
12	1		*BOOTLID RUBBER	Torn	0.00 F	*- F
13	1		*BOOTLID HINGE	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >