

ASS. REC. BY:

REF: CS3/A1G19011510/T1cd302

Special Instruction:

Surveyor: TayfikhASSIGNMENT (Office)From (Person): Chin Lee Yingof AIGDate/Time: 28/6/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: CB 7420DInsured: SKS 8789Aat Workshop m/s Ann JooTel: 64550747 Yuenof H6 SIM #01-17

Policy No:

Claim No: 343028377486

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28/6Person Contacted: YuenVehicle IN/OUT

Date/Time	Action/Instruction	
	<u>Vehicle! (X)</u>	
	<u>SKS 8789A : CC4/ASM19010399/apb3</u>	<u>D.O.A : 10/06/2019</u>
	<u>CB 7420D : CC4/ASM19010399/apb3</u>	<u>D.O.A : 10/06/2019</u>

Minimum

ASS. REC. BY:

REF:

AIG

ASSIGNMENT

From:

Date:

Veh No:

CB7420D

Yr Regn:

Jul / 04

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

CB7420D.

Make:

Mitsubishi

C.C.

2953

at Workshop m/s

Ann Joo Motor

Colour:

Silver

A/C:

Insured / Std / NI / NA

of

B/K 176 S/M #0117.

Sp. Reading

712/87

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JN1TG 4E2520701209.

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi:

Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:


195/R15

R:

2 -

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

5

days

Res.: Yes or No

D.O.A.

D.O.I.

28/6/14 2/652

Lump Sum:

%

3 Val.: Yes or No

Survey held at

Ann Joo Motor

CA / REV / REP. / 24 HRS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt m/s

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No 6/19.

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

5

1)



: Final Report

Resurvey No. of Trip:

-

Date/Time, File Return to?

Survey Fee:

180

2)

Add Fee:



: Site Insp (\$)

Transportation:

S+RS, SI



: Interview (\$)

Photos



: Tech. Insp (\$)

Others:



: Weekend (\$)

TOTAL

191

Report Format:

DAR

Lump Sum / Bal. (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019 Edit Reg		02 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	BIZLINK RENT-A-CAR PTE LTD , Co. Reg. No.: 200402911Z		
Main Claimant:	ELITE TRANSPORT SERVICE , Co. Reg. No.: 53073981W		
Vehicle Reg. No.:	CB7420D	Date of Loss:	10/06/2019 09:00 - :59
Claim Type:	TP / 3430283794SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKS8789A	Policy No. (Claimant):	
		Excess:	
Repairer:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721, 575721 Sin Ming - Tel: 64510747		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/07/2019]		


ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (03/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/28/2019 2:18:12 PM
Attachments:  tmp86FE.TIF

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Bee Ling Koh [mailto:kohbeeling@yahoo.com.sg]

Sent: Friday, June 28, 2019 11:18 AM

To: Hor, Yinrul; Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin

Subject: [EXTERNAL] Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKS8789A AND CB7420D ON 10/06/2019

This message is from an external sender; be cautious with links and attachments.

Our Ref: AJ/ CB 7420D

Your Ref: SKS 8789A

(Please quote our reference number when replying)

28 June 2019

AIG ASIA PACIFIC INSURANCE
Singapore



Dear Sirs

NOTICE OF ACCIDENT
Claimant: ELITE TRANSPORT SERVICES

***Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident
occurring on or after 1st April 2016 ["Protocol"]***

We refer to your letter dated 28 June 2019.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 27 June 2019.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 27 June 2019.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:-

Name of Workshop	:	Ann Joo Motor Pte Ltd
Address	:	Blk 176 Sin Ming Drive #01-17 Sin Ming Autocare Singapore 575721
Telephone No	:	64550747
Contact person	:	Yiwen

REGARDS
CINDY
KK CHENG AND CO
DID :6227-1272

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

K. K. CHENG & CO

Advocates and Solicitors
101 Upper Cross Street #05-21
People's Park Centre
Singapore 058357
Tel: 6227 1272 Fax: 6227 5563

Our Ref: AJ/ CB 7420D
Your Ref: SKS 8789A
(Please quote our reference number when replying)

27 June 2019

AIG ASIA PACIFIC INSURANCE By fax only: 6835-7416
Singapore

Dear Sirs

NOTICE OF ACCIDENT

Claimant: ELITE TRANSPORT SERVICES

*Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident
occurring on or after 1st April 2016 ["Protocol"]*

Our abovenamed client's vehicle has been damaged in a road traffic accident on 10 June 2019@0915hours along Ang Mo Kio Avenue 5 involving our client's vehicle CB 7420D and vehicle SKS 8789A driven by your insured driver at the material time. A copy of the Singapore Accident Statement/~~Traffic Police report~~ filed is enclosed.

Firstly, would you or your insured like to conduct a pre-repair survey of our client's abovesaid vehicle?

Fax your Reply to us at 6227 5563. Our client shall proceed to repair the said vehicle if we do not receive any reply from you within 2 days of this Notice.

Secondly, as regards paras 2.4 & 2.6 of the Protocol, *our client objects* to appointment of any of the motor surveyors in your List ["List"] *if the following surveyors are not in your List and proposes* the following motor surveyors instead:

(1) Amas Ong, (2) Foo Chi Yong, (3) JT Bok (4) Foo Philip

Thirdly, *if you object to any of our proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol.* In this event, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, *if you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.*

Yours faithfully


CHENG KIM KUAN

Encl

cc Workshop (REF: CB 7420D)



date
02/07/2018

policy number
CB3 / GA237225

Certificate of Insurance

-Commercial Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Commercial Vehicles (Third-Party Risks and Compensation) Rules, 1960 -Road Transport Act, 1987 (Malaysia) -Commercial Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	ELITETRANSPORT SERVICES	Certificate number	GA237225 / 1
Cover	Third Party, Fire & Theft	NCD	20%
Engine number	ZD30040314	Chassis number	JN1TG4E25Z0701209
Vehicle Registration number	CB7420D		
Period of Insurance	from 03/07/2018 to 02/07/2019 (both dates inclusive)		
Sum Insured	Market Value at The Time of Loss		
Finance Loan Company	CHUAN HUA CO PTE LTD		

Persons or classes of persons entitled to drive

Any person provided he is in the Policyholder's employ and/or is driving on their order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use*

- (a) Use only for the carriage of passengers or goods in connection with the Policyholder's business as specified in the Policy.
- (b) Use only in the Republic of Singapore.

The Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed testing
- (b) Use whilst drawing a trailer except the towing (other than for reward) of anyone disabled mechanically propelled vehicle

* Limitations rendered inoperative by Section 8 of the Commercial Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Excess

Section II	SGD1,500.00
------------	-------------

An additional excess is applicable as follows:

Additional All Claims Excess of S\$2,000 is applicable for any named/unnamed drivers who:

- a) Is 18 years old to 26 years old and/or
- b) Is 66 years old and above and/or
- c) with driving experience of less than 1 year on the relevant classes of driving license

Additional clauses & endorsements to your policy

Nil

[> Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	CB7420D		
Vehicle Type :	S20 - School Transport Bus/Coach/Minibus		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	School Bus without AWC		
Vehicle Make :	NISSAN		
Vehicle Model :	URVAN 3.0 M		
Chassis No. :	JN1TG4E25Z0701209		
Propellant :	Diesel		
Engine No. :	ZD30040314		
Engine Capacity :	2953 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3100 kg		
Unladen Weight :	1800 kg		
Year Of Manufacture :	2004		
Original Registration Date :	03 Jul 2004		
Lifespan Expiry Date :	02 Jul 2024		
Road Tax Expiry Date :	02 Jan 2020		
Inspection Due Date :	02 Jan 2020		
Intended Transfer Date :	08 Jul 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3981W
Vehicle Details	
Vehicle No.:	CB7420D
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	URVAN 3.0 M
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	ZD30040314
Chassis No.:	JN1TG4E25Z0701209
Maximum Power Output:	-
Open Market Value:	\$23,036.00
Original Registration Date:	03 Jul 2004
First Registration Date:	03 Jul 2004
Transfer Count:	8
Actual ARF Paid:	\$1,152.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 08 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/06/2019 16:47
Date Of Accident	10/06/2019 09:15
Exact Location Of Accident	JUNCTION OF ANG MO KIO AVE 5 & YIO CHU KANG ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	CB7420D
Insured/Policyholder	
Name Of Registered Owner	ELITE TRANSPORT SERVICES
Co Reg No	53073981W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96375640
Alternative Phone No	OFFICE-96375640
Vehicle Particulars	
Manufacturer	NISSAN
Model	URVAN-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	GA237225/1
Cover Note Number	
Driver	
Name of Driver	WONG CHONG HON
NRIC No	S0045489C
Date Of Birth	13/05/1954
Occupation	INDOOR
Date Of Driving Pass	30/05/1974
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96399263
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 111 SERANGOON NORTH AVENUE 1 #10-603
Postcode	550111
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TOO CHU KIOK GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 50 SERANGOON AVE 2 #01-02 , POSTCODE: 556129 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4880999 - FAX NO: 64883561
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS8789A
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG CHONG HON

Approximate Age

Injuries Sustain

Injured person in which vehicle? CB7420D

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT BUANGKOK GREEN

* Refer To Police KopanA *

T/20190610/2070 2

T/20190610/2139.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190610/2090

1 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20190610/2090

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/06/2019 13:57	Vide Report No.: F/20190610/0078	Station Diary No.: 33
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: WONG CHONG HON			Address: APT BLK 111 SERANGOON NORTH AVENUE 1 #10-603 SINGAPORE 550111	
ID Type / ID No.: NRIC NO / S0045489C			Contact No.: Home/Office:	Mobile: 96399263
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 65	Date of Birth: 13/05/1954	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: SCHOOL BUS DRIVER			Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 10/06/2019 09:15	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVENUE 5				
Junction of ang mo kio avenue 5 and yio chu kang road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CB7420D						1
SKS8789A						1

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20190610/2090

2 of 3

Police Station Of Origin:

Serangoon N.P.C

50 Serangoon Avenue 2 #01-02 SINGAPORE

556129

Tel No: 1800-4880999

Report No. T/20190610/2090

CONTINUATION OF REPORT

Driver			
Name	WONG CHONG HON	ID No.	S0045489C
Related Vehicle	CB7420D	Contact No.	96399263
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	10/06/2019	Date Discharge	10/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 10.06.2019, I was driving the school bus CB740D along Ang Mo Kio avenue 5. My vehicle was in the pocket intending to turn right. As I moved my vehicle, there was another vehicle from the opposite direction which hit onto my vehicles left side portion. Fortunately, there was a Civil defence rider who passed by and assist us. We were told to moved to the road shoulder and at that time my head was injured. Suddenly, the vehicle had already left and nowhere to be seen. I called for police and my supervisor to come down. My supervisor came down and called for ambulance as I was injured. Traffic police was at scene too. My supervisor managed to trace the fragments of the vehicle's plate number which was seen lying on the road. We did not manage to take down the particulars of the driver as he had left the scene.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999



T/20190610/2090

3 of 3

Report No. T/20190610/2090

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 3 MUHAMMAD ASYRAF BIN ARIS

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt SYED ZAYID MUHAMMAD BIN
SYED ABDUL WAHID ALHINDIAN
Contact No: 65476394

Authentication Stamp
NP168
151 NS

Signature Of Informant:

[Handwritten Signature]

Date/Time:
10/06/2019 13:57

Classification Of Case:

Amended Police Report Pg. 1



T/20190610/2139

1 of 3

Report No. T/20190610/2139

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No 0

Report Number T/20190610/2139

Vide Report Number T/20190610/2090

Date/Time of Report Made 10/06/2019 15:45

Place Report Lodged Traffic Police

Type of Informant Driver

Name of Informant wong chong hon

ID Type / ID No. NRIC NO / S0045489C

Home/Office

Mobile 96399263

Email

Type of Accident Injury / Attended by Police

Drink Drive No

Anyone conveyed by ambulance Yes

Date/Time of Accident 10/06/2019 09:15

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CB7420D						1
SKS8789A						1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20190610/2139

2 of 3

Report No. T/20190610/2139

Continuation of CSF For NP168

Driver			
Name	wong chong hon	ID No.	S0045489C
Related Vehicle	CB7420D	Contact No.	96399263
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Facts.

I had lodged an accident report vide T/20190610/2090. I wish to further add in the following statement. Before the accident happened, my bus CB7420D was stationery at the turning box, and green arrow was in our favor. There was another vehicle in front of me. After which, we start to move off when suddenly the said vehicle SKS8789A from the opposite traffic hit onto my vehicle's left side portion.



T/20190610/2139

3 of 3

Report No. T/20190610/2139

Continuation of CSF For NP168

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity	No
Officer-In-Charge of Case	TP / GIT / SYED ZAYID MUHAMMAD BIN SYED ABDUL WAHID ALHINDUAN
Classification of Case	1) INJURY / ATTENDED BY POLICE



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MKKH 9075549 Vehicle Registration No: CB 7420D
Name (as shown in NRIC) : _____ NRIC/FIN/Passport No : _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 10-6-19 Time of Accident : 09:15
Place of Accident : JUNCTION OF ANG MO KIO AVE'S
Insurance Company : AXA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

ENQUIRED AMENDED POLICE REPORT (MISSED OUT
By WORKSHOP DURING 1st SUBMISSION).

[Signature] 19/6
Policyholder / Driver's Signature
Date:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (07) Deformed
 (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
 (14) Unconfirmed (15) Not Working

VAN / LORRY (Frt)

ACTION (AC)

(1) Replace (✓) (2) Repair (R) (3) Check (P)
 (4) Not Consistent (NC)

Aug 2005

1/2

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	DD	NEC	6
2001	991477	Frt Bumper Upper Clips			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side Retainer LH	DD		
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No: CB 7420 D

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender	BUC	R	
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield	DIS		
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre	CUT	70%	
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel	DIS		
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim	DD		
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door	BUC		
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber	DD		
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar LH	DD	R	
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel	CUT		
2042	994498	Frt Step Panel Top Garnish	CUT		
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker	NEC		
		LH Sliding Door			
		Protector			

No of Items:

Assessor:

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

 Springer

2 $\sqrt{5}^2$

Vehicle No: CB 74201

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

Original copy










...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019 Edit Reg		28 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BIZLINK RENT-A-CAR PTE LTD , Co. Reg. No.: 200402911Z								
Main Claimant:	ELITE TRANSPORT SERVICE , Co. Reg. No.: 53073981W								
Vehicle Reg. No.:	CB7420D	Date of Loss:	10/06/2019 09:00 - :59 [179 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3430283794SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKS8789A	Policy No. (Claimant):							
		Excess:							
Repairer:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721, 575721 Sin Ming - Tel: 64510747								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (03/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***CB7420D (3430283794SG)**
[SKS8789A]
TP
ELITE TRANSPORT SERVICE
Jun 10 2019 9:00AM
[BIZLINK RENT-A-CAR PTE LTD]
Ann Joo Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
2	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
3	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
4	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
5	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
6	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
7	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
8	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
9	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
10	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
11	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
12	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
13	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
14	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
15	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
16	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
17	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
18	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
19	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
20	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
21	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
22	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
23	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
24	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
25	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
26	08/07/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print	
1	03/07/19 10:32	OI GIA REPORT														Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011510/T1CD3E2

Date: 30/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : CB7420D

Insured Vehicle No : SKS8789A

Date of Loss: 10/06/2019

Nature of Claim: TP

Claim No: 3430283794SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: CB7420D

Make & Model: NISSAN URVAN, 3.0 D (M)

Engine No: ZD30040314

Reg. Date: 03/07/2004 (Man. Year: 2004)

Chassis No: JN1TG4E25Z0701209

Colour: Silver

Odometer: 712181 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/06/2019

Date Inspected: 28/06/2019 Inspected At:

Ann Joo Motor Pte Ltd (HQ)

Blk 176 Sin Ming Drive #02-17, Singapore 575721

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER LH	Distorted	0.00 F	*- F
4	1		*FRT LH FENDER	Repair	0.00 F	*- F
5	1		*FRT LH FENDER INNER SHIELD	Distorted	0.00 F	*- F
6	1		*FRT LH TYRE (70%)	Cut	0.00 F	*- F
7	1		*FRT RH FENDER INNER GARNISH	Distorted	0.00 F	*- F
8	1		*FRT RH WHEEL RIM	Dented	0.00 F	*- F
9	1		*FRT LH DOOR	Buckled	0.00 F	*- F
10	1		*FRT LH DOOR GLASS REGULATOR	* Check	0.00 F	*- F
11	1		*FRT LH DOOR GLASS REGULATOR MOTOR	* Check	0.00 F	*- F
12	1		*FRT LH DOOR RUBBER	Dented	0.00 F	*- F
13	1		*FRT LH DOOR INNER TRIM BOARD	* Check	0.00 F	*- F
14	1		*FRT DOOR REAR PILLAR LH	Repair	0.00 F	*- F
15	1		*FRT STEP PANEL	Cut	0.00 F	*- F
16	1		*FRT STEP PANEL TOP GARNISH	Cut	0.00 F	*- F
17	1		*STICKER	Necessary	0.00 F	*- F
18	1		*LH SLIDING DOOR	Repair	0.00 F	*- F
19	1		*LH SLIDING DOOR FRT EDGE PROTECTOR	Cut	0.00 F	*- F
20	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*- F
21	1		*FRT LH SHOCK ABSORBER MOUNTING	* Check	0.00 F	*- F
22	1		*FRT LH KNUCKLE ARM	* Check	0.00 F	*- F
23	1		*FRT LH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
24	1		*FRT LH LOWER ARM	* Check	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >