

ASS. REC. BY:

REF: CS/CTI19011512/1/rd30

Special Instruction:

Surveyor: TaufikhASSIGNMENT (Office)From (Person): Chong Boon Sen

of

CTI

Date/Time:

28/6/2019.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 8918 H

Insured:

SKN 3190K

at Workshop m/s

Vantage Automotive

Tel:

6487 7409

of

305 Alexandra Rd.

Policy No:

Claim No:

SNM19D 202889

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/6/2019CA / REV / REP. / REV 24 HRS1/7/2019 After 2pm

H.O.D. Endorsement:

Date/Time:

28/6

Person Contacted:

MelodyVehicle IN / OUT

Date/Time	Action/Instruction
	<u>Vehicle</u> ✓
	<u>SKN 3190K</u> X
	<u>SLS 8918H</u> X
<u>19/8/19</u>	<u>Final fig \$ 4498.50 confirmed by email (Ref 3120, 419)</u>

ASSIGNMENT

From: _____ Date: 1.7.2019

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLS 89184at Workshop n/s Vantage Automobileof 305 Alexandra Road

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS no

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLS89184 Yr Regn: 2017, Dec.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Pugeot 3008 c.c. 1598Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 14942 T/Radio: Insured / Std / NI / NAEng/No: VF3M456EW.HS270286

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R18R: 225/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 11/07/190115Survey held at Vantage AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 19 AUG 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/8 - typistReport Format: merimenLump Sum / I.B.I. (\$) 4498.50Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 220Transportation: 3 + RS, SI

Photos

Others

TOTAL 220

Veron Chen (LKKAuto)

From: Melody Teoh Man Lin <melody.teoh.manlin@simedarby.com.sg>
Sent: Wednesday, 24 July 2019 5:20 PM
To: Veron Chen (LKKAuto)
Cc: Katherine Chong; Liu Chun Cheong; Andy Ooi Lee Keong; Simon Koh Eng Aun
Subject: RE: SLS 8918H-DOA: 19/6/2019

Dear Veron,

This vehicle is scheduled to come in for repairs next week.

Best regards,

MELODY TEOH

Customer Service Advisor (Bodyshop)

VANTAGE AUTOMOTIVE

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Regent Motors Limited (FORD)

AutoFrance (PEUGEOT)

DID: +65 6477 7409

HP : +65 9278 2710

Email: melody.teoh.manlin@simedarby.com.sg



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Wednesday, July 24, 2019 4:02 PM

To: Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>

Cc: Melody Teoh Man Lin <melody.teoh.manlin@simedarby.com.sg>; Katherine Chong <katherine.chong@simedarby.com.sg>; Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>

Subject: SLS 8918H-DOA: 19/6/2019

Dear Simon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 28 June 2019 8:11 AM
To: Melody Teoh Man Lin
Cc: assignments
Subject: RE: OUR REF: SNM19D202889 / TP CLAIM SLS 8918H AGAINST SKN3190K DOA: 19.6.19

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Melody Teoh Man Lin [mailto:melody.teoh.manlin@simerdarby.com.sg]
Sent: Thursday, 27 June, 2019 6:09 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202889 / TP CLAIM SLS 8918H AGAINST SKN3190K DOA: 19.6.19

Dear Officer-in-Charge,

We would like to choose XING QUO QIANG to conduct the pre-repair survey.

Thank you.

Best regards,

MELODY TEOH

Customer Service Advisor (Bodyshop)
Vantage Automotive Limited
305 Alexandra Road
Vantage Automotive Centre

1/7/19 After 2pm

Singapore 159942
Regent Motors Limited (**FORD**)
AutoFrance (**PEUGEOT**)
DID: +65 6477 7409
HP : +65 9278 2710
Email: melody.teoh.manlin@simedarby.com.sg



From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Thursday, June 27, 2019 4:08 PM
To: Melody Teoh Man Lin <melody.teoh.manlin@simedarby.com.sg>
Subject: OUR REF: SNM19D202889 / TP CLAIM SLS 8918H AGAINST SKN3190K DOA: 19.6.19

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2019 14:12
Date Of Accident	19/06/2019 19:00
Exact Location Of Accident	ALONG UPPER PAYA LEBAR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS8918H
Insured/Policyholder	
Name Of Registered Owner	KATHLEEN MOW KHONG LING
NRIC No	S2625512J
Email Address	KATMOW66@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82575100
Alternative Phone No	OTHERS-96385728

Vehicle Particulars

Manufacturer	PEUGEOT
Model	3008 ALLURE-1.6 E-THP EAT6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2046730
Cover Note Number	

Driver

Name of Driver	GAN KIAT CHAI
NRIC No	S1566202F
Date Of Birth	03/01/1962
Occupation	INDOOR
Date Of Driving Pass	09/01/1980
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96385728
Fax Number	
Contact Number	
Email Address	KCGANM@GMAIL.COM

Address	67C FLORENCE ROAD
Postcode	549554
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN3190K
Vehicle Make/Model/Colour	BLACK JAGUAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG CHOON MUI
NRIC/Passport Number	S7140890F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature

Date & Time:

21/06/2019

@ 2:55pm

GIA RMC SketchPlanForm_V3


Driver's Signature


(If driver is not the policyholder)

Date & Time:

21/06/2019

2:55pm




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


Melody Teoh

Customer Service Advisor
Accident & Bodyshop 1

SKETCH PLAN

3LS 8918H

3KN 3190K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

An accident had taken place on 19 Jun 2019 at around 7.00 pm along Upper Paya Lebar Road. [Opposite Tai Feng Garden] going towards Lorong Ah Soo.

I was (A: 3LS 8918H) was travelling straight towards Lorong Ah Soo and the other vehicle (B: 3KN 3190K) which was in the extreme right to make an U-turn.

Out of the blue, ~~she~~ she suddenly filtered left which hit my rear right.

After impact, I was stunned and feeling crumpled and nauseous. I could not drive due to my left arm sustain injury and unable to lift up my arm. Later, the vehicle B husband arrive to assist at the accident scene and he volunteered to send me to hospital (A & E Dept).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Mew Khay Lin

Policyholder's Signature

Date & Time:

21/06/2019 @ 2.55pm

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

21/06/2019

@ 2.55pm



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Melody Teoh

Customer Service Advisor
Accident & Bodyshop

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4233
Date Estimated : 26/06/2019
Prepared By : Melody Teoh Man Lin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Kathleen Mow Khong Ling
67C Florence Road

Singapore 549554

- ACCOUNT -

31432

China Taiping Insurance (Singapore) Pte Ltd
3 ANSON ROAD
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS8918H	VF3M45GZWHS270286	18/12/2017	3008 1.6 e-THP Allur	0

DESCRIPTION

TO CONDUCT TP CLAIM AGAINST SKN3190K (CHINA TAIPING
INS) DOA:19/06/2019

VALUE

0.00

SUNDRIES

✓ 30. 150.00

LABOUR TO REMOVE,REALIGN, REPLACE AND REPAIR RHS
REAR DOOR,RHS REAR FENDER WHEEL PROTECTOR AND ALL
AFFECTED AREAS

600

✓ 600. 2,400.00

LABOUR TO PUTTY AND RESPRAY RHS REAR DOOR AND ALL
AFFECTED AREAS

600

✓ 600. 1,800.00

TO TRANSFER AND REFIT RHS REAR DOOR,GLASS TRIM AND
MECHANICAL COMPONENT.(NETT)

✓ ✓ 600.00

SEALANT FOR BODY PANEL(PER PANEL \$90 NETT)

✓ ✓ 90.00

ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.(NETT)

✓ ✓ 120.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT
CODES RESTORE ALL PROGRAMME MODULE (NETT)

✓ ✓ 600.00

Total Labour 1: 5,760.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
9812317080	REAR DOOR RH ASS	1	1,300.00	10.00	1,170.00
9811258680	WEATHERSTRIP-RH REAR DOOR (AT DOOR)	1	65.00	10.00	58.50
9811260380	FINISHER - RH DOOR CENTER PILLER	1	100.00	10.00	90.00
9811518880	MOULDING RH AR	1	90.00	10.00	81.00
98116339XT	WING MOULDING RHR	1	200.00	10.00	180.00

Rear RH door protector int ✓

Total Parts : 1,579.50

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4233
Date Estimated : 26/06/2019
Prepared By : Melody Teoh Man Lin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS8918H	VF3M45GZWS270286	18/12/2017	3008 1.6 e-THP Allur	0

Handwritten:
3/1/19
Tangkin 97495749
WP-
21/07/19 @ 1115 am
Resurvey before paint.
sure lkkauto.com.
4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7618.50

Labour 1	:	5,760.00
Parts	:	1,579.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	513.77
Grand Total	:	7,853.27

Customer Name & Signature / Company Stamp

Date

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

AUTOFRANCE

(A Division of Vantage Automotive Limited)
Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

FINALIZATION REPORT



REPAIR ORDER NO. BP 115084	Date IN 29/07/2019 Payment Term 30 Days From Invoice Customer Service Advisor Melody Teoh Man Lin	Invoice Number Invoice Date ?? Invoice By Melody Teoh Man Lin	Page No. 1 of 1
--------------------------------------	---	--	------------------------

CUSTOMER INFORMATION	INVOICE TO 31432
Kathleen Mow Khong Ling 67C Florence Road Singapore 549554	China Taiping Insurance (Singapore) Pte Ltd 3 ANSON ROAD #16-00 Springleaf Tower Singapore 079909

REGISTRATION No. SLS8918H	CHASSIS No. VF3M45GZWS270286	STOCK No. 210590	REGISTRATION DATE 18/12/2017	MODEL 3008 1.6 e-THP Allur	MILEAGE 15858
-------------------------------------	--	----------------------------	--	--------------------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM AGAINST SKN3190K (CHINA TAIPING INS)	0	0.00	0.00
	DOA:19/06/2019			
	SUNDRIES	1	0.00	30.00
	LABOUR TO REMOVE,REALIGN, REPLACE AND REPAIR RHS REAR DOOR,RHS REAR FENDER WHEEL PROTECTOR AND ALL AFFECTED AREAS	1	0.00	600.00
	LABOUR TO PUTTY AND RESPRAY RHS REAR DOOR AND ALL AFFECTED AREAS	1	0.00	600.00
	TO TRANSFER AND REFIT RHS REAR DOOR,GLASS TRIM AND MECHANICAL COMPONENT.(NETT)	1	0.00	600.00
	SEALANT FOR BODY PANEL(PER PANEL \$90 NETT)	1	0.00	90.00
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.(NETT)	1	0.00	120.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	1	0.00	600.00
Sub-Total :				2,640.00
CODE	DESCRIPTION	UNITS	DISC %	NETT
98114033VV	DOOR PROTECTOR RHR (A)	1	10.00	279.00
9811518880	MOULDING RH AR	1	10.00	81.00
98116339XT	WING MOULDING RHR	1	10.00	180.00
9811260380	FINISHER - RH DOOR CENTER PILLER	1	10.00	90.00
9812317080	REAR DOOR RH ASS	1	10.00	1,170.00
9811258680	WEATHERSTRIP-RH REAR DOOR (AT DOOR)	1	10.00	58.50
Sub-Total :				1,858.50
Attending CSO : Melody Teoh Should you require further explanation, please reach me at 92782710				

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$ 4,498.50
Labour Charges	2,640.00	Less Insurance Excess	S\$ 0.00
Parts Charges	1,858.50	GST @ 7%	S\$ 314.90
Lubricant/Misc	0.00	Invoice Total Amounts	S\$ 4,813.40
		Less Deposit/Voucher	S\$ 0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$ 4,813.40

All amounts are in Singapore Dollars.
Work was carried out subject to the Company's Terms and Conditions of Service.
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.
For credit purchases, interest @1% per month will be debited on overdue amounts.



Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLS8918H

RO Number: BP 4233 / BP 115084

Date: 01 JUL 2019

NO.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1	DOOR PROTECTOR RHR <i>Cut</i>	98114033VV	1	\$310.00	10%	\$279.00
Parts Total:						\$279.00

NO.	Supplementary Labour Charges	Price
Total Labour:		\$0.00
Total Parts & Labour:		\$279.00
GST @ 7%:		\$19.53
Grand Total:		\$298.53

Raised By Technician	Approved By CSA MELODY	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	----------------------------------	-----------------------------------	--------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 19 August 2019 1:52 PM
To: Melody Teoh Man Lin; Taufikh (LKKAUTO); SUR
Cc: Liu Chun Cheong; Andy Ooi Lee Keong; Simon Koh Eng Aun; Katherine Chong
Subject: RE: SLS8918H - FINALIZATION

Dear Melody,

WITHOUT PREJUDICE

Finalize as COR: **\$4,498.50** (before GST) @ **4 days repair**.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Melody Teoh Man Lin <melody.teoh.manlin@simedarby.com.sg>
Sent: Monday, 19 August 2019 11:52 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>; Katherine Chong <katherine.chong@simedarby.com.sg>
Subject: SLS8918H - FINALIZATION

Hi Taufikh,

Above attached is **SLS8918H** Finalized report, together with supporting documents for your reference.

We would like to finalize as COR: **\$4,498.50** (before GST) @ **4 days repair**.

Please kindly check and confirm via reply email.

Thank You.

Best regards,

MELODY TEOH

Customer Service Advisor (Bodyshop)

VANTAGE AUTOMOTIVE
305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Regent Motors Limited (**FORD**)

AutoFrance (**PEUGEOT**)

DID: +65 6477 7409

HP : +65 9278 2710

Email: melody.teoh.manlin@simedarby.com.sg



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2019		10 Jul 2019 15:08 Edit Adj Rpt	S\$4,498.50 Edit Estimates	S\$4,498.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	KATHLEEN MOW KHONG LING , ID: S2625512J								
Vehicle Reg. No.:	SLS8918H	Date of Loss:	19/06/2019 19:00 - :59 [18 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202889C02	Policy/Cover Note No.:	DMPCSN31103019022						
Vehicle Reg. No. (Insured):	SKN3190K	Policy No. (Claimant):	VPA/P2046730						
		Excess:	S\$0.00						
Repairer:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre, 159942 Alexandra - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS8918H (SNM19D202889C02)
[SKN3190K]
TP
KATHLEEN MOW KHONG LING
Jun 19 2019 7:00PM
[-]
Vantage Automotive Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	21/06/19 19:28	Policyholder Identification Card [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 19:28	Driver Identification Card [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 19:28	CI [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
17	21/06/19 19:28	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/08/19 13:46	General View	Load PDF	
2	19/08/19 13:47	Reinspection Photo (1)	Load PDF	
3	19/08/19 13:47	Reinspection Photo (2)	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	21/06/19 19:26	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 19:26	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	26/06/19 08:27	Police Report [Linked Accident Report Documents]	Load TIFF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/09/19 12:30	Supplementary	Load PDF	

Linked Accident Report Documents

				View	View in Browser
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)		Thumbnail	Print
1	21/06/19 19:28	Policyholder Identification Card		Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 19:28	Driver Identification Card		Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 19:28	CI		Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
15	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
16	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
17	21/06/19 19:28	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)		Thumbnail	Print
1	21/06/19 19:26	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 19:26	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	26/06/19 08:27	Police Report		Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011512/T1VD3E2

Date: 02/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN31103019022

Claimant Vehicle
No : SLS8918HInsured Vehicle
No : SKN3190K

Date of Loss: 19/06/2019

Nature of Claim: TP

Claim
No: SNM19D202889C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS8918H**

Make & Model: PEUGEOT 3008, 1.6 (A)

Engine No: 10FJCC2373748

Reg. Date: 18/12/2017 (Man. Year: 2017)

Chassis No: VF3M45GZWHS270286

Colour: Bronze

Odometer: 14942 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,008.50	1,888.50	120.00	5.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,610.00	2,610.00	3,000.00	53.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,618.50	4,498.50	3,120.00	40.95
+ GST 7.00/7.00% (S\$)	533.30	314.90	218.40	40.95
Nett Amount (S\$)	8,151.80	4,813.40	3,338.40	40.95

INSPECTION

Date of Assignment: 10/07/2019

Date Inspected: 01/07/2019 Inspected At:

Vantage Automotive Limited (Alexandra)
305 Alexandra Road #02-01, Vantage
Automotive Centre
Singapore 159942

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2019)
Parts: 144	PEUGEOT 3008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS8918H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*30.00 FS
2	1		*REAR DOOR RH ASS	Bent	1,170.00 FS	*1,170.00 FS
3	1		*WEATHERSTRIP-RH REAR DOOR (AT DOOR)	Necessary	58.50 FS	*58.50 FS
4	1		*FINISHER-RH DOOR CENTER PILLAR	Necessary	90.00 FS	*90.00 FS
5	1		*MOULDING RH AR	Necessary	81.00 FS	*81.00 FS
6	1		*WING MOULDING RHR	Cut	180.00 FS	*180.00 FS
7	1		*DOOR PROTECTOR RHR	Cut	279.00 FS	*279.00 FS
Total Parts (S\$)					2,008.50	1,888.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE, REALIGN, REPLACE AND REPAIR RHS REAR DOOR, RHS REAR FENDER WHEEL PROTECTOR AND ALL AFFECTED AREAS	New	2,400.00	600.00
2	LABOUR TO PUTTY AND RESPRAY RHS REAR DOOR AND ALL AFFECTED AREAS	New	1,800.00	600.00
3	TO TRANSFER AND REFIT RHS REAR DOOR, GLASS TRIM AND MECHANICAL COMPONENT	New	600.00	600.00
4	SEALANT FOR BODY PANEL (PER PANEL \$90 NETT)	New	90.00	90.00
5	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	New	120.00	120.00
6	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE	New	600.00	600.00
Gross Labour Cost (S\$)			5,610.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >