










Acc 2010 595 PAS












X




Reer











12
Rear o/s. Body and
inner structure (lower)






























2

Rear o/s body cant
inner barbs rear
cracked







51