

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/06/2019 09:09
Date Of Accident	28/06/2019 15:45
Exact Location Of Accident	CTE TWDS CITY B4 PIE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC9457L
Insured/Policyholder	
Name Of Registered Owner	ONG JUNWEN
NRIC No	S8202434D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94515827
Alternative Phone No	OFFICE-94515827

Vehicle Particulars

Manufacturer	BMW
Model	320i
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103043737
Cover Note Number	-

Driver

Name of Driver	ONG JUNWEN
NRIC No	S8202434D
Date Of Birth	16/01/1982
Occupation	OUTDOOR
Date Of Driving Pass	28/03/2003
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94515827
Fax Number	
Contact Number	OFFICE-94515827
Email Address	NOEMAIL

Address	BLK 411A FERNVALE RD #25-82
Postcode	791411
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CTE TWDS CITY B4 PIE EXIT ON THE THIRD LANE FROM THE LEFT, SUDDENLY VEH B WHICH WAS INFRONT OF ME JAMME BRAKE, I MANAGE TO STOP BUT CANNOT STOP IN TIME, AS THE RESULT, MY VEH HIT ONTO VEH B REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC8053P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A = SMC 9457L
B = PC 8053P

CTG towards City B4 PIE Exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8202434D



Name

ONG JUNWEN
(WANG JUNWEN)

王 俊 文

Race
CHINESE

Date of birth
16-01-1982

Sex
M

Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence No. S8202434D
Name

ONG JUNWEN
(WANG JUNWEN)

Birth Date: 16 Jan 1982
Valid Until: 26 Mar 2003



4923610



NRIC No. S8202434D



Date of issue
14-01-2013


Address

APT BLK 411A FERNVALE ROAD
#25-B2
SINGAPORE 791411

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
20 Mar 2003



NP 426A

My Desktop
Notice of Loss

Policy Query

Policy No.		Date of Accident	28/06/2019 09:08
Vehicle No.(For Motor)	SMC9457L	Certificate Number	

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5103043737		ONG JUNWEN	S8202434D	GPC	drivo CLASSIC	SMC9457L	SMC9457L	17/08/2018	03/12/2019

Continue

Claim Handling

Accident MT/1051332

Policy No.	5103043737	Vehicle No.	SMC9457L	GST Registration No.	
Certificate No.				Policyholder NRIC	S8202/
Policyholder Name	ONG JUNWEN			Loading	0
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Contact No.(Home)	
Contact No.(Mobile)	94515827	Contact No.(Office)		eCode	No
Email Address		Special Remark		eCode Reason	
KFK	+ No Yes	TCA	No Yes	Private Hire	No
NCD Protection	Yes	NCD Entitlement(%)	50		
Accident Details					
Report Date	01/07/2019 16:06	Accident Report Within 24 hrs	Yes	Accident Type	Collision
Date of Accident	28/06/2019	Time of Accident hh:mm	15:45	Country of Accident	Singap
Reporting Centre		Orange Force		ICM No.	
Accident Location	CTE TWDS CITY B4 PIE EXIT				
Excess					
Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
Benefits					
GST Registered Information					
GST Registered	No	GST Registration Date			
GST Registration No.		GST Status Verified	Yes		
Modification History					
Policyholder Mailing Address					
Address 1	BLK 730 #03-57	Address 2	TAMPINES STREET 71	Address 3	TAMPIN
Address 4	SINGAPORE 520730	Address Type	Singapore address	Post Code	520730
Unit No.	03-57	Related Policy Number	5103043737		
O1 Driver Info					
Driver Name	ONG JUNWEN	Driver Type	Main Driver	Driver DOB	16/01/
Unnamed driver Name		Driver NRIC	S8202434D	Driving Experience	16
Register Date of Driver License	28/03/2003	Driver Age	37	Contact No.(Home)	
Contact No.(Mobile)	94515827	Contact No.(Office)		Address 3	TAMPIN
Address 1	BLK 730 #03-57	Address 2	TAMPINES STREET 71	Post Code	520730
Address 4	SINGAPORE 520730	Address Type	Singapore address		
Unit No.	03-57				
Does he own a Singapore Registered car?	Yes + No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading? 0 mg Any injury? Yes No

Modification History

Claim 001 New

Claim Type *	OD-MD	Insured Name	ONG JUNWEN
Contact No.(Mobile)	94515827	Contact No. (Home)	62600460
Email Address	EUGENE_TP@HOTMAIL.COM	O1 Vehicle Number	SMC9457L
Claim Description	SMC9457L / PC8053P ON 28 Jun 2019		
Preferred Workshop	0	Insured Liability	Fully at Fault
Report No. Finalisation	Yes	Preferred Repair Option	Income to assign workshop
Date Registered		GIA report	Received
Report Taken By		Claim Close Date	01/07/2019 16:09
			LIEW SHAN HUI
☒ Print AK letter			

Save Submit

Attachment

Accident No. MT/1051332 Claim No. 001

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motorcar ()
 - b) Motorcycle ()
 - c) Bicycle ()
- 2) Vehicle hit ??
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govn Property ()
(e.g. signboard, barrier, tree etc.)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other, _____
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case
 - a) Stolen ()
 - b) Damage found ()
when recovered.
- 8) Fire
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SMC 9457 L Yr Regn: 4 Jun 2013

Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / M2V
/ Truck / Trailer or

Make & Model: BMW 320i C.Y. 1997

Colour: Black Transmission Type: Auto / Manual

Eng/No: _____ Sp. Reading: 127919

C/Ro: WBA3B16030NP54661

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO YOKO or

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm

Parallel Import: Yes No

Repair Type: LS / I.B.J.

No of Repair Days: 7

D.O.I. 1/7/2019

Towed-In: Yes / No

Towing Required: Yes / No

Vehicle in Idac: Yes / No

Time: 340 pm

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govn Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

MOTOR CAR (Fr)

Front Portion

Vehicle No: **SMC 9457L**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	SCA		
1002	991887	Frt Number Plate Base	BT		
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD		
1005	992341	Frt Bumper Clips	NEC		6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS		
1008	991433	Frt Bumper Reinforcement	BT		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA		
1011	991427	Frt Bumper Top Rubber Strip.			
1012	991420	Frt Bumper Emblem.	DD		
1013	991363	Frt Bumper Grille	CRA		
1014	991301	Frt Bumper Low Eye Cover.	TN		
1015	991407	Frt Bumper L			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	994793	Frt Grille LH & RH	CRA		
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel	BT		
1029	995153	Frt LH Headlamp Assy	CRA		
1030	991821	Frt RH Headlamp Assy	CRA		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BUC		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock LH & RH			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	DD		
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	SCR	R	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Emblem	NEC		
1099	995148	Frt LH Fender			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	SCR	R	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Emblem	NEC		
1108	991752	Frt RH Fender			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Amount:

Claim Handling

Task Transfer Exit

LOS SAL SUB

▼ Accident MT/1051332

Policy No.	5103043737	Vehicle No.	SMC9457L	GST Registration No.	
Certificate No.					
Policyholder Name	ONG JUNWEN			Policyholder NRIC	S8202434D
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	94515827	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No ▼
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

▼ Accident Details

Report Date	01/07/2019 16:06	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	28/06/2019	Time of Accident hh:mm	15:45	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	4078719
Accident Location	CTE TWDS CITY B4 PIE EXIT				

▼ Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 730 #03-57	Address 2	TAMPINES STREET 71	Address 3	TAMPINES COURTVIEW
Address 4	SINGAPORE 520730	Address Type	Singapore address	Post Code	520730
Unit No.	03-57	Related Policy Number	5103043737		

▼ OI Driver Info

Driver Name	ONG JUNWEN	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S8202434D	Driver DOB	16/01/1982
Register Date of Driver License	28/03/2003	Driver Age	37	Driving Experience	16
Contact No.(Mobile)	94515827	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 730 #03-57	Address 2	TAMPINES STREET 71	Address 3	TAMPINES COURTVIEW
Address 4	SINGAPORE 520730	Address Type	Singapore address	Post Code	520730
Unit No.	03-57				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No
Modification History	01/07/2019 16:56 s035020 Modify Orange Force(N-->Y) 01/07/2019 16:56 s035020 Modify ICM No(-->4078719)		

▼ Investigation

Claim 001 OD-MD

LOS SAL SUB

▼ Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	ONG JUNWEN	Insured NRIC	S8202434D
Contact No.(Mobile)	94515827	Contact No. (Home)	62600460	Contact No. (Office)	
Email Address	EUGENE_TP@HOTMAIL.COM	OI Vehicle Number	SMC9457L	TP Vehicle Number	PC8053P
Claim Description	SMC9457L / PC8053P ON 28 Jun 2019			Name of Preferred Workshop	0
Preferred Workshop	☒ Yes ☐ No	Preferred Repair Option	income to assign workshop	Insured Liability report	Fully at resolved
Date Registered	01/07/2019 16:11	Claim Close Date		Date Received	02/07/2019 09:14
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
Print AK letter				OD Excess Collected by Workshop	

Modification History

▼ Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Activity Handling Attachment

Vehicle Info

Vehicle Make *	BMW	Vehicle Model	320i	Engine Capacity	
Date of Registration	04/06/2013	Classis No.	WBA3B16030NP54661		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	
Remark	REMARK:NO OF REPAIR DAYS:7 DAYS.1X FRT BUMPER TOP RUBBER STRIP - UNCONFIRM.1 X FRT GRILLE LH & RH - REPLACE.1X FRT SUPPORT PANEL TOP GARNISH COVER - UNCONFIRM.2X BONNET LOCK LH & RH - UNCONFIRM.1X AIRCON SUCTION PIPE - UNCONFIRM.1X AJRDUCT - UNCONFIRM.1X AIR CLEANER ASSY - UNCONFIRM.1X FRT LH FENDER EMBLEM - REPLACE.1X FRT RH FENDER EMBLEM - REPLACE.				

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
ABSORBER	3	16000101	BUMPER (FRONT)	1	Replace	X
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
ADVERTISEMENT STICKER	5	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
AIR BAG	6	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
AIR BLOWER	7	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
AIR BOX	8	16005901	BUMPER SPONGE (FRONT)	1	Replace	X
AIR CHAMBER BOX	9	16002601	BUMPER EMBLEM (FRONT)	1	Replace	X
AIR CLEANER	10	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR COMPRESSOR	11	16006701	BUMPER TOWING COVER (FRONT)	1	Replace	X
AIR CON	12	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
AIR CON (VAN)	13	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	X
AIR COOLER	14	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm	X
AIR DISTRIBUTOR	15	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	X
AIR FILTER	16	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
AIR FLOW	17	15600101	BRACE PANEL (FRONT)	1	Replace	X
AIR GRILLE	18	27700101	HEAD LAMP (LEFT)	1	Replace	X
AIR HORN	19	27700102	HEAD LAMP (RIGHT)	1	Replace	X
AIR INTAKE	20	149001	BONNET	1	Replace	X
AIR RESONATOR BOX	21	149029	BONNET INSULATOR	1	Unconfirm	X
AIR THROTTLE BODY AND SENSOR	22	14902201	BONNET HINGE (LEFT)	1	Unconfirm	X
ALARM	23	14902202	BONNET HINGE (RIGHT)	1	Unconfirm	X
ALTERNATOR	24	149043	BONNET RUBBER (LONG)	1	Unconfirm	X
ALUMINIUM PANEL - SIDE	25	112023	AIR CON CONDENSER	1	Replace	X
AMPLIFIER	26	112044	AIR CON DISCHARGE PIPE	1	Unconfirm	X
ANTENNA	27	344001	RADIATOR	1	Unconfirm	X
ANTI ROLL	28	344005	RADIATOR COWLING	1	Unconfirm	X
APRON	29	344008	RADIATOR FAN	1	Unconfirm	X
ARCH	30	344011	RADIATOR FAN CLUTCH	1	Unconfirm	X
ARM REST	31	243014	ENGINE LOWER COVER	1	Unconfirm	X
ASH TRAY	32	25400102	FENDER (FRONT LEFT)	1	Repair	X
AUTO CLUTCH	33	25400103	FENDER (FRONT RIGHT)	1	Repair	X
AUTO COOLER PIPE	34	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Unconfirm	X
AUTO CRUISE MOTOR	35	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm	X
AUTO TRANSMISSION						
AXLE						
BACK REST (M/C)						
BACK SEAT						
BALANCER						
BATTERY						
BEADING (M/C)						
BELT COVER (M/C)						
BELT TENSIONER						

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC
NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SMC 945FL Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Bodyfix

Collection Date: 03/07/19 Time: 1030 with Keys: Yes / No

Tow Truck No: VN7944K Tow Man: Liam Ming Kwong NRIC: 1822640C

Signature: [Signature] 96691023

For office use

Attended by: _____

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In
Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Tuesday, 2 July 2019 4:47 PM
To: NAC ; AutoPoint
Subject: SMC9457L, OD claim no : MT/1051332

Importance: High

Dear IDAC and AutoPoint,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

Dear AutoPoint,

OD excess of \$600/- is applicable, pls assist to liaise with owner Mr Ong at tel : 94515827.

We are waiving survey for this case only and it should not be taken as a precedence for future cases.

FOR PAYMENT: Please forward the Invoice & Discharge Voucher together with some photos on after repairs within 14 days after the repair has been done/ finalized with Surveyor to my email.

Regards.

Tan Siew Choo
Senior Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Our Ref: MT/CA/OD/051/1051332-001/TSC
02 Jul 2019

AMK AUTOPOINT PTE LTD
BLK 10 ANG MO KIO INDUSTRIAL PARK 2A
#01-22 AMK AUTOPOINT
SINGAPORE 568047

Dear Sir

CLAIM NUMBER: MT/1051332-001

REPAIR OF VEHICLE NUMBER: SMC9457L

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 02 Jul 2019

Make: BMW

Model: 320i

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.