

ASS. REC. BY:

REF:

CS/11619011556/Kgds<sup>32</sup>

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG.

Date/Time:

28/6/2019

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF7216A

Insured:

at Workshop m/s

Motor Image

Tel:

92912693.

of 19 Lorong 8 Boa Payoh

Policy No:

Claim No:

6753527359SG

Sum Insured:

Excess:

600

Make of Veh:

(Client's Record)

D.O.A.

24/6/2019.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction ( ) Estimate
	SLF7216A - CS/11619011260/Kgds DOA: 24/6/2019.
	\$4509.95 Confirm (Red \$4744.93, 51%)

ASS. REC. BY:

REF:

CS/ATG 19011556 / Kgd3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lump Sum:

1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 7216A

Yr Regn:

12, 14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Subaru Levorg c.c

1998

Colour:

M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading

30870

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VING

006897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/35 ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/6/19

D.O.A.

28/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

SLF 7216A - CS/ATG 19011556 / Kgd3

1/7/19 Kenneth said car Authorise but not more than \$6K (Repair)

1/7/19 Yvonne call Syedmiri Motor Image said authorise but cannot repair more

(330pm) than \$6K

1/7/19 Sent E-Mail to Authorise to Workshop Excess \$600

5:07pm

RECEIVED 25 FEB 2020

Date/Time, File Pass to?

☐

: Prel. Report

1) 24/2/19

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MEK-00

Lump Sum / I.B.I. (\$

4509.95

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 1 July 2019 5:07 PM  
**To:** 'Sayedinah'  
**Cc:** 'Daniel Lim'; 'Daniel Jude'; SUR  
**Subject:** RE: SLF 7216A AIG DOA: 24/6/2019

### Resent

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLF 7216A (Excess S\$600.00/-)**. All in not exceeding \$6000/-

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**SLF7216A-OD -AIG-SURVEY 28/06/2019**

From: Chin, Lee-Ying  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY  
Sent: 6/28/2019 8:48:49 AM

Attachments:  SLF7216A OD GIA.PDF  SLF7216A CERT.pdf  ERDY BIN ARIP IC AND DL.pdf  SLF7216A OD ESTIMATE.pdf

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Sayedinah [mailto:sayedinah@motorimage.net]  
**Sent:** Thursday, June 27, 2019 6:48 PM  
**To:** AIG SGP, Claims-Survey; Chin, Lee-Ying  
**Cc:** TPY Insurance Team; Mohamed Isman; Erdy Arip  
**Subject:** [EXTERNAL] SLF7216A-OD -AIG-SURVEY 28/06/2019  
**Importance:** High

**This message is from an external sender; be cautious with links and attachments.**

Hi Claims Team,  
kindly arrange survey of the above mentioned vehicle. Vehicle in

Regards  
Sayedinah Ali  
Service Executive  
Motor Image Enterprises Pte Ltd  
19 Lorong 8 Toa Payoh Singapore 319255  
HP:92992693 DID:67038109 FAX:+65-62535535  
Email:sayedinah@motorimage.net  
Website:www.tanchong.com :: [www.motorimage.net](http://www.motorimage.net)



use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/06/2019 16:07
Date Of Accident	24/06/2019 10:30
Exact Location Of Accident	TRAFFIC LIGHT @PENDING RD TOWARDS PETIR RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF7216A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOTORIMAGE ENTERPRISES PTE LTD
Co Reg No	198702032R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92992693
Alternative Phone No	OFFICE-67038109

### Vehicle Particulars

Manufacturer	SUBARU
Model	LEVORG 2.0 GT-S
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994260/100856924-00000
Cover Note Number	

### Driver

Name of Driver	ERDY BIN ARIP
NRIC No	S7333947B
Date Of Birth	29/09/1973
Occupation	INDOOR
Date Of Driving Pass	07/01/2003
Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90601380
Fax Number	
Contact Number	
Email Address	ERDY@MOTORIMAGE.NET

Address	1
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED STATEMENT

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW4678D
Vehicle Make/Model/Colour	HYUNDAI ADVANTE BLACK
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	SIVA KUMAR PILLAY S/O RAMA KRISHNAN
NRIC/Passport Number	S8216197Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/6/17 @ 10.30am, I was stopping at traffic junction along Petir Rd while waiting traffic change to green and for me to turn right to make my way to office. Suddenly a Hyundai Avante black colour with reg. no SJW 4678D hit back portion of my car. My ~~back~~ <sup>car</sup> back portion involved quite bad damage with rear boot, rear bumper & etc. (refer photos attached). The other party mentioned their vehicle was a long term rental car. Both particular, hirer and driver have been noted and taken for reporting purpose. (refer attached)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 11:45 am 24/6/17.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIA/PMC SketchPlanForm\_V3



## Common Statement



### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renege on policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 11:45am 24/6/17.

  
Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	2032R
<b>Vehicle Details</b>	
Vehicle No.:	SLF7216A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	SUBARU
Vehicle Model:	LEVORG AWD 2.0 GT-S A/T EYESIGHT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	FA20915631
Chassis No.:	VMG006897
Maximum Power Output:	221.0 kW (296 bhp)
Open Market Value:	\$44,594.00
Original Registration Date:	24 Dec 2014
First Registration Date:	24 Dec 2014
Transfer Count:	1
Actual ARF Paid:	\$54,432.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2024
PARF Rebate Amount:	\$40,824.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$74,389.00
COE Rebate Amount:	\$40,733.00
<b>Total Rebate Amount:</b>	<b>\$81,557.00</b>

The information contained herein is correct as at 01 Jul 2019

OK

**CERTIFICATE OF INSURANCE**

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M X 4

AUTOPLAN COMPREHENSIVE

CERTIFICATE NO. 999994260/100856924-00000

OWN DAMAGE EXCESS S\$600.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED S\$1.00

INSURING WITH COE/PARF YES

1) VEHICLE REGISTRATION NO.

SLF7216A

2) NAME OF INSURED

MOTOR IMAGE ENTERPRISES PTE LTD

3) EFFECTIVE DATE OF THE COMMENCEMENT  
OF INSURANCE FOR THE PURPOSES OF THE ACT

1 Jan 2019

4) DATE OF EXPIRY OF INSURANCE

31 Dec 2019

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE \*

Any person who is driving on the Insured's order or with their permission.

An additional Young and Inexperienced Driver (YIDR) Excess of S\$3,000 (unless otherwise stated) applies to any drivers (named and unnamed) who is below age 23 or has less than 2 years driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**6) LIMITATION AS TO USE \***

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

LOSS OF USE NOT INCLUDED

\* NAMED DRIVER N/A

HIRE PURCHASE COMPANY NA


\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 14 Feb 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.

000064-000  
DIRECT CLIENTS 01.4.95  
AIG BUILDING  
78 SHENTON WAY #07-16  
SINGAPORE 079120

  
Authorized Representative

ORIGINAL

SSCDSK

6256 4315

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0280/2019  
DATE : 24-JUN-2019

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL : 91007211  
FAX :  
MOTOR CLAIM DEPT

OWNER'S NAME : MOTOR IMAGE ENTERPRISES P/L  
ADDRESS : 25, LENG KEE ROAD  
S(159097)  
TELEPHONE NO :

TYPE OF CLAIM : COMPREHENSIVE CLAIM  
POLICY NO : 999994260/100856924-00000  
VEHICLE NO : SLF7216A  
MODEL CODE : LEVORG 2.0GT-S  
MODEL/YEAR : LEVORG 2.0GT-S  
ENGINE NO : FA20ESZH9A  
CHASSIS NO : VMG006897  
MILEAGE : 1 KM  
DATE IN : 24/06/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 600.00  
ESTIMATE BY : SAYEDINAH ALI\*\*  
ACCIDENT DATE : 24/06/2019

Print Date : 27/06/2019  
Print Time : 18:40:58

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLF7216A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM NTUC. DATE 24/06/2019 TIME:1030HR TRAFFIC LIGHT JUNCTION OF PENDING & PETIR ROAD		
3	ZZ/002	REPAIR/REPLACE RR BUMPER, END PANEL, TAILGATE & FLOORPAN	1000.00	750/-
4	ZZ/003	RESPRAY RR BUMPER, END PANEL, TAILGATE AND FLOORPAN	800.00	600/-
5	ZZ/004	REMOVE/REFIX RR UNDERCARRIAGE TO FACILITATE REPAIR	684.00	X
6	ZZ/005	REMOVE/REFIX EXHAUST	114.00	✓
7	ZZ/006	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	95.00	✓
8	ZZ/007	CONDUCT 4 WHEEL ALIGNMENT AFTER REPAIR	171.00	X
9	ZZ/008	REMOVE CARPET, TRIMS, SEATS AND GARNISH TO FACILITATE REPAIR	456.00	X
10	ZZ/009	REPLACE/REFIX REAR WINDSCREEN(NESS)	240.00	✓
11	ZZ/011	REMOVE/REFIX FUEL TANK TO FACILITATE REPAIR	171.00	X
12	ZZ/012	CONDUCT REAR LIGHTING TEST	28.00	✓
13	ZZ/013	CONDUCT REAR PORTION ANTI RUST COATING AFTER REPAIR	290.00	200/-
14	ZZ/014	SUPPLY & INSTALL REVERSE SENSOR 2 EYES	300.00	✓
15	ZZ/015	SUNDRIES	100.00	30/-
16	ZZ/10	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM(NESS)	145.00	✓
TOTAL LABOUR CHARGES			4594.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF7216A

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
1	FLOOR PAN R R CP WGN	52129VA0109P			360.00 X
2	SKIRT COMPL R WGN	52401VA0019P			252.00 2X
3	BUMPER FACE R WGN	57704VA031			540.00
4	BRKT CORNER R WGNRH	57707VA090			18.00 X
5	BRKT CORNER R WGNLH	57707VA100			18.00 X
6	BRKT SD R WGN RH (1)	57707VA130			21.60 2X
7	BRKT SD R WGN LH	57707VA140			21.60 2X
8	COVER HOOK R WGN	57731VA180NN			7.20
9	PANEL COMPL R GAT	60809VA0009P			803.30
10	GLASS ASSY R G	63019VA000			799.20
11	LATCH&ACT ASSY RG	63032VA000			216.00 X
12	STRIKER R/G	63264AG100			21.60 X
13	WSTR DR R G	63516VA000			100.80
14	DAM RUBBER	65245VA100			7.20
15	REFLEX AY RH	84281FG000			21.60
16	REFLEX ASSY LH	84281FG010			21.60
17	LENS & BODY COMPLERH	84912VA041			425.00 X
18	LENS & BODY COMPLELH	84912VA051			425.00 X
19	GARNISH MLD SB AY6	91111VA070			158.40 2X
20	ORNAMENT ASSY F SIX	91174SA181			68.40
21	LETTER MK R STI	93079VA040			39.60
22	LETTER MK R	93079VA060			39.60
23	EDGE FLOOR R ASSY	95073VA000VH			22.70 2X
24	CARGO STEP PANEL (RESIN) WITH LEVORG WORDING	E775EVA000			420.00 2X
25	REAR UNDER SPOILER(E5610VA360)	SG517VA360			1830.00 2X

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
	SUB TOTAL		0.00	0.00	0.00	6658.40
	LESS DISCOUNT ( S/LIST-30 %)		0.00	0.00	0.00	1997.52
	GRAND TOTAL		0.00	0.00	0.00	4660.88
	OVERALL TOTAL		4660.88			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLF7216A

TOTAL LABOUR CHARGES	4594.00
TOTAL SPARE PARTS CHARGES	4660.88
GRAND TOTAL	9254.88 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 600.00
LIABILITY	: 0.00
REMARKS	:

*[Signature]*  
Rea

*Not Notarised*  
*Repair Blowing*  
*Ex TBA*  
*6 days*

*Fax: 62564315*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0280/2019  
DATE : 01-JUL-2019

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL : 91007211  
FAX :  
MOTOR CLAIM DEPT

OWNER'S NAME : MOTOR IMAGE ENTERPRISES P/L  
ADDRESS : 25, LENG KEE ROAD  
S(159097)  
TELEPHONE NO :

TYPE OF CLAIM : COMPREHENSIVE CLAIM  
POLICY NO : 999994260/100856924-00000  
VEHICLE NO : SLF7216A  
MODEL CODE : LEVORG 2.0GT-S  
MODEL/YEAR : LEVORG 2.0GT-S  
ENGINE NO : FA20ESZH9A  
CHASSIS NO : VMG006897  
MILEAGE : 50874 KM  
DATE IN : 01/07/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 600.00  
ESTIMATE BY : DANIEL A JUDE\*\*  
ACCIDENT DATE : 24/06/2019

Print Date : 29/07/2019  
Print Time : 17:55:08

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLF7216A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1		ODRECOVERY TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY)		
2	ZZ/001	CONDUCT OD RECOVERY CLAIM AIG DATE:24/06/2019 TIME:1030HRS LOCATION:TRAFFIC LIGHT JUN @ PENDING		
3	ZZ/002	REPAIR/REPLACE RR BUMPER,END PANEL,TAILGATE & FLOORPAN	1000.00	750.00
4	ZZ/003	RESPRAY RR BUMPER,END PANEL,TAILGATE AND FLOORPAN	800.00	600.00
5	ZZ/004	REMOVE/REFIX RR UNDERCARRIAGE TO FACILITATE REPAIR	684.00	.00
6	ZZ/005	REMOVE/REFIX EXHAUST	114.00	114.00
7	ZZ/006	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	95.00	95.00
8	ZZ/007	CONDUCT 4 WHEEL ALIGNMENT AFTER REPAIR	171.00	.00
9	ZZ/008	REMOVE CARPET,TRIMS,SEATS AND GARNISH TO FACILITATE REPAIR	456.00	.00
10	ZZ/009	REPLACE/REFIX REAR WINDSCREEN(NESS)	240.00	240.00
11	ZZ/011	REMOVE/REFIX FUEL TANK TO FACILITATE REPAIR	171.00	.00
12	ZZ/012	CONDUCT REAR LIGHTING TEST	28.00	28.00
13	ZZ/013	CONDUCT REAR PORTION ANTI RUST COATING AFTER REPAIR	290.00	200.00
14	ZZ/014	SUPPLY & INSTALL REVERSE SENSOR 4 EYES	300.00	300.00
15	ZZ/015	SUNDRIES	100.00	30.00
16	ZZ/10	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM(NESS)	145.00	145.00
TOTAL LABOUR CHARGES			4594.00	2502.00

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF7216A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	FLOOR PAN R R CP WGN	52129VA0109P			360.00	X	
2	SKIRT COMPL R WGN	52401VA0019P			252.00	X	
3	BUMPER FACE R WGN	57704VA031			540.00	OK	
4	BRKT CORNER R WGNRH	57707VA090			18.00	X	
5	BRKT CORNER R WGNLH	57707VA100			18.00	X	
6	BRKT SD R WGN RH (1)	57707VA130			21.60	X	
7	BRKT SD R WGN LH	57707VA140			21.60	X	
8	COVER HOOK R WGN	57731VA180NN			7.20	OK	
9	PANEL COMPL R GAT	60809VA0009P			803.30	OK	
10	GLASS ASSY R G	63019VA000			799.20	OK	
11	LATCH&ACT ASSY RG	63032VA000			216.00	X	
12	STRIKER R/G	63264AG100			21.60	X	
13	WSTR DR R G	63516VA000			100.80	OK	
14	DAM RUBBER	65245VA100			7.20	OK	
15	REFLEX AY RH	84281FG000			21.60	OK	
16	REFLEX ASSY LH	84281FG010			21.60	OK	
17	LENS & BODY COMPLERH	84912VA041			425.00	X	
18	LENS & BODY COMPLELH	84912VA051			425.00	X	
19	GARNISH MLD SB AY6	91111VA070			158.40	X	
20	ORNAMENT ASSY F SIX	91174SA181			68.40	OK	
21	LETTER MK R STI	93079VA040			39.60	OK	
22	LETTER MK R	93079VA060			39.60	OK	
23	EDGE FLOOR R ASSY	95073VA000VE			22.70	X	
24	CARGO STEP PANEL (RESIN) WITH LEVORG WORDING	E775EVA000			420.00	OK	
25	REAR UNDER SPOILER(E5610VA360)	SG517VA360			1830.00	X	

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF7216A

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
SUB TOTAL		0.00	0.00	0.00	2868.50
LESS DISCOUNT ( S/LIST-30 %)		0.00	0.00	0.00	860.55
GRAND TOTAL		0.00	0.00	0.00	2007.95
OVERALL TOTAL		2007.95			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLF7216A

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	2868.50
LESS 30 %	-860.55
S/LIST AMOUNT	2007.95
TOTAL LABOUR CHARGES	2502.00
TOTAL SPARE PARTS CHARGES	2007.95
TOTAL CHARGES	4509.95
LESS EXCESS	600.00
TOTAL	3909.95
ADD 7 % GST	273.70
GRAND TOTAL	4183.65



**Motor Image Enterprises Pte Ltd**  
19 Lorong 8 Toa Payoh Singapore 319255  
Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535  
25 Leng Kee Road Singapore 159097  
Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137  
Website: www.motorimage.net



## TAX INVOICE

GST Reg No. M2-0076975-9  
Co. Reg No. 198702032R

**Sales: INSURANCE CUSTOMER**  
**Invoice No: L511483**

**For cash sales, payment will be  
endorsed on this invoice and no  
separate receipt will be issued.**

**DATE REC'D: 01-Jul-2019**  
**SERVICE ADVISOR: HOOI**  
**JOB No.: L503691**  
**MILEAGE: 50874**  
**ID:**

**NAME: AIG ASIA PACIFIC INSURANCE PTE LTD**  
**ADDRESS: 78 SHENTON WAY**  
#07-16 AIG BUILDING. S(079120)  
**TELEPHONE: 91007211**  
**MODEL: LEVORG 2.0GT-S**  
**ENGINE No.: FA20ESZH9A**  
**CHASSIS No.: VMG006897**  
**REGISTRATION No.: SLF7216A**

ITEMS	CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	TPCLAI	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SJW4678D - NTUC	
2	REMARK	CONDUCT TP CLAIM NTUC DATE:24/06/2019 TIME:1030HRS LOCATION:TRAFFIC LIGHT JUN@PENDING RD TWD PETIR RD	
3	INS01	FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4	INS02	IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
5	INS03	STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6	INS04	SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
7	INS05	INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
8	INS06	THE OWNER IS REQUIRED.	
9	INS07	CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
10	INS08	NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
11	INS09	CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
12	REMARK	REPAIR/REPLACE RR BUMPER,END PANEL,TAILGATE & FLOORPAN	750.00
13	REMARK	RESPRAY RR BUMPER,END PANEL,TAILGATE AND FLOORPAN	600.00
14	REMARK	REMOVE/REFIX EXHAUST	114.00
15	REMARK	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	95.00
16	REMARK	REPLACE/REFIX REAR WINDSCREEN(NESS)	240.00
17	REMARK	CONDUCT REAR LIGHTING TEST	28.00
18	REMARK	CONDUCT REAR PORTION ANTI RUST COATING AFTER	200.00



**Motor Image Enterprises Pte Ltd**  
 19 Lorong 8 Toa Payoh Singapore 319255  
 Service Centre Tel (65) 64170100/101 Fax (65) 62535535  
 25 Leng Kee Road Singapore 159097  
 Service Centre Tel (65) 64764776 Fax (65) 64791137  
 Website: www.motorimage.net



## TAX INVOICE

GST Reg No. M2-0076975-9  
 Co. Reg No. 198702032R

**Sales: INSURANCE CUSTOMER**

**Invoice No: L511483**

**For cash sales, payment will be  
 endorsed on this invoice and no  
 separate receipt will be issued.**

**DATE REC'D: 01-Jul-2019**

**SERVICE ADVISOR: HOOI**

**JOB No.: L503691**

**MILEAGE: 50874**

**ID:**

**NAME: AIG ASIA PACIFIC INSURANCE PTE LTD**  
**ADDRESS: 78 SHENTON WAY**  
**#07-16 AIG BUILDING, S(079120)**  
**TELEPHONE: 91007211**  
**MODEL: LEVORG 2.0GT-S**  
**ENGINE No.: FA20ESZH9A**  
**CHASSIS No.: VMG006897**  
**REGISTRATION No.: SLF7216A**

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
	REPAIR	
19	REMARK SUPPLY & INSTALL REVERSE SENSOR 4 EYES	300.00
20	REMARK SUNDRIES	30.00
21	REMARK SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	145.00
	TOTAL(LABOUR)	2,502.00
1	BUMPER FACE R WGN	378.00
	57704VA031(Qty : 1 @ 540.00 each(Discount 30.00%))	
2	COVER HOOK R WGN	5.04
	57731VA180NN(Qty : 1 @ 7.20 each(Discount 30.00%))	
3	PANEL COMPL R GAT	562.31
	60809VA0019P(Qty : 1 @ 803.30 each(Discount 30.00%))	
4	GLASS ASSY R G	559.44
	63019VA000(Qty : 1 @ 799.20 each(Discount 30.00%))	
5	WSTR DR R G	70.56
	63516VA000(Qty : 1 @ 100.80 each(Discount 30.00%))	
6	DAM RUBBER	5.04
	65245VA100(Qty : 1 @ 7.20 each(Discount 30.00%))	
7	REFLEX AY RH	15.12
	84281FG000(Qty : 1 @ 21.60 each(Discount 30.00%))	
8	REFLEX ASSY LH	15.12
	84281FG010(Qty : 1 @ 21.60 each(Discount 30.00%))	
9	ORNAMENT ASSY F SIX	47.88
	91174SA181(Qty : 1 @ 68.40 each(Discount 30.00%))	
10	LETTER MK R STI	27.72
	93079VA040(Qty : 1 @ 39.60 each(Discount 30.00%))	
11	LETTER MK R	27.72
	93079VA060(Qty : 1 @ 39.60 each(Discount 30.00%))	
12	CARGO STEP PANEL (RESIN) WITH LEVORG WORDING	294.00



**Motor Image Enterprises Pte Ltd**  
19 Lorong 8 Toa Payoh Singapore 319255  
Service Centre Tel (65) 64170100/101 Fax (65) 62535535  
25 Leng Kee Road Singapore 159097  
Service Centre Tel (65) 64764776 Fax (65) 64791137  
Website: www.motorimage.net



## TAX INVOICE

GST Reg No. M2-0076975-9  
Co. Reg No. 198702032R

**Sales: INSURANCE CUSTOMER**

**Invoice No: L511483**

**For cash sales, payment will be  
endorsed on this invoice and no  
separate receipt will be issued.**

**DATE REC'D: 01-Jul-2019**

**SERVICE ADVISOR: HOOI**

**JOB No.: L503691**

**MILEAGE: 50874**

**ID:**

**NAME: AIG ASIA PACIFIC INSURANCE PTE LTD**  
**ADDRESS: 78 SHENTON WAY**  
#07-16 AIG BUILDING. S(079120)  
**TELEPHONE: 91007211**  
**MODEL: LEVORG 2.0GT-S**  
**ENGINE No.: FA20ESZH9A**  
**CHASSIS No.: VMG006897**  
**REGISTRATION No.: SLF7216A**

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
	E775EVA000(Qty : 1 @ 420.00 each(Discount 30.00%))	
	TOTAL(SPARE PARTS)	2,007.95
	less INSURANCE EXCESS	600.00

Subtotal 3,909.95  
GST(7%) 273.70  
**TOTAL \$4,183.65**

DATE : 21-Feb-2020

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

**CUSTOMER**

**Not yet a DUO Member? Join us now at [www.DUO.com.sg](http://www.DUO.com.sg) and start accumulating your points for your invoice today!**





**Motor Image Enterprises Pte Ltd**  
19 Lorong 8 Toa Payoh Singapore 319255  
T (65) 6417 0333 F (65) 6252 5655  
W [www.motorimage.net](http://www.motorimage.net)  
Co Reg No: 198702032R

# DISCHARGE VOUCHER

Name of Insured: MOTOR IMAGE ENTERPRISES PTE LTD  
Address of Insured: 25, LENG KEE ROAD S(159097)  
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP  
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225  
Place of Accident: TRAFFIC LIGHT @ PENDING RD TOWARDS PETIR ROAD  
Date of Accident: 24/06/2019 Vehicle No: SLF7216A  
Policy No: 999994260/100856934-00000 Claim No: \_\_\_\_\_

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of **AIG ASIA PACIFIC INSURANCE PTE LTD** settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.

I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:

Company's Chop & Signature



INSURED:

IC No. & Signature/Company's Chop



198702032R

**DANIEL A JUDE**

Name

**05/07/2019**

Date

**MOTOR IMAGE ENTERPRISES PTE LTD**

Name

**05/07/2019**

Date

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jun 2019		01 Jul 2019 10:43 <a href="#">Edit Adj Rpt</a>	<b>S\$4,509.95</b> <a href="#">Edit Estimates</a>	<b>S\$4,509.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	<b>MOTORIMAGE ENTERPRISES PTE LTD</b> , Co. Reg. No.: 198702032R		
Vehicle Reg. No.:	<b>SLF7216A</b>	Date of Loss:	24/06/2019 10:00 - :59 [54 Months From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / 6753527359SG</b>	Policy/Cover Note No.:	(Comprehensive)
		Excess:	S\$600.00
Repairer:	<b>Motor Image Enterprises Pte Ltd (Toa Payoh)</b> 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Yap, Weijoe</b> ] Weijoe.Yap@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 10/07/2019]</b>		
Driver/Custodian:	ERDY BIN ARIP (45 / Male) , NRIC: S7333947B, Tel: +6590601380 Email: erdy@motorimage.net		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (01/07/2019): **SLF7216A / OD / 24/06/2019 / Coverage & Excess update**

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




























## Claim Documents

**\*SLF7216A (6753527359SG)**  
**OD**  
**Jun 24 2019 10:30AM**  
**[MOTORIMAGE ENTERPRISES PTE LTD]**  
**Motor Image Enterprises Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
2	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
3	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
4	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
5	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
6	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
7	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
8	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
9	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
10	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
11	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
12	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
13	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
14	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
15	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
16	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
17	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
18	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
19	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
20	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
21	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
22	01/07/19 16:13	General View													Load JPG	<input checked="" type="checkbox"/>				
23	29/10/19 10:02	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>				
24	29/10/19 10:02	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>				
															1 per page			<input checked="" type="checkbox"/>		
Documentation																				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	01/07/19 16:10	CI													Load PDF					
2	01/07/19 16:10	ESTIMATE													Load PDF					
3	01/07/19 16:10	GIA REPORT													Load PDF					
4	27/02/20 15:08	DISCHARGE VOUCHER													Load PDF					
5	27/02/20 15:08	WORKSHOP INVOICE													Load PDF					

## Linked Accident Report Documents

										View		View in Browser ▾	
Video										1 per page ▾		<input checked="" type="checkbox"/>	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)								Thumbnail	Print		

Video			1 per page ▼	✓
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	27/06/19 18:24	Video - Accident	 Load MP4	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	27/06/19 18:22	Addendum Sheet	 Load JPG	✓
2	04/09/19 01:34	Accident Statement	 Load HTM	
3	04/09/19 01:37	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	24/06/19 16:40	Accident Photo	 Load JPG	✓
2	24/06/19 16:40	Accident Photo	 Load JPG	✓
3	24/06/19 16:40	Accident Photo	 Load JPG	✓
4	24/06/19 16:40	Accident Photo	 Load JPG	✓
5	24/06/19 16:40	Accident Photo	 Load JPG	✓
6	24/06/19 16:40	Accident Photo	 Load JPG	✓
7	24/06/19 16:40	Accident Photo	 Load JPG	✓
8	24/06/19 16:40	Accident Photo	 Load JPG	✓
9	24/06/19 16:40	Accident Photo	 Load JPG	✓
10	24/06/19 16:40	Accident Photo	 Load JPG	✓
11	24/06/19 16:40	Accident Photo	 Load JPG	✓
12	24/06/19 16:40	Accident Photo	 Load JPG	✓
13	24/06/19 16:40	Accident Photo	 Load JPG	✓
14	24/06/19 16:40	Accident Photo	 Load JPG	✓
15	24/06/19 16:40	Accident Photo	 Load JPG	✓
16	24/06/19 16:40	Accident Photo	 Load JPG	✓
17	24/06/19 16:40	Accident Photo	 Load JPG	✓
18	24/06/19 16:40	Accident Photo	 Load JPG	✓
19	24/06/19 16:40	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	24/06/19 16:38	Accident Sketch Plan	 Load JPG	✓
2	24/06/19 16:38	Common Statement	 Load JPG	✓

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG19011556/KQD3S2  
Date: 27/02/2020

## REFERENCE

Insured/Claimant: MOTORIMAGE ENTERPRISES PTE LTD  
Date of Loss: 24/06/2019

Policy No:  
Nature of Claim: OD Claim No: 6753527359SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLF7216A	Engine No:	FA20915631
Make & Model:	SUBARU LEVORG, 2.0 (A)	Chassis No:	VMG006897
Reg. Date:	24/12/2014 (Man. Year: 2014)	Odometer:	50870 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	245/35ZR19	Rear Tyre Size:	245/35ZR19
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,205.88	2,482.95	2,722.93	52.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,049.00	2,027.00	2,022.00	49.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,254.88</b>	<b>4,509.95</b>	<b>4,744.93</b>	<b>51.27</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>8,654.88</b>	<b>3,909.95</b>	<b>4,744.93</b>	<b>54.82</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>605.84</b>	<b>273.70</b>	<b>332.14</b>	<b>54.82</b>
<b>Nett Amount (S\$)</b>	<b>9,260.72</b>	<b>4,183.65</b>	<b>5,077.07</b>	<b>54.82</b>

## INSPECTION

Date of Assignment:	01/07/2019	
Date Inspected:	28/06/2019	Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FLOOR PAN R R CP WGN	Repair	360.00 FL	*- FL
2	1		*SKIRT COMPL R WGN	Serviceable	252.00 FL	*- FL
3	1		*BUMPER FACE R WGN	Buckled / Cracked	540.00 FL	*540.00 FL
4	1		*BRKT CORNER R WGNRH	Serviceable	18.00 FL	*- FL
5	1		*BRKT CORNER R WGNLH	Serviceable	18.00 FL	*- FL
6	1		*BRKT SD R WGN RH	Serviceable	21.60 FL	*- FL
7	1		*BRKT SD R WGN LH	Serviceable	21.60 FL	*- FL
8	1		*COVER HOOK R WGN	Dented	7.20 FL	*7.20 FL
9	1		*PANEL COMPL R GAT	Bent / Buckled	803.30 FL	*803.30 FL
10	1		*GLASS ASSY R G	Mtg Necessary	799.20 FL	*799.20 FL
11	1		*LATCH&ACT ASSY RG	Repair	216.00 FL	*- FL
12	1		*STRIKER R/G	Repair	21.60 FL	*- FL
13	1		*WSTR DR R G	Necessary	100.80 FL	*100.80 FL
14	1		*DAM RUBBER	Necessary	7.20 FL	*7.20 FL
15	1		*REFLEX AY RH	Necessary	21.60 FL	*21.60 FL
16	1		*REFLEX ASSY LH	Necessary	21.60 FL	*21.60 FL
17	1		*LENS & BODY COMPLERH	Serviceable	425.00 FL	*- FL
18	1		*LENS & BODY COMPLELH	Serviceable	425.00 FL	*- FL
19	1		*GARNISH MLD SB AY6	Serviceable	158.40 FL	*- FL
20	1		*ORNAMENT ASSY F SIX	Necessary	68.40 FL	*68.40 FL
21	1		*LETTER MK R STI	Necessary	39.60 FL	*39.60 FL
22	1		*LETTER MK R	Necessary	39.60 FL	*39.60 FL
23	1		*EDGE FLOOR R ASSY	Serviceable	22.70 FL	*- FL
24	1		*CARGO STEP PANEL (RESIN) WITH LEVORG WORDING	Necessary	420.00 FL	*420.00 FL
25	1		*REAR UNDER SPOILER (E5610VA360)	Serviceable	1,830.00 FL	*- FL
26	1		*REVERSE SENSOR 2 EYES	Dented	300.00 FS	*300.00 FS
27	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
28	1		*REAR WINDSCREEN TINTED FILM (NESS)	Necessary	145.00 FS	*145.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,203.40</b>	<b>3,343.50</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	<b>1,997.52</b>	<b>860.55</b>
<b>Total Parts (\$\$)</b>	<b>5,205.88</b>	<b>2,482.95</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (S\$)</b>			<b>0.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPAIR / REPLACE RR BUMPER, END PANEL, TAILGATE & FLOORPAN.	New	1,000.00	750.00
2	RESPRAY RR BUMPER, END PANEL, TAILGATE AND FLOORPAN.	New	800.00	600.00
3	REMOVE / REFIX RR UNDERCARRIAGE TO FACILITATE REPAIR.	New	684.00	0.00
4	REMOVE / REFIX EXHAUST.	New	114.00	114.00
5	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.	New	95.00	95.00
6	CONDUCT 4 WHEEL ALIGNMENT AFTER REPAIR.	New	171.00	0.00
7	REMOVE CARPET, TRIMS, SEATS AND GARNISH TO FACILITATE REPAIR.	New	456.00	0.00
8	REPLACE / REFIX REAR WINDSCREEN (NESS)	New	240.00	240.00
9	REMOVE / REFIX FUEL TANK TO FACILITATE REPAIR.	New	171.00	0.00
10	CONDUCT REAR LIGHTING TEST.	New	28.00	28.00
11	CONDUCT REAR PORTION ANTI RUST COATING AFTER REPAIR.	New	290.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>4,049.00</b>	<b>2,027.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;