

INS. CASE OWNER:

CHIEF HONG

cc6, AG 190 (1587), Uha3

LKK: IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

4/7/19

Date / Time:

1/7/19

Registered in Meritmen:

1/7/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SLX 1364A

Claim No. : 301576290506

Name of Insured : Wong Khai Yu

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II :SS D.O.A : 29/6/2019

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: (YES / NO) ; TP GIA REPORT: (YES / NO)

Driver Tel No. : (V/L) (YES / NO)

Insured Liability : % Final ? Yes / No

GBJ 2562E



INSRS: WSP: Pastech Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
04/07/19	Call OI:	
	After call ltr to OI:	04/07/19 - vic
	Documentation Check List:	Handler Typist
4/7/19	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: L9 \$5 7,000.00 (6 days) Reduction: 69 % Email Call

FINAL SETTLEMENT Date/Time: 02/10/19 Confirm with: JASON Email Call

Final Liability: % 100 (Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: (OI COMP-ENDED TP)

Repair Cost: (w/ass) \$5 7,490.00

Loss of Rental (LOR): \$5 - (days)

Loss of Use (LOU): \$5 840.00 (\$120 x 7 days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/Independent)

Legal Cost \$5 -

Total: \$5 8,332.00 Global Sum \$5: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$5 8,332.00 Name 1: PASTECH AUTO PTE LTD

Payee 2: (Strike if N.A.) \$5 - Name 2: -

Payee 3: (Strike if N.A.) \$5 - Name 3: -

COPY SENT 4/10/19

108/11/13) web
ASS. REC. BY: MORIS

REF:

ALL

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: G3J2562E
at Workshop m/s: Rp.
of: _____
Insured: SL41364A
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: G3J2562E Yr Regn: 3.19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (M)
Make: Toyota Dyna c.c. 2982
Colour: S. blue A/C: Insured / Std / NI / NA
Sp. Reading: 8307 T/Radio: Insured / Std / NI / NA
Eng/No: _____

C/No: JTFA T35740K 212553
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/75 R15
R: 155 R12

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

(S) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6/6 mm
L/Bal. 6 mm L/Bal. 6/6 mm
D.O.A. 29/6/19 D.O.I. 1/7/19
Survey held at _____

Bal. or Market Value: 65k
IDAC Accident Report: Consistent? : Yes or No
(S) PR Seen: 2 Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 96206
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
17A 21996 have G.A

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____ Survey Fee: _____
Transportation: _____

1) _____
Date/Time, File Return to? _____
2) _____
Report Format : _____
Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$ _____) \$ + RS _____
 : Interview (\$ _____) Photos
 : Tech. Invs (\$ _____) Others
 : Weekend (\$ _____)

TOTAL _____

Not Authorized
 2/5/19 7000
 11/3/19
 647

FASTECH AUTO PTE LTD
 BLK1 KAKI BUKIT AVE 6
 #01-46,48,50 AUTOBAY
 SINGAPORE 417883

VEHICLE NO: GBJ 2562E

QTY	PARTICULAR			
1 PCS	TAILGATE		10/1/19	\$1,688.10
1 PCS	TAILGATE 'TOYOTA' STICKER	175	me	\$275.00
1 PCS	TAILGATE 'DYNA' STICKER		me	\$66.50
1 PCS	TAILGATE LOCK LATCH O/S		R	\$245.05 X
1 PCS	TAILGATE LOWER 'L' PANEL O/S		Scarf	\$105.00
1 PCS	TAILGATE LOWER 'L' PANEL RUBBER O/S		To.1	\$85.00
1 PCS	TAILGATE LOWER MEMBER		Body 20	\$899.10
1 PCS	TAILLAMPS O/S		cpu	\$290.00
1 PCS	TAILLAMP HOUSING PANEL O/S		Scarf	\$165.00
1 PCS	DROP SIDEGATE O/S		R	\$2,665.10 X
1 PCS	DROP SIDEGATE LOWER MEMBER O/S		Body 1/19	\$922.30
1 PCS	REAR SPARE TYRE BRACKET & CHAIN		ym	\$395.00
1 PCS	REAR SPARE TYRE CHAIN & BRACKET TOP PANEL		me	\$645.00
1 PCS	REAR LICENCE PLATE BRACKET		31	\$285.00
1 PCS	REAR EXHAUST		me	\$645.00
1 PCS	REAR EXHAUST BRACKET		eye	\$105.00
1 PCS	REAR CHASSIS MEMBER		R	\$2,200.00 X
1 PCS	REAR LEAFSPRING ASSY O/S		11	\$1,100.00 X
				\$12,781.15

(252)

QTY	PARTICULAR			
1 PCS	70KM/H STICKER		me	\$20.00 10
1 PCS	13 PAX STICKER		me	\$20.00 10
1 SET	REAR REVERSE SENSOR		Shohh	\$280.00 200
1 PCS	REAR LICENCE PLATE		Scarf	\$20.00 15
1 PCS	REAR STEP PANEL		10/1/19	\$480.00 280
1 PCS	REAR SPAER TYRE		me	\$200.00 X
1 PCS	DROP SIDEGATE COMPANY STICKER O/S		me	\$600.00 300
1 PCS	TAILGATE INNER ALUMINIUM PLATE		sel	\$600.00 450
1 PCS	REAR CARGO DECK ALUMINIUM PLATE		R	\$2,500.00 X

LABOUR CHARGES		
TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REPLACING REAR EXHAUST	\$100.00	60
TO LIFT UP CARGO DECK PANEL FOR REPAIR CHASSIS	\$800.00	60
TO REPAIR & STRAIGHTEN REAR CHASSIS	\$680.00	500
TO SPRAY RUST PROOFING	\$120.00	100
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,500.00	1000
TO PUTTY & SPRAY PAINTING	\$1,600.00	900
TOTAL	\$22,461.15	

6471
 8258.25
 7006

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9620E
Vehicle Details	
Vehicle No.:	GBJ2562E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2840862
Chassis No.:	JTFAT35Y40K212553
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	01 Mar 2019
First Registration Date:	01 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$22,762.00
COE Rebate Amount:	\$21,996.00
Total Rebate Amount:	\$21,996.00

The information contained herein is correct as at 01 Jul 2019

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



3.18% P.A. \$0 Admin Fees @ GV
Finance. 2 Years Warranty. \$3000
Down Monthly From \$688
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING
IDRINO PING OIBOR ENTERPRISES PTE LTD. GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted 20 results/page

110 vehicles

dyna

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
dyna		Any	Any	2019	Any	Any	Any	Available
	Toyota Dyna 150 3.0M	\$66,800	\$6,910 /yr	01-Mar-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel No Gimmick! No Hidden Charges! Ready Stock! Everything Included, Number 1 Best-Selling 10 Feet Lorry, High Loan Available, Call Us Now To Find Out More.								
SG Motor Link Pte Ltd Posted: 01-Jul-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$68,300	\$7,050 /yr	06-Mar-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Hurry Up! Best Selling 10Ft Lorry In Town. Guarantee COE. Immediate Stock Ready For Registration! 100% Loan Can Be Arranged. Monthly At \$991 Only! Vehicle Only Register After Loan Approved. Call Now!								
Ezy-1 Pte Ltd Posted: 01-Jul-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$67,988	\$6,950 /yr	10-Apr-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Over Here! 95% New Toyota Dyna With Excellent Interior, Exterior & Condition. Great Price Offer. On The Road Age Below 6 Months. Canopy, Box, Freczer Installation Available. A Good Unit That You Don't...								
ABWIN Bus Pte Ltd Posted: 01-Jul-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$66,800	\$6,800 /yr	24-Apr-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In The Market, No Hidden Fees, GST Inside Price, No Admin Fees. 3 Years And 100,000 Km Warranty And 2 Times Free Servicing Under Borneo Motor, 100% Loan Available. Easy Loan Approval. Contact O...								
SG Motor Link Pte Ltd Posted: 01-Jul-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0A	\$70,888	\$7,210 /yr	29-Apr-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel New Improved Diesel Engine By Toyota Japan. Your Most Reliable 10 Footer Truck Super Low Fuel Consumption. Limited Stock, Rare Auto Truck, Immediate Stock, 100% Loan Available. 3 Years Warranty / 100,0...								
SG Motor Link Pte Ltd Posted: 01-Jul-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$66,800	\$6,790 /yr	29-Apr-2019	2,982 cc	-	Truck	Available
Fuel Type: Diesel Newly Registered, No Gimmicks, GST Inside Price, No Admin Fees, Everything Included, Borneo Warranty And Free Servicing, High Trade In, Full Loan Available! Low Interest Rates. Fast Call Our Friendly Sa...								
SG Motor Link Pte Ltd Posted: 01-Jul-2019 Tags: 2019 Toyota Dyna, 2019 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								

Compare

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9620E
Vehicle Details	
Vehicle No.:	GBJ2562E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2840862
Chassis No.:	JTFAT35Y40K212553
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	01 Mar 2019
First Registration Date:	01 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$22,762.00
COE Rebate Amount:	\$21,996.00
Total Rebate Amount:	\$21,996.00

The information contained herein is correct as at 01 Jul 2019

OK

Print Received Message

This mail is associated with :

***GBJ2562E (3813763905SG)
[SLX1364A]**

TP

WEI LONG ENGINEERING & CONSTRUCTION PTE. LTD.

Jun 29 2019 11:00AM

[WONG KHAI YU]

Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/10/2019 14:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8332.00) - GBJ2562E - Claim Handler: Loh, Chee-Heng

Approved:8332.00.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date : 22.08.2019

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: GBJ 2562E AND SLX 1364A ON 29.06.2019

We are the authorized repair workshop for the owner of motor vehicle no: **GBJ 2562E**, which was involved in the captioned accident with your insured vehicle no: **SLX 1364A**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	7,490.00
2) Loss Of Use (6 days + 1 Sunday X \$120)	\$	840.00
3) GIA Search Fee	\$	2.00
	<u>\$</u>	<u>8,332.00</u>

We enclosed herewith the following documents to support the claims:

- | | |
|---------------------------------|------------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report/GIA Search Result | d) I/C & Driving Licence |
| e) Insurance Certificate | f) Letter of Authorisation, etc... |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang
For Fastech Auto Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19011587/Uha3

4 July 2019

WONG KHAI YU
10D BEDOK SOUTH AVENUE 2
#14-570
SINGAPORE 463010

Dear Sir/Madam,

ACCIDENT INVOLVING SLX1364A AND GBJ2562E ON 29/06/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third-Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) may be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third-Party claim. However, if your policy has an NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jimmy
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: jimmychen@lkkauto.com

*c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Wei Long Engineering & Construction Pte Ltd ("the third party claimant")
of 13 Bartley Biz Centre Kaki Bukit Road 4 #05-14 ⁵⁴¹⁷⁸⁰⁷ (address),
owner of GBJ 2562E (vehicle no.) hereby authorize
Fwotech Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. GBJ 2562E that was
damaged pursuant to the accident which occurred on 29/6/19 (date) along
Bartley Viaduct (location)
involving vehicle no/s SLX 1364A ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 01 day of 07 (month) 20 19 (year)



[Signature]

Signed by "the third party claimant"



[Signature]
Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Fostech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 7,490.00 (repair costs), S\$ 840.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. G1BJ 2562E that was damaged pursuant to the accident which occurred on 29/6/19 (date) along Bartley Viaduct (location) involving vehicle no/s SLX 1364A

This is pursuant to the inspection conducted on 01/07/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Wei Long Engineering & Construction Pte Ltd ("third party claimant") of vehicle no. G1BJ 2562E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to G1BJ 2562E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 02 day of 10 (month) 20 19 (year)



CKB

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax.Reg No: 200006262D

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 21212

Date: 22.08.2019

Vehicle No: GBJ 2562E

Make/Model: TOYOTA DYNA

Accident Date: 29.06.2019

Claim No : 0719-21212

Reference :

Policy No :

	Amount
To proceed on lump sum repair	SS 7,000.00

E. & O. E.

Total : S\$ 7,000.00

GST @ 7% : S\$ 490.00

Amount Due : **S\$ 7,490.00**


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-103944

Date of Request: 29/06/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd
 1 Kaki Bukit Avenue 6 #01-48
 AutoBay@Kaki Bukit
 Singapore 417883

Dear Sir/Madam,

Enquiry Date 29/06/2019

Enquiry By Tang Kok Wee, Allan

TP Vehicle No. SLX1364A

Accident Date 29/06/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLX1364A	AIG Asia Pacific Insurance Pte. Ltd.	16/03/2018-15/03/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-103944

Date of Request: 29/06/2019

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
 1 Kaki Bukit Avenue 6 #01-48
 AutoBay@Kaki Bukit
 Singapore 417883

Dear Sir/Madam,

Enquiry Date: 29/06/2019
 Enquiry By: Tang Kok Wee, Allan
 TP Vehicle No.: SLX1364A
 Accident Date: 29/06/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jul 2019 Edit Reg		01 Jul 2019 00:00 Edit Adj Rpt	\$7,000.00 Edit Estimates	\$7,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	WONG KHAI YU , ID: S8833496E								
Main Claimant:	WEI LONG ENGINEERING & CONSTRUCTION PTE. LTD. , Co. Reg. No.: 200819620E								
Vehicle Reg. No.:	GBJ2562E	Date of Loss:	29/06/2019 11:00 - :59 [3 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3813763905SG	Policy/Cover Note No.:	1800027588 (Comprehensive) Coverage: 16/03/2018 - 15/03/2020						
Vehicle Reg. No. (Insured):	SLX1364A	Policy No. (Claimant):	5107700233						
Excess:									
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (02/10/2019): Alert - Adj Mandate Approved (\$8332.00) - GBJ2562E - Claim Handler: Loh, Chee-H... AIG_SG (02/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBJ2562E (3813763905SG)
[SLX1364A]

TP

WEI LONG ENGINEERING & CONSTRUCTION PTE. LTD.

Jun 29 2019 11:00AM

[WONG KHAI YU]

Fastech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Letters/Correspondences											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit			
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	01/07/19 18:41	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
2	01/07/19 18:41	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
3	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
4	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
5	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
6	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
7	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
8	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
9	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
10	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
11	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
12	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
13	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
14	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
15	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
16	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
17	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
18	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
19	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
20	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
21	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
22	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
23	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
24	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
25	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
26	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
27	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
28	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
29	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
30	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
31	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
32	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
33	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
34	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
35	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
36	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
37	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
38	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
39	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		
40	01/07/19 18:42	General View							Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
				<input checked="" type="checkbox"/>
41	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
42	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
43	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
44	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
45	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
46	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
47	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
48	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
49	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
50	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
51	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
52	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
53	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
54	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
55	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
56	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
57	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
58	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
59	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
60	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
61	01/07/19 18:42	General View		Load JPG <input checked="" type="checkbox"/>
62	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
75	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
76	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
77	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
78	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
79	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
80	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
81	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
82	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
83	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
84	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
85	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
86	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
87	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
88	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
89	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
90	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
91	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
92	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
93	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
94	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
95	01/07/19 18:42	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
97	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
98	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
99	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
100	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
101	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
102	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
103	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
104	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
105	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
106	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
107	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
108	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
109	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
110	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
111	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
112	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
113	01/07/19 18:42	Reinspection Photo		<input checked="" type="checkbox"/>
114	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
115	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
116	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
117	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
118	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
119	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
120	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
121	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>
122	01/07/19 18:43	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/19 13:41	TP GIA REPORT		
2	04/07/19 10:04	Letter to OI		
3	03/09/19 14:33	TP ESTIMATE - FINALIZED		
4	27/09/19 15:23	GIA SEARCH		
5	27/09/19 15:23	LOD		
6	17/10/19 11:16	WORKSHOP INVOICE		
7	17/10/19 11:16	AUTHORISATION TO ACT FORM		
8	17/10/19 11:16	Release Voucher		

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/07/19 09:50	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLX1364A (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D 5MT (M)
	GBJ2562E (TP veh)		
Date of Accident:	29/06/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	24,033.43	
Final Repair Cost	: \$	7,490.00	
Loss of Use	: \$	840.00	7.00 days at \$120.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	8,332.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ___100___(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	: \$	8,332.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Oct
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011587/UHA3Q2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800027588
 Claimant: GBJ2562E Insured Vehicle No: SLX1364A
 Vehicle No: GBJ2562E Nature of Claim: TP Claim No: 3813763905SG
 Date of Loss: 29/06/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ2562E**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2840862
 Reg. Date: 01/03/2019 (Man. Year: 2018) Chassis No: JTFAT35Y40K212553
 Colour: Silver Odometer: 8307 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12 (D)
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,501.15	6,118.25	11,382.90	65.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	2,640.00	2,320.00	46.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,461.15	8,758.25	13,702.90	61.01
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	22,461.15	7,000.00	15,461.15	68.84
+ GST 7.00/7.00% (S\$)	1,572.28	490.00	1,082.28	68.84
Nett Amount (S\$)	24,033.43	7,490.00	16,543.43	68.84
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,332.00		

INSPECTION

Date of Assignment: 01/07/2019
 Date Inspected: 01/07/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent / Twisted	1,688.10 F	*1,688.10 FL
2	1		*TAILGATE TOYOTA STICKER	Necessary	275.00 F	*175.00 FL
3	1		*TAILGATE DYNA STICKER	Necessary	66.50 F	*66.50 FL
4	1		*TAILGATE LOCK LATCH O/S	Repair	245.05 F	*- FL
5	1		*TAILGATE LOWER L PANEL O/S	Bent	105.00 F	*105.00 FL
6	1		*TAILGATE LOWER L PANEL RUBBER O/S	Torn	85.00 F	*85.00 FL
7	1		*TAILGATE LOWER MEMBER	Badly Dented	899.10 F	*899.10 FL
8	1		*TAILLAMP O/S	Cracked	290.00 F	*290.00 FL
9	1		*TAILLAMP HOUSING PANEL O/S	Bent	165.00 F	*165.00 FL
10	1		*DROP SIDEGATE O/S	Repair	2,665.10 F	*- FL
11	1		*DROP SIDEGATE LOWER MEMBER O/S	Bent / Twisted	922.30 F	*922.30 FL
12	1		*REAR SPARE TYRE BRACKET & CHAIN	Jammed	395.00 F	*395.00 FL
13	1		*REAR SPARE TYRE CHAIN & BRACKET TOP PANEL	Dented	645.00 F	*645.00 FL
14	1		*REAR LICENCE PLATE BRACKET	Bent	285.00 F	*285.00 FL
15	1		*REAR EXHAUST	Dented	645.00 F	*645.00 FL
16	1		*REAR EXHAUST BRACKET	Damaged	105.00 F	*105.00 FL
17	1		*REAR CHASSIS MEMBER	Repair	2,200.00 F	*- FL
18	1		*REAR LEAFSPRING ASSY O/S	Not Necessary	1,100.00 F	*- FL
19	1		*70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
20	1		*13 PAX STICKER	Necessary	20.00 FS	*10.00 FS
21	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
22	1		*REAR LICENCE PLATE	Bent	20.00 FS	*15.00 FS
23	1		*REAR STEP PANEL	Dented / Bent	480.00 FS	*280.00 FS
24	1		*REAR SPARE TYRE	Serviceable	200.00 FS	*- FS
25	1		*DROP SIDEGATE COMPANY STICKER O/S	Necessary	600.00 FS	*300.00 FS
26	1		*TAILGATE INNER ALUMINIUM PLATE	Bent	600.00 FS	*450.00 FS
27	1		*REAR CARGO DECK ALUMINIUM PLATE	Repair	2,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,501.15	7,736.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,617.75
Total Parts (S\$)	17,501.15	6,118.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
4	TO LIFT UP CARGO DECK PANEL FOR REPAIR CHASSIS	New	800.00	500.00
5	TO REPAIR & STRAIGHTEN REAR CHASSIS	New	680.00	0.00
6	TO SPRAY RUST PROOFING	New	120.00	100.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	1,000.00
8	TO PUTTY & SPRAY PAINTING	New	1,600.00	900.00
Gross Labour Cost (S\$)			4,960.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >