

1/1/2019

INS. CASE OWNER:

CC 4/AIG1901

LKK:

IDAC:

Surveyor:

KNSM

DOI:

1/7/19

Date / Time:

28/6/19

Registered in Merimen:

1/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

XE 853U ✓

Name of Insured:

MBSINDO LOGISTIC Pte ✓

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

117218744529

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA- YES/NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

XE 3807J ✓



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ryder



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

XE 3807J - X

XE 853U - X

- no OI GIA. SENT OUT AT 16/1/19

11/1/19 - FILED PMS TO LSP TO CLOTH

STAGE

DATE / PIC

Non-Reporting Itr (1st):

02/08/2019

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE: Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 6/11/19

Confirm with: Orion

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS 1700.00

02 truck carrier out & hit TP

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 300.00

(S 150 x 2 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only

LOU only

LOR + LOU

LOR + L.O

(Tick only one)

GIA/LTA Search

SS 29.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 2029.00

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$320

4) AR Fee: \$234

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 2029.00

Name 1:

Ryder Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Wale

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

wheel arch inner garnish cut ✓
wheel arch inner garnish bracket cut ✓
XE3807J Pg 1/1

ESTIMATE OF REPAIR

Veh # : XE3807J Model : UD TRUCKS (13/12/2017) - JNCMFL10

Date Of Accident : 11/3/2019 3P : XE853U (AIG)

Location : ALONG PIONEER RD HEADING TOWARDS JLN BUKIT RD

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj.	Amount \$	
		Special-NEET Items				
1	1 pc	Front wheel guard	CM ✓		619.10	
2	1 pc	Front wheel arch	cut ✓		531.00	
3	1 pc	Front wheel arch step garnish	scr ✓		331.00	
		Sub-Total			1,481.10	
		Labour				
1		To remove and replace front damage parts			400.00	150
2		To spray painting			300.00	150
		Sub-Total			700.00	
		Total			2,181.10	
		After -20%			1,744.88	

1481.10
102
1372.99

300

Chan San Choon
Director
DipEng. AAE MIM(MSAE)(Aust)



Authorised Workshop
Authorised Reporting Centre

AL 8778 1999

24 hr accident call

Mobil 1

bigSAFE

Rasul
Hp 90016068
2 days
4/3

01/07/19 @ 1400 hrs

Resy after repair
email: rasul@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

XE3807J Pg 1/1


Veh # : XE3807J Model : UD TRUCKS (13/12/2017)

Date Of Accident : 11/3/2019 3P : XE853U (AIG)

Location : ALONG PIONEER RD HEADING TOWARDS JLN BUROH RD

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
		Special Net Items LBF				
1	1 pc	Front o/s wheel arch inner garnish			421.40	
2	1 pc	Front o/s wheel arch inner garnish bracket			112.20	
		Sub-Total			533.60	
		After -20%			426.88	

533.60
10%
480.24


Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

P - 1332.99
L - 300.00
Supp - 480.24
T = 2113.23
20%
1690.58
45 - 1,700
2 days



Authorised Workshop
Authorised Reporting Centre

8778 1999
24 hr accident call

Mobil 1

bizSAFE₁

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

wheel arch inner garnish at ✓
wheel arch inner garnish bracket at ✓
XE3807J Pg 1/1

ESTIMATE OF REPAIR

Veh # : XE3807J Model : UD TRUCKS (13/12/2017)

Date Of Accident : 11/3/2019 3P : XE853U (AIG)

Location : ALONG PIONEER RD HEADING TOWARDS JLN BUROH RD

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
<u>Special Nett Items</u>						
1	1 pc	Front wheel guard <i>cm</i> ✓			619.10	
2	1 pc	Front wheel arch <i>at</i> ✓			531.00	
3	1 pc	Front wheel arch step garnish <i>sun</i> ✓			331.00	
		Sub-Total			1,481.10	
<u>Labour</u>						
1		To remove and replace front damage parts			400.00	<i>150</i>
2		To spray painting.			300.00	<i>150</i>
		Sub-Total			700.00	
		Total			2,181.10	
		After -20%			1,744.88	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Rasul
Hp 90016068
2 days

4/3
01/07/19 @ 1400 hrs

Resy after repair
email: rasul@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To remedy before later spray painting
- To display damaged part(s) during reserves
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reserved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Authorised Workshop
Authorised Reporting Centre

AL 8778 1999
24 hr accident call

Mobil 1

bigSAFE

View Received Message

This mail is associated with :

***XE3807J (1582522306SG)**
[XE853U]

TP
LIEW BROTHERS TRANSPORTATION
Mar 11 2019 12:00AM
[Masindo Logistic Pte Ltd]
Ryder Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)


From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/11/2019 11:53 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2029.00) - XE3807J - Claim Handler: Ler, Bernard-JQ

Approved:2029.00:Cost of Repairs 1,700.00 Loss of Use 300 (2days x \$150) LTA/GIA Search Fee 29 Total 2,029.00

DOCUMENTS SUMMARY

There are no documents.

PRE-REPAIR INSPECTION: Your vehicle XE853U; Our vehicle XE3807J Ac...

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/28/2019 10:32:04 AM
Attachments:  XE3807J PRS NOTICE..pdf

Hi LKK,

Kindly assist to survey.

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]
Sent: Thursday, June 27, 2019 4:23 PM
To: Chin, Lee-Ying
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION REQUEST - XE3807J vs XE853U (01) on D.O.A: 11/03/2019

This message is from an external sender; be cautious with links and attachments.

Dear Lee Ying,

Kindly assist to arrange your surveyor to survey the vehicle on Monday 1/7/19, 1-3pm. Our client vehicle will be at No. 53 Pioneer Road S(628505) for repair.

Thank you.

Best regards

June

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

1/7/19 2pm

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]
Sent: Wednesday, May 29, 2019 11:11 AM
To: Azlan, Syazairdina; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] Urgent: PRE-REPAIR INSPECTION: Your vehicle XE853U; Our vehicle XE3807J Accident involving XE3807J & XE853U On 11 March 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We refer to the above matter.

Kindly find attached PRS for your necessary action.

For Direct Settlement cases, we only use your in-house surveyor. Kindly arrange your in-house surveyor.

Thank you.

Best regards

June

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Tel : 67418277 Fax: 67468277

5 Tuas Ave 3 BS Logistics Hub Singapore 639405

Fax: 64815390

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921


Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Our Ref : XE3807J

Date : 29 May 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-06
Singapore 079120



Dear Sir,

PROPERTY DAMAGE CLAIM

CLAIMANT

: LIEW BROTHERS TRANSPORTATION

ACCIDENT INVOLVING

: XE3807J & XE853U ALONG CTE TOWARDS CITY
BEFORE BRADDELL EXIT ON 24 APRIL 2019

We act for **LIEW BROTHERS TRANSPORTATION**, the owner of vehicle no. **XE3807J**, which was involved in the aforesaid accident.

Kindly be notified that we are claiming against your insured motor vehicle no. **XE853U** for damages, costs and disbursements as a result of your insured driver's negligence. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at our workshop, 2 Kaki Bukit Ave 2, #02-19, Autohub @ Kaki Bukit, Singapore 417921.

Please arrange with the undersigned via mobile 90908277 Mr Orson or 97924673 Mr Chan. Kindly reply within the next two (2) working days or we shall proceed with our own necessary procedures and repairs.

This PRS is on a "Direct Settlement" basis, hence we shall be furnishing an estimate for your surveyor to finalise as soon as possible.

Kindly reply either via email, fax or mobile.

Thank you.

Yours faithfully,

Ryder Auto Pte Ltd

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



Authorised Workshop
Authorised Reporting Centre

☎ 8778 1999
24 hr accident call

Mobil 1

bizSAFE₁

View Received Message

This mail is associated with :

***XE3807J (1172583447SG)**
[XE853U]

TP

LIEW BROTHERS TRANSPORTATION

Apr 24 2019 12:00AM

[Masindo Logistic Pte Ltd]

Ryder Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/07/2019 09:45 AM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be informed that no OI GIA report received till date.
Please find OI details below for your further action.

OI name: Masindo Logistic Pte Ltd

Address:
3017 Ubi Road 1, #02-131
Kampong Ubi Industrial Estate
Singapore 408708

Regards,
Wah Xin

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19011592/R1db3

03 July, 2019

Masindo Logistic Pte Ltd
3017 Ubi Road 1, #02-131
Kampong Ubi Industrial Estate
Singapore 408708

Dear Sirs,

**ACCIDENT INVOLVING XE 853U AND XE 3807J ON 24/04/2019 ALONG/ AT
PIONEER ROAD HEADING TOWARDS JALAN BUROH ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Carlor Chan
Claims
Tel : 6749 5792
Fax: 6741 4108
Email : jiale@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Our Ref: CC4/AIG19011592/R1db3

02 AUGUST 2019

By Registered Mail

Masindo Logistic Pte Ltd

3017 Ubi Road 1,
#02-131 Kampong Ubi Industrial Estate
Singapore 408708

Dear Sir,

**ACCIDENT INVOLVING XE 853U AND XE 3807J ON 24/04/2019 ALONG/ AT
PIONEER ROAD HEADING TOWARDS JALAN BUROH ROAD**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 03/07/2019

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by 19/08/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Carlor Chan
Claims

Tel : 6749 5792

Fax: 6741 4108

Email : jiale@lkkauto.com

c.c *Claims Manager*
 AIG Asia Pacific Insurance Pte. Ltd
 (Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jul 2019 Edit Reg		28 Jun 2019 00:00 Edit Adj Rpt	\$51,700.00 Edit Estimates	\$51,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Masindo Logistic Pte Ltd, Co. Reg. No.: 200301939M, Tel: +6599999999								
Main Claimant:	LIEW BROTHERS TRANSPORTATION, Co. Reg. No.: 53191580L								
Vehicle Reg. No.:	XE3807J	Date of Loss:	11/03/2019 00:00 - :59 [14 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1582522306SG	Policy/Cover Note No.:	0999994545 (Comprehensive)						
Vehicle Reg. No. (Insured):	XE853U	Policy No. (Claimant):	5098962376						
		Excess:							
Repairer:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (06/11/2019): Alert - Adj Mandate Approved (\$52029.00) - XE3807J - Claim Handler: Ler, Bernard... AIG_SG (25/07/2019): Re: Request For OI GIA Report AIG_SG (02/07/2019): Request To Upload TP GIA Report AIG_SG (02/07/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE3807J (1582522306SG)
[XE853U]

TP

LIEW BROTHERS TRANSPORTATION

Mar 11 2019 12:00AM

[Masindo Logistic Pte Ltd]

Ryder Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown															Edit			
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	09/10/19 16:45	Adjuster Immediate Advice															Load HTM			
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	09/10/19 16:48	Odometer Reading															Load JPG <input checked="" type="checkbox"/>			
2	09/10/19 16:48	Chassis Number															Load JPG <input checked="" type="checkbox"/>			
3	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
4	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
5	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
6	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
7	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
8	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
9	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
10	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
11	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
12	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
13	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
14	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
15	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
16	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
17	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
18	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
19	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
20	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
21	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
22	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
23	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
24	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
25	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
26	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
27	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
28	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
29	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
30	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
31	09/10/19 16:48	General View															Load JPG <input checked="" type="checkbox"/>			
32	09/10/19 16:49	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
33	09/10/19 16:49	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
34	09/10/19 16:49	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
35	09/10/19 16:49	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
36	09/10/19 16:49	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	09/10/19 16:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	09/10/19 16:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	09/10/19 16:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	09/10/19 16:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	09/10/19 16:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/07/19 15:09	EMAIL FROM AIG DD 28062019		Load PDF	
2	01/07/19 15:09	WKSP NOTICE		Load PDF	
3	02/07/19 19:50	TP ESTIMATE- MARKED		Load PDF	
4	02/07/19 19:54	TP GIA REPORT		Load PDF	
5	03/07/19 10:33	NON REPORTING LETTER		Load PDF	
6	09/10/19 16:57	LOD		Load PDF	
7	09/10/19 16:57	GIA SEARCH FEE		Load PDF	
8	20/11/19 08:16	WORKSHOP INVOICE		Load PDF	
9	20/11/19 08:16	AUTHORISATION TO ACT FORM		Load PDF	
10	20/11/19 08:16	Release Voucher		Load PDF	
11	20/11/19 08:16	Registered Mail Fee		Load PDF	
12	20/11/19 08:16	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/08/19 16:27	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	XE853U (Insd veh)	Model:	UD TRUCKS
	XE3807J (TP veh)		GKB85ELDHNT 10.8 D (M)
Date of Accident:	11/03/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		2,714.70
Final Repair Cost	:	\$		1,700.00
Loss of Use	:	\$		300.00
Rental (if any)	:	\$		0.00
LTA / GIA Search Fee	:	\$		29.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		2,029.00

2.00 days at \$150.00 per day

days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ryder Auto Pte Ltd	:	\$ 2,029.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

20 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011592/R1DB3Q2

Date: 20/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994545
 Claimant: XE3807J Insured Vehicle No: XE853U
 Vehicle No: XE3807J
 Date of Loss: 11/03/2019 Nature of Claim: TP Claim No: 1582522306SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE3807J
 Make & Model: UD TRUCKS GKB85ELDHT, 10.8 D (M) Engine No: GH11746607
 Reg. Date: 13/12/2017 (Man. Year: 2017) Chassis No: JNCM1F1A3JU026685
 Colour: Blue Odometer: 100950 km
 Engine Capacity: 10837 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
 Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8/8 mm
 Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,014.70	1,813.23	201.47	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	300.00	400.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,714.70	2,113.23	601.47	22.16
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	2,714.70	1,700.00	1,014.70	37.38
+ Loss of Use (2.0 x S\$150.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,029.00		

INSPECTION

Date of Assignment: 28/06/2019
 Date Inspected: 01/07/2019 Inspected At: 53 UBI PIONEER ROAD
 Estimated Period of Repair: 2.0 days Repairer: Ryder Auto Pte Ltd (HQ)

Adjuster: MOHD RASUL

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL GUARD	Cracked	619.10 F	*619.10 FL
2	1		*FRONT WHEEL ARCH	Cut	531.00 F	*531.00 FL
3	1		*FRONT WHEEL ARCH STEP GARNISH	Scratched	331.00 F	*331.00 FL
4	1		*FRONT O/S WHEEL ARCH INNER GARNISH	Cracked	421.40 F	*421.40 FL
5	1		*FRONT O/S WHEEL ARCH INNER GARNISH BRACKET	Bent	112.20 F	*112.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,014.70	2,014.70
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	201.47

Total Parts (S\$)	2,014.70	1,813.23
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE FRONT DAMAGE PARTS	New	400.00	150.00
2	TO SPRAY PAINTING	New	300.00	150.00
Gross Labour Cost (\$\$)			700.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >