

ASS. REC. BY:

REF: CS1SMO19011593/Asd322

Special Instruction:

SUBJECT: Adnan

ASSIGNMENT (Office)From (Person): Hwang Shang Yi of SMD Date/Time: 01.7.19 13.52p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 5023T Insured: SGA 9622Cat Workshop m/s Liang Hu Motor Tel: 67474416of 1 Kaki Bukit Ave C #01-62Policy No: D19MTPV 01000209 Claim No: CMTD1903079

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 26.6.2019
(Client's Record)CA / REV / REP. / REV 24 HRS ^{my} H.O.D. Endorsement: _____Date/Time: 1.7.19 2.19p.m Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SGA 9622C CS1SMO19011593/Asd322 0:0:0 26/6/2019
	SLC 5023T X
02/07/19	@ 16:37 pm revert pending estimate from repairer to shang yi via messenger.

ASSIGNMENT

From: _____ Date: 1.7.2019
 Estimated Cost _____
 OD TP PWS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLC 5023T
 at Workshop n/s Liang Hee Motor
of 1 Kerkai Bukit Pvr C # 01-62
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rptot: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs, _____ days Res.: Yes or No
 Lump Sum: _____ % J Val: Yes or No
 CA / REV / REP. / 24 HRS my
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SLC 5023T Yr Regr: 2016 / May
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel o.e 1496
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 59356 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 241114385
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil (S/Rim) / STD A/Rim or
 Tyre Size: F: 205/60R15
 R: 205/60R15
 BS / BUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 01/07/19
 Survey held at Liang Hee
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front O/S, Rear O/S, N/S, U/C
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Sampo
<u>22/10/19</u>	<u>Confirmed L/S \$ 16K @ 14 days with Adrian</u> <u>(\$ 18,242.30 Res - 53%)</u> <u>MV: 631K</u> <u>PV: 407K</u> <u>Nett: 22.5K</u>

RECEIVED 22 OCT 2019

Date/Time, File Pass to?

1) 22/10/19

Date/Time, File Return to?

2) _____

: Prel. Report
 : Final Report

Days Of Repair: 14
 Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>490</u>
Transportation:	
Photos	
Others	<u>11</u>
TOTAL	<u>461</u>

Report Format :

Lump Sum / I.B.I: (\$ 16,000/- / 45)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2019		01 Jul 2019 13:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	EDDY LIM SZE NGUAN, ID: S1699579G								
Main Claimant:	KOH WEE LANG, ID: S7318133Z								
Vehicle Reg. No.:	SLC5023T	Date of Loss:	26/06/2019 17:00 - :59						
Claim Type:	TP / CMTD1903079	Policy/Cover Note No.:	D19MTPV01000209 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGB9622C	Policy No. (Claimant):							
		Excess:							
Repairer:	Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67474416								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/07/2019]								
Adj Asg. Remarks:	Please assign to Mr Adrian Ling.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8133Z
Vehicle Details	
Vehicle No.:	SLC5023T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4034391
Chassis No.:	RU11114385
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,638.00
Original Registration Date:	17 May 2016
First Registration Date:	17 May 2016
Transfer Count:	0
Actual ARF Paid:	\$10,894.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2026
PARF Rebate Amount:	\$8,170.00
Intended COE Expiry Details	
COE Expiry Date:	16 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$32,512.00
Total Rebate Amount:	\$40,682.00

The information contained herein is correct as at 01 Jul 2019

OK



Honda Vezel 1.5A X | \$69,800 | \$9,490 /yr | 14-Apr-2016 | 1,496 cc | 71,000 km | SUV | Available

Only 1 Owner. Well Maintained Unit! Need No Repairs. Selling Cheap! Practical And Fuel Efficient SUV! Spacious And Easy To Maintain! High Loan And Trade In Available! Don't Miss It. Call For A Viewing...

Benefit Auto Enterprise Pte Ltd

☆ Posted: 26-Jun-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X | \$62,800 | \$8,550 /yr | 15-Apr-2016 | 1,496 cc | 48,088 km | SUV | Available

Guaranteed Non Private Hire/Leasing Car! 1 Lady Owner. Super Low Mileage Done 48088km! Like Brand New, Test Drive/See To Certify. Road Tax Till Oct. 19. 100% Accident Free. Price Negotiable. Call Now!

Lake View Credit Pte Ltd

☆ Posted: 29-Jun-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X Honda Sensing | \$63,555 | \$8,560 /yr | 19-Apr-2016 | 1,496 cc | 39,756 km | SUV | Available

Most Reliable And Well Known SUV! Very Low Fuel Consumption And Low On Maintenance! Trade In Welcome! Flexible Bank/In-House Financing Available With Fast And Easy Loan Approval! 100% Loan Can Be Arr...

☆ Posted: 14-Jul-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



BlackVue DR750S Car Camera

Equipped with Sony Starvis CMOS Sensor, this blackvue full HD cloud camera gives you best image quality under any light condition. Find the list of the best cameras available, each with product information and user reviews.

Find out more!



Honda Vezel 1.5A X | \$65,800 | \$8,900 /yr | 27-Apr-2016 | 1,496 cc | 61,000 km | SUV | Available

High Loan Approval Rate! Flexible In House Financing Options.Option For Long Term Leasing Available. New Arrival In Showroom, Elegant White, Nice Bid Number. Excellent Conditions, Super Great Fuel Eff...

☆ Posted: 09-May-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X | \$64,800 | \$8,800 /yr | 28-Apr-2016 | 1,496 cc | - | SUV | Available

Graded **B** by **STW**

Well Maintained Unit, Low Depreciation! (High Loan Are Available) No Repairs Needed! High Trade-In Are Welcome! View To Believe, Kindly Call For More Information.

Universe Motoring

☆ Posted: 06-Jul-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X Honda Sensing | \$63,555 | \$8,540 /yr | 03-May-2016 | 1,496 cc | 45,000 km | SUV | Available

Attractive Interest Rates! Beautiful Black Vezel Is Here! Best Selling Small Sized SUV! Well Maintained By Previous Owner! Best Deal With The Finance With Guaranteed 100% Loan Approval. Free 1 Year Wa...

☆ Posted: 24-Jun-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X | \$66,800 | \$8,990 /yr | 03-May-2016 | 1,496 cc | 48,000 km | SUV | Available

Comes With Free 6 Months In House Warranty And 1 Free Servicing! Supreme Condition! Excellent Fuel Consumption! Flexible In House Financing And High Trade In Given! Call Now To Enquire!

Hui Hua Credit Pte Ltd

☆ Posted: 07-Jun-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X | \$62,800 | \$8,460 /yr | 09-May-2016 | 1,496 cc | 72,000 km | SUV | Available

(3 Years Warranty Plus 3 Years Maintenance Package) 100% Loan Provided! Convert To Z10 Usage If Needed. Attractive 1.98% In House Loan Or Bank Loan Available! Touch Screen Head Unit. Reverse Camera....

☆ Posted: 23-Jul-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X | \$65,500 | \$8,860 /yr | 11-May-2016 | 1,496 cc | 30,000 km | SUV | Available

Very Well Maintained Unit With Low Mileage. Classy Brown Interiors. Good Drive. Trade In And Flexible Loan Available. Call Now To View. Viewing By Appointment Only.

360 VR Cars

☆ Posted: 03-Jun-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda



Honda Vezel 1.5A X | \$66,000 | \$8,780 /yr | 12-May-2016 | 1,496 cc | - | SUV | Available

Non PHV Unit! Nicely Done Up By Car Enthusiastic. Responsive Yet Fuel Efficient. Irresistible To Its Superb Condition. Perfectly Well Balanced Between Power & Comfort. Super High Paper Value! Zero Mis...

☆ Posted: 18-Jun-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Honda Vezel Hybrid 1.5A X | \$69,800 | \$9,800 /yr | 13-May-2016 | 1,496 cc | 59,000 km | SUV | Available

Fuel Type: Petrol-Electric

1 Owner Only, Excellent Fuel Efficiency. 100% Loan Approval. 100% Accident Free. Very Well Maintained! As Good As New! Low Depreciation. Bank

SHARE LISTED | CONTACT

Compare



And In House Loan Available. Call Our Sales Now.

☆ Posted: 13-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



📄 **Honda Vezel 1.5A X** \$63,800 \$8,500 /yr 16-May-2016 1,496 cc 63,000 km SUV Available

(3 Years Warranty + 3 Years Maintenance Package) 100% Loan Provided! Convert To Z10 Usage If Needed. Attractive 1.98% In House Or Bank Loan Available! Touch Screen Head Unit, Reverse Camera, Rear Ca...

☆ Posted: 15-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



📄 **Honda Vezel Hybrid 1.5A X** \$71,000 \$9,950 /yr 18-May-2016 1,496 cc 60,000 km SUV Available

Fuel Type: Petrol-Electric

Hybrid Battery 2 Year Warranty, 2 Years Warranty Check, Good As New, Worth The Money Compare To New Car, One Owner Take Very Good Care. Car Is Spotless And Just Polished. Good For Urban And Long Distan...

360 VR Cars

☆ Posted: 27-Jun-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

📄 Save Search

Make ▼ Model ▼ Price ▼ Depreciation ▼ Reg Date ▼ Eng Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

For old advertisements, view Expired ads

< Back (1 2 3 4 5 6) Next >

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for popular import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CNG cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, compare prices & car insurance. Find buy used Vezel, Vezel Singapore, used Vezel Singapore, used Vezel, used vehicles Singapore or even buy used Vezel Singapore. We have new car dealers competing directly: importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CO2 results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assistance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SPONSORSHIP HISTORY

Compare

View Sent Message

This mail is associated with :

***SLC5023T (CMTD1903079)**
[SGB9622C]
TP
KOH WEE LANG
Jun 26 2019 5:00PM
[EDDY LIM SZE NGUAN]
Liang Hee Motor Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **02/07/2019 16:37 PM.**
To shiangyi.hwang@sompo.com.sg
CC sur@lkkauto.com
Subject **SLC5023T (CMTD1903079) [SGB9622C] TP**

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SLC 5023T on 01/07/2019.

We are pending estimate from repairer.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/06/2019 10:26
Date Of Accident	26/06/2019 09:00
Exact Location Of Accident	JALAN BUKT MERAH BLK 131A MULTI STOREY CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC5023T
Insured/Policyholder	
Name Of Registered Owner	KOH WEE LANG
NRIC No	S7318133Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86141311
Alternative Phone No	OFFICE-86141311

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PARKING AT THE CARPARK LOT
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080136504-03
Cover Note Number	

Driver

Name of Driver	KOH WEE LANG
NRIC No	S7318133Z
Date Of Birth	18/05/1973
Occupation	INDOOR
Date Of Driving Pass	07/06/1999
Driving Experience	20 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-86141311
Fax Number	
Contact Number	OFFICE-86141311
Email Address	NOEMAIL

Address	BLK 107 JALAN BUKIT MERAH #09-1842
Postcode	S160107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGB9622C
Vehicle Make/Model/Colour	NISSAN SUNNY 1.6A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM KIM SENG
NRIC/Passport Number	S0926604F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) - My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:

26/5/2019

Driver's Signature
(If driver is not the policyholder)

Date & Time:


Reporting Centre Personal's Signature
Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26 June 2019, I have parked my car, SLK 5023 T Honda
Vezel at 9am at Jln. Bt Merah Blk 113 A Multistorey Car
park Lot 14.
When I reached home at 7pm, I found my car was
been hit by this car SG9 9622C Nissan, my car was
landed on the kerb.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Kart
Policyholder's Signature
Date & Time:
26/6/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/PM No.:

Name / Insurance Co : TP Sompo Blarley Vehicle No : SLC5023T
 Chassis Number : EU421114385 Make / Model : Honda Vezel
 Date In : 27/06/19

S/N	QTY	PARTS DESCRIPTION	LIST PRICE	COST PRICE
1	1PC	front bumper. Distorted.	880.80	✓
2	2PC	front bumper side retainer ^{RH and} 30.60x2	61.20	30.60
3	10PC	front bumper clip. New @ 3.90x10	39.00	✓
4	2PC	head lamp. Cracked @ 1920.90x2	3841.80	✓ 3569
5	3PC	head lamp bracket. ^{RH cracked} @ 45x2	90.00	45
6	1PC	front bumper reinforcement Belt	421.00	✓
7	2PC	front bumper reinforcement rubber ^{new} @ 3420x2	68.40	X
8	1PC	front bumper tow cover Missing	27.00	✓
9	1PC	front bumper lower lid. Distorted	451.60	✓
10	1PC	front bumper lower grille. Deformed	92.60	✓
11	1PC	radiator grille base. Cracked	318.90	✓
12	1PC	radiator grille logo. New	34.70	✓
13	2PC	radiator grille chrome. @ 253.40x2	506.80	X.
14	1PC	RH fog lamp. Cracked	367.70	✓
15	1PC	LH fog lamp cover Deformed	65.00	✓
16	1PC	horn. New cracked	62.80	✓
17	1PC	front support panel garnish torn	105.00	✓
18	1PC	front support panel Deformed.	676.20	✓
19	9PC	front support panel garnish clips @ 3.90x9	35.10	✓
20	1PC	front support panel garnish top bracket ^{new}	65.80	X.
21	1PC	RH front fender Deformed	588.00	✓
22	1PC	RH front fender shield. New	180.00	X
23	1PC	RH front fender garnish Deformed	183.00	✓
24	10PC	RH front fender shield clips. @ 3.90x10	59.00	X.
25				
Total Amount			8885.40	

Subject to 7% gst

total parts 26,754.20

total labor 6,010.00

32,764.20

34,272.30

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4706.40

Name / Insurance Co : _____

Vehicle No : SLC 5023T

②

Make / Model : honda vezel

Chassis Number : _____

Date In : _____

S/N	QTY	PARTS DESCRIPTION	LIST PRICE	COST PRICE
1	1PC	RH front tyre - dunlop 215/60R16 ^{NEU}	220.00	x.
2	1PC	RH front spare rim - 16" lit	965.80	480(SN)
3	1PC	RH front shock absorber Best	460.10	✓
4	1PC	LH front shock absorber mounting ^{NEU}	65.00	x.
5	1PC	RH front wheel bearing. Dnd	155.00	✓
6	1PC	RH front wheel hub. Dnd	158.00	✓
7	1PC	RH front knuckle arm Best	278.70	✓
8	1PC	RH front lower arm. Best	370.00	✓
9	1PC	RH front linkage. Best	80.00	✓
10	1PC	Steering rack. Best	1372.40	✓
11	1PC	RH driveshaft NEU	1200.60	x.
12	1PC	RH front door. Dented	1150.00	✓
13	1PC	RH front door sticker (black tape). NEU	58.10	✓
14	1PC	RH wing mirror base. NEU	750.30	x.
15	1PC	RH wing mirror cover. Dnd	100.00	x.
16	1PC	RH rocker panel garnish. Lit	407.50	✓
17	1PC	RH tail lamp. NEU	528.70	x.
18	1PC	RH rear corner panel. Dented	165.00	✓
19	1PC	RH rear wheel arch garnish. Lit	180.00	✓
20	1PC	rear bumper. Dented	708.50	✓
21	10PC	rear bumper clips. @ 2.90x1.0 NEU	39.00	✓
22	1PC	LH rear corner panel. } NEU	225.00	x.
23	1PC	LH tail lamp. } NEU	528.70	x.
24	1PC	LH rear door. Dented	1030.60	✓
25	1PC	LH rear door stone guard. NEU	65.00	✓
Total Amount			11260.40	

Subject to 7% gst

11764

Name / Insurance Co : _____
 Chassis Number : _____

Vehicle No : SLC 50237
 Make / Model : Nonda vezel
 Date in : _____

S/N	QTY	PARTS DESCRIPTION	LIST PRICE	COST PRICE
1	1PC	LH rear door sticker (black tape) New	45.00	✓
2	1PC	door rain guard. New	180.00	60(SW)
3	1PC	LH rear door window regulator gear	490.50	✓
4	1PC	LH rear door window motor		
5	1PC	LH front door. Dented	1180.50	✓
6	1PC	LH front door black tape New	41.20	✓
7	1PC	LH wing mirror base. Lot	250.30	✓
8	1PC	LH wing mirror cover. Repair	100.00	X
9	1PC	LH front tyre - dunlop 215/60R16 ^{100%}	220.00	180(SW)
10	1PC	LH front sports rim. Lot	465.80	480(SW)
11	1PC	LH front shock absorber. Best	460.10	✓
12	1PC	LH front shock absorber mounting New	65.00	X
13	1PC	LH front knuckle arm. Best	278.70	✓
14	1PC	LH front lower arm. Best	370.00	✓
15	1PC	LH front linkage - New	80.00	X
16	1PC	LH front wheel bearing 2 1/2" ^{2 1/2"}	155.00	✓
17	1PC	LH front wheel hub.	158.00	✓
18	1PC	front subframe (crossmember) New	895.00	X
19	1PC	engine undercover (centre) foil	116.80	✓
20	1PC	RH radiator air guide ^{1/2"}	56.80	✓
21				
22				
23				
24				
25				
Total Amount			6608.40	

Subject to 7% gst

list 1872730
 len 20%: 1498184

S.N: 1200

6608.40

(16K)

total: 2001184
L/S: 16K

14 Days

- To check wiring and refocus headlamps ——— ~~100.00~~ 30
- To remove/repair aircon condenser,
vacuum top up gas to facilitate repair ——— ~~180.00~~ 120
- To remove/repair front undercarriage ——— ~~300.00~~ ✓
- To realignment vehicle on chassis jigs ——— 300.00 X
- carry out wheel alignment ——— ~~90.00~~ 80
- To transfer new tyres and perform
wheel balancing x2 ——— 100.00 X.
- To transfer door parts and
mechanisms @ 80/each ——— ~~240.00~~ 180 ✓
- To apply body sealant on car joints ——— 150.00 X
- To straighten bonnet, bonnet hinges,
RHL rear door, RHL rear fender, LHL front
fender, ~~RHL~~ RHL front wheel house
including replacement of parts ——— ~~1500.00~~ 1400
- To spray paint bonnet, front bumper,
front bumper reinforcement, front support panel,
LHL/RHL front fender, LHL/RHL front door,
LHL/RHL rear door, LHL/RHL rear fender, LHL/RHL
rear corner panel, tailgate, rear bumper. ——— ~~2800.00~~ 1600
- towing (using dolly + winching) ——— ~~250.00~~ 120

3830

120

2/10/2010

6/10

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2019		01 Jul 2019 13:52 Edit Adj Rpt	S\$16,000.00 Edit Estimates	S\$16,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	EDDY LIM SZE NGUAN , ID: S1699579G								
Main Claimant:	KOH WEE LANG , ID: S7318133Z								
Vehicle Reg. No.:	SLC5023T	Date of Loss:	26/06/2019 17:00 - :59 [37 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903079	Policy/Cover Note No.:	D19MTPV01000209 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGB9622C	Policy No. (Claimant):							
		Excess:							
Repairer:	Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67474416								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/07/2019]								
Adj Asp. Remarks:	Please assign to Mr Adrian Ling.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC5023T (CMTD1903079)
[SGB9622C]
TP
KOH WEE LANG
Jun 26 2019 5:00PM
[EDDY LIM SZE NGUAN]
Liang Hee Motor Workshop

Upload Documents			Upload Photos			Compose New Letter			View
									View in Browser
Assessment Reports									1 per page
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)					Thumbnail	Print	
1	01/07/19 13:53	Accident Statement From:OD - Reg. No: SGB9622C, Claimant: EDDY LIM SZE NGUAN					1	Load HTM	
Photos/Images									3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
2	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
3	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
4	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
5	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
6	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
7	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
8	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
9	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
10	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
11	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
12	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
13	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
14	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
15	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
16	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
17	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
18	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
19	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
20	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
21	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
22	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
23	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
24	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
25	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
26	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
27	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
28	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
29	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
30	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
31	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
32	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
33	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
34	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
35	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
36	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
37	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
38	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>
39	21/10/19 17:09	General View					1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
40	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
41	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
42	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
43	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
44	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
45	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
46	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
47	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
48	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
49	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
50	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
51	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
52	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
53	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
54	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
55	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
56	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
57	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
58	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
59	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
60	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
61	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
62	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
63	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
64	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
65	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
66	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
67	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
68	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
69	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
70	21/10/19 17:09	General View		<input checked="" type="checkbox"/>
71	21/10/19 17:12	Reinspection Photo		<input checked="" type="checkbox"/>
72	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
73	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
74	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
75	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
76	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
77	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
78	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
79	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
80	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
81	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
82	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
83	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
84	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
85	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
86	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
87	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
88	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
89	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
90	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
91	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
92	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
93	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
94	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
95	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
96	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
97	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
98	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
99	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
100	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
101	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
102	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
103	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
104	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
105	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
106	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
107	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
108	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
109	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
110	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
111	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
112	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
113	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
114	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
115	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
116	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
117	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
118	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
119	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
120	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
121	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
122	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
123	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
124	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
125	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
126	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
127	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
128	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
129	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
130	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
131	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
132	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
133	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
134	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
135	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
136	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
137	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
138	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
139	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
140	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
141	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
142	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
143	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
144	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
145	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
146	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
147	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
148	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
149	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
150	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
151	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
152	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
153	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
154	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
155	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
156	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
157	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
158	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
159	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
160	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
161	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
162	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
163	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
164	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
165	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
166	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
167	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
168	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
169	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
170	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
171	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
172	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
173	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
174	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
175	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
176	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
177	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
178	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
179	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
180	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
181	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
182	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
183	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
184	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
185	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
186	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
187	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
188	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
189	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
190	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
191	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
192	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
193	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
194	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
195	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
196	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
197	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
198	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
199	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
200	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
201	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
202	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
203	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
204	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
205	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
206	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>
207	21/10/19 17:13	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
208	21/10/19 17:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	21/10/19 17:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	21/10/19 17:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	21/10/19 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	01/07/19 13:51	PRI - LKK	 Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011593/ASD3E2

Date: 07/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01000209
Claimant Vehicle No :	SLC5023T	Insured Vehicle No :	SGB9622C
Date of Loss:	26/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1903079

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC5023T	Engine No:	L15B4034391
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11114385
Reg. Date:	17/05/2016 (Man. Year: 2015)	Odometer:	59356 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R15	Rear Tyre Size:	205/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,077.10	16,223.04	10,854.06	40.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,010.00	3,830.00	2,180.00	36.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,087.10	20,053.04	13,034.06	39.39
Approved Total (Overridden) (S\$)		16,000.00		
Nett Amount (S\$)	33,087.10	16,000.00	17,087.10	51.64

INSPECTION

Date of Assignment:	01/07/2019		
Date Inspected:	01/07/2019	Inspected At:	Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC5023T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	880.80 F	*880.80 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	61.20 F	*30.60 FL
3	10		*FRONT BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
4	2		*HEAD LAMP	Cracked	3,841.80 F	*3,569.00 FL
5	1		*HEAD LAMP BRACKET	O/S Cracked	90.00 F	*45.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	421.00 F	*421.00 FL
7	2		*FRONT BUMPER REINFORCEMENT RUBBER	Not Necessary	68.40 F	*. FL
8	1		*FRONT BUMPER TOW COVER	Missing	27.00 F	*27.00 FL
9	1		*FRONT BUMPER LOWER LID	Distorted	451.60 F	*451.60 FL
10	1		*FRONT BUMPER LOWER GRILLE	Deformed	97.60 F	*97.60 FL
11	1		*RADIATOR GRILLE BASE	Cracked	318.90 F	*318.90 FL
12	1		*RADIATOR GRILLE LOGO	Necessary	34.70 F	*34.70 FL
13	2		*RADIATOR GRILLE CHROME	Not Necessary	506.80 F	*. FL
14	1		*RH FOG LAMP	Cracked	367.70 F	*367.70 FL
15	1		*RH FOG LAMP COVER	Deformed	65.00 F	*65.00 FL
16	1		*HORN	Cracked	62.80 F	*62.80 FL
17	1		*FRONT SUPPORT PANEL GARNISH	Torn	105.00 F	*105.00 FL
18	1		*FRONT SUPPORT PANEL	Dented	676.20 F	*676.20 FL
19	9		*FRONT SUPPORT PANEL GARNISH CLIPS	Necessary	35.10 F	*35.10 FL
20	1		*FRONT SUPPORT PANEL GARNISH TOP BRACKET	Not Necessary	65.80 F	*. FL
21	1		*RH FRONT FENDER	Dented	588.00 F	*588.00 FL
22	1		*RH FRONT FENDER SHIELD	Not Necessary	180.00 F	*. FL
23	1		*RH FRONT FENDER GARNISH	Deformed	183.00 F	*183.00 FL
24	10		*RH FRONT FENDER SHIELD CLIPS	Not Necessary	39.00 F	*. FL
25	1		*RH FRONT TYRE - DUNLOP 215/60R16	Not Necessary	220.00 F	*. FL
26	1		*RH FRONT SPORTS RIM - 16	Cut	965.80 FS	*480.00 FS
27	1		*RH FRONT SHOCK ABSORBER	Bent	460.10 F	*460.10 FL
28	1		*RH FRONT SHOCK ABSORBER MOUNTING	Not Necessary	65.00 F	*. FL
29	1		*RH FRONT WHEEL BEARING	Damaged	155.00 F	*155.00 FL
30	1		*RH FRONT WHEEL HUB	Damaged	158.00 F	*158.00 FL
31	1		*RH FRONT KNUCKLE ARM	Bent	278.70 F	*278.70 FL
32	1		*RH FRONT LOWER ARM	Bent	370.00 F	*370.00 FL
33	1		*RH FRONT LINKAGE	Bent	80.00 F	*80.00 FL
34	1		*STEERING RACK	Bent	1,372.40 F	*1,372.40 FL
35	1		*RH DRIVESHAFT	Not Necessary	1,200.60 F	*. FL
36	1		*RH FRONT DOOR	Dented	1,150.00 F	*1,150.00 FL
37	1		*RH FRONT DOOR STICKER (BLACK TAPE)	Necessary	58.10 F	*58.10 FL
38	1		*RH WING MIRROR BASE	Not Necessary	750.30 F	*. FL
39	1		*RH WING MIRROR COVER	Repair	100.00 F	*. FL
40	1		*RH ROCKER PANEL GARNISH	Cut	407.50 F	*407.50 FL
41	1		*RH TAIL LAMP	Not Necessary	528.70 F	*. FL
42	1		*RH REAR CORNER PANEL	Deformed	165.00 F	*165.00 FL
43	1		*RH REAR WHEEL ARCH GARNISH	Cut	180.00 F	*180.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR BUMPER	Deformed	708.50 F	*708.50 FL
45	10		*REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
46	1		*LH REAR CORNER PANEL	Not Necessary	225.00 F	*- FL
47	1		*LH TAIL LAMP	Not Necessary	528.70 F	*- FL
48	1		*LH REAR DOOR	Dented	1,030.60 F	*1,030.60 FL
49	1		*LH REAR DOOR STONE GUARD	Necessary	65.00 F	*65.00 FL
50	1		*LH REAR DOOR STICKER (BLACK TAPE)	Necessary	45.00 F	*45.00 FL
51	1		*DOOR RAIN GUARD	Necessary	180.00 FS	*60.00 FS
52	1		*LH REAR DOOR WINDOW REGULATOR GEAR	Damaged	490.50 F	*490.50 FL
)			
53	1		*LH REAR DOOR WINDOW MOTOR		0.00 F	*- FL
)			
54	1		*LH FRONT DOOR	Dented	1,180.50 F	*1,180.50 FL
55	1		*LH FRONT DOOR BLACK TAPE	Necessary	41.20 F	*41.20 FL
56	1		*LH WING MIRROR BASE	Cut	750.30 F	*750.30 FL
57	1		*LH WING MIRROR COVER	Repair	100.00 F	*- FL
58	1		*LH FRONT TYRE - DUNLOP 215/60R16	Punctured	220.00 FS	*180.00 FS
59	1		*LH FRONT SPORTS RIM	Cut	965.80 FS	*480.00 FS
60	1		*LH FRONT SHOCK ABSORBER	Bent	460.10 F	*460.10 FL
61	1		*LH FRONT SHOCK ABSORBER MOUNTING	Not Necessary	65.00 F	*- FL
62	1		*LH FRONT KNUCKLE ARM	Bent	278.70 F	*278.70 FL
63	1		*LH FRONT LOWER ARM	Bent	370.00 F	*370.00 FL
64	1		*LH FRONT LINKAGE	Not Necessary	80.00 F	*- FL
65	1		*LH FRONT WHEEL BEARING	Damaged	155.00 F	*155.00 FL
66	1		*LH FRONT WHEEL HUB	Damaged	158.00 F	*158.00 FL
67	1		*FRONT SUBFRAME (CROSSMEMBER)	Not Necessary	895.00 F	*- FL
68	1		*ENGINE UNDERCOVER (CENTRE)	Torn	116.80 F	*116.80 FL
69	1		*RH RADIATOR AIR GUIDE	Deformed	56.80 F	*56.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,077.10	19,978.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,755.76
Total Parts (\$\$)	27,077.10	16,223.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REFOCUS HEADLAMPS	New	100.00	30.00
2	TO REMOVE / REFIT AIRCON CONDENSER, VACUUM / TOP UP GAS TO FACILITATE REPAIR	New	180.00	120.00
3	TO REMOVE / REFIX FRONT UNDERCARRIAGE	New	300.00	300.00
4	TO REALIGNMENT VEHICLE ON CHASSIS JIG	New	300.00	0.00
5	CARRY OUT WHEEL ALIGNMENT	New	90.00	80.00
6	TO TRANSFER NEW TRIM AND PERFORM, WHEEL BALANCING X2	New	100.00	-
7	TO TRANSFER DOOR PARTS AND MECHANISMS @80/EACH	New	240.00	180.00
8	TO APPLY BODY SEALANT ON CAR JOINTS	New	150.00	0.00
9	TO STRAIGHTEN BONNET, BONNET HINGES, RH REAR DOOR, RH REAR FENDER, LH FRONT FENDER, RH FRONT WHEELHOUSE INCLUDING REPLACEMENT OF PARTS	New	1,500.00	1,400.00
10	TO SPRAY PAINT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL, LH / RH FRONT FENDER, LH / RH FRONT DOOR, LH / RH REAR DOOR, LH / RH REAR FENDER, LH / RH REAR CORNER PANEL, TAILGATE, REAR BUMPER	New	2,800.00	1,600.00
11	TOWING (KING DOLLY + WINCHING)	New	250.00	120.00
Gross Labour Cost (S\$)			6,010.00	3,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >