

H3190 Powl



Date : 22/08/2019

To : EQ INSURANCE COMPANY LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTRENT000038 Accident Date : 06/03/2019

Vehicle No : SLX-1037-U Make & Model : TOYOTA WISH 1.8 (A) STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	FRONT BUMPER RESTORE	580.00	0.00
1	FRONT BUMPER RETAINER RH	58.00	0.00
10	FRONT BUMPER CLIPS	50.00	0.00
1	FRONT FENDER RH RESTORE	0.00	0.00
Sub Total		108.00	0.00
Discount 25% On Parts		(0.00)	(0.00)
<u>Labour & Misc</u>			
LABOUR TO FACILITATE REPAIR		500.00	150.00
TO RESPRAY AFFECTED AREAS		500.00	200.00
Sub Total		1000.00	350.00

PAGE : 1



Date : 22/08/2019

To : EQ INSURANCE COMPANY LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTRENT000038 Accident Date : 06/03/2019

Vehicle No : SLX-1037-U Make & Model : TOYOTA WISH 1.8 (A) STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	1,516.00	350.00
	GST 7.0 %	106.12	24.50
	Total	1,622.12	374.50

Surveyor Name : RASUL - LKK

Date & Time : 28/06/2019 4:00:00 PM

Selamatshahh

PAGE : 2

CLAIM DEPARTMENT

DID : 66547519

FAX :

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 27/06/2019

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTRENT000038

Accident Date : 06/03/2019

Vehicle No : SLX-1037-U

Make & Model : TOYOTA WISH 1.8 (A) STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER <i>repair</i>	580.00	
1	FRONT BUMPER RETAINER RH <i>X</i>	58.00	
10	FRONT BUMPER CLIPS <i>X</i>	50.00	
1	FRONT FENDER RH <i>X</i>		
		RESTORE	
	Sub Total	688.00	
	Discount 25% On Parts	(172.00)	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	500.00	150
	TO RESPRAY AFFECTED AREAS	500.00	200

Date : 27/06/2019

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTRENT000038

Accident Date : 06/03/2019

Vehicle No : SLX-1037-U

Make & Model : TOYOTA WISH 1.8 (A) STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1000.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1,516.00

Remarks:

2 days - 7/1P

SUB TOTAL

GST 7.0 % 106.12

TOTAL 1,622.12

Surveyor's name: Rafael - 4p 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 28/06/19 @ 1600hrs