

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 27/06/2019

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTRENT000038

Accident Date : 06/03/2019

Vehicle No : SLX-1037-U

Make & Model : TOYOTA WISH 1.8 (A) STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER <i>repair</i>	580.00	
1	FRONT BUMPER RETAINER RH <i>X</i>	58.00	
10	FRONT BUMPER CLIPS <i>X</i>	50.00	
1	FRONT FENDER RH <i>X</i>		
	RESTORE		
	Sub Total	688.00	
	Discount 25% On Parts	(172.00)	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	500.00	150
	TO RESPRAY AFFECTED AREAS	500.00	200

Date : 27/06/2019

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTRENT000038

Accident Date : 06/03/2019

Vehicle No : SLX-1037-U

Make & Model : TOYOTA WISH 1.8 (A) STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1000.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1,516.00

Remarks:

2 days - P/P

SUB TOTAL

GST 7.0 % 106.12

TOTAL 1,622.12

Surveyor's name:

Rafael - 4p 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

28/06/19 @ 1600hrs