ALG

Transfer

Ref

Survey Report

Date

Eligible Loss:

OD / TP / WS / IP / PLS / OD+TP / OD+WS / OA / HP / MV

Inspect Vehicle Here:

Ad Hoc / Mg Insp:

Id:

Incurred:

Policy No:

Claim No:

Insured: Losses:

Client's Ref:

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

H/S O/S

Veh Reg: SMK 91454. Yr Engin: 2019 (April).

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 216I 1499

Colour: Silver.

Yr: Insured / Std / Nil / NA

Sp Reading: 5807.

Engine No:

WBA6U1206ED05858

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoperative / Jammed / Leaked / Burnt or

Brake: Inoperative / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R:

BS / DUN / EXNOVA / GY / TS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: Rear:

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: mm

D.O.A: D.O.L: 6/8/19 0345pm

Survey held at: PML

Des. of Damages: F/L / Rear / O/S / H/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision

Estimated Value of Market Value: 91300K.

IDAC Accident Report: Consistent? Yes or No

GIA / PE Report: Consistent? Yes or No

Est. Repairs: days Res. Yes or No

Lump Sum: % J.Val. Yes or No

CA / FLV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: Chua

| Date / Time | Action / Instruction |
|---|---|
| | |

Date/Time File Pass to?

Profit Report

Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Report Format

Lump Sum / LBUC

Add Fee:

Site Insp. ($

Interview ($

Tech. Insp. ($

Weekend ($

Survey Fee:

Transportation

S.C.P.S. ($

Photos

Other

Total