

ASS. REC. BY:

REF: CS/III 19011628/UtD3

Special Instruction:

Mimin

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Gabriel Wee of



Date/Time: 28/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 2241P

Insured:

SMA 3441R

at Workshop m/s

KATZEN

Tel:

of

68 KAKI BUKIT

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/6/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

WPI

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SJS 2241P x
	SMA 3441R x

ASS. FED. BY: Marcus

REF:

IP

ASSIGNMENT

4/8/09

From: _____ Date: 1/7/2019

Veh No: SJS 2241P Yr Regn: _____
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost: _____

Truck / Trailer or

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Make: Toyota Corolla AHC 1598

To inspect Vehicle No: SJS 2241P

Colour: Blue A/C: Insured / Std / NI / NA

at Workshop m/s Kaizen
of 68 Kaki Bukit Ave 6 #02-12

Sp. Reading: 210801 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No: _____

C/No: MR 0532EE 106151161

Claims No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: Insured / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Insured / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

After 1pm anytime.

(Policy Condition)

Tyre Size: F: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / WIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 10500

Front 6 mm Rear 6 mm
R/Bal. mm R/Bal. mm

IDAC Accident Report: _____ Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: _____ Consistent? : Yes or No

D.O.A. 25/6/19 D.O.I. 1/7/19

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

ATA 9052

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Vehicle: IN / OUT

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: _____

Date / Time	Action / Instruction
	<u>not 100%</u>
	<u>Indulgence by 1500</u>

3/7/19 confid r/s \$900 with sherr. (Red: 1210; 57%)

RECEIVED 08 JUL 2019

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 3

37 Typist : Final Report

Resurvey No. of Trip: 1

Date/Time, File return to? _____

Survey Fee:	<u>250</u>
Transportation:	
3+RS, SI	
Photos	
Other:	
	<u>4</u>

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Insp. (\$)

: Weekend (\$)

Report Format: _____

Lump Sum / L.B. (\$): 900/-

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 28 June 2019 9:19 AM
To: ct-admin@visionlawllc.com; 'jactan@visionlawllc.com'; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Zuhaidah Samsuri
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJS2241P (Accident involving SJS2241P and SHA3441R on 25.06.2019)
Attachments: 2474_001.pdf; 4343_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJS2241P and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 27 June, 2019 1:27 PM
To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'jactan@visionlawllc.com' <jactan@visionlawllc.com>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJS2241P (Accident involving SJS2241P and SHA3441R on 25.06.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Marcus - 1/7/19.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: 27 June, 2019 11:37 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.K88.110848.19 (sj)
Your Ref: SHA 3441 R

27 June 2019

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Attention: Motor Claims Department

BY FAX: 6224 4174

motorclaim@iii.com.sg

Dear Sirs,

**ACCIDENT INVOLVING SJS 2241 P & SHA 3441 R ON 25 JUNE 2019 ALONG JALAN BUKIT MERAH TOWARDS COLLEGE ROAD AT ABOUT 1320 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email 27 June 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Kaizen Motors Pte Ltd
68 Kaki Bukit Avenue 6
#02-12 ARK@KB
Singapore 417896

Contact Person: Shawn Yap 9150-0670 /6384-1956

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLTM
(HEAD OFFICE)

cc: **SJS 2241 P** – By fax: 6384-1957 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor : _____
(Name & Signature)

2nd Survey on _____
Appointed surveyor : _____
(Name & Signature)

3rd Survey on _____
Appointed Surveyor : _____
(Name & signature)

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2019 17:29
Date Of Accident	25/06/2019 13:20
Exact Location Of Accident	JALAN BUKIT MERAH TWDS COLLEAGUE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS2241P
Insured/Policyholder	
Name Of Registered Owner	KINETIC REGENCY PTE LTD
Co Reg No	201632177M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62642231
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101649624
Cover Note Number	
Driver	
Name of Driver	HUI YIP KHIONG
NRIC No	S6917515E
Date Of Birth	29/05/1969
Occupation	INDOOR
Date Of Driving Pass	12/01/2001
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91053150
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 18 CANTONMENT CLOSE #11-61
Postcode	080018
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PETER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED MY VEHICLE DUE TO PEOPLE CROSSING THE ZEBRA CROSSING. SUDDENLY, VEHICLE B REAR ENDED ME.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3441R
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please fill in correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

QUARTERMASTER



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My ~~car~~ I stopping my vehicle due to people crossing the zebra crossing. Suddenly vehicle's rear ended me.

Zu

DECLARATION
I/We declare that the particulars are true in every respect.



Policyholder's Signature
Date & Time:

Zu

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2177M
Vehicle Details	
Vehicle No.:	SJS2241P
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4918281
Chassis No.:	MR053ZEE106151161
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	04 Aug 2009
First Registration Date:	04 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Aug 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	03 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$126.00
Total Rebate Amount:	\$9,052.00

The information contained herein is correct as at 01 Jul 2019

OK

Sketch Plan #3 Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE
 S6917515E
 Name: HUI YIP KHIONG
 Birth Date: 29 May 1959
 Issue Date: 06 May 2003
 100042295F




REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S6917515E



Name: HUI YIP KHIONG
 許業強
 Race: CHINESE
 Date of Birth: 29-05-1959 Sex: M
 Country of Birth: SINGAPORE



Land Transport Authority



VOCATIONAL LICENCE
 Licence No: S6917515E
 Name: HUI YIP KHIONG
 Card Issue Date: 02/03/2018
 Please visit www.lta.gov.sg to check the status of this vocational licence



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 2E Motorcycles up to 250 CC 30 Jan 2003
 Class 3 Motor cars up to 3500 kg with up to 7 passenger seats, excluding off-highway, and motor tractors/tractors up to 2500 kg 22 Jan 2003

S6917515E
 Licence No: S6917515E



0261719



0261719
 Licence No: S6917515E
 Blood Group: A61 Date of Issue: 22-09-1992
 APT BIK 16 CANTONMENT CLOSE #11-61
 S/N: 387046100018
 Date: 17/08/2008 (IN) No: 5972222



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	02/03/2018





Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5101649624 Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : SJS2241P
 Chassis Number : MROS3ZEE106151151

2. Name of Policyholder : KINETIC REGENCY PTE LTD

3. Effective Date of Insurance : 22 Jun 2018

4. Expiry Date of Insurance : 03 Aug 2019

5. Persons or Classes of Persons entitled to drive#
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his/her permission.
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#
 (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered Inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 35 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : S & M ALLIANCE PTE LTD (0000614873)
 Date of Issue : 22 Jun 2018 17:00 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorized Officer

Chief Executive

KAIZEN MOTORS




KAIZEN MOTORS PTE. LTD.

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H GST Reg No. 201502816H

Tel: (+65) 6384 1956 Fax: (+65) 6384 1957

Webpage: <https://www.kaizenmotors.com.sg>



Date : 01/07/2019
 Vehicle No : SJS2241P
 Model : Toyota Altis
 Mileage :

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	REAR BUMPER ASSY <i>20/02</i>	1	\$ 600.00 <i>485</i>	\$ 600.00 ✓
2	REAR BUMPER BRACKET <i>return</i>	2	\$ 70.00	\$ 140.00 ✓
3	REAR BUMPER REFLECTOR <i>11</i>	2	\$ 50.00	\$ 100.00 <i>252</i> X
4	REAR SENSOR PARKING SET <i>STC</i>	1	\$ 150.00	\$ 150.00 X
5	LABOUR FOR CHECKING ON WIRING		\$ 120.00	\$ 120.00 20
6	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR BUMPER ASSY		\$ 600.00	\$ 600.00 350
7	SPRAYPAINTING & PUTTY OF TAIL GATE, END PANELS, REAR BUMPER		\$ 400.00	\$ 400.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

*not added
 n/s \$900
 3dy.
 1/7/19
 through Always.*

*P-625
 252
 46875
 123675
 991*

Sub-Total	\$	2,110.00
GST 7%	\$	147.70
Grand Total	\$	2,257.70

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jul 2019 09:28 Edit Reg		28 Jun 2019 00:00 Edit Adj Rpt	S\$900.00 Edit Estimates	S\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SJS2241P	Date of Loss:	25/06/2019 00:00 - :59 [118 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA3441R	Policy No. (Claimant):	
		Excess:	
Repairer:	Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT, 417896 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS2241P
[SHA3441R]
TP

-
Jun 25 2019 12:00AM

[-]
Kaizen Motors Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
2	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
3	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
4	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
5	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
6	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
7	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
8	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
9	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
10	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
11	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
12	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
13	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
14	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
15	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
16	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
17	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
18	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
19	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
20	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
21	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
22	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
23	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
24	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
25	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
26	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
27	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
28	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
29	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
30	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
31	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
32	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
33	05/07/19 17:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
34	05/07/19 17:44	Reinspection Photo	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
35	05/07/19 17:44	Reinspection Photo	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	05/07/19 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	05/07/19 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	05/07/19 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	05/07/19 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/07/19 08:57	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19011629/UTD3S2
Date: 12/07/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SJS2241P	Insured Vehicle No :	SHA3441R
Date of Loss:	25/06/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS2241P	Engine No:	3ZZ4918281
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L (A)	Chassis No:	MR053ZEE106151161
Reg. Date:	04/08/2009 (Man. Year: 2009)	Odometer:	210801 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	990.00	468.75	521.25	52.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	770.00	350.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,110.00	1,238.75	871.25	41.29
Approved Total (Overridden) (S\$)		900.00		
(S\$)	2,110.00	900.00	1,210.00	57.35
+ GST 7.00/7.00% (S\$)	147.70	63.00	84.70	57.35
Nett Amount (S\$)	2,257.70	963.00	1,294.70	57.35

INSPECTION

Date of Assignment:	28/06/2019	
Date Inspected:	01/07/2019	Inspected At: Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2019)
Parts: 143 TOYOTA COROLLA ALTIS 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJS2241P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented / Deformed	600.00 F	*485.00 FL
2	2		*REAR BUMPER RETAINER	Bent	140.00 F	*140.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	100.00 F	*- FL
4	1		*SET REAR SENSOR PARKING	Serviceable	150.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	990.00	625.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	156.25
Total Parts (S\$)	990.00	468.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING.	New	120.00	20.00
2	LABOUR FOR DISMANTLE & REPLACING OF ACCIDENT DAMAGED PARTS. INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR BUMPER ASSY.	New	600.00	350.00
3	SPRAY PAINTING & PUTTY OF TAIL GATE, END PANELS. REAR BUMPER.	New	400.00	400.00
Gross Labour Cost (S\$)			1,120.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >