

ASS. REC. BY:

REF: CS/SMO 4011201 AV d302

Special Instructions:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Huang Shiang Yi

of SMO

Date/Time: 27.19.16.11pm

Estimated Cost: Bill to:

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No: SLH 51086

Insured:

at Workshop m/s Autoluk 17 Industrial

Tel: 29.6.2019

9645 0084

of 17 451 Road 4

Policy No: DIB/INTPV 01017572

Claim No: CMTD 1903148

Sum Insured:

Excess:

0

Make of Veh:

D.O.A. 29.6.19

(Client's Record)

3.7.2019

CA / REV / REP. / REV 24 HRS

R.O.D. Endorsement:

Date/Time: 27.19.16.56pm

Person Contacted:

Chyen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

4/7/19

Revert via merimen

4/7/19

Rece approved \$ 1524.14 from Shiang Yi by merimen

4/7/19

Informed Elmer c/A ex O by email

15/7/19

Final fig \$ 1245.14 confirmed by email (Ref 2743, 6990)

ASS. REC. BY:

REF SMO

ASSIGNMENT

From: Date: 3.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SLH 5108G

at Workshop n/s Automation Industries

of 19 ubi road 4

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: 10.00 a.m. - 12.00 p.m.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 75K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / (REV) REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLH5108G Yr Regn: 2016 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai cc 1197

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 70407. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFEAJ1111764025

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17.

R: 215/60R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 03/07/19

Survey held at Tan Chong cub

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

60 Sonyo.

RECEIVED 15 JUL 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 15/7 -typist

Report Format :

merimen

Lump Sum / L.B. (\$) 1245.14

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

3 + 103.31

Photos

Others

TOTAL

260

11

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019		02 Jul 2019 16:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
[Created by Insurer]									
Insured:	LIEW CHIN SIEW, ID: S7341202A, Tel: +6591731857, Email: LIEWCHINSIEW@GMAIL.COM								
Vehicle Reg. No.:	SLH5108G	Date of Loss:	29/06/2019 06:00 - :59						
Claim Type:	OD / CMTD1903148	Policy/Cover Note No.:	D18MTPV01017572 (Comprehensive)						
		Excess:	\$50.00						
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/07/2019]								
Driver/Custodian:	LIEW CHIN SIEW (45 / Male), NRIC: S7341202A, Tel: +6591731857 Email: LIEWCHINSIEW@GMAIL.COM								
Adj Asg. Remarks:	Survey on 03.07.2019, 10AM to 12PM								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 July 2019 1:41 PM
To: Elmer Alfonso; SUR
Subject: SLH 5108G-DOA: 29/6/2019 (SOMPO OD)

Dear Elmer,

As instructed by our client , please proceed to repair the **insured vehicle SLH 5108G (Excess S0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLH5108G (CMTD1903148)**

OD

Jun 29 2019 6:00AM

[LIEW CHIN SIEW]

Autolution Industrial Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 04/07/2019 12:34 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$1524.14) - SLH5108G - Claim Handler: Hwang Shiang Yi

Approved:1524.14.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn: Hwang Shiang Yi

Date: 04 Jul 2019

Preliminary Advice

Vehicle No	: SLH5108G	Accident Date	: 29/06/2019
Make	: NISSAN QASHQAI	Policy No.	: D18MTPV01017572
Assignment Date	: 02/07/2019	Excess	: S\$0.00
Date of Inspection	: 3/7/2019	Est. Duration of Repair	: 3
Inspection At	: AUTOLUTION INDUSTRIAL PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,988.14
Revised Amount	:S\$	995.14
Check Items (Estimated)	:S\$	529.00
Total	:S\$	1,524.14

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	47,714.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,286.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1202A
Vehicle Details	
Vehicle No.:	SLH5108G
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	HRA2330607A
Chassis No.:	SJNFEAJ11U1764025
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	07 Nov 2016
First Registration Date:	07 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$13,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2026
PARF Rebate Amount:	\$10,293.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$37,421.00
Total Rebate Amount:	\$47,714.00

The information contained herein is correct as at 04 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/07/2019 13:18
Date Of Accident	29/06/2019 06:00
Exact Location Of Accident	CARPARK INFRONT OF BLK 326 WOODLANDS STREET 32
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH5108G
Insured/Policyholder	
Name Of Registered Owner	LIEW CHIN SIEW
NRIC No	S7341202A
Email Address	LIEWCHINSIEW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91731857
Alternative Phone No	OTHERS-91731857

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01017572
Cover Note Number	

Driver

Name of Driver	LIEW CHIN SIEW
NRIC No	S7341202A
Date Of Birth	20/11/1973
Occupation	INDOOR
Date Of Driving Pass	27/11/2006
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91731857
Fax Number	
Contact Number	OTHERS-91731857
Email Address	LIEWCHINSIEW@GMAIL.COM

Address	APT BLK 173A PUNGGOL FIELD #11-599
Postcode	821173
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN, PHOTO AND POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

UNION INDUSTRIAL PTE LTD
15 UBI ROAD 1
SINGAPORE 408023
Tel: 6342 7111 Fax: 6342 7111
Reporting Centre Personnel's Signature
Name: ETHER AIFANSU
NRIC/ID No: G3462824L

carpenter 10 + 96



I bumped into a stationary car while trying to do a 3 ~~point~~ point turn.

I alight my car to take a look and found that there are no obvious dent ~~do~~ ~~for~~ on the car which I bumped into.

I did not took the car plate number ~~and~~ ~~the~~.

I discovered that my bumper is cracked when I reached home and he decided to report the accident.

I went back to the accident location to leave my contact but the car is no longer there.

I/We declare the foregoing particulars are true in every respect

劉正文

Driver's Signature
(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature
Name: **ETHEL MIFOLSO**
NRIC PIN No: **69462824L**

CERTIFICATE OF INSURANCE Pg. 1



Sompo Insurance Singapore Pte. Ltd.

30 Harbour Place, #01-01/02, Singapore 1 and Tower, Singapore 049807
Tel: (65) 6333 1111 / Fax: (65) 6333 3333 / Website: www.sompo.com.sg
CIN Reg No: 1999000000 / GST Reg No: S070000194

Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No.:	D18MTPV01017572
Insured	LIEW CHIN SIEW
Motor Car (Registration No.)	SLH5108G
Cover	Comprehensive - ExcelDrive GOLD
Policy Commencement Date	07 NOVEMBER 2018 00:00
Policy Expiry Date	08 NOVEMBER 2019 23:59
Maximum Liability (Section I)	Market value at time of loss
Excess*	\$400 - Section I (Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess*	N/A
Windscreen Excess*	S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use	Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured:
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the profits to which this Certificate relates is based in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exclusions of the Private Car Policy ref MTP-27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue: 18 OCTOBER 2018 18:16

IMPORTANT NOTICE

- a. Keep the Certificate in your Motor Car.
- a. Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- a. On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- a. This Policy will cease to be valid once the Motor Car has been sold to another person. This Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name: 11F02505 & FINANCIAL ALLIANCE PTE LTD | CI Code: J2A LXAD05V2RTYTY026





**SINGAPORE
POLICE FORCE**



T/20190629/2046

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3

Report No: T/20190629/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/06/2019 10:50		Vide Report No.:		Station Diary No.: 26	
Informant's Particulars					
Name of Informant: LIEW CHIN SIEW			Address: APT BLK 173A PUNGGOL FIELD #11-599 SINGAPORE 821173		
ID Type / ID No.: NRIC NO / S7341202A			Contact No.: Home/Office: Mobile: 91731857		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 20/11/1973	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: UNEMPLOYED			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 29/06/2019 06:00	Type of Location: Car Park
Location: Along Road 1 WOODLANDS STREET 32 Blk 326				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLH5108G	Car	NISSAN	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR	Red		2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLH5108G	TENET SOMPO INSURANCE PTE LTD.	D18MTPV0101757 2	07/11/2018	06/11/2019



**SINGAPORE
POLICE FORCE**



T/20190629/2046

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No. T/20190629/2046

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIEW CHIN SIEW	ID No.	S7341202A
Related Vehicle	SLH5108G (Car)	Contact No	91731857
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 29/06/2019 at about 6am, I was at the car park of Blk 326 Woodlands Street 32. I was making a 3 point turn when my rear right bumper slightly hit onto a car which was parked at lot 96. I got down from my car to check and did not see any damage to the car parked at lot 96 and no damage to my car but it was very dark at that time.

When I arrived home at about 8am, I discovered that there was a crack at the rear right bumper. I rushed back to Blk 326 Woodlands Street 32 car park to check on the car again and wanted to leave a note on the car but the car was no longer there. I did not take down the registration number of the car as I have checked and there was no damage.

I reported the matter to my insurance and they suggested to me to lodge a Traffic Police Report. I wish to state that if there is any damage to the car, the owner can claim my insurance for the damage.



**SINGAPORE
POLICE FORCE**



T/20190629/2046

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 3

Report No: T/20190629/2046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt TAN WEILONG, JONATHAN

Signature Of Informant:

刘政仁

Signature Of Interpreter:

Not applicable

Date/Time:

29/06/2019 10:50

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP158



Singapore Police Force

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE. LTD.
19 UBI ROAD 1
SINGAPORE 408823
TEL: 6348 7488 FAX: 6348 7489

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0354/19

DATE : 01-JUL-2019

M/S SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

S(048623)

TEL : 64616655

FAX : 62213147

ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR LIEW CHIN SIEW (LIU ZHENGXIU)

ADDRESS : BLK 173A PUNGOL FIELD

#11-599

S(821173)

TELEPHONE NO : 91731857

TYPE OF CLAIM : CO OR OD RECOVERY CLAIM

POLICY NO : 018MTPV01017572

VEHICLE NO : SJH5108G

MODEL CODE : FRLA8BJ11UEA--A--

MODEL/YEAR : NISSAN DASHDAI 1.2

ENGINE NO : HRA2330607A

CHASSIS NO : SJNFEAJ11U1764025

MILEAGE : 69972 KM

DATE IN : 01/07/2019

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 29/06/2019

-9645 0084 elmer@tamchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJH510BG

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S	
			CHARGES	RECOMMENDATION	
1	22/001	LABOR CHARGES TO REPAIR REAR END PANEL & RH REAR FENDER, RENEW REAR BUMPER	1470.00	180	✓
2	22/002	CHARGES TO SPRAY PAINTING SAME	600.00	180	✓
3	22/003	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE REAR BUMPER REPLACEMENT	48.00	✓	✓
4	22/004	RENEW REVERSE SENSOR	110.00	✓	✓
TOTAL LABOUR CHARGES			2228.00		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH5308G

DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT LIST S/NETT REMARKS
1	RH REFLECTOR REAR BUMPER <i>new</i>	25560-J290A	34.00 <i>X</i>
2	RH REAR FENDER OUTER WHEEL ARC MOULDING <i>new</i>	93826-4EADA	293.00 <i>X</i>
3	SUNDRIES <i>new</i>	NPN	50.00 <i>20</i>
4	REAR LICENCE PLATE <i>new</i>	RLP	60.00 <i>X</i>
5	SENSOR-REVERSE <i>from Pongd.</i>	SENSOR	250.00 <i>X ✓</i>
6	LH STAY REAR BUMPER <i>new</i>	H5211-4EAMA	77.00 <i>X</i>
7	RH STAY REAR BUMPER <i>new</i>	H5210-4EAMA	77.00 <i>? X</i>
8	REINFORCEMENT REAR BUMPER <i>new</i>	H5030-4EAMA	375.00 <i>? X</i>
9	ENERGY ABSORBER REAR BUMPER <i>new</i>	B5090-4EAOB	77.00 <i>? X</i>
10	LH SIDE BRACKET REAR BUMPER <i>new</i>	B5221-4EADA	21.00 <i>✓ ✓</i>
11	RH SIDE BRACKET REAR BUMPER <i>new</i>	B5220-4EADA	21.00 <i>✓ ✓</i>
12	CLIP REAR BUMPER & SGD \$0.69 EACH <i>new</i>	01553-05933	4.14 <i>✓ ✓</i>
13	TOW HOOK COVER RR BUMPER <i>new</i>	B5071-4EADA	10.00 <i>X</i>
14	REAR BUMPER <i>Delid</i>	B5022-4EADH	411.00 <i>✓ ✓</i>
SUB TOTAL			
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			
GRAND TOTAL			
OVERALL TOTAL			

LEGEND: REMARKS (X) = APPROVED, REMARKS (✓) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH51086

TOTAL LABOUR CHARGES	2228.00
TOTAL SPARE PARTS CHARGES	1760.14
GRAND TOTAL	3988.14 *

* All charges do2 not include GST.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Adrian Ling 96893735 Exam: To be advised.
03/07/19. No Anticased, 03 Days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0364/19

DATE : 01-JUL-2019

M/S SONPO INSURANCE SINGAPORE PTE LTD

60 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

S(048623)

TEL : 64616655

FAX : 62213147

ATTN : MOTOR CLAIM MANAGER

SURVEYOR ADRIAN

3 DAYS

OWNER'S NAME : MR LIEW CHIN SIEM (LIU ZHENGXIU)

ADDRESS : BLK 173A PUNGGOH FIELD

#11-599

S(821173)

TELEPHONE NO : 91731857

TYPE OF CLAIM : CO OR CO RECOVERY CLAIM

POLICY NO : D18MTPV01017572

VEHICLE NO : 5JH51086

MODEL CODE : FRLARBZ011UEA-A

MODEL/YEAR : NISSAN QASHQAI 1.2

ENGINE NO : HRA2330607A

CHASSIS NO : 5JNFEA111U1764025

MILEAGE : 71195 KM

DATE IN : 01/07/2019

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 29/06/2019

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJH5108G

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 22/001	LABOR CHARGES TO RENEW REAR BUMPER	1470.00	180.00
2 22/002	CHARGES TO SPRAY PAINTING SAME	600.00	180.00
3 22/003	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE REAR BUMPER REPLACEMENT	48.00	48.00
4 22/004	RENEW REVERSE SENSOR	110.00	110.00
	TOTAL LABOUR CHARGES	2228.00	518.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH530BG

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	RH REFLECTOR REAR BUMPER	20560-3J90A			34.00	X
2	RH REAR FENDER OUTER WHEEL ARC MOULDING	93828-4EADA			293.00	X
3	SUNDERIES	NPN			20.00	OK
4	REAR LICENCE PLATE	RLP			60.00	X
5	SENSOR-REVERSE	SENSOR			250.00	OK
6	LH STAY REAR BUMPER	H5211-4EAMA			77.00	X
7	RH STAY REAR BUMPER	H5210-4EAMA			77.00	X
8	REINFORCEMENT REAR BUMPER	H5030-4EAMA			375.00	X
9	ENERGY ABSORBER REAR BUMPER	85090-4EADB			77.00	X
10	LH SIDE BRACKET REAR BUMPER	85221-4EADA			21.00	OK
11	RH SIDE BRACKET REAR BUMPER	85220-4EADA			21.00	OK
12	CLIP REAR BUMPER @ SGD 10.69 EACH	01563-05933			4.14	OK
13	TOW HOOK COVER RR BUMPER	85071-4EADA			10.00	X
14	REAR BUMPER	85022-4EADH			411.00	OK
SUB TOTAL			0.00	0.00	727.14	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%)			0.00	0.00	0.00	
GRAND TOTAL			0.00	0.00	727.14	
OVERALL TOTAL			727.14			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGD NO SLH5108G

NETT ITEM	0.00
LESS 20.00%	0.00
NETT AMOUNT	0.00

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	727.14
LESS .00%	0.00
SPECIAL NETT AMOUNT	727.14

TOTAL LABOUR CHARGES	518.00
TOTAL SPARE PARTS CHARGES	727.14

TOTAL CHARGES	1245.14
ADD 7 % GST	87.16

GRAND TOTAL	1332.30
-------------	---------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 15 July 2019 2:54 PM
To: Elmer Alfonso; Marcus Chua (LKKAUTO)
Cc: Mavis Chng; SUR
Subject: RE: SLH5108G OD CLAIM 29.06.2019

Dear Elmer,

Confirmed finalize amount \$1245.14 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents directly to SOMPO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elmer Alfonso <elmer@tanchong.com>
Sent: Thursday, 11 July 2019 2:11 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>
Cc: Mavis Chng <mavis@tanchong.com>
Subject: Re: SLH5108G OD CLAIM 29.06.2019

Dear Veron,

Attached file is the finalized estimate.

Best Regards,

Elmer Alfonso

96450084

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, July 11, 2019 1:58:20 PM
To: Elmer Alfonso
Subject: FW: SLH5108G OD CLAIM 29.06.2019

Dear Elmer,

This is mark estimate not finalize estimate.

Kindly re-forward finalize estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Thursday, 11 July 2019 1:54 PM

To: SUR <sur@lkkauto.com>

Subject: FW: SLH5108G OD CLAIM 29.06.2019

[CS/SMO19011630/Avd3](#)

From: Elmer Alfonso <elmer@tanchong.com>

Sent: Thursday, 11 July, 2019 11:31 AM

To: Admin A <admin-a@lkkauto.com>

Cc: Mavis Chng <mavis@tanchong.com>

Subject: Re: SLH5108G OD CLAIM 29.06.2019

Dear Sir/Ma'am,

Attached file is the finalized estimate.

Best Regards,

Elmer Alfonso

96450084

From: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Sent: Tuesday, July 9, 2019 10:17:14 AM

To: Elmer Alfonso

Subject: RE: SLH5108G OD CLAIM 29.06.2019

Dear Elmer,

You may refer the email from LKK on 04/07/2019.

Best Regards

Hwang Shiang Yi

Claims Division

D: 6329 5205 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Elmer Alfonso <elmer@tanchong.com>

Sent: Tuesday, 9 July, 2019 10:06 AM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SLH5108G OD CLAIM 29.06.2019

Dear Melvin,

Kindly advise if the claim is authorized already?

Best Regards,

Elmer Alfonso

96450084

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Sent: Wednesday, July 3, 2019 10:35:28 AM

To: Elmer Alfonso

Cc: Hwang, Shiang Yi; Henry, Irene James; Teo, Grace

Subject: RE: SLH5108G OD CLAIM 29.06.2019

Hi Elmer,

We have already inform LKK Auto to survey between 10am – 12pm/

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Elmer Alfonso <elmer@tanchong.com>

Sent: Wednesday, 3 July, 2019 10:32 AM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SLH5108G OD CLAIM 29.06.2019

Dear Melvin,

Please be inform that the vehicle is already here.

Best Regards,

Elmer Alfonso

96450084

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Tuesday, July 2, 2019 4:12:53 PM
To: Elmer Alfonso
Cc: Hwang, Shiang Yi; Henry, Irene James; Teo, Grace
Subject: RE: SLH5108G OD CLAIM 29.06.2019

Dear Elmer,

We have appointed LKK Auto to survey the vehicle on 03.07.2019, between 10am to 12pm.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Elmer Alfonso <elmer@tanchong.com>
Sent: Tuesday, 2 July, 2019 4:03 PM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SLH5108G OD CLAIM 29.06.2019

Dear Melvin,

Can we arrange the survey between 10-12 pm? because my customer need the vehicle after lunch.

Kindly revert.

Best Regards,

Elmer Alfonso

96450084

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Sent: Tuesday, July 2, 2019 3:57:12 PM

To: Elmer Alfonso

Cc: Hwang, Shiang Yi; Henry, Irene James; Teo, Grace

Subject: RE: SLH5108G OD CLAIM 29.06.2019

Dear Elmer,

I have tried calling you but unable to reach you.

Our surveyor recommend to leave the vehicle from 10am – 5pm in the workshop.

Please call me if any doubt.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Elmer Alfonso <elmer@tanchong.com>

Sent: Tuesday, 2 July, 2019 3:50 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SLH5108G OD CLAIM 29.06.2019

Dear Melvin,

Kindly confirm the schedule date and time. 03.07.2019 10:00 am.

Please advise.

Best Regards,

Elmer Alfonso

96450084

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Sent: Tuesday, July 2, 2019 1:40:53 PM

To: Elmer Alfonso

Cc: Hwang, Shiang Yi; Henry, Irene James; Teo, Grace

Subject: RE: SLH5108G OD CLAIM 29.06.2019

Our Ref : CMTD1903148

Hi Elmer,

We acknowledged receipt of your claim documents.

Please be informed that Ms Hwang Shiang Yi is the handler of this case.

We have appointed our in-house surveyor to conduct the survey on 03.07.2019.

Excess : Waive

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Elmer Alfonso <elmer@tanchong.com>

Sent: Tuesday, 2 July, 2019 8:56 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: SLH5108G OD CLAIM 29.06.2019

Dear Sir/Ma'am,

Please make arrangement survey on 03.07.2019 10:00 am.

Attached file is the workshop estimate and accident reporting.

Best Regards,

Elmer Alfonso

96450084

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019		02 Jul 2019 16:11 Edit Adj Rpt	S\$1,245.14 Edit Estimates	S\$1,245.14 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: LIEW CHIN SIEW , ID: S7341202A, Tel: +6591731857, Email: LIEWCHINSIEW@GMAIL.COM									
Vehicle Reg. No.: SLH5108G		Date of Loss: 29/06/2019 06:00 - 159 [31 Months and 22 Days From LTA Reg Date (Mah Yr)]							
Claim Type: OD / CMTD1903148		Policy/Cover Note No.: D18MTPV01017572 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/07/2019]									
Driver/Custodian: LIEW CHIN SIEW (45 / Male) , NRIC: S7341202A, Tel: +6591731857 Email: LIEWCHINSIEW@GMAIL.COM									
Adj Asg. Remarks: Survey on 03.07.2019, 10AM to 12PM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
SOMPO_SG (04/07/2019): Alert - Adj Mandate Approved (S\$1524.14) - SLH5108G - Claim Handler: Hwang Shian...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH5108G (CMTD1903148)
OD
Jun 29 2019 6:00AM
[LIEW CHIN SIEW]
Autolution Industrial Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)								Thumbnail	Print	
1	01/07/19 13:36	Accident Statement							1	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	04/07/19 11:09	Adjuster Immediate Advice							1	Load HTM		
									3 per page		☒	
Photos/Images									3 per page		☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)								Thumbnail	Print	
1	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
2	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
3	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
4	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
5	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
6	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
7	01/07/19 13:29	Accident Photo [Linked Accident Report Documents]							1	Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	04/07/19 10:59	General View							1	Load JPG	☒	
2	04/07/19 10:59	General View							1	Load JPG	☒	
3	04/07/19 10:59	General View							1	Load JPG	☒	
4	04/07/19 10:59	General View							1	Load JPG	☒	
5	04/07/19 10:59	General View							1	Load JPG	☒	
6	04/07/19 10:59	General View							1	Load JPG	☒	
7	04/07/19 10:59	General View							1	Load JPG	☒	
8	04/07/19 10:59	General View							1	Load JPG	☒	
9	04/07/19 10:59	General View							1	Load JPG	☒	
10	04/07/19 10:59	General View							1	Load JPG	☒	
11	04/07/19 10:59	General View							1	Load JPG	☒	
12	15/07/19 12:24	Reinspection Photo							1	Load JPG	☒	
13	15/07/19 12:24	Reinspection Photo							1	Load JPG	☒	
14	15/07/19 12:24	Reinspection Photo							1	Load JPG	☒	
15	15/07/19 12:24	Reinspection Photo							1	Load JPG	☒	
16	15/07/19 12:24	Reinspection Photo							1	Load JPG	☒	
17	15/07/19 12:24	Reinspection Photo							1	Load JPG	☒	
									1 per page		☒	
Documentation									1 per page		☒	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)								Thumbnail	Print	
1	02/07/19 13:38	Repair Estimates							1	Load PDF		

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	01/07/19 13:36	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	01/07/19 13:29	Accident Photo	 Load JPG	☒
2	01/07/19 13:29	Accident Photo	 Load JPG	☒
3	01/07/19 13:29	Accident Photo	 Load JPG	☒
4	01/07/19 13:29	Accident Photo	 Load JPG	☒
5	01/07/19 13:29	Accident Photo	 Load JPG	☒
6	01/07/19 13:29	Accident Photo	 Load JPG	☒
7	01/07/19 13:29	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	01/07/19 13:33	CERTIFICATE OF INSURANCE	 Load TIF	
2	01/07/19 13:33	ICDL	 Load TIF	
3	01/07/19 13:33	POLICE REPORT PAGE 1	 Load TIF	
4	01/07/19 13:33	POLICE REPORT PAGE 2	 Load TIF	
5	01/07/19 13:33	POLICE REPORT PAGE 3	 Load TIF	
6	01/07/19 13:33	Sketch Plan	 Load TIF	
7	01/07/19 13:33	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19011630/AVD3E2

Date: 17/07/2019

REFERENCE

Insured/Claimant: LIEW CHIN SIEW Policy No: D18MTPV01017572
Date of Loss: 29/06/2019 Nature of Claim: OD Claim No: CMTD1903148

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH5108G**
Make & Model: NISSAN QASHQAI, 1.2 DIG-T (A) Engine No: HRA2330607A
Reg. Date: 07/11/2016 (Man. Year: 2016) Chassis No: SJNFEAJ11U1764025
Colour: Red Odometer: 70407 km
Engine Capacity: 1197 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,760.14	727.14	1,033.00	58.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,228.00	518.00	1,710.00	76.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,988.14	1,245.14	2,743.00	68.78
+ GST 7.00/7.00% (S\$)	279.17	87.16	192.01	68.78
Nett Amount (S\$)	4,267.31	1,332.30	2,935.01	68.78

INSPECTION

Date of Assignment: 02/07/2019
Date Inspected: 03/07/2019 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2019)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH5108G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REFLECTOR REAR BUMPER	Not Necessary	34.00 FS	*- FS
2	1		*RH REAR FENDER OUTER WHEEL ARC MOULDING	Not Necessary	293.00 FS	*- FS
3	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
4	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS
5	1		*SENSOR-REVERSE	Damaged	250.00 FS	*250.00 FS
6	1		*LH STAY REAR BUMPER	Not Necessary	77.00 FS	*- FS
7	1		*RH STAY REAR BUMPER	Not Necessary	77.00 FS	*- FS
8	1		*REINFORCEMENT REAR BUMPER	Not Necessary	375.00 FS	*- FS
9	1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	77.00 FS	*- FS
10	1		*LH SIDE BRACKET REAR BUMPER	Necessary	21.00 FS	*21.00 FS
11	1		*RH SIDE BRACKET REAR BUMPER	Necessary	21.00 FS	*21.00 FS
12	6		*CLIP REAR BUMPER	Necessary	4.14 FS	*4.14 FS
13	1		*TOW HOOK COVER RR BUMPER	Not Necessary	10.00 FS	*- FS
14	1		*REAR BUMPER	Deformed	411.00 FS	*411.00 FS
Total Parts (S\$)					1,760.14	727.14

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPAIR REAR END PANEL & RH REAR FENDER, RENEW REAR BUMPER	New	1,470.00	180.00
2	CHARGES TO SPRAY PAINTING SAME	New	600.00	180.00
3	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE REAR BUMPER REPLACEMENT	New	48.00	48.00
4	RENEW REVERSE SENSOR	New	110.00	110.00
Gross Labour Cost (S\$)			2,228.00	518.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >