4 1552010	cc3/A/6 190/	1/22 / /	RI das HILKK	
INS. CASE OWN	RASIGNM DOI: ASSIGNM	ENT	Date / Time :	(17/19
Jun rejun	411	1-1	Registered in Merimen:	4719
Pre-assign / CC	U/FTE		and the second s	101.1
Insured Vehicle	No. Stu 6450D	Claim No.		
				-
Name of Insured	200	Policy No.		
Insured Tel No.	HP:	Make / Model :		
Excess Sec II :S	D.O.A.: 24/6/2019	Place of Acciden	t:	
Is driver the own	ner? (YES / NO) Nature of Accident :		_	_
If NO, Driver N Driver T		Of GIA REPORT	YES NO ; TP GIA RI	EPORT (YES) NO
SJW 200		moute manny		
3311 811		-		
INSRS: WSP: Volks (Tel: Liability: RMKS:	wasen INSRS: WSP: Tel: Linbility: RMKS:	INSRS: WSP: Tel: Liability: RMKS:		NSRS: WSP: fel: .iability; tMKS:
Date/ Time				
	S3W 2008 B 1		STAGE	DATE / PIC
	SKU 6450D YX		Non-Reporting ltr (1st): Non-Reporting ltr (2nd):	
	SEG 6420 0		Non-Reporting ltr (Final):	
	1		Notification ltr (if non-pickup	p):
26/8/19	- FILE PAS) TO HIM IL TO CLOTE		Call Of: >3/7	119
			Occumentation Check List	: Handler Typist
			Notification ltr (if non-pickup	
			After call ltr to Ol:	
			Authorisation To Act:	
			Release Voucher: Final Repair Bill:	
			Car Rental Invoice	
			Towing Invoice	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction	*
			LOD Payment Breakdown Form	
RELIMINARY ADVIC	E Date/Time: Sent By:		Post-Repair Photos:	
			Others:	
NALIZATION	Date/Time: Confirm with:		Confirm by:	
epair Cost	SS (days) Reduction:	96	Email	Cáll
INAL SETTLEMENT	% 100 (Agreed / Assessed) BOLA S/N No. : 26		Email Call If NO or B 28, Ass. Lia	
epair Cost. (w(631)	SS 2133.40		11 190 to 13 20, 700 Life	
oss of Rental (LOR):	(51)55 171.20 (2 days) × \$80			12015
oss of Use (LOU):	SS - (S x days)		- n 10	119
oss of Income (LOI):	SS - (S x days)		1 V/18	1,1
OR only LOU or	SS 7.45 LOR + LOU LOR + LOI Tick only one			
IA/LTA Search ledical:	22 4.42		1) Claim status: Normal/R	cject/Private Settle
isbursement	55 - (e.g. Tow/ Independent.)		2) Report Format: 10	
	SS -		3) Survey fee: \$32	0
otal:	SS 2312.05 Global Sum SS:			
INAL PAYMENT	Date/Time: Confirm with:		Email Catt	
ayee 1:	SS 2140.85 Name 1: Vallewayer Gray SS 171.20 Name 2: Blow Ref -A-Cov	p songapore P	le Ltd	ALM SLAX
tyee 2: (Strike if N.A.)		rite Utol		100
Payee 3: (Strike if N.A.)	S\$ Name 3:			11.5

Content Cont	ASS. REC. BY: REF ME	4 11633 PM d 24480
To impact Verticine Note SUN 2-COR B SUN	1.7	ASSIGNMENT
To impact Verticine Note SUN 2-COR B SUN	From Date: OUT THE	Vida No. CILL DOTER VERNING DOLL CORP
Truck Trailer or Make: Voltanges Vertacle No: S J V 2008 B at Workshop mis Voltanges Project de Kartigory Project lessared: Policy No. Chairs No. Stum insured: Excess: (Climer's Record) Make of Velt: (Policy Condition) Remark: The wh had commenced its registr at the time of inspection. But or Market Value: (DAG Accident Rport: Consistent?: Yes or No. Call r FR. Seare: Consistent?: Yes or No. Lam Soun: Sum insured: Action / Instruction Policy Condition) Remark: The who had commenced its registr at the time of inspection. But or Market Value: (DAG Accident Rport: Consistent?: Yes or No. Lam Soun: Sum J Val. Yes or No. Call r FR. Seare: Consistent?: Yes or No. Call r FR. Seare: Consistent?: Yes or No. Call r FR. Seare: Yes or No. Call r FR. J 24 HS. Velsick: IN / OUT Date: Person Confacted: Date: Action / Instruction P(P - 1993 - 85 (Red. 15323 OS 75 7) Add Feo: Site Insp. (\$		
To inspect Verticio No: at Workshop mis of Karapore Profest Policy Na. of Karapore Profest Policy Na. Clears No. Sum insured: Clears No. Chem's No. Sum insured: Excess: (Clearts Record) Make of Vet: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. But or Market Value: DAC Accident Rport: Consistent?: Yes or No Lum Sum: Save: Yes or No CA REV REP. 24 HRS Date: Person Contacted: Date: Person Con	OD /TP /WS / TP RES / OD RES / EVA / INV / MV	
of		10 TO
Engillo: C/Ros: WY W222 7N2 F V03 50 79		Colour 6464 A/C: Insured / Std / NA / NA
Engillo: C/Ros: WY W222 7N2 F V03 50 79	of 1 Karegore Arrest.	See Resortion \$1.681 TAtadicy Insured / Std / NI / NA
Chairs No. Chairs No. Chairs No. Chairs No. Chairs No. Chairs Record Clearts Record Make of Veh: Clearts Record Clearts Record Make of Veh: Clearts Record Make of Veh: Clearts Record Consistent? : Yes or No Clearts Record Clearts Record Clearts Record Clearts Record Clearts Record Clearts Record Consistent? : Yes or No Clearts Clearts Record Clearts		
Clears No. Sum Insured: Excess: Client's Record Make of Veh: Client's Record Client's Record Make of Veh: Client's Record Consistent's Yes or No	Policy No.	
Steering: broader Jammed Leaked Burnt or	1,000	
Brake Collect's Record	2 1 5 60	
Model: Nill (Rim / STD ARim or Tyre Size: F: 228/55/R17 R: BS / DUN / EXCHANGE (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bol. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seer: Consistent?: Yes or No Lum Sum: % 3 Val. Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Webside: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: The UIC / Chassis frame / Body Structure affected due to collision. P(P - 1993. & Real Size: Final Report Date: Strong Fir Pass to? Final Report Date: Strong Fir Pass to? Final Report Condition, Fire Return in? Add Foo: Site Insp. (\$ Survey Fee: Interview (\$ Interv	area yes	
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAG Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Luns Sum: Sa Val.: Yes or No CA / REV / REP. / 24 HRS Date / Time Action / Instruction P(P - 1993. 85 (Red + 5335.05) The UC / Chassis frame / Body Structure affocted due to collision. P(P - 1993. 85 (Red + 5335.05) The UC / Chassis frame / Body Structure affocted due to collision. Cald Foo: Survey No. of Trip: Survey Fee: Interview (\$ Frost.		
Remark: The veh had commenced its repair at the time of inspection. Remark: The veh had commenced its repair at the time of inspection. Remark: The veh had commenced its repair at the time of inspection. Remark: The veh had commenced its repair at the time of inspection. Remark: Toyo / YoRo or		
Remark: The veh had commenced its repair at the time of inspection. Bid. or Market Value: IDAG Accident Rport: Consistent? : Yes or No GIA / PR Soen: Consistent? : Yes or No Lum Sum: % 3 Val. Yes or No CA / REV / REP. / 24 HRS Date / Time Action / Instruction P(P - 1993.83 (ReA 53325.05) The UIC / Chassis frame / Body Structure affected due to collision. P(P - 1993.83 (ReA 53325.05) Add Fee: Site Insp Giant Instruction Strivey Fee: Transport Tr	11475 1 1476 7 1411 157	A
repair at the time of inspection. Bal. or Market Value: IDAG Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No L/Bal. D.O.A. 24/66/19 Bal. or min L/		The state of the s
Bal. or Market Value: IDAG Accident Rport: Consistent? : Yes or No GIA / PR Secn: Consistent? : Yes or No Est. Repairs: 2 days Res.: Yes or No Lum Sum: 5 3 Val. : Yes or No CA / REV / REP. / 24 HRS Date / Time Action / Instruction P(P - 1993. 85 (Red + 5325.05 73 7.) Date / Time Action / Instruction Date / Time Action / Instruction Date / Time Action / Instruction P(P - 1993. 85 (Red + 5325.05 73 7.) Candiffring, File Return for Action / Instruction Date / Time Action / Instruction P(P - 1993. 85 (Red + 5325.05 73 7.) Candiffring, File Return for Action / Instruction Date / Time Action / Instruction P(P - 1993. 85 (Red + 5325.05 73 7.) Candiffring, File Return for Action / Instruction Candiffring, File Return for Action / Instruction Candiffring, File Return for Instruction Candiffring, File Return for Action / Instruction Candiffring, File Return for Action / Instruction Candiffring, File Return for Candiffring, File Rea		DO FORT EXHOUNT OF THE PLEAT ONLY
IDAG Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Consistent? : Yes or No Consistent? : Yes or No Call PR Seen: Seen: Yes or No Call Rpairs: 2 days Res. : Yes or No Call Report Report Call Report		TOYO/YOKO or
GIA / PR Seen: Consistent? : Yes or No Est. Repairs: 2 duys Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / I ime		Front / Rear
Est. Repairs: 2 duys Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Confacted: Vehicla: IN / OUT Date / Tume Action / Instruction P(P - 1993 - 83 (Red 15325 05 73 7.) Cale/Time, File Pass 107 : Final Report	V2V 105 00000 10	R/Bal. 6 mm R/Bal. 6 mm
Lum Sum: % 3 Val. Yes or No CA / REV / REP. / 24 HRS Date: Person Confacted: Vehicle: IN / OUT Date / Tumo	GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm
Date / Time Person Confacted: Des. of Daniages : Frt Rear O/S FM The U/C Chassis frame Body Structure affected due to collision. P(P - 1993 - 83 (Red 15325 O5 73 7.)	Est. Repairs; 2 days Res.: Yes or No	D.O.A. 24/66/19 D.O.I. 04/07/19
Date / Time Action / Instruction Date / Time Action / Instruction P(P - 1993 - 83 (Red 15325 .05 73.7.) Date/Time, File Pass to? : Prell. Report Days Of Repair: Date/Time, File Return to? Add Fee: Site Insp (\$) _ 3 + R3_ gr interview (\$) Prodos Report Format :	Lum Sum: % 3 Val. Yes or No	Survey held at KG AMPAT
Date / Time Action / Instruction P(P - \$ 1993.83 (Red \$ 5325.05) 73.7.) Date/Time, File Pass to7 : Preli. Report Days Of Repair: Date/Time, File Return to? Add Fee: Site Insp (\$) Survey Fee: Inserting Insert Ins	CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date / Time Action / Instruction P P 1993.83 (Red \$ 5328.05 73.7.) Date/Time, File Pass to? : Prell. Report Days Of Repair: Date/Time, File Return to? : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? : Site Insp (\$) : 5+Ri5 : Site Insp (\$) Cater Format : : Tech. Invs (\$) Others Cater Format : : Tech. Invs (\$) : Weekend (\$)		
P(P - \$ 1993.83 (Red \$ 5325.05 73.7.) Collet Fine, File Pass to? I: Preli. Report Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: Salvey Fee: Transportation: Salvey Fee: Transportation: Salvey Fee: Transportation: Tech. Invs (\$) Photos Others Others Others		The U/C / Chassis frame / Body Structure affected due to collision.
Cate/Time, Fite Pass to? Preli. Report Days Of Repair:	Date / rime Action / Instruction	·.
Content Cont	PIP - \$ 1993.83 (Red \$ 5325.0	3 737.)
Survey Fee: Date/Time, File Return 107 Add Fee: Site Insp (\$)S+RSSt interview (\$) Photos Report Format :Tech. Invs (\$) Lump Sum / I.B.I: (\$) Weekend (\$)	Chate/Time, File Pass to? : Preli. Report	Days Of Repair:
Add Fee: Site Insp (\$) 5 + R5 50 Report Format : Tech. Invs (\$) Lump Sum / I.B.I: (\$) Weekend (\$)	i) : Final Report	were an experience of the second
Add Fee: Site Insp (\$)	Classofthown, File Return 307	
Tech. Invs (\$) Others Lump Sum / I.B.I: (\$) Weekend (\$)	2) Add	Fare Land
_ump Sum / I.B.I: (\$)		interview (\$) Photos
	Report Format:	Tech. Invs (\$) Others
	Lump Sum / I.B.I: (\$	
		TOTAL

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue Singapore 639176

Biz. Reg. No.: 199101494Z GST No.: M200985052

78 Shenton Way

#07-16 AIG Building

Singapore 079120







Quotation

Non binding - Preview

Page

1/1

Customer Details: Ms. MEGAN TAN LI SHAN 1 CACTUS CRESCENT

Singapore 809710

Document no. Document date Customer no. Customer GST-ID Dealer Job order number

01-07-2019 5211043795 201009404M 39999 2019001155/1 01-07-2019

Job order date TIOW CHUAN CHEE Service Advisor

License plate SJW2008B

Madel cade 7N14H3

AIG ASIA PACIFIC INSURANCE P/L

First registration 29-09-2015

VIN W/WZZZ7NZFV036079

Model Sharan succ. HL 147 TSIDEF

Mileage 56,182

Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
Diagnostic and Programming	1	pos.	480.00	#1	/480.00 /	513.60
Check Short Circuit / Harness Repair	1	pos.	280.00	#1	280.00	A 1 298.60
Rear View Mirror Housing RH SIDE MIRROR HOUSING	1	pos.	813.83	#1	813.83	870.80
Mirror Cap Primed 7 Xnn	1	pcs.	125.22	#1	125.22	133.99
Mirror Glass 7 XMn	1	pos.	176.71	#1	176.71	189.06
Window Stot Seal Aluminiu	1	pos.	243.10	#1	243.10	260.12
	3	DOS.	840.00	#18	80 2 52HOOY	20 2,696.40
	1			81		299.60
Spray Painting AIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH: SKU6450D SURVEY BY	3	pos	800 00 Xnn	#1 W		
	Diagnostic and Programming Chack Short Circuit / Harness Repair Reinr View Mirror Housing RH SIDE MIRROR HOUSING Wirror Cap Primed 7 RH Wirror Glass 7 RH Window Slot Seal Aluminiu RH Panel Repair and Straightening Spray Painting mirror housing Spray Painting MIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH: SKU6450D	Diagnostic and Programming Chack Short Circuit / Harness Repair Reinr View Mirror Housing RH SIDE MIRROR HOUSING Mirror Cap Primed 7 XNA Mirror Glass 7 XNA 1 RH Window Slot Seal Aluminiu RH Panel Repair and Straightening Spray Painting mirror housing 1 Spray Painting MIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH SKU6450D	Diagnostic and Programming Chack Short Circuit / Harness Repair Reiar View Mirror Housing RH SIDE MIRROR HOUSING RH Wirror Cap Primed 7 X X 1 pcs. RH Wirror Glass 7 X 1 pcs. RH Window Siot Seal Aluminiu X 1 pcs. RH Panel Repair and Straightening 3 pcs. Spray Painting mirror housing 1 pcs. Spray Painting mirror housing 1 pcs. Spray Painting Tilror housing 3 pcs. MIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH: SKU6450D	Diagnostic and Programming 1 pcs. 480.00 Chack Short Circuit / Harness Repair 1 pcs. 280.00 Reitr View Mirror Housing 1 pcs. 813.83 RH SIDE MIRRIOR HOUSING 1 pcs. 125.22 RH pcs. 125.22 RH pcs. 125.22 RH pcs. 176.71 RH pcs. 176.71 RH pcs. 243.10 RH panel Repair and Straightening 3 pcs. 840.00 Spray Painting mirror housing 1 pcs. 280.00 Spray Painting mirror housing 3 pcs. 800.00 Mrg Direct Settlement 9 pcs. 800.00 Mrg Direc	Diagnostic and Programming 1 pcs. 480.00 #1 Chack Short Circuit / Harness Repair 1 pcs. 280.00 #1 Reinr View Mirror Housing 1 pcs. 813.80 #1 RH SIDE MIRROR HOUSING 1 pcs. 125.22 #1 RH Wirror Cap Primed 7 x x x x x x x x x x x x x x x x x x	Panel Repair and Straightening 1 pcs. 480.00 #1 480.00 280.00 #1 280.00 280.00 #1 280.00 280.00 #1 280.00 280.00 #1 280.00 280.00 #1 280.00 280.00 #1 280.00 280.00 #1 280.00 280.00 #1 280.00 28

Tax Code	Labour	Material	GST %	GST		Lay Total amount excl. GST	Total amount incl. GST
#1	760.00	6,558.86	7%	512.32	04/67	19 C1000 7,318.88	7,831.18
Total	760.00	6.558.86		512.32		7,318.86	7.831.18
				(Roby s	for or bake po	.it

LKK Auto Consultants hence notify the Repairer of the following: Customer Service Advisor . To resurvey before/after spray painting To display damaged partial during recursely Parts prices are subject to confirmation. Third party survey is on a reviewed President bear No fleas in the service accomments; and ashawage
 Supplementary remains the sources and
 subject to fer it. -VISIT OUR WEBSITE, aftersains y and promotone) Acknowledged by Reports Square Date:

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue Singapore 639176

Biz. Reg. No.: 199101494Z GST No.: M200985052







Tax invoice Preview

Page

1/2

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120 Customer Details: Ms. MEGAN TAN LI SHAN 1 CACTUS CRESCENT Singapore 809710

Document no. Document date Customer no. Customer GST-ID

Dealer Job order number Job order date Service Advisor 26-07-2019 5211043795 201009404M 39999

2019001296/ 1 11-07-2019 TIOW CHUAN CHEE

License plate SJW2008B Model code 7N14H3 First registration 29-09-2015

VIN WVWZZZ7NZFV035079 Model

Sharan succ. HL 147 TSID6F

Mileage 56,182

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount 1	Total amount incl. GST
7N2857508AC9B9	Diagnostic and Programming Rear View Mirror Housing RH SIDE MIRROR HOUSING*XR-120719	1	pcs. pcs.	480.00 813.83	#1 #1	480.00 - 813.83 /	
	labour Spray Painting AIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH: SKU6450D SURVEY BY: RASUL (LKK)	0.5	pcs.	840.00 280.00	#1	420.00 280.00	449.40 299.60

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount Incl. GST
#1	480.00	1,513.83	7%	139.57	1,993.83	2,133.40
Total	480.00	1.513.83		139.57	1,993.83	2,133.40

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

VOĽKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue Singapore 639176 Biz. Reg. No.: 199101494Z GST No.: M200985052







Tax invoice

Preview

Page

2/2

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120

Customer Details: Ms. MEGAN TAN LI SHAN 1 CACTUS CRESCENT Singapore 809710

Document no. Document date Customer no. Customer GST-ID Dealer

Job order number Job order date Service Advisor

26-07-2019 5211043795 201009404M 39999 2019001296/1

11-07-2019 TIOW CHUAN CHEE

License plate SJW2008B

Model code 7N14H3

First registration 29-09-2015

WVWZZZ7NZFV035079

Model

Sharan succ. HL 147 TSID6F

Mileage 56,182

This is an authorised document. No signature is required.

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue Singapore 639176

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Company

AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way

#07-16 AIG Building Singapore 079120

Customer Details:

MEGAN TAN LI SHAN

1 CACTUS CRESCENT Singapore 809710

Document no. Document date Customer no. Customer GST-ID Dealer

Service Advisor

01-07-2019 5211043795 201009404M

1/1

39999 2019001155/1 Job order number Job order date

01-07-2019 TIOW CHUAN CHEE

License plate SJW2008B

Model code 7N14H3

First registration 29-09-2015

VIN WVWZZZ7NZFV035079 Model

Sharan succ. HL 147 TSID6F

Page

Mileage 56,182

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
7N2857508AC9B9	Rear View Mirror Housing RH SIDE MIRROR HOUSING	1	pcs.	813.83	#1	813.83	870.80
5N0857538 GRU	Mirror Cap Primed 7 RH	:1	pcs.	125.22	#1	125.22×	133.99
5N0857522C	Mirror Glass 9 RH	1	pcs.	176.71	#1	176.71★	189.08
7N0837476D 3Q7	Window Slot Seal Aluminiu	1	pcs.	243.10	#1	243.10	260.12
	Panel Repair and Straightening	3	pcs.	840.00	#18	CO 2,520:00	2,696.40
	Spray Painting mirror housing	1	pcs.	280.00	#1	280.00	299.60
	Spray Painting AIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH: SKU6450D	3	pcs.	800.00X	#1 Sud	2,400.00	2,568.00
Quotation valid till 08	3-07-2019			14	900100	68	

1-2 long Total amount excl. GST 67/67/19 @10vu 7.318.86 Tax GST Labour Material GST % Code #1 760.00 6,558.86 7% 760.00 512.32 6,558.86

ind. GST

Total amount

7,831.18

7.831.18

LKK Auto Consultants hence notify the Repairer of the following: Customer Service Advisor . To resurvey before latter spray painting To display damaged partial during resurvey · Parts prices are subject to confirmation -VISIT OUR WEBSITE: aftersales, vw.com.sg for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions) y terms must be resurreyed and is subject to final accreval from Insurance Company Adknowledged by Rizparlet Signature: Date:

Jia Le (LKK Auto)

From:

Md Noor, Norsiah <Norsiah.MdNoor@aig.com>

Sent:

Friday, 16 August 2019 3:51 PM

To:

Jia Le (LKK Auto)

Subject:

RE: (MANDATE REQUEST) Your ref: 0459559692SG [ACCIDENT INVOLVING

VEHICLES SKU6450D AND SJW2008B ON 24/06/2019]

Dear Jia Lee.

Approved in Merimen

Thank you

Kind regards Norsiah

Norsiah Md Noor

Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606
Norsiah MdNoor@aig.com | www.aig.com.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]

Sent: Friday, August 16, 2019 3:02 PM

To: Md Noor, Norsiah < Norsiah. MdNoor@aig.com>

Subject: [EXTERNAL] (MANDATE REQUEST) Your ref: 0459559692SG [ACCIDENT INVOLVING VEHICLES SKU6450D

AND SJW2008B ON 24/06/2019]

This message is from an external sender; be cautious with links and attachments.

AIG Ref: 0459559692SG

Dear Sirs/Madam.

ACCIDENT INVOLVING SKU6450D(OI) AND SJW 2008B(TP) ON 24/06/2019

We refer to the above matter.

Mandate summary and the relevant documents had been uploaded in Merimen.

For your approval please.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: <u>Jiale@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with:

*SJW2008B (0459559692SG) [SKU6450D] TP MEGAN TAN LI SHAN Jun 24 2019 12:00AM

			Loaine		Singapore Pte Ltd		
Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward		
From	AIG As		nce Pte. Ltd. (E	xpress) (AIG_SG	EXPRESS), sent on 16/08	/2019 15:48 PM.	
Subject			proved (S\$2312	.05) - SJW2008B	- Claim Handler: MdNoor,	Norsiah	
DOCUM	ENTS SU	MMARY					
There ar	e no docu	ments.					

PAYMENT ADVICE

Your ref: AIG 'Insura	nce Vehi	cle No		sku	64297		_					
Claimant's Vehicle N	o	WES	2008	B			2					
Accident on 296											08	В
or sky frago			al	ong/a	T	aulst	ok	Au	e			
& skullysod Bildprd Ave	8 0	mda	y_ A	ve -	 		-			-	-	
	BREA	KDOW	IN O	F P	AYM	ENT	/s					
1. Repair Cost S\$	2,133	٥٣.	_ Pa	yable	to	Volksw	agen (Group	Singar	ore i	Pte L	.td _
2. Loss-of-Use/ Car Rental S\$_			– Pa	yable	to	BK	m		-	- 5	-	
3. Medical and Search Fees 5\$	_7.4	2 -	_ Pa	yable	to	Volksw	agen	Group	Singa	pore -	Pte I	.td
Remarks ;		70.7			T. T.		-	-		-	-	-
				-		5.7	-	-	-	-	-	*
Service Adviser Tan	g Shu Shi			-		-						
Contact No.H/P. 692	23502											



	SKU 6450D				
	SJWZOOBB				
Our Ref:	Ala		_		
То:	loid		-		
Dear Sirs,					
ACCIDENT INVO	€CW52 DNIV.	esb e sku	6429D	ON 246	2415
We are claiming	on behalf of our	client Megan	Ton Li	Shan	
owner of vehicle	number Sdw	2008B invol	ved in accid	lent on 24	6/2019
		111101	ACM III BOTH		
with vehicle SK	M6420D	_along/at Tavisto)			
with vehicle <u>SK</u>	M6420D				& Cowdray
with vehicle SK	M6450D ims: \$	_along/at <u>Tavisto</u>) 2, 133.40	k Ave Bi	rdport Ave	& Cowdray
with vehicle <u>SK</u> Description of cla Cost of Repairs Loss of Use/Rent	M6450D ims: \$	_along/at <u>Tavisto</u>) 2, 133.40	k Ave Bi	rdport Ave	GST) _(Incl 7% GST)
with vehicle <u>SK</u> Description of cla Cost of Repairs	M6450D ims: \$ al \$	_along/at <u>T</u> avisto) 2,133.48	k Ave Bi	rdport Ave	GST) (incl 7% GST) GST)

Kindly send us a written acknowledgement within 14 days from receipt of this document. Please note that finalization/settlement offer of this claim should be within 8 weeks from the date of this document. Please email all settlement offers to shushi.tang@vw.com.sg / steven.chee@vw.com.sg.

0 6 AUG 2019

payable to Volkswagen Group Singapore Pte Ltd.

SINGAPORE 81030002

Jia Le (LKK Auto)

From:

Jia Le (LKK Auto)

Sent:

Wednesday, 3 July 2019 11:48 AM

To:

'benny.chong@daimler.com'

Subject:

ACCIDENT INVOLVING SKU 6450D AND SJW 2008B ALONG/AT TAVISTOCK AVE

ON 24/06/2019

Our Ref: CC3/AIG19011633/da3

03 JULY 2019

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

Attn: Benny

Dear Sir/Madam,

ACCIDENT INVOLVING SKU 6450D AND SJW 2008B ALONG/AT TAVISTOCK AVE ON 24/06/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJW 2008B against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your passenger who opened the door and caused the incident. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further gueries.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: <u>Jiale@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT

(AIG Asia Pacific - Express Third Party Claim)

1. Megan Tan Li Shan	(the th	ird party claimant")
or 87702448D		(address), owner
of 50000188 (vehicle no.) hereby authorize ve	lkswagen Group Singapore Pte Ltd	_("the workshop")
to act for me with respect to my claim for repair co		of use ("claim") for
	amaged pursuant to the accid	
on 241 2019 (date) along Tavistock Av	e Birdport Ave Alaudry	Avenue (location)
involving vehicle no/s Stubend ("the accident		
I further authorize the workshop to settle my above	mentioned claim in a manne	er that they deem fit
and the workshop is further authorized to receive	payment further to settlemen	nt of my claim with
payment cheque/s being made in favour of the work	cshop.	
I further acknowledge that any settlement the wor		
prejudice and without admission of liability basis i	insofar as the driver/owner/i	nsurers of the other
vehicle/s is concerned.		
Dated this 15 (day) of 7 (mont	h) 20 <u>14</u> (year)	
No.	SINGAPO	GEN P ORE
Signed by "the third party claimant"	Signed by "the work	0.2 Shep
(with chop if applicable)	(with cho	op)

Volkswagen Centre Singapore



Biz Reg. No. 53303069E GST No. M20098505-2

LETTER OF AUTHORITY

BY THE LETTER OF AUTHORITY, I/WB. Mugan Tan Li Shan
of S7704480 owner of Vehicle Registration
Number Singapore hereby irrevocable appoint Volkswagen Centre Singapore
(hereinafter refer to VGS), a company incorporated in Singapore and having its registered office at 247 Alexandra Road, Singapore 159934, its agents of any person authorized by VGS to be "my / our Attorney n * my / our name(s) on *my / our behalf to do all or any of the following:
To submit, resolve and make any claim(s) (including the commencement of legal proceedings) which *I/we have against the other *party/parties to the Accident and under the insurance *policy/policies taken up by sit party/parties or alternatively under Insurance Policy number
To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be ma way of Cheque in favour of Volkswagen Centre Singapore and give a valid receipt and discharge therefore
For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever in relation thereto.
Generally do all such acts as it shall deem necessary for the purpose of settling such claim.
I/We hereby declare that all acts, instruments and documents done by virtue of this letter of authority on *n
behalf by the Attorney, its agents or any person authorized by VGS in that behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by *me/us in *me own proper person(s) and *I/we hereby ratify and confirm, all acts, instruments and documents done or execute of the authority and powers hereby conferred.
effectual to all intents and purposes whatsoever as if the same had been done or executed by "me/us in "mown proper person(s) and "I/we hereby ratify and confirm, all acts, instruments and documents done or exe
affectual to all intents and purposes whatsoever as if the same had been done or executed by *me/us in *moven proper person(s) and *I/we hereby ratify and confirm, all acts, instruments and documents done or exempt virtue of the authority and powers hereby conferred.
effectual to all intents and purposes whatsoever as if the same had been done or executed by "me/us in "mown proper person(s) and "I/we hereby ratify and confirm, all acts, instruments and documents done or exempt virtue of the authority and powers hereby conferred. *I/We hereby further declare that the letter of authority hereby conferred shall remain irrevocable. *I/We further confirm that the acceptance by VGS of the settlement amount in respect of such constitute the
effectual to all intents and purposes whatsoever as if the same had been done or executed by "me/us in "mown proper person(s) and "I/we hereby ratify and confirm, all acts, instruments and documents done or exempts of the authority and powers hereby conferred. "I/We hereby further declare that the letter of authority hereby conferred shall remain irrevocable. "I/We further confirm that the acceptance by VGS of the settlement amount in respect of such constitute the discharge of "my/our claim(s) in respect of such loss and damage.

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, VOLKSWAGEN GROWP STNARFORE PIE VIP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$\frac{\text{SS2,133.40}}{\text{Repair Cost}}\$, \$\frac{\text{SS171.20}}{\text{Loss of Use/Rental}}\$, \$\frac{\text{SS7.45}}{\text{Clisbursement}}\$ (Disbursement) for vehicle no. \$\frac{\text{SJW 2008B}}{\text{that was damaged pursuant to the accident which occurred on \$\frac{\text{24/06/2019}}{\text{(date)}}\$ along \$\frac{\text{TAVISTOCK AVE BRIDPORT AVE AND COWDRAY AVE}}{\text{(location)}}\$ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>MEGAN TAN LI SHAN</u> ("the third party claimant") of vehicle no. <u>SJW 2008B</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJW 2008B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 (day) of 8	(month) 20 19 (year)
(W)	VOLKSWAGEN GROUP SINGAPORE
MRB	
Signed by appointed surveyor	Signed by "the workshop" (with chop)

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue Singapore 639176 Biz. Reg. No.: 199101494Z GST No.: M200985052



1/2





Tax invoice

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120

Customer Details: Ms. MEGAN TAN LI SHAN 1 CACTUS CRESCENT Singapore 809710

Page 12333900800 Document no. 27-07-2019 Document date 5211043795 Customer no. Customer GST-ID 201009404M Dealer Job order number Job order date

Service Advisor

39999 2019001296/1 11-07-2019 TIOW CHUAN CHEE

License plate SJW2008B

Model code 7N14H3

First registration 29-09-2015

WVWZZZ7NZFV035079


Sharan succ. HL 147 TSID6F

Mileage 57.565

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
7N2857508AC9B9	Rear View Mirror Housing RH SIDE MIRROR HOUSING*XR-120719	1	pcs.	813.83	#1	813.83	870.80
	labour	0.5	pcs.	840.00	#1	420.00	449.40
	Spray Painting AIG DIRECT SETTLEMENT DOA: 24/06/2019 TP VEH: SKU8450D SURVEY BY: RASUL (LKK)	1	pcs.	280.00	#1	280.00	299.60

Tax Code	Labour	Material	GST%	GST	Total amount excl. GST	Total amount incl. GST
#1	480.00	1,513.83	7%	139.57	1,993.83	2,133.40
Total	480.00	1,513.83		139.57	1.993 83	2,133.40

Customer



Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

--VISIT OUR WEBSITE: altersales,vw.com.ag (for online service appointments) and volkswagen.com.ag and www.akoda.com.ag (for additional services, products and promotions).-

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier,

For warranty terms and conditions please visit our website www.volkswagen.com.sg

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue Singapore 639176 Biz. Reg. No.: 199101494Z GST No.: M200985062



2/2





Tax invoice

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120

Customer Details: Ms. MEGAN TAN LI SHAN 1 CACTUS CRESCENT Singapore 809710

Document no. Document date Customer no. Customer GST-ID Dealer Job order number Job order date Service Advisor

12333900800 27-07-2019 5211043795 201009404M 39999 2019001296/1 11-07-2019 TIOW CHUAN CHEE

License plate SJW20088

Model code 7N14H3

First registration 29-09-2015

WVWZZZ/NZFV035079

Model

Sharan succ. HL 147 TSID6F

Page

Mileage 57,565

This is an authorised document. No signature is required.



TAX INVOICE

GST REG. NO.: 200106276D

DATE	INVOICE NO.
26-Jul-2019	P 2625

INVOICE TO

AIG ASIA PACIFIC INSURANCE PTE. LTD. 78 SHENTON WAY #07-16 SINGAPORE 079120 ATTN: CLAIMS DEPARTMENT C/O: LKK AUTO CONSULTANT PTE LTD

	VHA NO.	DUE DATE	VEH. NO.
	P 2625	26-Jul-2019	SLN 4110 Z
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 23 JULY 2019 (0915 HRS) TO 24 JULY 2019 (1700 HRS) OUR REF: SJW2008B & SKU6450D (VOLKSWAGEN)	2	80.00	160.00
GST @ 7%			\$11.20
TOTAL			\$171.20

All cheques must be made payable to BKW Rent A Car Pte Ltd. Please write the vehicle and invoice number on the reserve.

BKW Rent-A-Car Pte Ltd

120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg A subsidiary of BKW Automobile Pte Ltd





BKW RENT A CAR PTE LTD

120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 20-0106276-D GST Reg. No: 20-0106276-D

24 HOURS HELPLINE: 6223 1122

VEHICLE HIRING AGREEMENT

VHA No: P 2625

Workshop: VW - MP

	HIRER	'S PARTICULA	150 July 15 15 1 25 10 1 10 10 10 10 10 10 10 10 10 10 10 1	Hirer's O		No: QT	W 20	ok Ree	place Veh No		
Name (as in I/C).	MEGAN -	TAN LI SH	KM	Loan Val		SLN 4			VR No		
NRIC/Passnort N	S7762	4480 Data of F	28-1-199	4		Hundan'		hoia	AutoMan		
Address: 6	Sevense	on aarden	Pise Age 4	1_ Make a	wooel, sa	-		111	· ·	- O-O-O-O	
	- XXII		st 22,43 P.	21		CHAR		90	Dec dec	1/-	cts
Name & Address	of Employer			Daily	2 +	day @		80	Per day	160	00
	N 100			Weekly/N	Aonthly	week (@\$	Per wee	sk/Monthly		1
Occupation		Driving	Exp: 21	Others							
Driving Licence N	Va:	Passed	Date: 12-9-19	17 CDW/PA	i	@\$		Per da	sy/Monthly		
Fall Turner Locality	CHEST SEPARATE			Trenvery.	Collection	Svc					
Tel(O)	(R)		HP 9688 74	63				GST			
		R'S PARTICUL		OR No:				(A) SI	UB-TOTAL		
				Petrol Level	- E	E 1/4	/ 1/2				+
77 27		NITTING TO SELECT		- Fersi Lave	OUT	V					-
NRIC/Passport N	lo:	Date of 8	Sirth:	Surcharge	IN						
Address:			Αρα:	First	km F	REE per day	y	GST	7%	11	20
					ileage is chi cents p	-		TOTAL	CHARGES	171	20
			Exp:	Ym	Contra p	WI SIII		Macro		17.1	_
Driving Licence N	lo:	Passed / E	xpiry Date:	Security	Deposit : 5	5			Bank:		
D/L Type: Local/Ir	nt'l/Others:		Contact No:	CASH/N	ETS/VISA	MCIAMEX	CHO N	0:376	218758	3730	09
	島〇	1	4		_	Card I					
INDICATE: A - Accidents D - Dents				See C		Tyre Open		☐ Petrol	ap 🗋 Rad Cap 🗋 Spar	re Tyre	
S - Scratches X - Crack	1	17	6日	SINGAPO	ORE Use C	Inly					
payable under t	this agreement a	and for parking and	n both sides of this ag traffic infringements in nformation. I have be	nay be billed to the	hat accoun	t and my s	ignature	above w	ill be conside	ered to have	ve been
years and be and qualifie damages of 2. All vehicles. A service of he fail to ret. 3. No mand in for any laim where applied day notal. 4. Use of the vehicle strick without price penalty fee of noo-discide. The hirer an caused, all whatsoever 7. The hirer and the care of	nd the authorized e holding valid and driving experied outs to be Barne b are supplied with surge of \$5 on top surge of \$5 on top surge of \$5 on top surge of \$5 on top surge of \$6 on the pattern of the rate is subtle. Any return retiside for illegal p trafficiancy, among city for 5 impapers or written content of \$200 in addition source of Malaysia adder driver shall be presson in respect didner driver shall be reason in respect didner driver shall be source of the supplied and the driver shall be and the supplied and the supplied and and and and and and and an	wing licenses and have noe. Failure to observe by the Hirscittle Author petrol and should retu- or a petrol surcharge the appropriate petrol enicle. The hirs made shown per hour per da- shown per hour per da- ter only and may not of EKW Bent A Car Ph nat to the appropriate sarage. e responsible for all di- nes and penalties impli- of or in connection wi-	med with petrol level like is payable by the hirer shi level. be liable for additional ch y, inclusive of CDW and/ ours will be charged as a in connection with theft.	se 65 suffere vehicle for a special in the control or a sp	id or incurred, Full excess, Full excess, Full excess, where reserve ed. Any dams to see small e.g. at of remover rer agrees, it keys maide event the ow courrence, it is and of an accomplisher and see of accident results from all and of an accomplisher and see of complete are as sufficient water. An accompany of the see of complete as a complete are of complete as a complete and	d by you in n is amount has amount has a the right no lage to the comoking and it is cigarette, dog the offensional a punctua of verticle, biner's 24-Hothe Hierar shall, the hierar shall, the hierar shall, the hierar shall to be the comoking down. So have the rent and do not will be kept timit the shall be the propertion of the properties of the properties of the shall the properties of	respect of the beginning of the replacement of the replacement of the same of	the vehicle vehicle immediate control pets in the set's smediate or pet's harmony pets one not cought cost of as cost of cost of cost	and howseeve a or the use or dataley in the e- accement vehicle kW authorized kW authorized the vehicle are to he even so or between \$2 or tank, loss of oratibite a breat wice is called us uch response a of the hire not have to be a ure that the rad whice is stall are bear by the hire not have to be a ure that the rad whice is stall are bear by the life.	the operation of an a color of an a color of an accidence of workshop, not allowed or disver shu 00 - \$400, wehicle's ke kidown and pan in responsible of the color of the col	on of the coldent, dent I. Any all bear ey or that and to r trip, dent borne stely in
Date Out	Time Out	Mileage	Check By	Ren	narks			1	*//	T	-1
23-7-19	0915	45228	kiki						Sprijer Signat		
Day And Time Tr	he Vehicle Is Retu	rned To BKW Rent A (In The Column "Signatur Car Pte Ltd And The Sam red my belonging items t	e Shall Be Accepte	d As Conclu	sive Evident	ce Of The	Same An			
Date in	Time In	Mileage	Check By		narks			M	\	4	T.
24-07-19	1700	45317.	icile i					Hiller	Signat		-

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

01 Jul 2019 / 12:05:21

Receipt Date/Time: 01 Jul 2019 / 12:05:21

Tax Invoice/Receipt

Receipt No.: ITNET-00000-190701-001367

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference		Amount Before	GST Amount	Amount After GST
	No.		GST (S\$)	(55)	(S\$)
Resul	t of Insurance Enquiry - SKU6450D				
As at	24 Jun 2019/08:30:00				
Insura	ince Co: AIG ASIA PACIFIC INSURAL	NCE PTE, LTD.			
	Insurance Enquiry - SKU6450D				
	Enquiry Fee 20190701120410489062		7.00	0.49	7.49
	EU 1897 UT EU T 10 T G G G G G	Sub-Total	7.00	0.49	7.49
		Total Before Rounding	7.00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		xxxxxxxxxxxxx6171	Credit Card: Visa/MasterCard		7.45
		Total			7.45
		Cash Change			0.00
		Tendered Amount			7.45
		Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report) Express

LAIM SUB	FOLDER TRA	CKING									
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	Status	6	
Main	26 Jun 2019 Edit Reg		04 Jul 2019 00:00 Edit Adj Rpt	S\$1,993.83 Edit Estima			993.83 w Rpt	Pending for Surve Report Cancel Case			
	Main) R	eference	Clair	m Deta	nils		Documents		Show All	
CLAIM SU	BFOLDER DE	TAILS					[Created	by adjuster]			
Insured:	DAIMLER	FLEET MANAGE	MENT SINGAPORE	PTE. LTD, C	o. Reg	No.:	199803778	BZ.			
Main Claimant:	MEGAN T	AN LI SHAN, II	D: 57702448D								
Vehicle Reg No.:	SJW200	8B		De	te of L	.065		9 00:00 - :59 s and 26 Days From	LTA Re	Date (Man Yr)]	
Claim Type	TP / 045	9559692SG			licy/Co ete No.		(Comprehe	ensive)			
Vehicle Reg No. (Insured):	SKU6450	D			licy No laiman		10695825				
				Ex	cess:						
Repairer:	Volkswag 63057299	en Group Singa	pore Pte Ltd (Maci	Pherson) 1 Ka	mpong	Amp	at, Singapo	re 368314, 368314	Macpher	son - Tel:	
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel: 65-6	419-30	00	. [Handled t	y MdNoor, Norsia	h) Norsi	ah.MdNoor@aig.co	
Claimant's Insurer:	Aviva Ltd	(HQ) - Tel: (65)	6827 9966								
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	andled	by M	OHD RASU	L] [Final Rpt	due 10	/07/2019]	
ASSOCIAT	ED MAIL RE	CEIVED						View	AII I	Compose Case Mail	
AIG_SG	EXPRESS (16	/08/2019): Alert	- Adj Mandate App	proved (5\$23	12.05)	- SJ	W20088 -	Claim Handler: Mo			
ALL ASSO	CIATED TAS		voisiones menorana	OF ESHOUSTER	UE	_			ate New	Task Complete	
	Priority	Type Task	Group Subjec	t Handler	As	ssign	ed By	Completed On	Crea	ted On Done	

Claim Documents

*SJW2008B (0459559692SG)

[SKU6450D]

TP

MEGAN TAN LI SHAN

Jun 24 2019 12:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD]

Volkswagen Group Singapore Pte Ltd

Let	ters/Corresponder	nces	1 per	page 🔽	V
Νo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	(Draft)	Third Party Express Settlement – Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page V	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	LA. MILT.	Thumbnail	-
t	16/08/19 14:57	Adjuster Immediate Advice	0	Load HTM	
		The state of the s			
	otos/Images	The state of the s	3 per	7	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	
1	16/08/19 14:38	Odometer Reading	0	Load JPG	₩.
2	16/08/19 14:38	Chassis Number	0	Load 3PG	W
3	16/08/19 14:38	General View	0	Load JPG	M
4	16/08/19 14:38	General View	0	Load JPG	V
5_	16/08/19 14:38	General View	0	Load JPG	\mathbf{Z}
6	16/08/19 14:38	General View	0	Load JPG	N
7	16/08/19 14:38	General View	0	Load JPG	V
8	16/08/19 14:38	General View	0	Load 3PG	W
9	16/08/19 14:38	General View	0	Load JPG	3
10	16/08/19 14:38	General View	0	Load JPG	V
11	16/08/19 14:38	General View	0	Load JPG	V
12	16/08/19 14:38	General View	0	Load JPG	V
13	16/08/19 14:38	General View	0	Load JPG	W
14	16/08/19 14:38	General View	0	Load JPG	V
15	16/08/19 14:38	General View	0	Load JPG	1
16	16/08/19 14:38	General View	0	Load JPG	V
17	16/08/19 14:38	General View	0	Load JPG	V
18	16/08/19 14:38	General View	0	Load JPG	V
19	16/08/19 14:38	General View	0	Load JPG	V
20	16/08/19 14:38	Reinspection Photo	0	Load JPG	W
21	16/08/19 14:38	Reinspection Photo	0	Load JPG	V
22	16/08/19 14:38	Reinspection Photo	0	Load JPG	V
23	16/08/19 14:38	Reinspection Photo	0	Load 3PG	8
24	16/08/19 14:38	Reinspection Photo	0	Load JPG	V
25	16/08/19 14:38	Reinspection Photo	0	Load JPG	₩.
26	16/08/19 14:38	Reinspection Photo	0	Load 3PG	2
27	16/08/19 14:38	Reinspection Photo	0	Load JPG	Ø
28	16/08/19 14:38	Reinspection Photo	0	Load JPG	₩.
29	16/08/19 14:38	Reinspection Photo	0	Load JPG	Ø.
30	16/08/19 14:38	Reinspection Photo	0	Load JPG	N.

Lett	ters/Corresponder	nces	1 per	page V	N
tio	Finalized Cm	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
31	16/08/19 14:38	Reinspection Photo	0	Load JPG	V
32	16/08/19 14:38	Reinspection Photo	0	Load JPG	V
Doc	umentation	8	1 per	page v	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/07/19 18:13	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT	0	Load PDF	
2	05/07/19 16:11	TP ESTIMATE	0	Load PDF	
3	26/07/19 14:06	BKW - RENTAL RECEIPT	0	Load PDF	
4	16/08/19 14:31	INVOICE	0	Load PDF	
5	16/08/19 14:31	LTA SEARCH FEE	0	Load PDF	
6	16/08/19 14:35	TP ESTIMATE - MARKED	0	Load PDF	
7	22/08/19 12:22	MANDATE APPROVAL EMAIL	0	Load PDF	
8	06/09/19 08:56	AUTHORISATION TO ACT FORM	0	Load PDF	
9	06/09/19 08:56	Release Voucher	0	Load PDF	
10	06/09/19 08:56	LETTER TO OI	0	Load PDF	
11	06/09/19 08:56	LOD	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/07/19 10:00	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SU

т	_			
	,	-	. n	л
	-	_	u٠	••

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

ver	nicle No:	SJW2008B (TP veh)						-	Model:				TSI (A)			
Date of Accident: 24/06/2019																
Glo	bai Sum Settlem	nent	:	1	1	Yes		(1	(1	No		1				
_	pair Estimate		1	-	-		: \$	- 1	- 4		31.18					
Fina	al Repair Cost						:\$			2,13	3.40					
Los	s of Use						: \$						d	ays	at \$0.00 per d	ay
Rer	ntal (if any)						:\$			17	1.20	2	d	ays		
LTA	A / GIA Search F	ee					: \$				7.45					
Oth	ers:						:\$			I.	0.00	1				
							:\$					1				
Fina	al Settlement Su	m					: \$			2,31	2.05	1				
ls T belo	hird Party Worl	ksho	p G	IA R	egis	tered	?	1	1	YES	[x j	NO		(Kindly indicat	е
A)	For Non GIA R	egist	tere	d W	orks	hop:		1	Agre	ed Lia	bility		100_		_(%)	
B)	For GIA Regist BOLA Liability:			((%)			7	Asse	ssed l	Liabil	ity (*):			LA Scenario N (%)	
Ren	* Assessed Liai narks	bility	10 00	o Title	ed or	nly for	chair	o colli	sion	s and	tor c	ases v	vnere t	BOL	A does not ap	oly.
Pay	ment Instruction	n: P	ayee	o's B	Break	kdowr	1									
1)	Volkswagen G	roup	Sing	gapo	re P	te Ltd				: \$					2,	140.85
2)	BKW Rent -A-0	CarF	te L	td						: \$					1	71.20
3)										: \$						
4)										: \$						
	JOANNE L		100,000	111	120011.11				20	Sep 119						

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG19011633/R1DA3Q2

Date:

06/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No:

SJW2008B

Insured Vehicle No:

SKU6450D

Date of Loss:

24/06/2019

Nature of Claim:

TP

Claim No: 0459559692SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SJW2008B

Make & Model:

VOLKSWAGEN SHARAN, 2.0 TSI (A)

Engine No:

CCZ481847

Reg. Date: Colour:

Grev

29/09/2015 (Man. Year: 2015)

Chassis No: Odometer:

WWWZZZ7NZFV035079 56681 km

Engine Capacity:

1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side: Front Right Side: Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,358.86	813.83	545.03	40.11
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,960.00	1,180.00	4,780.00	80.20
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,318.86	1,993.83	5,325.03	72.76
	+ GST 7.00/7.00% (S\$)	512.32	139.57	372.75	72.76
	Nett Amount (S\$)	7,831.18	2,133.40	5,697.78	72.76
	+ Car Rental (2.0 x S\$80.00/day	+ 7.00% GST) (S\$)	171.20		

+ Doc/Search Fee (S\$)

Nett Liability (S\$)

INSPECTION

Date of Assignment:

04/07/2019

Date Inspected:

04/07/2019 Inspected At:

Volkswagen Group Singapore Pte Ltd

(MacPherson)

1 Kampong Ampat, Singapore 368314

Singapore 368314

7.45

2,312.05

Estimated Period of Repair:

2.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen p... 6/9/2019

Adjuster: MOHD RASUL Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR VIEW MIRROR HOUSING RH SIDE MIRROR HOUSING	Cracked	813.83 FS	*813.83 FS
2	1		*MIRROR CAP PRIMED RH	Not Necessary	125.22 FS	*-FS
3	1		*MIRROR GLASS RH	Not Necessary	176.71 FS	*-FS
4	1		*WINDOW SLOT SEAL ALUMINIU RH	Not Necessary	243.10FS	*-FS
F=Franchise part. S=SpcNett.		Total Parts (S\$)	1,358.86	813.83		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	DIAGNOSITIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	PANEL REPAIR AND STRAIGHTENING	New	2,520.00	420.00
4	SPRAY PAINTING MIRROR HOUSING	New	280.00	280.00
5	SPRAY PAINTING	New	2,400.00	0.00
		Gross Labour Cost (S\$)	5,960.00	1,180.00
	Report was uns	submitted during this print-out.		

< END OF ESTIMATES >