

INSURANCE

INS. CASE OWNER

CC 4/III1901 1691, Keas

LJK

IDAC

Surveyor:

CSC

DOI:

ASSIGNMENT

2/3/19

Date / Time:

2/3/19

Registered in Merimen:

2/3/19

Pre-assign / CCU / FTE

SH 8215C



Insured Vehicle No. :

COMFORT TRANSPORTATION PTE LTD

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A.:

30/6/19

Place of Accident :

Is driver the owner? (YES) (NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES) (NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLM 3083E



INSRS:
WSP: Esteem
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
16/7/19	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/>
	Release Voucher	<input checked="" type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/>
	Car Rental Invoice	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / CIA :	<input checked="" type="checkbox"/>
	Medical Bill	<input type="checkbox"/>
	PIR	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: ksc

Repair Cost: RRP \$52,884.49 (2 days) Reduction: 32 % Email Call

FINAL SETTLEMENT Date/Time: 19.12.19 Confirm with: CARMAN Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 26. If NO or B 28, Ass. Lia :

Repair Cost: 0/162 \$52,337.63

Loss of Rental (LOR): \$5 25.80 (3 days) x 871.99

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GLA/LTA Search: \$5 7.99

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$52,560.93 Global Sum SS:

FINAL PAYMENT Date/Time: 19.12.19 Confirm with: CARMAN Email Call

Payee 1: \$52,560.93 Name 1: ESTEEM PERFORMANCE PTE LTD

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT 14/11/2020

ASS. REC. BY:

REF: TU /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Estcom

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.2% % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLM 3083E Yr Regn: 03, 17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour: M. P. White A/C: Insured / Std / NI / NA

Sp. Reading: 175558 T/Radio: Insured / Std / NI / NA

Eng/No: _____ C/No: JTDKB3FU1103554516

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm - R/Bal. 7 mm

L/Bal. 6 mm L/Bal. 7 mm

D.O.A. 30/6/19 D.O.I. 2/7/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or RA O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>
	<u>PIP: +2,184.69 (RED: +1,035.65 32%)</u>

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____

\$ - RS. \$

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLM 3083 E
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU103554516

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (motor)	1			
2	RH wing mirror (glass)	1	\$1,374.20		✓
3	RH wing mirror (signal lamp)	1			
4	RH wing mirror (cover)	1	\$87.40		X
5	RHF door glass	1	\$670.30		✓
6	RHF door glass outer moulding	1	\$121.75		✓
7	RHF door quarter glass pillar	1	TBA		X
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 2 July 2019 9:43 AM
To: serence ctc; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Carmen Lim; jenny chong; Manivel Priyadarshini
Subject: RE: REQUEST FOR PRI SURVEY
Attachments: ITNET-00000-190701-002561.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLM3083E and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: serence ctc [mailto:serence@esteemperf.com.sg]
Sent: 01 July, 2019 7:39 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Carmen Lim <carmen@esteemperf.com.sg>; jenny chong <jenny@esteemperf.com.sg>
Subject: Re: REQUEST FOR PRI SURVEY SLN 3083 E

Dear Sir/Madam

We are prefer LKK Auto Consultants Pte Ltd - Kenneth to survey the car.

Thanks



Freundliche Grüße / Best Regards

Serence Chee


Claims Assistant | Operation Division
Esteem Performance Pte Ltd

Veh lu - Kenneth

P: 6566 2112
E: serence@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)
385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



On Mon, Jul 1, 2019 at 5:11 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: serence ctc [mailto:serence@esteemperf.com.sg]
Sent: 01 July, 2019 3:48 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Carmen Lim <carmen@esteemperf.com.sg>; jenny chong <jenny@esteemperf.com.sg>
Subject: REQUEST FOR PRI SURVEY SLN 3083 E

Dear Sir / Madam,

Accident involving SLN3083E & SH8215C on 30.06.2019 at 19:50

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SLN 3083 E.

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385 SIN MING DRIVE (S) 575718 (INSIDE VICOM)

Tel : 6566 2112 / 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We will email GIA once receive

Thank you



Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6566 2112

E: serence@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SLM3083E (MCT19060789)**
[SHB215C]

IP
GRAB RENTALS PTE LTD
Jun 30 2019 12:00AM

Esteem Performance Pte Ltd - Sin Ming

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/07/2019 16:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLM3083E - Claim Handler: Priya

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 Jul 2019 16:04	Cim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	02 Jul 2019 16:04	Cim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	02 Jul 2019 16:04	Cim Created	Reg No: SLN3083E. Acct Date: 2019/06/30. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Esteem Performance Pte Ltd - Sin Ming (HQ)	[A] Lau Shu Pei
4	02 Jul 2019 16:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	02 Jul 2019 16:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/11	[A] Lau Shu Pei
6	02 Jul 2019 16:04	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	02 Jul 2019 16:05	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	02 Jul 2019 16:05	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
9	03 Jul 2019 15:15	Cim Dtl Modified	Claimant's Name: - -> GRAB RENTALS PTE LTD. Claimant's ID: -> 201617200G.	[A] Lau Shu Pei
10	03 Jul 2019 15:15	Cim Veh Model Changed	(206086) -> (205436) TOYOTA PRIUS HYBRID 1.8 CVT (A).	[A] Lau Shu Pei
11	03 Jul 2019 15:16	Cim Registration Modified	Reg No:SLN3083E->SLM3083E.	[A] Lau Shu Pei
12	10 Jul 2019 16:06	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: BOLA 26. OID passenger open door	[A] VIVIAN LAU PEI FENG
13	10 Jul 2019 16:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/11	[I] Priya
14	10 Jul 2019 16:44	Adj Mandate Set	Approved:0.00.	[I] Priya
15	11 Dec 2019 11:44	Adj Rpt Initiated		[A] Asher Sng Rong Yi
16	11 Dec 2019 11:45	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD. Insured ID: -> 199303821R.	[A] Asher Sng Rong Yi
17	11 Dec 2019 11:45	Cim Dtl Modified	JPJ Reg. Date: -> 2017/03/27.	[A] Asher Sng Rong Yi
18	11 Dec 2019 11:45	Cim Details Notified		[A] Asher Sng Rong Yi
19	11 Dec 2019 14:36	Adj Mandate Request	Cur.Req:2560.93:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$2,337.62 + (b) LOR : \$215.82 (3days x \$71.94) + LTA : \$7.49 Total: a+b+c = \$2,560.93 VEH MODEL: TOYOTA PRIUS HYBRID 1798cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS,	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[16/07/2019 10:25] VIVIAN LAU PEI FENG:
liability clear via merimen
[10/07/2019 16:06] VIVIAN LAU PEI FENG:
seek liability via merimen

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name	Ref 1	Ref 2	Amount
-------------	-----------	-----------	----------	----------	---------	-------	-------	--------

12/12/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SLM3083E (MCT19060789)**
[SH8215C]

TP

GRAB RENTALS PTE LTD

Jun 30 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]
Esteem Performance Pte Ltd - Sin Ming

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/12/2019 16:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2560.93) - SLM3083E - Claim Handler: Priya

Approved:2560.93:Request TP WS to issue Tax invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019 Edit Reg		02 Jul 2019 00:00 Edit Adj Rpt	S\$2,184.69 Edit Estimates	S\$2,184.69 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G									
Vehicle Reg. No.:	SLM3083E	Date of Loss:	30/06/2019 00:00 - :59 [27 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19060789	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH8215C	Policy No. (Claimant):	A29114756MKF						
Excess:									
Repairer: Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (11/12/2019): Alert - Adj Mandate Approved (S\$2560.93) - SLM3083E - Claim Handler: Priya • III_SG (10/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SLM3083E - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM3083E (MCT19060789)
[SH8215C]
TP
GRAB RENTALS PTE LTD
Jun 30 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Esteem Performance Pte Ltd - Sin Ming

Upload Documents		Upload Photos		Compose New Letter		View View in Browser		
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
2	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
3	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
4	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
5	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
6	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
7	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
8	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
9	11/12/19 14:31	Odometer Reading				Load JPG	<input checked="" type="checkbox"/>	
10	11/12/19 14:31	General View				Load JPG	<input checked="" type="checkbox"/>	
11	11/12/19 14:31	Chassis Number				Load JPG	<input checked="" type="checkbox"/>	
12	11/12/19 14:34	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>	
13	11/12/19 14:34	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	02/07/19 16:05	EMAIL FROM III DD 02072019				Load PDF		
2	03/07/19 18:05	TP ESTIMATE- MARKED				Load PDF		
3	03/07/19 18:05	TP GIA REPORT				Load PDF		
4	11/12/19 14:13	WORKSHOP INVOICE				Load PDF		
5	11/12/19 14:13	RENTAL RECEIPT				Load PDF		
6	11/12/19 14:13	LTA SEARCH				Load PDF		
7	11/12/19 14:13	LOD				Load PDF		
8	15/01/20 10:47	AUTHORISATION TO ACT FORM				Load PDF		
9	15/01/20 10:47	DISCHARGE VOUCHER				Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)				Thumbnail	Print	
1	03/07/19 08:57	Singapore Accident Statement				Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19011691/KEA3Q2

Date: 15/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SLM3083E Insured Vehicle No : SH8215C
 Date of Loss: 30/06/2019 Nature of Claim: TP Claim No: MCT19060789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM3083E
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS030875
 Reg. Date: 27/03/2017 (Man. Year: 2017) Chassis No: JTDKB3FU103554516
 Colour: White Odometer: 175558 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,690.24	1,624.69	65.55	3.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	560.00	970.00	63.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,220.24	2,184.69	1,035.55	32.16
+ GST 7.00/7.00% (S\$)	225.42	152.93	72.49	32.16
Nett Amount (S\$)	3,445.66	2,337.62	1,108.04	32.16
+ Car Rental (3.0 x S\$71.94/day) (S\$)		215.82		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,560.93		

INSPECTION

Date of Assignment: 02/07/2019 Present Location: 2184.69
 Date Inspected: 02/07/2019 Inspected At: Esteem Performance Pte Ltd - Sin Ming (HQ)
 385 Sin Ming Drive
 Singapore 575718
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2019)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM3083E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*RH WING MIRROR (GLASS) }	Broken	1,374.20 FL	*1,374.20 FL	
2	1		*RH WING MIRROR (MOTOR) }		0.00 FL	*- FL	
3	1		*RH WING MIRROR (SIGNAL LAMP) }		0.00 FL	*- FL	
4	1		*RH WING MIRROR (COVER)	Serviceable	87.40 FL	*- FL	
5	1		*RHF DOOR GLASS	Cut	670.30 FL	*670.30 FL	
6	1		*RHF DOOR GLASS OUTER MOULDING	Cut	121.75 FL	*121.75 FL	
7	1		*RHF DOOR QUARTER GLAS PILLAR (NPA)	Serviceable	0.00 FL	*- FL	
					Sub Total (\$\$)	2,253.65	2,166.25
					- List Item Discount on L Items 25.00/25.00% (\$\$)	563.41	541.56
					Total Parts (\$\$)	1,690.24	1,624.69

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (RHF DOOR ,RHF FENDER,RHS MIRROR)	New	600.00	150.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (RHF DOOR,RHF FENDER ,RHS MIRROR)	New	600.00	280.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT RHF DOOR GLASS	New	120.00	60.00
5	TO TUFF COAT	New	100.00	0.00
6	TOWING	New	60.00	50.00
Gross Labour Cost (S\$)			1,530.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >