

22/03/2002

ASS. REC. BY:

REF: CS3/AIG19011701/Gcd302

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Chin Lee Ying of ALG Date/Time: 2/7/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 5432 A. Insured: FBH 9504 M

at Workshop m/s Caremith Pte Ltd. Tel: 90910000

of 13 Kaki Bukit Rd 4 #01-20

Policy No: 1900097270 Claim No: 593994099556

Sum Insured: Excess:

Make of Veh: D.O.A. 28/6/2019.
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2/7/19. Person Contacted: Alex. Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBH 9504 M : X
	SLG 5432 A : X
	Dismantle: 2/7/2019
	After repair: 8/7/2019

Surveyor

PRS
GEL

REF: ALG


71521

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Carsmith
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 5432A Yr Regn: 04 Oct 2016
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda vezel C.C. 1496
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 50390 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: RU1120 6300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 215 / 60 R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 02-07-19

Survey held at W/S 3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format : DAR

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS, \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____) ☐ : _____

Survey Fee:

Transportation:

Photos

Others

TOTAL

180

11

101

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019 Edit Reg		03 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	MOHAMMED SADHIK SHANSHA S/O SALEEM MOHAMMED, ID: S9618562F		
Main Claimant:	HOW CHENG BOON, ID: S8617192I		
Vehicle Reg. No.:	SLG5432A	Date of Loss:	28/06/2019 14:00 - :59
Claim Type:	TP / 5939940995SG	Policy/Cover Note No.:	1900097270 (Comprehensive)
Vehicle Reg. No. (Insured):	FBH9504M	Policy No. (Claimant):	
		Excess:	
Repairer:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/07/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (04/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 7/2/2019 10:39:08 AM

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: jiamin.mak@alt.sg
To: Yinrul.Hor@aig.com
Cc: AIGSGP_ClaimsSurvey@aig.com ,jerdine.wang@alt.sg ,vincent@alt.sg ,allister@alt.sg ,carsmithpl@gmail.com
Subject: [EXTERNAL] PRI - SLG 5432 A
Date: Mon, 1 Jul 2019 06:12:08 +0000
This message is from an external sender; be cautious with links and attachments.

Your Ref: FBH 9504 M

Our Ref: AL.INS.2019.SLG5432A

1 July 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL & FAX: 6835 7416 ONLY

78 Shenton Way

Tower 2 #07-16

Singapore 079120

Dear Sirs,

ACCIDENT INVOLVING SLG 5432 A & FBH 9504 M ALONG HOUGANG STREET 91 ON 28 JUNE 2019 AT ABOUT 1410 HOURS

We act for the owner of vehicle no. SLG 5432 A.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

CARSMITH PRIVATE LIMITED

13 Kaki Bukit Road 4

#01-20 Bartley Biz Centre

Singapore 417807

Person In-Charge: Alex / Wilson

Mobile Number: 9091 0000 / 8838 3318

veh in

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at jiamin.mak@alt.sg / jerdine.wang@alt.sg for future correspondences.

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	7192I
Vehicle No.:	SLG5432A
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	L15B4406303
Chassis No.:	RU11206300
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,169.00
Original Registration Date:	04 Oct 2016
First Registration Date:	04 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$13,037.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Oct 2026
PARF Rebate Amount:	\$9,777.00
COE Expiry Date:	03 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$36,263.00
Total Rebate Amount:	\$46,040.00

The information contained herein is correct as at 02 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/07/2019 10:27
Date Of Accident	28/06/2019 14:10
Exact Location Of Accident	HOUGANG STREET 91
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5432A
Insured/Policyholder	
Name Of Registered Owner	HOE CHENG BOON (HE QINWEN)
NRIC No	S8617192I
Email Address	BR1AN.HOE2021@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97533773
Alternative Phone No	OTHERS-97533773

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084732593-02
Cover Note Number	

Driver

Name of Driver	HOE CHENG BOON (HE QINWEN)
NRIC No	S8617192I
Date Of Birth	20/06/1986
Occupation	INDOOR
Date Of Driving Pass	11/05/2009
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97533773
Fax Number	
Contact Number	OTHERS-97533773
Email Address	BR1AN.HOE2021@GMAIL.COM

Address	11 FERNVALE LANE #19-01 THE TOPIARY
Postcode	797495
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH9504M
Vehicle Make/Model/Colour	YAMAHA / FZ 16
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

2005/01/01/001

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415033
Reporting Name: **Singapore 415033**
Tel: 67416697
Fax: 67492305
Email: **vackh@singnet.com.sg**

GIA/IMC SKELTIP Form 1/05



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along hougang street 91 and slow down to turn left into Car Park 926-931 suddenly I felt a straight impact from my left so I alighted from my vehicle and I saw vehicle B which was behind my try to overtake me and collided onto my left side front portion of my vehicle. case Tyre rim, Front bumper side door damage

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GARLIC SketchPlanForm_V5

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Reporting Centre
Name:
Tel: 67416697
NRIC/FIN No.:
Fax: 67492305
Email: vackb@singnet.com.sg

Front Portion

Vehicle No: SLG5432A

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	Cut		
1005	992341	Frt Bumper Clips	MC		
1006	991325	Frt Bumper Bracket LH	GR		
1007	991462	Frt Bumper Side Retainer LH	RL		
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	X Repair		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	bu		
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector	Cut		
1100	991740	Frt LH Fender Inner Shield	TV		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	Cut		
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre	SCR		
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt LH Door	X repair		
		Frt LH wheel bearing	MC		

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 Edit Reg		02 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MOHAMMED SADHIK SHANSHA S/O SALEEM MOHAMMED , ID: S9618562F									
Main Claimant: HOW CHENG BOON , ID: S8617192I									
Vehicle Reg. No.: SLG5432A		Date of Loss: 28/06/2019 14:00 - :59 [32 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5939940995SG		Policy/Cover Note No.: 1900097270 (Comprehensive)							
Vehicle Reg. No. (Insured): FBH9504M		Policy No. (Claimant):							
		Excess:							
Repairer: Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (04/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG5432A (5939940995SG)

[FBH9504M]






































TP
















































HOW CHENG BOON

Jun 28 2019 2:00PM

[MOHAMMED SADHIK SHANSHA S/O SALEEM MOHAMMED]

Carsmith Private Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View In Browser	
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
2	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
3	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
4	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
5	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
6	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
7	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
8	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
9	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
10	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
11	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
12	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
13	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
14	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
15	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
16	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
17	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
18	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
19	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
20	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
21	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
22	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
23	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
24	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
25	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
26	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
27	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
28	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
29	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
30	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
31	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
32	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
33	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
34	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
35	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
36	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	
37	09/07/19 17:47	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	09/07/19 17:47	General View		Load JPG	<input checked="" type="checkbox"/>
39	09/07/19 17:47	General View		Load JPG	<input checked="" type="checkbox"/>
40	09/07/19 17:47	General View		Load JPG	<input checked="" type="checkbox"/>
41	09/07/19 17:47	General View		Load JPG	<input checked="" type="checkbox"/>
42	09/07/19 17:47	General View		Load JPG	<input checked="" type="checkbox"/>
43	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
51	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
52	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
60	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
61	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
62	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
63	09/07/19 17:47	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
64	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
65	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
66	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
67	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
68	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
69	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
70	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
71	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
72	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
73	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
74	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
75	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
76	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
77	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
78	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
79	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
80	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
81	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
82	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
83	09/07/19 17:48	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/07/19 10:35	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011701/GCD3E2

Date: 18/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900097270
Claimant Vehicle No : SLG5432A **Insured Vehicle No :** FBH9504M
 Date of Loss: 28/06/2019 Nature of Claim: TP Claim No: 5939940995SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG5432A**
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4406303
 Reg. Date: 04/10/2016 (Man. Year: 2016) Chassis No: RU11206300
 Colour: Green Odometer: 50390 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/07/2019
 Date Inspected: 02/07/2019 Inspected At: Carsmith Private Limited (HQ)
 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY
 BIZ CENTRE
 Singapore 417807
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET LH	Broken	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER LH	Deformed	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
6	1		*BONNET	Repair	0.00 F	*- F
7	1		*FRT LH FENDER	Buckled	0.00 F	*- F
8	1		*FRT LH FENDER PROTECTOR	Cut	0.00 F	*- F
9	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
10	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
11	1		*FRT LH TYRE	Scratched	0.00 F	*- F
12	1		*FRT LH DOOR	Repair	0.00 F	*- F
13	1		*FRT LH WHEEL BEARING	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >