

22/03/2002

ASS. REC. BY:

REF: CS3/III19011709/Ged302

Special Instruction:

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Gabriel

of

III

Date/Time:

2/7/2019

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLD 6858 P

Insured:

SHD 4085 M

at Workshop m/s

Motor Intelligence

Tel:

62810087

of

13 Kaki Bukit Rd 4 #01-20

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2/7

Person Contacted:

Ivy

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SHD 4085 M : X
	SLD 6858 P : X
	Dismantle: 3/7/2019 04:44 p.m
	After repair: 9/7/2019 03:18 p.m

ASS. REQ. BY

PRS
Cul.

REF:

III

C0430G

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLD 6858 P

at Workshop m/s Motor Intelligence

of 13 Kaki Bukit Rd 4 #01-20

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$45K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD 6858P

Yr Regn:

27 Jun 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Attrage

c.c

1193

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

192264

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NMBS TA 13AHM001685

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

185/55 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Roadstone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

02-07-19

Survey held at

w/s

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: West-end (\$)

Survey Fee:

120

Transportation:

S + RS, \$1

Photos

Office:

11

TOTAL

131

Report Format:

PRS

Lump Sum / L&B: (\$)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 2 July 2019 9:28 AM
To: Wendy Jiang; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Lua Siew Hui; Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD6858P (Accident involving SLD6858P and SHD4085M on 28.06.2019)[1907-7343](MI)(PD)]
Attachments: shd4085m_20190701161040.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLD6858P
III INSURED VEHICLE NO. : SHD4085M
DATE OF LOSS : 28.06.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Priya**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Veh In

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: 01 July, 2019 4:54 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Lua Siew Hui <lua_siewhui@rssolomon.com>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD6858P (Accident involving SLD6858P and SHD4085M on 28.06.2019)[1907-7343](MI)(PD)]

Good Afternoon Gabriel,

We refer to your email.

We write to inform that our clients will be appointing their own Surveyors.

In this respect, please arrange your surveyors to contact Ms. Ivy Pang of Motor Intelligence Automo Pte. Ltd. at tel no. 62810087 for a pre-repair survey of our client's vehicle located at 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Yours sincerely
Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Mon, Jul 1, 2019 at 4:44 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,



64 Cecil Street: #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	0430G
Vehicle No.:	SLD6858P
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6i
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	3A92UDH3823
Chassis No.:	MMBSTA13AHH001685
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,983.00
Original Registration Date:	27 Jun 2016
First Registration Date:	27 Jun 2016
Transfer Count:	2
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2026
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	26 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$32,129.00
Total Rebate Amount:	\$35,879.00

The information contained herein is correct as at 02 Jul 2019

OK

► Mitsubishi Attrage Used Vehicle List (8 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Mitsubishi Attrage 1.2A	\$43,988	\$6,370 /yr	04-Jan-2016	1,193 cc	41,000 km	Cycle & Carriage.Fulco Motor Dealer	Available

Vehicle With 5 Years Unlimited Mileage Warranty From The Date Of Purchase And 10 Years Engine Warranty By C&C, Well Maintained By 1 Owner. Economical And Low Maintenance.

Office No. - 67468117

Paul Yong - 97694879 | Alan Ng - 96710232

Mitsubishi Attrage 1.2A	\$47,800	\$6,910 /yr	20-Jan-2016	1,193 cc	73,402 km	Yong Lee Seng Motor	Available
--------------------------------	-----------------	-------------	-------------	----------	-----------	---------------------	------------------

Know More About The Car Through Vicom Evaluation Report, All Our Cars Are Vicom Evaluated! Free 6 Months Maintenance And 1 Grooming.

Office No. - 68440123

Richmond Tang - 96200045 | Raymond Tang - 96250045

Mitsubishi Attrage 1.2A	\$45,700	\$6,230 /yr	09-Jun-2016	1,193 cc	78,000 km	Seng Lee Hong Vehicle Trading	Available
--------------------------------	-----------------	-------------	-------------	----------	-----------	-------------------------------	------------------

Non PHV Car. 1 Owner Only. Free 3 Servicing. Full Servicing Records With Agent, Cycle And Carriage. Most Spacious Cabin In Its Class With Low Fuel Consumption. Low Depreciation. Loan And Trade In Avail...

Office No. - 64672802

Neo Poh Hau - 85885252 | Neo Lam Lee - 96202802

Mitsubishi Attrage 1.2A	\$49,800	\$6,760 /yr	30-Jun-2016	1,193 cc	34,000 km	Hua Yang Credit Pte Ltd	Available
--------------------------------	-----------------	-------------	-------------	----------	-----------	-------------------------	------------------

Fully Cycle And Carriage Servicing! 10 Years Engine Warranty! Excellent Condition! No Repair Needed! Buy With A Peace Of Mind! Attractive Loan Package From Interest 2.28%! Competitive Trade In Price! ...

Office No. - 64635111

Alvin - 82645711 | Kamen - 88621923

Mitsubishi Attrage 1.2A Sports	\$49,800	\$6,580 /yr	08-Sep-2016	1,193 cc	16,000 km	SE 2000 Motor Leasing Pte Ltd	Available
---------------------------------------	-----------------	-------------	-------------	----------	-----------	-------------------------------	------------------

Sports Edition With Body Kit. Agent Servicing With Low Mileage. Non Private Hire Car. Flexible Loan / High Trade In. Please Call For Viewing Now.

Office No. - 62192000

Sam - 98994499

Mitsubishi Attrage 1.2A	\$48,800	\$6,360 /yr	13-Oct-2016	1,193 cc	16,971 km	Corsica Trading	Available
--------------------------------	-----------------	-------------	-------------	----------	-----------	-----------------	------------------

Fully Cycle And Carriage Servicing! 10 Years Engine Warranty! Excellent Condition! 1 Owner, Low Mileage At 16971km, Guaranteed Non Private Hire/Leasing Car, Sports Rims, Leather Seats, Built In Audio ...

Office No. - 67775005

Woo Kok Wah - 90086666 | Kelvin Goh - 96786666

Mitsubishi Attrage 1.2A	\$49,800	\$6,390 /yr	24-Nov-2016	1,193 cc	33,177 km	Lake View Credit Pte Ltd	Available
--------------------------------	-----------------	-------------	-------------	----------	-----------	--------------------------	------------------

Guaranteed Non Private Hire/Leasing Car! Serviced At C&C With Proof. Amazing Low Mileage Done 33177km. Excellent Condition. 1 Lady Owner. New Paintwork. 100% Accident Free. Price Negotiable. Call Now!

Office No. - 67499895

Sunny - 90468282 | Jeffrey - 97268887 | Tong Hoe - 96433160

Mitsubishi Attrage 1.2A	\$49,800	\$6,380 /yr	30-Nov-2016	1,193 cc	66,811 km	Republic Auto	Available
--------------------------------	-----------------	-------------	-------------	----------	-----------	---------------	------------------

Agent Serviced And Maintained. Vehicle With 5 Years Unlimited Mileage Warranty From The Date Of Purchase And 10 Years Engine Warranty By C&C, Well Maintained By 1 Owner. Eligible For Up To 70% Loan Of...

Office No. - 65672000

Aloysius Tay - 96956596

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/07/2019 14:51
Date Of Accident	28/06/2019 20:55
Exact Location Of Accident	AIRPORT BOULEVARD ROAD TWRDS (PIE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD6858P
Insured/Policyholder	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD
Co Reg No	201320430G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63882323

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102734533
Cover Note Number	

Driver

Name of Driver	LOO SEA KUAN
NRIC No	S7344130G
Date Of Birth	03/12/1973
Occupation	OUTDOOR
Date Of Driving Pass	02/02/2009
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96477325
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 450 BUKIT PANJANG RING ROAD #14-595
Postcode	670450
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO: 67673650
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4085M
Vehicle Make/Model/Colour	HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SBV1299J

Vehicle Make/Model/Colour CHERY / T11 2.0L MANUAL ABS AIRBAG SUNROOF 2WD

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOO SEA KWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLD6858P

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address BLK 450 BUKIT PANJANG RING ROAD #14-595

Postcode 670450

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that;

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Reporting Centre
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT

(A) SLD6858P

(B) SHD 4085m

(C) SBV 1299J

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

IBANVC SketchPlanForm_V3

IDAC KAKI BUKIT(VAC)
 71 KAKI BUKIT AVE 4
 Reporting Centre
 Name: Singapore 413953
 Tel: 67416697
 NRIC/FIN No.:
 Fax: 67492305
 Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190629/2037

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

1 of 4

Report No. T/20190629/2037

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/06/2019 09:59	Vide Report No.:	Station Diary No.: 23
--------------------------------------------	------------------	--------------------------

Informant's Particulars

Name of Informant: LOO SEA KWAN	Address: APT BLK 450 BUKIT PANJANG RING ROAD #14-595 SINGAPORE 670450		
ID Type / ID No.: NRIC NO / S7344130G	Contact No.: Home/Office: Mobile: 96477325		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 45	Date of Birth: 03/12/1973	Type of Informant: Driver
Race: Chinese	Language: English		Institution / School Name:
Occupation: GRAB DRIVER	Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 28/06/2019 20:55	Type of Location: Straight Road
Location: Along Road 1 AIRPORT BOULEVARD Airport Bouvelard road towards Pan-Island Expressway (PIE)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SBV1299J	Car	CHERY		Silver	No Damage	1
SHD4085M	Car	HYUNDAI	Sonata	Blue	Seriously Damaged	1
SLD6858P	Car	MITSUBISHI	ATTRAGE 1.2 CVT	Red	Slightly Damaged	1

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190629/2037

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

2 of 4

Report No. T/20190629/2037

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ANG GEK PING	ID No.	S6975524J
Related Vehicle	SBV1299J (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHUA YONG KHNG	ID No.	S1041476H
Related Vehicle	SHD4085M (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LOO SEA KWAN	ID No.	S7344130G
Related Vehicle	SLD6858P (Car)	Contact No.	96477325
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28/06/2019 at about 2057hrs, I am driving my vehicle, SLD6858P, working for Grab and picked up a passenger at Changi Airport Terminal and proceeding to Jurong West. I was travelling on lane 3 of Airport Boulevard Road exiting towards Pan-Island Expressway (PIE) when a vehicle, SBV1299J, in front of me suddenly come to a complete stop. I was able to stop in time and avoid colliding into the rear of the vehicle. However, another vehicle, SHD4085M, travelling behind me, was unable to stop and collided into the rear of my vehicle.

After which, I stepped out of my vehicle to check on the damages and the other driver when I discovered

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



T/20190629/2037

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 4

Report No T/20190629/2037

CONTINUATION OF REPORT

that there is another vehicle behind which collided into vehicle, SHD4085M. All the drivers and passengers involved did not sustain any injury. We assessed the damages and my vehicle sustained dents to the rear and the other vehicle, SHD4085M, was totally unmovable and sustained damages to the front and rear. I was informed by the driver of SBV1299J that another vehicle had cut into her lane, causing her to stop. We exchanged particulars, and afterwards, tow truck came to shift vehicle SHD4085M away. The other drivers and I moved off afterwards to prevent congestion on the expressway.

I wish to state that at the point of time, the traffic condition was moderate and I was travelling at around 70km/h. The road surface is dry and the weather is clear. There is dash camera installed to the front of my vehicle. All drivers involved agreed to lodge a Police report and inform insurance regarding the matter. I will be seeking doctor regarding my back ache due to the incident.

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



T/20190629/2037

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

4 of 4

Report No. T/20190629/2037

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

CHOY ZHAN HAO

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

29/06/2019 09:59

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No: 65476151

SN 117

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019 13:54 Edit Reg		02 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: -									
Vehicle Reg. No.: SLD6858P		Date of Loss: 28/06/2019 00:00 - :59 [36 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHD4085M		Policy No. (Claimant):							
		Excess:							
Repairer: Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD6858P
[SHD4085M]

TP



















































-








































Jun 28 2019 12:00AM

[-]

Motor Intelligence Automo Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
2	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
3	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
4	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
5	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
6	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
7	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
8	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
9	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
10	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
11	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
12	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
13	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
14	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
15	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
16	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
17	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
18	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
19	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
20	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
21	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
22	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
23	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
24	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
25	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
26	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
27	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
28	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
29	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
30	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
31	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
32	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
33	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
34	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
35	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
36	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	
37	11/07/19 19:28	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/07/19 19:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/07/19 19:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/07/19 19:28	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/19 19:28	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/19 19:28	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/19 19:28	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
46	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
47	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
48	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
49	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
50	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
51	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
52	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
53	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
54	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
55	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
56	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
57	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
58	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
59	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
60	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
61	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
62	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
63	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
64	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
65	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
66	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
67	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
68	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
69	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
70	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
71	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
72	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
73	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
74	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
75	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
76	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
77	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
78	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
79	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
80	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
81	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
82	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
83	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
84	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
85	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
86	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
87	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
89	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
90	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
91	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
92	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
93	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
94	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
95	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
96	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
97	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
98	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
99	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
100	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
101	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
102	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
103	11/07/19 19:30	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
104	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	11/07/19 19:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/07/19 08:56	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19011709/GCD3E2

Date: 15/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLD6858P

Insured Vehicle No : SHD4085M

Date of Loss: 28/06/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD6858P**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UDH3823

Reg. Date: 27/06/2016 (Man. Year: 2016)

Chassis No: MMBSTA13AHH001685

Colour: Red

Odometer: 192264 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Roadstone 6 mm

Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm

Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/07/2019

Date Inspected: 02/07/2019 Inspected At:

 Motor Intelligence Automo Pte Ltd (HQ)
 13 KAKI BUKIT ROAD 4, #01-20
 BARTLEY BIZ CENTRE
 Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Jul 2019)

Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD6858P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >