23/03/2002 ASS, REC, BY:		REF: CS	INCIPOLI	718 Ug	d3n2 Specie	Instruction:	
Surveyor:	Marcus	AS	SIGNMEN	(Office)			0001 20
From (Person):	Hazalysa	of _	INC	7)	D	ite/Time:	1 plac 12/1
Estimated Cost			Б	ill to:			1 '
ob fre ws	TP RES / OD R	ES/EVA/IN	V/MV/CS				
To Inspect Vel	nicle No: SM	G 2316 K			Insured:	GBD 2	M-SFI
	us Blunel Lei Bukit Av				Tel: _	67452	088.
Policy No:		/		Claim No:	MT 105	0924-00	12
Sum Insured:				Excess:			
Make of Veh: (Client's Record	)				D.	7.CA.O	6/2019
CA / REV /	REP. / REV 24	HRS				H.O.D. Endorsem	ent:
_ Date/Time:	2/7	Person	Contacted:		····Vel	icle (IN) OU	Г
Date/Time	Action/Instructio	on ( × )	Estimate.				
	SMG:23161	C-X					
	GBD 2178-1						
		- /					

		INI

The Control of the Co	Date:	Veh No: SM G 25166	
Estimated Cost:		Type: (A.Car / M.Cycle / Bus / Van / Lor	ry / Taxi / Prime Mover /
OD TP/WS/TP RES/O	DD RES / EVA / INV / MV	Truck / Trailer or (A)	
To Inspect Vehicle No:	SMG 2316 K	Make: Worde Veze	1 Hypered 1496
William Control	unel	Colour Green	A/C: Insured / Std / NI / NA
of		Sp.Reading / 3 / 9/2	T/Radio: Insured / Std / NI / NA
Insured:		Eng/No:	10.0
Policy No.		C/No: _ RU3/	302495
Claims No.		Gen. Cond Good / Fair / Poor / Burnt	V
Sum Insured:	Excess:	Steering: (norde) / Jammed / Leaked / I	Burnt or
(Client's Record)		Brake: Inorder Jammed / Leaked / I	Burnt or
Make of Veh:		Modi: Ni / S/Rim / STD A/Rim or	/
		Tyre Size: F: 2/5/	53-217
(Policy Condition)		R:	
Remark: The veh had con	nmenced its N/S O/S	BS / DUN / EXNQVA / GY / FS / LIZA /	MIC / OHTSU / PIR / SUMI /
repair at the time	ne of inspection.	TOYO / YOKO Or	
Bal. or Market Value:	92/2	Front	Rear 1
IDAS Accident Rport:	Consistent? : Yes or No	R/Bal. 6 mm	R/Bal. O mm
GA/ PR Seen &	Consistent?: Yes or No	L/Bal. 6 mm	L/Bal. 6, mm
Est. Repairs: #	days Res.: Yes or No	D.O.A. 27/6/19	D.O.I. 2/7/18
Lum Sum: 20	% 3 Val.: Yes or No	Survey held at	10.43
	1 - 42 026	Des. of Damages : Frt / Rear / O/S /	N/S / U/C / Rooftop or
CA / REV / REP. /	24 HRS Vehicle: IN / OUT	10 010	
Date: Per	rson Contacted:	The U/C / Chassis frame / Body	Structure affected due to collision.
	/ Instruction		
	ata Estrala		
	of of the late		
	200	1	1 & learn on x1-17
	\$ 3900 confirm	I will MR Yap. CR	2d 8 4977 80, 56%)
	ofy Estimbor Confirm		2d 8 4977.80, 56%)
	\$3900 confirm		2d & 4977 80, 56%)
			2d 8 497780, 56%)
			2d 8 497780, 56%)
s/7/19 4/5	RECEIVED	7 JUL 2019	2d 8 4977.80, 56%)
Date/Time, File Pass 107	RECEIVED 1	7 JUL 2019  Days Of Repair: 4	
s/7/19 4/5	RECEIVED	7 JUL 2019	Survey Fee:
Date/Time, File Pass to?  1) 12/3 Human  Date/Time, File Potum to?	RECEIVED 1	7 JUL 2019  Days Of Repair: 4  Resurvey No. of Trip: 2	
Dale/Time, File Pass 107 1) 12/2 Min Mar	RECEIVED 1 : Preli. Report : Final Report	7 JUL 2019  Days Of Repair: 4  Resurvey No. of Trip: 2	Survey Fee:
Dale/Time, File Pass 107  1) 12/2 High Total Time, File Potum to 2  2)	RECEIVED 1 : Preli. Report : Final Report	7 JUL 2019  Days Of Repair: 4  Resurvey No. of Trip: 2	Survey Fee: Transportation: )8+P\$, _St
Dale/Time, File Pass to?  1) 18/4 Humber [ Date/Time, File Robum to?	RECEIVED 1  : Preli. Report  : Final Report  Add Fe	Days Of Repair: 4  Resurvey No. of Trip: 2  e: Site Insp (\$	Survey Fee: Transportation: ) 5+PS,St

# Nivitha (LKK Auto)

From:

Sent:

Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg> Monday, 1 July 2019 5:33 PM

> To: Cc Subject:

assignments; Admin-D (LKKAuto)

Thio Tse Kiat

Pre-Repair Survey by LKK

Dear Nivitha,

Please assist to survey the vehicle as per Tse Kiat's instruction :-

s/n	S/n PARTY	OUR	WORKSHOP / CONTACT NO.	DOA / CLAIM NO / OFFICER	REMARKS
1	SMG2316K	MG2316K GBD2178M	BLUWEL AUTOMOTIVE SERVICE PTE LTD (67452088)	27/06/19 (MT/1050924-002) M NEDUMARAN & CO ALICE LOW	M NEDUMARAN & CO

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank You

Warmest Regards

Hazalysa Bte Ibrahim Admin Assistant Motor Department

www.income.com.sg

T+65 6430 7902

Vels In

















PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. At Income, we are 'In with You' on Performance, Growth, Find out more at income.com.sg/careers

# Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.





Your Ref: MN.IG.B1.1913140.st

Our Ref : MT/CA/TP/138/1050924-002/AL/AY

01 Jul 2019

M NEDUMARAN & CO 11 SIN MING ROAD #B2-09 (UNIT 2) THOMSON V TWO SINGAPORE 575629

Dear Sir/Madam

CLAIM NUMBER: MT/1050924-002 ACCIDENT INVOLVING GBD2178M / SMG2316K on 27 Jun 2019

We refer to your letter of 28 Jun 2019.

We have selected Lkk Auto Consultants Pte Ltd from your list of surveyors to be our single joint expert for this matter. May we highlight that pre-repair survey as per NIMA protocol includes survey of the vehicle when its damaged parts are being dismantled before repairs. Please provide a list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

In addition, please note our intention to conduct a post-repair survey before the vehicle has been returned to your client. Please co-ordinate with the appointed single joint expert immediately after the repairs is completed.

If you have any queries, please contact Alice Low at 6430 7932 or email us at alice.lowkc@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

cc Lkk Auto Consultants Pte Ltd

#### SGCARMART.COM

Login Sign up

New Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Up To 100% Loan, Not A Phy. Full Servicing Records



SKL Automobile Star



Post an Ad

Browse by Category

Advertiser Login

Sort by Date Posted

Any

▼ 40 results/page

5 vehicles

Vezel Hybrid 1.5A X

Model

Ways of Selling

Price

Depreciation

Eng Cap

Mileage

Veh Type Arry

SUV

Available

Search Selection

Vezel Hybrid 1.5A X

Honda Sensing

Arry \$105,988

\$10,440 /yr

Any

12-Dec-2018

2018

1,496 cc

Arry

11 km

Available

Fuel Type: Petrol-Electric Latest 2018 Facelift With Honda Sensing Model, Most Popular SUV On The Road, Easy Financing, Immediate Registration.

TTS Eurocars

Posted: 28-Jun-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel Hybrid 1.5A X

Honda Vezel Hybrid 1.5A X

\$95,800

\$9,690 /vr

06-Jun-2018

1.496 cc

18,236 km

SUV Available

Fuel Type: Petrol-Electric

1 Owner, Low Mileage, Well Kept, Accident Free, Bank Loans And In-house Financing Available, View Now!

Posted: 22-Jun-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X

\$104,988

\$10,460 /yr

31-Aug-2018

1,496 cc

28 km

SUV Available

Fuel Type: Petrol-Electric

2018 Facelifted Honda Vezel Hybrid. Best Fuel Consumption SUV In Town. - Fast Loan Approve - Welcome For Trade In 5 Years/130 000km Warranty. Call Now And View To Appreciate.

Posted: 31-May-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X

\$104,888

\$10,380 /yr

06-Sep-2018

1,496 cc

SUV

Available

STREET, STREET

\*\*SMINN AC

Fuel Type: Petrol-Electric

Make And Assemble In Japan. 5 Years Or 130,000Km Warranty! View To Appreciate. Call Now For More Etails

Posted: 26-May-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but Unsure of its Condition? Get. STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle

SUV



Honda Vezel Hybrid 1.5A X Honda Sensing

\$102,988

\$10,320 /vr

28-Aug-2018

1,496 cc

74 km

Available

FRAUDIN 42

Fuel Type: Petrol-Electric

Make And Assemble In Japan. 5 Years Or 100,000Km Warranty! View To Appreciate. Call Now.

Vincar Pte Ltd

Posted: 24-May-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda Vezel, vezel, Used Honda

Save this search criteria, to get email alerts whenever a match is found:

Model

Depreciation Price

Eng Cap

Mileage

Veh Type

▼ results/page

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

spCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car sed Vezel Hybrid 1.5A X, Vezel Hybrid 1.5A X Singapore, used Vezel Hybrid 1.5A X, used vehicles Singapore or even buy used Vezel ins Compare

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Owner ID Type:	Singapore NRIC
Owner ID:	1655E
Vehicle Details	
Vehicle No.:	SMG2316K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Green
Manufacturing Year:	2018
Engine No.:	LEB6722505
Chassis No.:	RU31302498
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,927.00
Original Registration Date:	11 Dec 2018
First Registration Date:	11 Dec 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$16,898.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2028
PARF Rebate Amount: Intended COE Rebate Details	\$12,673.00
COE Expiry Date:	10 Dec 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,101.00
COE Rebate Amount:	\$29,353.00
Total Rebate Amount:	\$42,026.00

The information contained herein is correct as at 02 Jul 2019

OK

MSME19084298 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 28/06/2019 15:59 SUBMITTED BY: Chia Pei Ying

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT	ГСТАТ	4-1	RENIT
ACCIDEN	SIA		

Date Of Report

Date Of Accident

28/06/2019 15:59 27/06/2019 14:15

Exact Location Of Accident

CARPENTER STREET

Country/State of Loss

SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMG2316K

#### Insured/Policyholder

Name Of Registered Owner

LOW CHEN KOON

NRIC No

S1171655E

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-96832322

Alternative Phone No.

OFFICE-96832322

#### Vehicle Particulars

Manufacturer

HONDA

Model

VEZEL

Exact Purpose for which vehicle was being used at

time of accident

NO

Are you claiming under your own insurance policy for repair to your vehicle?

NO.

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

#### Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5105991674

Cover Note Number

#### Driver

Name of Driver

LOW CHEN KOON

NRIC No Date Of Birth S1171655E

Occupation

29/07/1956 OUTDOOR

Date Of Driving Pass

24/01/1979

Driving Experience

40 YEARS AND 5 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-96832322

Fax Number

Contact Number

OFFICE-96832322

EMail Address

NOEMAIL

Address

BLK 93 YISHUN ST 81 #10-02

Postcode

768451

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO.

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: STEVEN

GENDER:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO.

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

VEHICLE A WAS TRAVELLING STRAIGHT ALONG CARPENTER STREET. SUDDENLY, VEHICLE B REVERSE OUT FROM A SMALL LANE AND BANG INTO MY CAR.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD2178M

Vehicle Make/Model/Colour Details Of Properties

VEHICLE B

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

PATRICK SHAWN CHRISTOPHER

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28 6/19,103092

Driver's Signature

(If driver is not the policyholder)

Bate & Time: 286

Reporting Centre Personnel's Signature


NRIC/FIN No.:

STABNE StatchPlanForm\_3/3

BUNGE

#### Sketch Plan #2 Pg. 1

A-SM42316K. B-GBD2178M.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

rehicle A	was.	trave Min	5%	raight	along	carpente
dealy reh	icle B	reverse	out	from	a smal	Il lane
isto m	y car		-			
	denly reh	donly relicle B	deally relicte B reverse	dealy relicte B reverse out	dealy relicte B reverse out from	thicle A was travelling straight along deally relicle B reverse out from a small into my car.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 28/6/19/1030 - (If driver is not the policyholder)
Date & Time: 28/6/19/1030 - NRIC/FIN No.:

Reporting Centre Personnel's Signature

BLUWEL AUTOMOTIVE SERVICE PTE LTD 1 KAKI BUKIT AVE 6 # 01-28/55

SINGAPORE 417883

#### VEHICLE No:SMG 2316K

1PC	FRONT BUMPER	\$762.00
1PC	FRONT BUMPER SIDE HOLDER O/S	Sel \$66.50 _
1SET	FRONT BUMPER CLIPS	M \$50
1PC	FRONT BUMPER REINFORCEMENT	, 11 \$321.00 X
1PC	FRONT BUMPER LOWER SKIRTING	nogel /10.1 \$680.00
1PC	FRONT BUMPER FOG LAMP O/S	CM \$325.00
1PC	FRONT BUMPER FOR LAMP COVER O/S	Tu/ \$86.30
1PC	FRONT GRILLE	17 \$361.00 X
1PC	HEADLAMP ASSY O/S	Cre \$1,759.10
1PC	HEADLAMP LOWER BRACKET O/S	c/e \$105.00
1PC	FRONT FENDER O/S	<b>↑</b> \$566.20 ×
1PC	FRONT FENDER OUTER PROTECTOR O/S	70-1 \$285.00
1SET	FRONT FENDER INNERSHIELD CLIPS O/S	( \$50.00_
1PC	FRONT FENDER HYBRID EMBLEM O/S	202 111 \$109.30
1PC	BONNET	\$1,105.30      ★
		\$6,817.80

HEADLAMP TINTING(LIGHT BLUE) S. NETT 1SET

> TO CHECK WIRING TO SPRAY RUST PROOFING TO CONDUCT WHEEL ALIGNMENT TO SPRAY CERAMIC COATING LABOUR FOR PANEL BEATING TO PUTTY & SPRAY PAINTING

NU \$100.00 5.05

\$50.0020 11 \$50.00X 11 \$100.00 X \$200.00 /572 \$680.00 520 \$880.00 680 \$8,877.80

8691.70

LKK Auto Consultants hence notify the Repairer of the following:

TOTAL

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary itam(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

7-4278,20 202 3422.56 489250



Tel: +65 6/86 6016

Fax: +65 6786 6014

Nets

Acct # : SMG2316K

: Andrew 16K (Honda Vezel)

5832322 H/P: 96832322

)	ITEM CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	RP-Yellow	Rim Protector Yellow (RP-Yellow)	1	65.00	65.00
	BCL-Yellow	Brembo Type Brake Cover Big (Yellow)	2	75.00	150.00
		Headlight Tinting (Light Blue)	1	100.00	100.00

mer's Signature

E-Rev Motor Sports LUP Authorized Signature

SUB-TOTAL	315.00
TOTAL AMT	315.00
PAID AMT	315.00
BAL. DUE	0.00





sold are not refundable for cash st rate of 5% per month will be imposed on Overdue Account Wrapstyle Singapore Pte Ltd 24 LENG KEE ROAD, #04-03 A/B Singapore 159096 edison@wrapstyleasia.com www.wrapstyle.com.sg



# INVOICE

INVOICE TO

Andrew

Honda Vezel

INVOICE NO. 2736

DATE 10/12/2018

DUE DATE 10/12/2018

TERMS Due on receipt

WARRANTY PERIOD

3 years on glossiness

SALES REP.

Estelle

ACTIVITY

Cosmics

DESCRIPTION

December Promotions - 9h Ceramic coat

New Car - 3 layers

TY RATE

AMOUNT

308.00

308.00

308.00

\$\$0.00

DECEIVED 1 0 6 DEC 2018

BY: Extelle.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

9		DAMAGE ASSES	SMENT REPORT	
NTUC	INCOME INSUR	ANCE CO-OPERATIVE LTD	Ref: CS/INC19011718	
3 BF 605-0		D UNION HOUSESINGAPORE	Date: 18-07-2019	
ATTN	: ALICE LOW		Code: INC	
		Policy Particulars	:- THIRD PARTY CLAIM	SAUDICE
	Insured Veh.	GBD 2178M	Veh. Inspected	SMG 2316K
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1050924-002	Excess (\$)	0.00
	Assign From	HAZALYSA	Assign Date	01/07/2019
2.		Vehicle Parti	culars & Condition	
	Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	RU31302498	Colour	GREEN
	Odometer	13190 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.	200100	Condit	ions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
	L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
-	R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
4.	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Descripti	on of Damages	San Barrier
	THE VEHICLE SU DAMAGES SEE D	STAINED DAMAGES AT THE FR	RONT O/S PORTION.	
5.	ALCOHOL: NAME OF THE PARTY OF	Genera	al Information	ROBERT HERE
	Accident Date	27/06/2019	Inspect Date / Time	02/07/2019 ( 10:45 AM )
	Survey held at	BLUWEL AUTOMOTIVE SERV	ICE PTE LTD	
		BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE SINGAPORE 417883	E)	
5a.	15087003/03/4		Remarks	MARKET TO STATE
	A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A'WI CE TO YOUR INSTRUCTIONS, N	WE HAVE NOT AUTHORISE	S. ED REPAIRS.
5b.			Days of Repair	A STATE OF THE PARTY OF
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Days	



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2316K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			fr.
1	FRONT BUMPER	DENTED	762.00	762.00
1	FRONT BUMPER SIDE HOLDER O/S	BENT	66.50	66.50
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	321.00	
1	FRONT BUMPER LOWER SKIRTING	WARPED / TORN	680.00	680.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	325.00	325.00
1	FRONT BUMPER FOG LAMP COVER O/S	TWISTED	86.30	86.30
1	FRONT GRILLE	NOT NECESSARY	361.00	199
1	HEADLAMP ASSY O/S	CRACKED	1,759.10	1,759.10
1	HEADLAMP LOWER BRACKET O/S	CRACKED	105.00	105.00
- 6	FRONT FENDER O/S	TO REPAIR SEE LABOUR	566.20	
1	FRONT FENDER OUTER PROTECTOR O/S	TORN	285.00	285.00
1	SET FRONT FENDER INNERSHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT FENDER HYBRID EMBLEM O/S	NECESSARY	109.30	109.30
1	BONNET	TO REPAIR SEE LABOUR	1,105.30	
	LESS 20% DISCOUNT	Navarda Gen 1000		-855.64
			6,631.70	3,422.56
	SPECIAL NETT ITEMS			
1	SET HEADLAMP TINTING (LIGHT BLUE)(SN)	NECESSARY	100.00	100.00
	65 850 18	1	100.00	100.00
	LABOUR			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	
	TO SPRAY CERAMIC COATING.		200.00	150.00
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S AND BONNET.		680.00	520.00
	TO PUTTY & SPRAY PAINTING.		880.00	680.00
			1,960.00	1,370.0

Report Ref No. CS/INC19011718/Uqd3n2



Page No.:2 of 2

GRAND TOTAL	8,691.70	4,892.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		3,900.00

Report Ref No. CS/INC19011718/Uqd3n2

**CHUA KANG SENG** 

Licensed Appraiser



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.