

ASS. REQ. BY:

REF:

CS3/CT19011719/Gcd3er

Special Instruction:

Surveyor: GG

ASSIGNMENT (Office)

From (Person): Chong Boon Sen. of CTI

Date/Time: 1/7/2019 6.14pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJQ 4461T

Insured: GBB 6383X

at Workshop m/s 6 Speed Autoworkz

Tel:

or 68 Kaki Bukit Ave 6

Policy No: DMCSN30190918022

Claim No: 8NM190203022C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJQ 4461P-X
	GBB 6383X-
	Dismantle: 3/7/2019.
	After repair: 5/7/2019

PRG
Surveys

PRG
Enl.

REF:

41

ASSIGNMENT

0-2024)

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s 6 speed Autowerk3

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$25k

IDAC Accident Rpt.

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIQ44617

Yr Regn:

13 May 2008

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante c.c 1591

Colour:

beige

A/C: Insured / Std / NI / NA

Sp. Reading

181876

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU41BR 9U759928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In/Out / Jammed / Leaked / Burnt or

Brake: In/Out / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / B/Rim or

Tyre Size:

F:

195/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

02-07-19

Survey held at

W/S

4pm

Des. of Damages: Frt / Rear / DIS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

3/7/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

190

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

190

Report Format :

PRG

Lump Sum / I.B.I.: (\$

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 1 July 2019 6:14 PM
To: Sally
Cc: assignments
Subject: RE: your ref: cl/190675/t/saw.sg / our ref: snm19d203022

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

SSQ 4461 P
6 Speed Autowerkz

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sally [mailto:info@catherinelimllc.com]
Sent: Monday, 1 July, 2019 5:54 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: your ref: cl/190675/t/saw.sg / our ref: snm19d203022

Dear Boon Sen (Without Prejudice)

We refer to your email.

Our client is not agreeable to your list of surveyor and wish to appoint Constant as single joint.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01

Veh In.

Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Monday, July 01, 2019 5:34 PM
To: Shirley
Subject: your ref: cl/190675/t/saw.sg / our ref: snm19d203022

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	4355Z
Vehicle No.:	SJQ4461T
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	G4FC9U654029
Chassis No.:	KMH DU41BR9U759928
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,465.00
Original Registration Date:	13 May 2009
First Registration Date:	13 May 2009
Transfer Count:	2
Actual ARF Paid:	\$3,685.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	12 May 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,943.00
COE Rebate Amount:	\$13,553.00
Total Rebate Amount:	\$13,553.00
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Jul 2019

OK

▶ Avante Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Hyundai Avante 1.6A S (COE till 03/2024)	\$26,800	\$5,640 /yr	31-Mar-2009	1,591 cc	83,000 km	Victory Cars Trading Pte Ltd	Available
New Paintwork, New Interior! Beautiful White Matched With Black Interior. Next Popular Model With Minimal Issues Good For Renewal! Healthy Engine And Gearbox, Coupled With Our In House 6 Months Warran...							
Office No. - 63854916 Mr Lee - 86885879 Mr Quek - 90096473 Mr Lim - 92470299 Mr Tan - 90999505							
Hyundai Avante 1.6A (COE till \$23,000 03/2024)	\$4,840 /yr		31-Mar-2009	1,591 cc	-	Sing Thai Hin Car	Available
Very Well Maintained By Previous Owner! No Repairs Needed! Hesitate No More! Call Our Friendly Sales Consultant To Book An Appointment Now! All Loan And Insurance Available.							
Office No. - 67490238 Lester - 90027501 Des - 81867412 Ng - 93666036							
Hyundai Avante 1.6A (COE till \$27,800 04/2024)	\$5,810 /yr		14-Apr-2009	1,591 cc	82,000 km	Victory Cars Trading Pte Ltd	Available
Excellent Kept With Very Low Mileage Done! Looks, Feels And Drive Like New. Healthy Engine And Gearbox. Low In Fuel Consumption, Big In Cabin Space Coupled With Powerful Engine. 6 Months Comprehensive...							
Office No. - 63854916 Mr Quek - 90096473 Mr Lim - 92470299 Mr Lee - 86885879 Mr Tan - 90999505							
Hyundai Avante 1.6A S (COE till 04/2024)	\$25,800	\$5,380 /yr	17-Apr-2009	1,591 cc	-	Banyan Auto	Available
Call Now For Viewing. Office No. - 64550059 Jess - 90663813 Simon - 91447349							
Hyundai Avante 1.6A S Sunroof (COE till 04/2024)	\$28,800	\$5,970 /yr	28-Apr-2009	1,591 cc	158,667 km	Car Guru.Com Pte Ltd	Available
Smooth Engine, Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now B...							
Office No. - 67639595 Lawrence - 92228747 Jimmy - 90079944							
Hyundai Avante 1.6M (COE till 04/2024)	\$21,800	\$4,520 /yr	28-Apr-2009	1,591 cc	-	Net Link Partners Pte Ltd	Available
Cheaper In Town. Easy Approval In House Loan With Low Interest Rate Available. Tip Top Condition On Both Interior And Exterior. Call Now Fast!							
Office No. - 67531661 Eddie - 90788894							
Hyundai Avante 1.6A (COE till \$40,800 04/2029)	\$4,150 /yr		28-Apr-2009	1,591 cc	109,000 km	Just Paper Motoring	Available
New 10 Years COE, 1 And Only Owner. Price Negotiable, Genuine Mileage Clocked By Agent (Komoco Motors), Excellent Condition Preserved, Lowest Fuel Consumption, Low Maintenance, Accident Free & Hassle ...							
Office No. - 68484333 Fendy - 94655569							
Hyundai Avante 1.6A S Sunroof (COE till 04/2024)	\$25,800	\$5,350 /yr	28-Apr-2009	1,591 cc	181,000 km	Edmund Motor Pte Ltd	Available
Original Paintwork And Beautiful Original Leather Seat. Transmission System And Engine Still In Excellent State. No Further Repair Needed. Flexible Loan At At Low Rate And Trade In Welcome. Act Fast B...							
Office No. - 62523339 Joe Kek - 98326732 David Lau - 93889178							
Hyundai Avante 1.6A S (COE till 04/2029)	\$39,800	\$4,050 /yr	28-Apr-2009	1,591 cc	-	Tan Motor Car Enterprise	Available
New Arrival! Beautiful Sedan Among Its Class. Very Well Taken Care By Ex Owner. Spacious, Comforts To Fit Your Family Size. Service Regularly Without Fail. No Repairs Needed And We Deliver Our Promise...							

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2019 11:48
Date Of Accident	26/06/2019 21:10
Exact Location Of Accident	JUNC RAFFLES QUAY & CROSS ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ4461T
Insured/Policyholder	
Name Of Registered Owner	STARK EXPRESS PTE LTD
Co Reg No	201434355Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	HD AVANTE 1.6 A
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	50837825759-02
Cover Note Number	
Driver	
Name of Driver	TERENCE TAN WEI LENG
NRIC No	S7630402E
Date Of Birth	23/09/1976
Occupation	OUTDOOR
Date Of Driving Pass	09/11/2016
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98800993
Fax Number	
Contact Number	OFFICE-98800993
Email Address	NOEMAIL

Address	BLK 103 BUKIT BATOK CENTRAL #07-243
Postcode	S50103
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	
Insurance Company of Driver's Own Vehicle	

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, AS I APPROACHED THE JUNCTION OF RAFFLES QUAY, THE TRAFFIC JUNCTION WAS GREEN. I PROCEED TO MAKE A RIGHT TURN TOWDS CROSS ST. VEHICLE B WAS TRAVELLING ALONG 2ND LANE WHICH 2ND LANE IS ONLY TURN RIGHT LANE ONLY. AS A RESULT, VEHICLE B HIT ONTO MY VEHICLE RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR ONG
Phone Number	81572212
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB6383X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YAP HENG MOH
NRIC/Passport Number	S7788284G
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Passenger 1

2

NAME: :

GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

paths are:

A. 50 UNIT
B. 65632X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to Hwde ment.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

REPUBLIC OF SINGAPORE DRIVING LICENCE

License No: **S7630402E**

TERENCE TAN WELLEN

Birth Date: **23 Sep 1976**
Issue Date: **09 Nov 2016**

0026277398

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7630402E**



Name

TERENCE TAN WEI LENG

陈伟龙

Race

CHINESE

Date of birth

23-09-1976

Country of birth

SINGAPORE

Sex

M

S7630402E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Effective Date
Class 3	Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$	09 Nov 2016

NP 428A



Licence No: **S7630402E**



4908930

NRIC No. **S7630402E**



Date of issue
28-11-2012

Address

**APT BLK 103 BUKIT BATOK CENTRAL
#07-243
SINGAPORE 650103**



























...CLAIM SUBFOLDER...(Pending for Survey Report)













































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:38 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: STARK EXPRESS PTE LTD , Co. Reg. No.: 201434355Z									
Vehicle Reg. No.: SJQ4461T		Date of Loss: 26/06/2019 21:00 - :59 [121 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203022C02		Policy/Cover Note No.: DMCVSN30190918022							
Vehicle Reg. No. (Insured): GBB6383X		Policy No. (Claimant): 5083782759-02							
		Excess: S\$0.00							
Repairer: 6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/08/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJQ4461T (SNM19D203022C02)
[GBB6383X]
TP
STARK EXPRESS PTE LTD
Jun 26 2019 9:00PM
[-]
6 Speed Autowerkz Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	27/06/19 12:01	Accident Statement	 Load HTM		
2	03/07/19 18:11	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>	
3	03/07/19 18:12	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
4	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
5	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
6	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
7	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
8	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
9	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
10	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
11	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
12	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
13	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
14	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
15	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
16	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
17	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
18	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
19	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
20	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
21	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
22	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
23	27/06/19 11:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
12	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/08/19 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
18	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 10:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 10:27	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	27/06/19 11:59	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/19 11:59	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	27/06/19 12:01	Accident Statement	Load HTM	
2	03/07/19 18:11	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	03/07/19 18:12	Accident Statement Addm. #1	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
22	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
23	27/06/19 11:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	27/06/19 11:59	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	27/06/19 11:59	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; padding: 5px; min-height: 100px;"> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19011719/GCD3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30190918022

Claimant Vehicle
No: SJQ4461T

Insured Vehicle
No: GBB6383X

Date of Loss: 26/06/2019

Nature of Claim: TP

Claim
No: SNM19D203022C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ4461T**

Make & Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)

Engine No: G4FC9U654029

Reg. Date: 13/05/2009 (Man. Year: 2009)

Chassis No: KMH DU41BR9U759928

Colour: Beige

Odometer: 181876 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 02/07/2019 Inspected At:

6 Speed Autowerkz Pte Ltd (HQ)
68 KAKI BUKIT AVENUE 6, #02-05
ARK@KB
Singapore 417896

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts:	143	HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ4461T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >