From (Person): Theresa	of	INC	D	ate/Time: _	2/7/2019
Estimated Cost:		Bill to:			
OD (IP) WS+TP RES / OD		MV / CS			01
To Inspect Vehicle No:	3BD 7327S	5	_ Insured: _	_	86124
at Workshop m/s Xinya			Tel: _	_62fc	3481
of BIK 1003 By Mera	h #01-75		/		
Policy No:		Claim No: _	MT/10	51435	-001
Sum Insured:		Excess: _	1		
Make of Veh:			D	.O.A.	8105/61/81
(Client's Record)				_	
CA / REV / REP. / REV 2	4 HRS			H.O.D. Endor	sement:
Date/Time:	Person Contr	acted:	Vel	nicle(IN) O	UT
Date/Time Action/Instructi	on (V) Esti	imate	-	+ ;	
		00759 NC D	2012	YOUR-	
A contract of the contract of					
10086191	-CI/IID1700	0760 Zc DOA	1: 18/12/3	DIE .	<u> </u>
2615- Sulamit	oveli v				
	$\alpha m = 1/2$	eport			

	4
BITTUILE: NA2	INC
1411.174.	ASSIGNMENT
From: Dale:	Ven No: 480 73273 Yr Rogn: 31 MAR 2013
fisiumated Cost:	Type: M.Carl M.Cycle/Busl Von / Worry Taxl / Prime Movor
OD TRIWS/TRRES/OD RES/EVA/INV/MV	Truck/Trollor or
to hispect venicle No;	Helde royorA DYNA 150 rAMMALCO. 2,982
ul Workshop m/s	Colour SILVER AC: 650. 013101 NI 1814
01	Sp.Reading 128, 788 T/Radip: (6:501001514) NITHA
Inaurod	Eng/No:
Policy No.	CNO: 37FA135470K204219
Claims No.	Gon, Cond; Good / Pair) Poor / Burnt
Sum Insurad: Excoss:	Sloering: Iforder Dammed / Luaked / Burnt or
(Client's Record)	Brake: (norder) Jammed / Leaked / Burnt or
Moke of Vehi	Modl: HII / S/RIM / STD A/RIM or
	Tyre Sizo: F: 195 R 15 C.
(Pascy Condition)	R: 155 R (12C
Remark. The veh had commenced its N/S	O/S BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /
repair at the time of inspection.	TOYOTYORO OF TOYO (F) LASSA(R)
Est or Market Value: 37. K	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Conststent? : Yes or No	RVBnl. 6 mm R/Gal. 5
Gke / PR Score Consistent? : Yes or Ho	UBal. 6 mm L/Bal. 5 mm
Est Repairs: days Res.: Yes or No	D.O.A. 18/12/18 U.O. 2/7/19
Luin Suin: % 3 Val.; Yes or No	Survey hold of XINYA
CA / REV / REP. / 24 HRS	Dos. of Damagos : Fred Rear OIS MIS UIC Roottop or
Vehicle: IN /	The U/C / Cheenia frame / Dody Structure effected due to contiste
Date / Time Action / Instruction	INC L/S
mable to paint out COE Rebate.	(No enquing or lland). Rights tuksup to print COERESATE
20/11/9 (alled whenp waiting for 7	iralfic Police to release vehicle details to pint
ant COE (ebate. Will inform once	
(DE Rebate \$22, 4, 2. Repair	Limit \$13,000.
Dense	id could all a - Non
warting tol Yinga to 1940	ut courter offer Noz
Que/I via, File Pass 107 Proll: Roport	Days Of Repair:
26/5 Typist : Final Roport	Rosurvoy No. of Trip: Survey Foo:

Cute/I was, File Pass 107 Proll: Roport	Days Of Repair:	27/12/10
20 5 Typist : Final Report	Rosurvoy No. of Trip:	Survey Foo:
Osterlans, File Roturn 197	Add Fee: :Slie Insp (\$	
Roport Format:	: Interview (S) Photos
Luma Star 11.8.L (\$:Weakend (\$	'CIA

Nivitha (LKK Auto)

From:

Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Sent:

Wednesday, 3 July 2019 1:41 PM

To:

Admin-D (LKKAuto); assignments

Subject:

RE: TP CASES FARMED OUT TO LKK ON 02/7/2019

Hi, attached below are the OIC details, clm nbr etc.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T+65 6430 7898
www.income.com.sg













At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers



SN	OIC	Claim No.	Survey	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	CHARLOTTE	MT/1050971- 002	2/7/2019	SMK217E	CHENG AUTO	5 SOON LEE STREET #01-62 PIONEER POINT	Murugesan / 86667775		SKD4039L	27/6	
2	JEFF LIN	MT/1051577-	2/7/2019	\$KG9675B	HO LEONG AUTO SERVICES	27A JURONG PORT ROAD #01- 30 SINGAPORE 619101	Daniel Tan / 96924113		GBF5081C	29/6	
3	JARED LIU	MT/1050338- 002	2/7/2019	PC3458M	SIN SHENG ENGINEERING SERVICES	8 TUAS AVENUE 18 (LEVEL 5) SINGAPORE 638892	Susan / 6863 9595	10:30- 12:30	PC2034J	14/6	Owner waiting
4	AZHARI	MT/1051435- 001	2/7/2019	GBD7327S	XINYA AUTO SERVICES PTE LTD	BLK 1002 #01-75 BUKIT MERAH LANE 3 SINGAPORE 159719	/ 62703481		FBB8612Y	18/12/2018	

Please contact workshops.

Please revert to officer-in-charge after survey.

Nivitha (LKK Auto)

From:

Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Sent:

Tuesday, 2 July 2019 9:36 AM

To:

assignments; Admin-D (LKKAuto)

Cc: Subject: Theresa Vimala D/O Balagangadharan; Thio Tse Kiat FW: TP CASES FARMED OUT TO LKK ON 02/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction:-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OLVEH	DOA	Additional Remarks
1		MT/1050971- 002	2/7/2019	SMK217E	CHENG AUTO	5 SOON LEE STREET #01-62 PIONEER POINT	Murugesan / 86667775				
2			2/7/2019	SKG9675B	HO LEONG AUTO SERVICES	27A JURONG PORT ROAD #01-30 SINGAPORE 619101	Daniel Tan / 96924113				
3		MT/1050338- 002	2/7/2019	PC3458M	SIN SHENG ENGINEERING SERVICES	8 TUAS AVENUE 18 (LEVEL 5) SINGAPORE 638892	Susan / 6863 9595	10:30- 12:30			Owner waiting
4			2/7/2019	GBD7327S	XINYA AUTO SERVICES PTE LTD	BLK 1002 #01- 75 BUKIT MERAH LANE 3 SINGAPORE 159719	/ 62703481				

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala Senior Administrator Motor Insurance 7+65 6430 7898 www.income.com.sg











At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers



> Back to OneMotoring

Enquire Transfer Fee

Vehicle No.:	GBD7327S
Vehicle Type:	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1:	With Hood
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	TOYOTA DYNA 150 MANUAL
Chassis No.:	JTFAT35Y70K204219
Propellant:	Diesel
Engine No.:	1KD2476980
Engine Capacity:	2982 cc
Maximum Power Output:	
Maximum Laden Weight:	3500 kg
Unladen Weight:	1900 kg
Year Of Manufacture :	2014
Original Registration Date:	31 Mar 2015
Lifespan Expiry Date :	30 Mar 2035
COE Category:	C - Goods Vehicle & Bus
PQP Paid :	\$39,547.00
COE Expiry Date:	30 Mar 2025
Road Tax Expiry Date :	18 Dec 2018
Inspection Due Date :	31 Mar 2019
Intended Transfer Date:	03 Jul 2019
CO2 Emission :	257.00 (g/km)
CEV/VES Rebate Utilised	387
Amount :	
CO Emission :	y
HC Emission:	
NOx Emission :	
PM Emission:	
Late renewal fee(s) will be impos	ed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

-MARKANA ET LIGHT I HAN BELLEVIN	BILL Of Lotter Aftern		
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(\$\$)	(S\$)
Transfer Fee:	25.00	•	25.00
Sub Total:			25.00
Nett Road Tax Amount (After	0.00		0.00
Offsetting Over Payment):			
Total Amount Payable:			25.00


TOTAL PRODUCT OF THE			
	White its des Albert	No. of the last of	
	Amount Before GST	GST Amount	Amount After GST
	(5\$)	(5\$)	(S\$)
Transfer Fee:	25.00	2	25.00
Sub Total:			25.00
Nett Road Tax Amount (After	0.00	-	0.00
Offsetting Over Payment):			
Total Amount Payable:			25.00

Transfer of ownership is not allowed for this vehicle.

This vehicle has a road tax Over Payment of \$212.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.









0101210/2012

1 of 3 Report No. T/20181219/2042

Police Station Of Origin: Queenstown N.P.C 3 Queensway #01-03 SINGAPORE 149073 Tel No: 1800-4719999

REPORT OF A TRAFFIC ACCIDENT

	ne Report N 018 12:31	Made:	Vide Report No.: J/20181218/0118		Station Diary No.: 23		
Informa	nt's Partic	ulars					
Name of	f Informant:		Address:				
HOSSAIN ANOWAR			APT BLK 70 TUAS SOUTH AVENUE 1 #03-18 TUAS VIEW DORMITORY SINGAPORE 637285				
ID Type	/ ID No.:		Contact No.:				
FIN NO	/ F7746117	7P	Home/Office: Mobile: 91029966				
National BANGLA	•		Email:				
Sex:	Age:	Date of Birth:	Type of Informant:				
Male	44	25/06/1974	Driver	* ·			
Race:			Language:	*	Institution / School Name:		
Indian					**		
Occupation:			Driving Licence Inf	ormation:	Date of Expiry:		

General Infor	mation of the Accident				
Type of Accident:	Fatal Attended by Police	Drink Drive: No	Date/Time of Accident: 18/12/2018 19:00	Type of Location:	
Location: Along Road 1 TUAS WEST Junction Tuas	ROAD			×	
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Wor	Traffic Volume: Moderate		
CAMPS PROPERTY COMPA	sion:		>	Anyone conveyed by ambulance:	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBB8612Y						0
GBD7327S	Lorry				Seriously Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Queenstown N.P.C 3 Queensway #01-03 SINGAPORE 149073 Tel No: 1800-4719999

Report No. T/20181219/204;

CONTINUATION OF REPORT

Driver		1000		San			
Name	HOSSAIN ANOWA	R		ID No).	F7746117P	
Related Vehicle	NIL			Conta	act No.	91029966	
Hospital/Clinic	espital/Clinic NIL			Class Drivin Licen Expin	ıg	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		Date Disc	1	NIL		1
No. of Days gran	ted Medical Leave	NIL	Degree of		NIL		- (

Brief Details.

On 19/12/2018 at about 1900hrs, m y vehicle was stationary along Tuas West Road towards Tuas South Ave 3 X Tuas Link 4 on the extreme right of 4 lanes Road and i was the 2nd veicles before the stop line as i am going to make a right turn into Tuas Link 4.

Once Traffic Light change to red with green right arrow in my favor, the front vehicle infront of me proceeded to make a right turn as such i proceeded to make a right turn subsequently. Vehicle at the opposite vehicles stop at the stop line however suddenly while i was making my turn, a motorcycle (FBB8612y) from opposite direction dash out and collided onto my vehicle front portion.

I have no built in camera inside my front vehicle, i wish to state that there is CCTV around the vicinity. Traffic police and ambulance was at scene, my passenger and i was not injured. The motorcyclist was conveyed by ambulance.





GSET SOTES

Police Station Of Origin: Queenstown N.P.C

3 Queensway #01-03 SINGAPORE 149073

Tel No: 1800-4719999

CONTINUATION OF REPORT

3 of 3 Report No. T/20181219/2042

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: D / Sgt 1 LIM TIAN WEN	Signature Of Inf	ormant:	
Signature Of Interpreter:	Date/Time:		
Not applicable	19/12/2018 12:3	31	
Officer In Charge Of Case:	Classification O	f Case:	
TP / FAIT / Sr Staff Sgt MUHAMMAD FARHAN BIN MALIK	,	•	
Contact No.: 65476202	SN 49		
Authentication Stamp NP168			
SIGNATURE			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid,	e mereby consert to the archiving of this report at the centre and to copies of the report being made available	Die
	ACCIDENT STATEMENT	
Date Of Report	19/12/2018 13:20	
Date Of Accident	18/12/2018 19:00	
Exact Location Of Accident	JUNCTION OF TUAS WEST RD & TUAS LINK 4	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBD7327S	
Insured/Policyholder		
Name Of Registered Owner	SIEW KONG GLASS MAKERS PTE. LTD.	
Co Reg No	197802202E	
Email Address	SALES@SIEWKONGGLASS.COM.SG	
Mobile Phone No	(LOCAL) +65-90276279	

Alternative Phone No Vehicle Particulars

Manufacturer TOYOTA

Model DYNA 100-3.0 D (M)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

NO

If No, Please state action to be taken

THIRD PARTY

OFFICE-68633303

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy

Policy Number DMCVSN108031800

Cover Note Number

Driver

Name of Driver HOSSAIN ANOWAR

 Passport No/FIN
 F7746117P

 Date Of Birth
 25/06/1974

 Occupation
 OUTDOOR

 Date Of Driving Pass
 11/12/2014

Driving Experience 4 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91029966

Fax Number Contact Number

EMail Address NOEMAIL

Address

3, TUAS LINK 3, SINGAPORE 638523

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

_

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

YES

ambulance?

YES

difficulting.

Was any other material or property damaged?

I have been approached by unknown person(s)

YES

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: MANDOL BIMAL

GENDER:

: MALE

Passenger 2

NAME:

: RAMASAMI SATHISH KUMAR

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

YES

Police Station Name

QUEENSTOWN N.P.C

Police Station Address

ROAD: 3 QUEENSWAY #01-03, POSTCODE: 149073, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4719999 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20181219/2042 REMARK: VEHICLE AT TP COMPOUND

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBB8612Y

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBB8612Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:


SKETCH PLANTON BO	1)	
- Land	LANY ST	UI JUBINAS
Y LE	1	<u>y 301180</u>
TUAS WEST ROAD	·	
and the second of the second o		
	$ \langle \rangle$	
		2
a lag many and a demanda in the second		
and the contract of the contra		
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	1' 11	1 smil
	. 1 24.31	hina Embassy
	ohre, an	
	bassy affe	r my co-worker
	passess.	about 1740.
	embassy arek to ou	
Tuas However	we had	
10		anteen before.
reporting back	1 2	
	Soon Li ar	
		nd other
Co-Worker ha	. 0 -	till about
1840 - 1845. I	then. Les	
1 - 1 - 1 - 1	heading	back to office
at Tieas Link		dreveng along
THES WEST RD	I approad	
Junction of T	Les AVE 7	. I Then move
into extreme	121 11	and Lane as
T was going to	2 turn 11	
4 . / T+s 121 v.d	ant turn L	and only) At
this time trai	rie light	was Showing
DECLARATION	3	ال
I/We declare the foregoing particulars are true in eve	ry respect.	11
Ser Son Aw	u.	' %
Policyholder's Signature Driver's Signa		Reporting Centre Personnel's Signature
Date & Time: [If driver is no Date & Time:	ot the policyholder)	Name: NRIC/FIN No.:

contract and a standard magical

SKETCH PLAN	
	<u> </u>
	<u> </u>
	And the state of t
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	A
A	oward the green
	outdo the free
arrow then came an in	my favours
a vortica it is	CONTINUE TO
cross the Junction and	I followed
0 1 1 1 1 1 1 1 1	nction I Saw
MUENT TENTERED ON OF	
a motor cycle, comens;	from the
	dictoly Jammes.
	A to tall 1
my lorakes my Lorry Stopp	- 11.1 COLO)
as I was travelling sco	w, However
	ill come fourerd.
He said motor cycle St	3 4
and Smashed onto my	Lorry and
The second of the second of	the Pa. I came
motor cylest jell onto	Caro transa tha
down with my co-work	Ler from the
Lorry. I told my co-wor	Fer to call my
boss and I went to so	ee the motorcyclist
at this point a pedest	rain, also
	alled en
approcehod and had a	DOLLOG GISO
ambulance. Later the	poid Co
arrived. I would also he	ke mention,
that all vehicles on	the opposite
divertion had all Stop	ped as et
DECLARATION	
/We declare the foregoing particulars are true in every respect.	11
_ //	14
Set Kong Our	
(a) (a) (b) (b)	Describes Contro Darronnal's Sirantura
Policyholder's Signature (15) Driver's Signature	Reporting Centre Personnel's Signature Name:
Date & Time: (If driver is not the policyholder) Date & Time:	NRIC/FIN No.:
Dete de la me.	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
was red light for their direction.
All thes would have been recorded
in the police comera on lamp post pine. Along Tuas Ave 7. and en my
direction there is also a speed
camera.

SKETCH PLAN	
DECEMBER CHOCK BACTABLETE OF THE ACCIDENT	Liniantani du la la la La La La
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	3 1 13
red, and as I continue	foward the green
arrow then come an ir	my favour,
a vehicle intront at m	e continue to
cross the Junction and	I followed
When I entered the Ju	nction I saw
a motor cycle, comeng	from the
opposite direction I imm	edictely Jammes
my brakes my Lorry Stop	ped immediately
as I was travelling sco	w. However
He said motor cycle St	ill come fouxird.
and Smashed onto my	Lorry and
motor cylest fell onto	the Rd. I came
down with my co-wor	Ker from the
Lorry. I told my co-wo	rker to call my
boss and I went to s	ee the motorcyclist
at this point a peges.	train, also
approached and had	called an
ambulance, Later the	police_also
arrived. I would also L	ike mention,
that all vehicles on	the opposite
direction had all stop	ped as et
DECLARATION	
I/We declare the foregoing particulars are true in every respect.	2
Sty Kong Dun	· 0
Policyholder's Signature (5) (2) (2) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	Reporting Centre Personnel's Signature
Date & Time: (If driver is not the policyholder)	Name:
Date & Time:	NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value: Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 26 Jul 2019

Company 202E

GBD7327S

000,0

26 Jul 2019

TOYOTA

TOYOTA DYNA 150 MANUAL

Silver

2014

1KD2476980

JTFAT35Y70K204219

-

\$27,856.00

31 Mar 2015

31 Mar 2015

0

\$1,393.00

No

.

\$0.00

30 Mar 2025

C - Goods Vehicle & Bus

10

\$39,547.00

\$22,452.00

\$22,452.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID: Vehicle Details

Vehicle No.;

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 26 Jul 2019

Company 202E

GBD7327S

Yes

26 Jul 2019

TOYOTA

TOYOTA DYNA 150 MANUAL

Silver

2014

1KD2476980

JTFAT35Y70K204219

120

\$27,856.00

31 Mar 2015

31 Mar 2015

0

\$1,393.00

No

.

\$0.00

30 Mar 2025

C - Goods Vehicle & Bus

10

\$39,547.00

\$22,452.00

\$22,452.00

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail: xinyaauto@singnet.com.sg Tel: 6270 3481 Fax: 6278 7522

Date

: 27/06/19

Address : SIEW KONG GLASS MAKERS PTE LTD

3 TUAS LINK

SINGAPORE 638523

Reference

: TP 1207/06/19

Vehicle No

: GBD7327S

2,982

Make/Model : TOYOTA DYNA 150 MANUAL

Insurance Co. : CHINA TAIPING

LIEGAHO

- JTFAT35 Y70K204219

						CC
RE: QUOTATION TO G	BD 7	327S	FOR	THIRD	PARTY	CLAIMS.

PARTS	REQUIRED	REG DATE :	31	MAR 2015
1)	FRONT BUMPER	1	e	478.54 DEF
1) 2)	FRONT BUMPER ENFORCEMENT	1	*****	165.32 / 37
3)	FRONT GRILLE	1	\$	420.16 / DEF
4)	TOYOTA "LOGO"	1	\$	69.20 MIS
5)	"DYNA" EMBLEM	i	\$	65.53 /NEL
6)	HEADLAMPS	2	\$	1,187.56 / CKIC
7)	FRONT CROSS MEMBER	1	Š	680.00 ?
8)	FRONT PANEL	i	s	910.79 OEE
9)	FRONT MOULDING CENTRE	i	\$	285.15 DEF LH XJUL
10)	FRONT SIDE LH / RH BLACK	2	\$	189.76 RH JM
11)	WIPER PANEL	1	\$	261.84 / DEF
12)	WIPER MOTOR	1	\$	768.03 X JVC
13)	WIPER LINKAGE	1	\$	332 30 2
14)	WIPER WATER NOZZLE	2	\$	93.94 LH SCR 180.06 RH MIS
15)	WIPER BLADE	2 2 2	\$	189.06 - WT
16)	WIPER ARM	2	\$	229.96 - 502
17)	FRONT WINDSCREEN	1	\$	1,065.74 - CRK
18)	FRONT WINDSCREEN RUBBER	1	\$	233.60 P 65
19)	DASHBOARD ASSY	1	\$	827.01 7
20)	FRONT TORSION BAR COMPLETE SET	1	\$	1,574.94 ?
21)	ASSORTED CLIPS	10	\$	50.00 ₹
22)	FRONT PANEL PROTECTION BAR	1	\$	366.52 ?
	LIST PRICE TOTAL		\$	10,445.04
	LESS DISCOUNT 25%		\$ \$ \$	2,611.26
	LIST PRICE TOTAL AFTER LESS		\$	7,833.78
	NETT PRICE TOTAL			\$0.00

TOTAL PARTS COST

\$7,833.78

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, FRONT GRILLE, FRONT HEADLAMPS, WIPER PANEL AND TO PANEL BEAT CUT & WELD FRONT PANEL PULL & ALIGN FRT CHASSIS.	\$	2, 000.00 1, 200 (10 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT CABIN PANEL, FRONT BUMPER, CORNERS PANEL & OTHER AFFECTED AREA.	\$	1,400.00 800 (7 PANEL)
3)	TO REMOVE & REPALCE COMPLETE DASHBOARD ASSY	\$	220.00
4)	TO REMOVE & REFIT ALL ELECTRICAL SYSTEMS AND SWITCHES TO ALLOW REPALCEMENT OF DASHBOARD AND FRONT WIRING	\$	289:00 100
5)	TO FOCUS HEADLAMPS	\$	40.00/NEC
6)	TO REMOVE & AIR CON BLOWER ,LOURVE AIR CON SYSTEM & TOP UP AIRCON FREON	\$	250.00
7)	TUFF KOTE	\$	280.00 80
8)	TOWING FEE FROM TRAFFIC POLICE COMPOUND TO WORKSHOP	\$	120.00 324 ACC
	LABOUR TOTAL	\$	4,590.00
		200	

NAZ UKK 2/7/19 1630

LIS
6 DAYS
CHTECK MENS PHOTOS
PATTER REPORT PHOTOS

TOTAL ESTIMATED REPAIR COST

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

12,423.78

- No Regal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail: xinyaauto@singnet.com.sg Tel: 6270 3481 Fax: 6278 7522

Date

: 27/06/19

Address : SIEW KONG GLASS MAKERS PTE LTD

3 TUAS LINK

SINGAPORE 638523

Reference

: TP 1207/06/19

Vehicle No Make/Model : GBD7327S : TOYOTA DYNA 150 MA

Insurance Co. : CHINA TAIPING

CHADSIL CC

· JTFA+35 Y70K2042

RE : QUOTATION TO GBD 7327S FOR THIRD PARTY CLAIM	S.	2,98	<u>ک</u>	
	REG DATE;	31 MA	R 2015	
PARTS REQUIRED	QIY	A	WII D	/
		dis	4990 P. /	

1)	FRONT BUMPER	1	\$	478.54	DEF
2)	FRONT BUMPER ENFORCEMENT	1	\$	165.32	
3)	FRONT GRILLE	1	\$		1021
4)	TOYOTA "LOGO"	1	\$	69.20	111
5)	"DYNA" EMBLEM	1	\$	65.53	INEL
6)	HEADLAMPS	2 1,000	\$	1,187.56	Character State of the Control of th
7)	FRONT CROSS MEMBER	1	\$ X !	00.086 JV2	?
8)	FRONT PANEL	1	\$	910.79	MEE
9)	FRONT MOULDING CENTRE	1	\$_	_285.15	
10)	FRONT SIDE LH / RH BLACK	2 VEHCRY	864	89.76	المراكب
11)	WIPER PANEL	1 KH MU	\$	261.84	/DEF
12)	WIPER MOTOR	1	\$	768.03	
13)	WIPER LINKAGE	1	\$	332.39	?XIVL
14)	WIPER WATER NOZZLE	2	\$	93.94	
15)	WIPER BLADE	2	\$ 1	60 189.06	FELT
16)	WIPER ARM	2	\$	229.96	
17)	FRONT WINDSCREEN	1	\$	1,065.74	~ CR
18)	FRONT WINDSCREEN RUBBER	1 200	\$.	233.60	10 B
19)	DASHBOARD ASSY	1 2	> \$ Pho	75- 827.01	?af
20)	FRONT TORSION BAR COMPLETE SET	1	\$	1,574.94	
21)	ASSORTED CLIPS	10	\$	50.00	?XN
22)	FRONT PANEL PROTECTION BAR	1	\$	366.52	
2007					.,/ 70
	LIST PRICE TOTAL		\$	10,445.04	ļ

LESS DISCOUNT

LIST PRICE TOTAL AFTER LESS

7,897,88

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

\$7,833.78

2,611.26

7,833.78

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, FRONT GRILLE, FRONT HEADLAMPS, WIPER PANEL AND TO PANEL BEAT CUT & WELD FRONT PANEL PULL & ALIGN FRT CHASSIS.	\$	2, 000:00 1,200 (10 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT CABIN PANEL, FRONT BUMPER, CORNERS PANEL & OTHER AFFECTED AREA.	\$	1,400.00 800 (7 PANEL)
3)	TO REMOVE & REPALCE COMPLETE DASHBOARD ASSY	\$	220.00 ? 100
4)	TO REMOVE & REFIT ALL ELECTRICAL SYSTEMS AND SWITCHES TO ALLOW REPALCEMENT OF DASHBOARD AND FRONT WIRING	\$	280.00 100
5)	TO FOCUS HEADLAMPS	\$	40.00 NEC
6)	TO REMOVE & AIR CON BLOWER ,LOURVE AIR CON SYSTEM & TOP UP AIRCON FREON	\$	250.00 7×NN
7)	TUFF KOTE	\$	280.00 80
8)	TOWING FEE FROM TRAFFIC POLICE COMPOUND TO WORKSHOP	\$	90 120.00 300 K
	LABOUR TOTAL	\$	4,590.00
		_	

NAZ UKK 217119 1630 LIS 6 DAYS CHECK MENS PHOTOS AFTER REPORTE PHOTOS

TOTAL ESTIMATED REPAIR COST

PARTS \$7,897.58

LESS 25% \$5,923.41

LABOUR \$2,410.00
TOTAL \$8,333.41

LESS L/S 20% \$6,616,72

LISTOTAL \$6,650.00/6DAYS

12,423.78