

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X

VIC



Final Report

Estimate No. : **b1 51766**
Date Estimated : **01/07/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Ng Siang Chin Sandra
54 Lorong Stangee

- ACCOUNT - 121
AIIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 425045

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5701S	C864617	14/03/2011	523iA	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To make good the rear bumper, rear right fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job	1,700.00	0	1,700.00 ✓
To respray rear bumper and rear right fender	1,730.00	0	1,730.00 ✓
To check steering geometry and conduct wheel alignment according to BMW specification	451.00	0	451.00 ✓
To replace rear right wheel rim including balancing.	80.00	0	80.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 8JX18 V SPOKE STY 328	966.50	1	0	966.50 ✓

TO	DATE	WORKING DAYS
FAX TO FAX NO FAX TO FAX NO CONFIRMED DATE PLEASE FINALISE BY	Rasul LK 20/8/19	5

Total Labour :	4,191.00
Total Parts :	966.50
Total Repair Costs less Excess:	5,157.50
GST @7%:	361.03
Grand Total :	5,518.53

LOSS OF USE = \$100 X 5 DAYS

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

02 JUL 2019

ESTIMATE

Estimate No. : b1 51766	Page No. : 1 of 5
Date Estimated : 01/07/2019	
Prepared By : Joseph Yaguel	

- ESTIMATE REPAIR FOR - Ng Siang Chin Sandra 54 Lorong Stangee Singapore 425045	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5701S	C864617	14/03/2011	523iA	0

DESCRIPTION	VALUE		
Replacing rear bumper panel and right rear side panel	1700 2,125.00		
Spray rear bumper and right rear side panel	1730 1,923.00		
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	450 531.00		
To replace tyre and wheel rim including balancing. (1x).	80 94.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00		
Sundries	80/? 150.00		
Total Labour 1:	5,000.00		
DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 8JX18 V SPOKE STY 328 <i>SC</i>	1	966.50	966.50
RR BUMPER CTR GUIDE <i>? ?</i>	1	69.05	69.05
RR BUMPER LH MOUNT <i>? ? X50L</i>	1	142.55	142.55
RR BUMPER RH MOUNT <i>? ?</i>	1	155.90	155.90
RR BUMPER PANEL PRIMED (PDC) <i>? repair</i>	1	1,571.95	1,571.95
DECOUPLING RING PDC TORQUE CONVERTE <i>? X50L</i>	4	5.05	20.20
Total Parts :			2,926.15

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 51766	Page No. :	2 of 5
Date Estimated	: 01/07/2019		
Prepared By	: Joseph Yaguel		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA5701S	C864617	14/03/2011	523iA	0

Claims OD 3rd Party Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/07/18 14:45 Excess S\$ _____

Surveyor's Name APRIL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

5 days



Labour 1	:	5,000.00
Parts	:	2,926.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	554.83
Grand Total	:	<u>8,480.98</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **