

(08/11/13) wef

ASS. REC. BY:

REF:

CS/7P/19011726/Uqd3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKS6076L

at Workshop m/s

Bm

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

666.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A51665

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKS6076L

Yr Regn:

1, 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mer Benz

2250

c.c

1796

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

1605/1

T/Radio: Insured / Std / NI / NA

Eng/No:

W.D. 21204724532035

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/6/18

D.O.I.

2/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep/5

inc Ajax 24hrs bus. net 1433

4/5 9000 (Red to 8657.51, 44%)

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 08/7 1433

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

7P

Lump Sum / I.B.I. (\$

9000

7x15=105

170+105

50

50

103

80

558

Ref. No : <u>CS/TP/1901/726/UGD3</u>	Res. Date: <u>4/3/18</u>	Date Received:
Veh. No : <u>SKS 6076C</u>	SP:	WKSP: <u>Bul</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By: <u>[Signature]</u>

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

ESCAPE NOW TO OVER
60 CITIES!

ALL-IN FARE FROM

\$56*

ScootBiz from \$177*

Book Now

*Terms & conditions apply

1 X

scoot

e250

Price Range ▼

Depreciation ▼

2012 ▼

Vehicle Type ▼



Home » Used Cars » Easy Link Automobile Pte Ltd » Mercedes-Benz E-Class E250 CGI Elegance

Mercedes-Benz E-Class E250 CGI Elegance

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$78,800**Depreciation** ? \$19,250 /yr
View models with similar depre**Reg Date** 12-Mar-2012
(2yrs 8mths 8days COE left)**Mileage** N.A.**Manufactured** ? 2011**Road Tax** ? \$974 /yr**Transmission** Auto**Dereg Value** ? \$53,758 as of today (change)**OMV** ? \$54,036**COE** ? \$79,304**ARF** ? \$54,036**Engine Cap** 1,796 cc**Power** 150.0 kW (201 bhp)**Curb Weight** ? 1,650 kg**No. of Owners** ? 2**Type of Vehicle** Luxury Sedan

Features

1.8L 4 Cylinder Inline Turbocharged Engine At 201Bhp, 7G-Tronic Auto Transmission, Paddle Shift, Cruise Control, Keyless Entry And Start. View specs of the Mercedes-Benz E-Class Saloon (2009-2013)

Accessories

LED Daytime Running Lights, Electric Memory Leather Seats, Auto Head Lights, Rain Sensors, Rear Aircon, Parking Sensor, Multi Function Steering Wheel.

Description

1 Owner, Well Maintained And Excellent Condition Unit. Call To Book An Appointment. Trade-in Can Be Worked Up.

Category

PARF Car

Status

Available

Re: Compare



Location Map

Shortlist

Con

Report Error

M

Seller Information

Company

Easy I

» deale

» 6 veh

Address

60 Jala

68

Search

Location

Carros

Office No

63633

Contact

Jin

Person(s)

Tracy

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



AVIVA

e250

Price Range ▼

Depreciation ▼

2012 ▼

Vehicle Type ▼



Home » Used Cars » Hanns Auto » Mercedes-Benz E-Class E250 CGI

Mercedes-Benz E-Class E250 CGI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$68,800

Depreciation ⓘ

\$15,900 /yr
View models with similar depre

Reg Date

17-Feb-2012
(2yrs 7mths 13days COE left)

Mileage

91,000 km (12.3k /yr)

Manufactured ⓘ

2011

Road Tax ⓘ

\$974 /yr

Transmission

Auto

Dereg Value ⓘ

\$51,835 as of today (change)

OMV ⓘ

\$54,036

COE ⓘ

\$73,890

ARF ⓘ

\$54,036

Engine Cap

1,796 cc

Power

150.0 kW (201 bhp)

Curb Weight ⓘ

1,650 kg

No. of Owners ⓘ

1

Type of Vehicle

Luxury Sedan

Features

1.8L 4 Cylinder Inline Turbocharged Engine At 201Bhp, 7G-Tronic Auto Transmission, Paddle Shift, Cruise Control, Keyless Entry/Push Start. View specs of the Mercedes-Benz E-Class Saloon (2009-2013)

Accessories

LED Daytime Running Lights, Electric Memory Leather Seats, Auto Head Lights, Rain Sensors, Rear Aircon, Parking Sensor, Multi Function Steering Wheel.

Description

1 Owner, Low Mileage Used, Elegance Model With 125th Anniversary Edition. 18 Inches Wheel, Lowered Original Suspension, Crossdrill Disc, 7 Speed With Paddle Shifter. All Round Parktronic, Electric Rear Blind, Side Blind. Very Well Maintained, Quiet Undercarriage, Black Leather Trim. Smooth Driving. New Engine Mounting, Fresh Coat Of Paint. Call Us Now For Viewing.

Category

PARF Car

Status

Avr***

Compare



Location Map

Shortlist

Com

Report Error

M

Seller Information

Company

Han

» de

» 46

Address

1 Cor

Searc

Location

One

Office No

6271

Contact Person(s)

Desn

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4487J
Vehicle Details	
Vehicle No.:	SKS6076L
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030364615
Chassis No.:	WDD2120472A532035
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$53,979.00
Original Registration Date:	19 Jan 2012
First Registration Date:	19 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$53,979.00 26989
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2022
PARF Rebate Amount:	\$32,387.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$75,889.00
COE Rebate Amount:	\$19,278.00
Total Rebate Amount:	\$51,665.00

The information contained herein is correct as at 03 Jul 2019

OK

29/06 2019 SAT 11:08 FAX

001/004

MSME10064358 / SIME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 28/06/2019 10:36
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Data Of Report	28/06/2019 16:36
Date Of Accident	28/06/2019 10:35
Exact Location Of Accident	SIMEI AVE TWDS PIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKS6076L
Insured/Policyholder	
Name Of Registered Owner	LIM HOCK SENG
NRIC No	S1594487J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93621511
Alternative Phone No	OFFICE-93621511
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E250
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099428131
Cover Note Number	
Driver	
Name of Driver	LIM HOCK SENG
NRIC No	S1594487J
Date Of Birth	12/04/1963
Occupation	OUTDOOR
Date Of Driving Pass	11/11/1983
Driving Experience	35 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93621511
Fax Number	
Contact Number	OFFICE-93621511
Email Address	NOEMAIL

29/06 2019 SAT 11:08 FAX

002/004

Address BLK 566 CHOA CHU KANG ST 52 #10-134
 Postcode 680566
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 28/06/2019 AT 10.35AM, I WAS DRIVING ALONG SIMEI AVE ON THE LEFT LANE WHEN SUDDENLY, CAR B HIT MY CAR FROM BEHIND.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GW3781E
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver NG CHEE KWANG
 NRIC/Passport Number S7100275F
 Contact Number 81170383
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

29/06 2019 SAT 11:09 FAX

003/004

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind a policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28/6/19, 12:05pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/6/19 12:05pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


GIA/MSK SketchPlanForm_V03

29/06 2019 SAT 11:09 FAX

2004/004

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/6/19 at about 1035am, I was driving along Simei Ave on the left lane when suddenly Car B hit my car from behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/6/19, 12:05pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/6/19, 12:05pm


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIA/IMC SketchPlanForm_V3

2



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-33/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

Not Admin
 2/5/2008
 6/5/2008

SKS 6076L

	Bootlid	Body	2052.41	
	Bootlid Rear logo	re	65.00	
	Bootlid 'E250' emblem	re	70.98	
	Bootlid '7 G-TRONIC' emblem	re	68.00	
	Bootlid outer chrome moulding	re	188.32	
	Bootlid outer opening switch	11	265.00	X
	Bootlid inner lock	Twil/shd	366.00	
	Bootlid inner trim	11	455.00	X
2pc	Bootlid reflectors @ 428.00	o/s cr	856.00	1PL
	Bootlid weatherstrip	TM	233.65	
	Rear bumper	DLS	148.32	
	Rear bumper lower skirting	DLS	385.11	
	Rear bumper tow cover	re	42.50	
2pc	Rear bumper PDC sensors @ 266.11	shd	532.22	
	Rear bumper reinforcement	re	755.00	
	Rear bumper CTR guide	cr	181.00	
1set	Rear bumper clips	re	60.00	
7pc	taillamps @ 645.00	cr	1290.00	
	Rear end panel	Body	1082.00	
	Rear end panel top garnish	TM	315.00	
	Rear floor panel top board	11	640.00	X
	Rear Lender	re	2665.00	X
	Rear bumper chrome moulding centre	re	181.00	
2pc	Rear bumper chrome moulding sides @ 145.00	re	290.00	
	Rear end panel sealant	re	50.00	
			14582.57	
	To check wiring		50.00	20
	To Diagnose & replacing Rear PDC sensor		100.00	50
	To Diagnose & ref. x seat cushion upholstery		120.00	60
	To Spray rust proofing		100.00	80
	labour for panel heating		1200.00	800
	To putty & spray painting		1500.00	1100
			TOTAL @	17652.57



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref : CS/TP19011726/Uqd3n2	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883			Date : 12-07-2019	
ON BEHALF OF LIM HOCK SENG			Code : TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SKS 6076L
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		02/07/2019
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250 (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2120472A532035	Colour	GREY	
Odometer	160511	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/40 R18	YOKOHAMA	6 mm	
L/H Front Tyre	215/40 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	215/40 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	215/40 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/06/2019	Inspection Date	02/07/2019	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 6076L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	BADLY DENTED	2,052.41	2,052.41
1	BOOTLID REAR LOGO	NECESSARY	65.00	65.00
1	BOOTLID 'E250' EMBLEM	NECESSARY	70.98	70.98
1	BOOTLID '7G-TRONIC' EMBLEM	NECESSARY	68.00	68.00
1	BOOTLID OUTER CHROME MOULDING	NECESSARY	188.32	188.32
1	BOOTLID OUTER OPENING SWITCH	NOT NECESSARY	265.00	-
1	BOOTLID INNER LOCK	TWISTED / SHORTED	366.00	366.00
1	BOOTLID INNER TRIM	NOT NECESSARY	455.00	-
2	BOOTLID REFLECTORS @\$428.00	O/S CRACKED	856.00	428.00
1	BOOTLID WEATHERSTRIP	TWISTED	233.65	233.65
1	REAR BUMPER	DISTORTED	1,485.32	1,485.32
1	REAR BUMPER LOWER SKIRTING	DISTORTED	385.11	385.11
1	REAR BUMPER TOW COVER	DEFORMED	42.50	42.50
2	REAR BUMPER PDC SENSOR @\$266.11	SHORTED	532.22	532.22
1	REAR BUMPER REINFORCEMENT	DENTED	755.00	755.00
1	REAR BUMPER CTR GUIDE	CRACKED	185.00	185.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
2	TAILLAMPS @\$645.00	CRACKED	1,290.00	1,290.00
1	REAR END PANEL	BADLY DENTED	1,082.00	1,082.00
1	REAR END PANEL TOP GARNISH	TWISTED	315.00	315.00
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	640.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	2,665.00	-
1	REAR BUMPER CHROME MOULDING CENTRE	NECESSARY	185.00	185.00
2	REAR BUMPER CHROME MOULDING SIDES @\$145.00	NECESSARY	290.00	290.00
1	REAR END PANEL SEALANT	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-	-1,012.95
			14,582.51	9,116.56
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING REAR PDC SENSOR.		100.00	50.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	80.00
	TP SPRAY RUST PROOFING.		100.00	80.00

Report Ref No. CS/TP19011726/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER. TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
			1,500.00	1,100.00
			3,070.00	2,140.00
	GRAND TOTAL		17,652.51	11,256.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS/TP19011726/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.