

Service

Marcus

REF: CS/LAW19011739/Mod3e2

Special Instruction:

13,86000/-

ASSIGNMENT (Office)

From (Person): Michelle Liew of TKRP Date/Time: 17/6/2019

Estimated Cost: Bill to:

Third Parties:

Claimant: Owner

Surveyor: Aeon

Workshop: Global Motorsport

OD/IP Re-inspection Evaluation

To Inspect Vehicle No: FBG 1135C Insured: SFN 330C
at Workshop m/s Global Motorsport. Tel: 6345 3687 Jenny
of 53 Ubi Ave 1 #01-12

Policy No: Claim No: TWK/AR/1253.1R/nuc/ml/PI+PD

Sum Insured: Excess:

Make of Veh: D.O.A. 21/2/2016

(Client's Record)

~~5/7/2019 11am~~ 10/7/2019 11am. H.O.D. Endorsement/Date: STF

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 10 days)

Date/Time: 11/7/19 Submit Final Fig 453800, 5 days (Red \$ 2,200 / 37 %; Original 10 days)

Date/Time	Action/Instruction
	FBG 1135C - X
	SFN 330C - CCG TP15014893 / U00392 D.O.A: 13/7/2015
5/7 9am	Informed Jacqueline on urgent leave, request to re-arrange appointment. (Instruction from Marcus, he overlook the appointment)
5/7 10.45am	Jacqueline re-arrange appointment on 10/7/2019 at 11am.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 15 JUL 2019

Do Not Finalise

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1000
1000

- 1) Date/Time _____ File Pass to _____
- 2) Date/Time _____ File Return to _____
- 3) Date/Time _____ File Pass to _____
- 4) Date/Time _____ File Return to _____
- 5) Date/Time _____ File Pass to _____
- 6) Date/Time _____ File Return to _____

Nivitha (LKK Auto)

From: Jacqueline Tan <jactan@visionlawllc.com>
Sent: Tuesday, 2 July 2019 11:01 AM
To: 'Admin-D (LKKAuto)'
Cc: 'assignments'; 'Angeline Rajoo'; 'Michelle Liew on behalf of Angeline Rajoo'; 'Lee Jenny'
Subject: RE: Appointment of Marcus Chua Kang Seng as Single Joint Expert - MC Suit No. 10326/2018 - TKQP Ref: TWK/AR/1253.18/ntuc/ml/PI+PD || Vision Law Ref: AM.jt.Ins.G41.100318.16(sj)

Dear Nivitha,

Refer to your email herein, please be informed that we have make arrangement for our client motor cycle to be available on the following date and time for SJE reinspection.

Date: 5 July 2019
Time: 11 am
Location: Global Motorsport
53 Ubi Avenue 1
#01-12
Singapore 408934
Contact: Jenny (6345-3687)

Please acknowledge and revert with your confirmation on the said appointment.

Regards

Jacqueline Tan
Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811, Fax: 6535-6802


From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 18 June, 2019 10:17 AM
To: jactan@visionlawllc.com
Cc: assignments
Subject: Appointment of Marcus Chua Kang Seng as Single Joint Expert - MC Suit No. 10326/2018 - TKQP Ref: TWK/AR/1253.18/ntuc/ml/PI+PD || Vision Law Ref: AM.jt.Ins.G41.100318.16(sj)

Dear Sir/Mdm,

Kindly assist to provide us the venue and time for the Re-inspection of FBG 1135C.

Best Regards,

G.Nivitha] Admin
LKK Auto Consultants Pte Ltd



This email has been checked for viruses by AVG antivirus software.
www.avg.com

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

Nivitha (LKK Auto)

From: Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>
Sent: Monday, 17 June 2019 10:02 AM
To: LKK (assignments@lkkauto.com); 'LKK (sur@lkkauto.com)'
Cc: Angeline Rajoo; 'jactan@visionlawllc.com'
Subject: Appointment of Marcus Chua Kang Seng as Single Joint Expert - MC Suit No. 10326/2018 - TKQP Ref: TWK/AR/1253.18/ntuc/ml/PI+PD || Vision Law Ref: AM.jt.Ins.G41.100318.16(sj)
Attachments: SAS+2016-8-22.PDF;
AJAX+PRS+report-+visual+survey+without+any+repair+estimate+provided.PDF;
Survey+Report+(for+Tablet)+2016-12-13.pdf.PDF; LOD2+2016-12-13.pdf.PDF; Plt GIA + repair bill.pdf
Importance: High

LKK Auto Consultants Pte Ltd

Ref: To be advised

Dear Sirs

MC SUIT NO. 10326 OF 2018 – CLAIMANT: RUDY ASMARA BIN ABDUL SAMAD ACCIDENT INVOLVING FBG 1135C & SFN 330C ON 21.08.16 ALONG TAMPINES AVE 9

We act for NTUC Income Insurance Co-operative Limited, the insurers of motor vehicle no. SFN 330C. The Plaintiff's is represented by M/s Vision Law LLC, of motorcycle o. FBG 1135C.

Please be informed that the Court has appointed your **Mr Marcus Chua Kang Seng** as the Single Joint Expert for this action to provide an independent assessment in respect of costs of repairs for motorcycle no. FBG 1135C.

For purposes of SJE report, we enclose a copy of the relevant documents for your attention:-

1. Plaintiff GIA / police report
2. Defendant's GIA / police report with photos
3. Final repair bill from Global Motorsport
4. Pre-repair survey report from AJAX Inspection Services Pte Ltd with colour photos
5. Survey report from Aeon Auto Consultants LLO with colour photos

Please liaise with M/s Vision Law to make the necessary arrangements for **physical** re-inspection.

We look forward to receiving the SJE report by **17 July 2019**.

Best Regards

Michelle Liew
Secretary
For and on behalf of Ms Angeline Rajoo

TKQP

Tan Kok Quan Partnership
Advocates & Solicitors, Singapore
1 Wallich Street #07-02 Guoco Tower Singapore 078881
T (65) 6225 9333
D (65) 6496 9569
F (65) 6225 0111
E michelleliew@tkqp.com.sg

W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5112A
Vehicle Details	
Vehicle No.:	FBG1135C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	SUZUKI
Vehicle Model:	GSR750AL2
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	R749112258
Chassis No.:	JS1C5112100101658
Maximum Power Output:	-
Open Market Value:	\$10,260.00
Original Registration Date:	28 Mar 2012
First Registration Date:	28 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$1,539.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,000.00
COE Rebate Amount:	\$542.00
Total Rebate Amount:	\$542.00

The information contained herein is correct as at 10 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2016 16:40
Date Of Accident	21/08/2016 20:15
Exact Location Of Accident	Tampines Avenue 9
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFN330C
Insured/Policyholder	
Name Of Registered Owner	LIM SOK HENG
NRIC No	S1728375H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96506016
Alternative Phone No	Others-96506016

Vehicle Particulars

Manufacturer	KIA
Model	CERATO
Exact Purpose for which vehicle was being used at time of accident	Leisure
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5048231906-05
Cover Note Number	drivo CLASSIC (E.W+T.A)

Driver

Name of Driver	LIM SOK HENG
NRIC No	S1728375H
Date Of Birth	17/07/1965
Occupation	Indoor
Date Of Driving Pass	05/07/1983
Driving Experience	33 Years And 1 Month
Gender	Male
Mobile Number	(Local) +65-96506016
Fax Number	
Contact Number	Others-96506016
EMail Address	NOEMAIL

Address	BLK 486B #04-56 Tampines Ave 9
Postcode	521486
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	Unknown - Hit by TP exiting side road
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Tampines North Neighbourhood Police Post
Police Station Address	ROAD: Blk 461 Tampines Street 44 #01-56 , POSTCODE: 520461 , COUNTRY: Singapore
Police Station Contact	TEL NO: 1800-7818999 - FAX NO: 67838603
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

Refer to Sketch Plan,	
Are accident photos available for attachment?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG1135C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	RUDY ASMARA BIN ABDUL SAMAD
NRIC/Passport Number	S8435112A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	RUDY ASMARA BIN ABDUL SAMAD
Approximate Age	

Injuries Sustain

Injured person in which vehicle? FBG1135C

Were seat belts worn?

Was injured conveyed to hospital by ambulance? Yes

Address

Postcode

DETAILS OF INJURED PERSON 2

Name PILLION

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBG1135C

Were seat belts worn?

Was injured conveyed to hospital by ambulance? Yes

Address

Postcode

Sketch Plan Pg.1

NTUC Income Motor Service Centre

Vehicle No: SFN330C

Report Date & Start Time: 22-08-16 / 16:33

Report No: MT/_____

D.O.A: 21-08-2016
Time: 2015 hrs

Make / Model: KIA CERATO

Reporting Type: CD End Time: ___ / ___

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

22-08-16 / 16:33

Policyholder's Signature / Date & Time


22-08-16 / 16:33

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Sketch Plan



Vehicle A: SFN330C

Vehicle B: FBG1135C

Sketch Plan Pg.2

Describe Circumstances of the Accident

Brief Details.

On the 21/08/2016 at about 2015hrs, I was driving my car bearing license plate no.SFN330C along the right lane of Tampines Ave 9 when I approached the entrance to carpark of Blk 485A Tampines Ave 9. I had turn on my left signal but I had intended to filter to the left to prepare to turn into the Blk 499 Tampines Ave 9 multi story carpark which is further down the road however, just as I was filtering to the left, a motorcycle bearing license plate no.FBG1135C had went out of open carpark between Blk 485A and 499C and as a result, his motorcycle had collided with my vehicle's left front portion. As a result, the motorcycle went into the grass patch beside the road and as such, the rider and his pillion fell off the motorcycle. As the rider and his pillion who is pregnant had sustained some injuries, the rider had called for ambulance. Ambulance and traffic police soon came and attended to the rider and his pillion and conveyed both of them away. As a result of the accident, my left front bumper had scratches and my left headlight is broken.

Traffic police then told me lodge a traffic accident report vide G/20160821/0201, IO In charge: Rashidah, Tel: 65476216.As such, I am lodging this report to assist in traffic police investigation.

I want to add on that I was already travelling in the extreme left lane before the side road leading to T81 carpark.

Declaration

I/We declare the foregoing particulars are true in every respect.


22-08-16 16:33
Policyholder's Signature / Date & Time

22-08-16 16:33
Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre


Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Police Report



**SINGAPORE
POLICE FORCE**



1201533212136

1 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520451
Tel No: 1800-7815999

Report No: T201900212136

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/09/2016 21:29	File Report No.: G/20160821/0201	Station Diary No.: 39
Informant's Particulars		
Name of Informant LIM SOK HENG	Address: APT BLK 496B TAMPINES AVENUE 9 #01-56 SINGAPORE 521466	
ID Type / ID No.: NRIC NO / S1728375H	Contact No. Home/Office:	Mobile: 86508016
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Age: Date of Birth: Male 51 17/07/1965	Type of Informant: Driver	
Race: Chinese	Language: English	Institution / School Name:
Occupation: OPERATION MANAGER	Driving Licences Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/09/2016 20:15	Type of Location: T-Junction
Location: Along Road 1 TAMPINES AVENUE 9				
junction between main road and exit of Blk 496 MSCP				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
FBG1135C	Motorcycle	SUZUKI	GSR750	Black	Slightly Damaged	1
3FN33CC	Car	KIA	CERATO FORTE 1.8 SX MT ABS D/AB 2WD 4DR	Red	Slightly Damaged	0

Police Report



**SINGAPORE
POLICE FORCE**



T201608212195

2 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-65 SINGAPORE
520461
Tel No: 1800-7816996

Report No: T201608212195

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SFN330C	NTUC Income Insurance Co-Operative Limited	5048231906-05	18/01/2016	18/01/2017

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	RUDY ASMARAH BIN ABDUL SAMAD		ID No.	88435* 12A
Related Vehicle	FBG1135C (Motorcycle)		Contact No	NIL
Hospital/Clinic	CHANGI GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Driver				
Name	LIM SOK HENG		ID No.	81728375H
Related Vehicle	SFN330C (Car)		Contact No	88506016
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B 2A,2,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On the 21/08/2016 at about 2015hrs, I was driving my car bearing license plate no.SFN330C along the right lane of Tampines Ave 9 when I approached the entrance to carpark of Blk 485A Tampines Ave 9. I had turn on my left signal but I had intended to filter to the left to prepare to turn into the Blk 499 Tampines Ave 9 multi story carpark which is further down the road however, just as I was filtering to the left, a motorcycle bearing license plate no FBG1135C had went out of open carpark between Blk 485A and 498C and as a result, his motorcycle had collided with my vehicle's left front portion. As a result, the motorcycle went into the grass patch beside the road and as such, the rider and his pillion fell off the motorcycle. As the rider and his pillion who is pregnant had sustained some injuries, the rider had called for ambulance. Ambulance and traffic police soon came and attended to the rider and his pillion and conveyed both of them away. As a result of the accident, my left front bumper had scratches and my left headlight is broken.

Traffic police then told me lodge a traffic accident report vide G/201608210201, IO in charge: Rashidah, Tel: 85476215 As such, I am lodging this report to assist in traffic police investigation.

Police Report



**SINGAPORE
POLICE FORCE**



T2D16CR212198

3 of 4

Police Station Of Origin:
Tampines North NPP
481 Tampines Street 44 #01-55 SINGAPORE
520481
Tel No: 1800-7818999

Report No: T2D16CR212198

CONTINUATION OF REPORT

Police Report



SINGAPORE
POLICE FORCE



201900212128

Police Station Of Origin:
Tampines North NPP
451 Tampines Street 44 #01-58 SINGAPORE
620451
Tel No: 1800-7818989

4 of 4
Report No. T201900212128

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt MUHAMMAD DANIYAL BIN BAHARUDDIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/08/2018 21:29
Officer In Charge Of Case: TP / GIT / Sgt RASHIDAH BINTI AZIZAN Contact No.: 65476215	Classification Of Case:

Authentication Stamp
N°158



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2016 16:40
Date Of Accident	21/08/2016 20:30
Exact Location Of Accident	TAMPINES AVE 9 OPP BLK 485A TAMPINES AVE 9
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG1135C
Insured/Policyholder	
Name Of Registered Owner	RUDY ASMARA BIN ABDUL SAMAD
NRIC No	S8435112A
Email Address	rudzvankovic@gmail.com
Mobile Phone No	(LOCAL) +65-91062110
Alternative Phone No	Office-91062110

Vehicle Particulars

Manufacturer	SUZUKI
Model	GSR750AL2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Motorcycle

Insurance Company

Name of Insurance Company	Etika Insurance Pte Ltd
Type Of Coverage	Third Party Fire and/or Theft
Fleet Policy	No
Policy Number	DMLA16S001003
Cover Note Number	

Driver

Name of Driver	RUDY ASMARA BIN ABDUL SAMAD
NRIC No	S8435112A
Date Of Birth	15/11/1984
Occupation	Indoor
Date Of Driving Pass	28/02/2005
Driving Experience	11 Years And 5 Months
Gender	Male
Mobile Number	(Local) +65-91062110
Fax Number	
Contact Number	Office-91062110
EMail Address	rudzvankovic@gmail.com

Address
Postcode
Was driver an employee of the Insured's Company No
If No, Relationship of the Driver with the Insured Owner
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)
Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
Was any body injured in the Accident? Yes
Was any other material or property damaged? Yes
Was there any video captured by Car Camera? No
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? Yes
If Yes, Please state which Police Station
Police Station Name [Other] CHANGI NPC 9 SIMEI STREET 2 SINGAPORE 529914
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

Please refer to the attached Sketch Plan and the Accident Report for the accident details
Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFN330C
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIM SOCK HENG
NRIC/Passport Number S1728375H
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name NUR YULIYANA AFFNY BINTE YUNOS
Approximate Age 32
Injuries Sustain SERIOUS - STILL IN CHANGI HOSPITAL
Injured person in which vehicle? FBG1135C
Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Yes

Address

BLK 478 PASIR RIS DRIVE 4 #02-425

Postcode

510478

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repealate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 25/09/16
Policyholder's Signature / Date & Time 1619

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Please refer to the attached
Police Report T/20160822/2134
dated 21/8/2016.

Third Party Details - above
Car No : SPW 330 C (Car B)
Name : Lim Sock Henry
IC : 51728375 H

Declaration

We declare the foregoing particulars are true in every respect

 23/08/16
Policyholder's Signature / Date & Time

16/5

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20160822/2134

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No. 1800-5872999

1 of 4

Report No. T/20160822/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 22/08/2016 17:23	Vide Report No.. G/20160821/0201	Station Diary No.: 57
---	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: RUDY ASMARA BIN ABDUL SAMAD		Address: APT BLK 478 PASIR RIS DRIVE 4 #02-425 SINGAPORE 510478	
ID Type / ID No.: NRIC NO / S8435112A		Contact No.:	Mobile: 91062110
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 31	Date of Birth: 15/11/1984	Type of Informant: Rider
Race: Malay		Language:	Institution / School Name:
Occupation: FIREMAN		Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/08/2016 20:30	Type of Location: Straight Road
Location Along Road 1 TAMPINES AVENUE 9 OPP BLK 485A TAMPINES AVE 9				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
FBG1135C	Motorcycle	SUZUKI	GSR750AL2	Black	Seriously Damaged	2
SFN330C	Car	KIA	CERATO FORTE 1.6 SX MT ABS D/AB 2WD 4DR	Red	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20160822/2134

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

2 of 4

Report No. T/20160822/2134

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBG1135C	ETIQA INSURANCE BERHAD	DMLA16S001003	28/03/2016	27/03/2017

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Pillion				
Name	NUR YULIYANA AFFNY BINTE YUNOS	ID No.	S84081801	
Related Vehicle	FBG1135C (Motorcycle)	Contact No.	98800850	
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	21/08/2016	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious	
Rider				
Name	RUDY ASMARA BIN ABDUL SAMAD	ID No.	S8435112A	
Related Vehicle	FBG1135C (Motorcycle)	Contact No.	91062110	
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL	
Date Treatment	21/08/2016	Date Discharge	22/08/2016	
No. of Days granted Medical Leave	04	Degree of Injury	Serious	
Driver				
Name	LIM SOCK HENG	ID No.	S1728375H	
Related Vehicle	SFN330C (Car)	Contact No.	NIL	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	



**SINGAPORE
POLICE FORCE**



T/20160822/2134

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No. 1800-5872999

3 of 4
Report No. T/20160822/2134

CONTINUATION OF REPORT

Brief Details.

On the 21/08/2016 at 2020hrs, I left my in laws place at Blk 486C Tampines Ave 9 and wanted to have dinner at Tampines St 21. At 2030hrs I was riding my motorcycle, FBG1135C, and was exiting the carpark of Blk 486C Tampines Ave 9 together with my wife, Yuliyana, when I stop at the stop line right before exit to check for on coming traffic when I spotted a Red Kia Cerato, SFN330C, coming from a bend along Tampines Ave 9 before a traffic light about 70metres away. The mentioned vehicle had his left signal light on which I infer that he intended to make left turn into the car park that I was exiting. Therefore, I moved off and made a left turn, when I was right about opposite Blk 485A Tampines Ave 9, I was hit from the rear which cause myself and my wife to mount the curb on the left and fall over.

I then quickly got up and checked on my wife who is 8months pregnant, groaning in a seating position by the time I got up. I then called for the ambulance for assistance and also called my mother in law to informed my brother in law about the accident. Shortly after the ambulance came and we were conveyed to Changi General Hospital for treatment. My brother in law, Hakeem, came down to the scene to assist the Traffic Police who was a scene with the investigation. My brother in law then helped me in the retrieval of particulars of the other party and also the report number from the Police.

I received treatment for the injuries sustained on my left leg and arms and I also suffer stiffness on the right side of my neck. I was treated on the 21/08/2016 and was discharged later on the 22/08/2016. My wife is currently still at the hospital receiving treatment for fractured left shoulder blade.

GLOBAL MOTORSPORT

53 Ubi Ave 1 #01-12 Paya Ubi Industrial Park, Singapore 408934

Tel : 63453687 Fax : 67485449

Company Registration No: 53143853L

INVOICE

To: Rudy Asmara Bin Abdul Samad
Blk 478 Pasir Ris Drive #02-425
Singapore 510478


Invoice No.: GM1116/078
Date : 25 Nov 2016
Vehicle No.: FBG1135C
Page : 1 of 1

RE: ACCIDENT INVOLVING FBG1135C & SFN330C ON 21 AUG 2016 ALONG
TAMPINES AVENUE 9 OPP BLK 485A TAMPINES AVENUE 9 AT ABOUT
2030 HOURS

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Lump Sum Repair	\$6,000.00
Towing Fee	<u>\$ 35.00</u>
	\$6,035.00
	=====

Singapore Dollars: Six Thousand and Thirty - Five Only.

For and on behalf of
Global Motorsport



A handwritten signature in black ink, consisting of a large, stylized loop that crosses itself, positioned above a horizontal line.

AJAX

Inspection Services Pte Ltd

Date : 12 December 2016

To : **NTUC Income Co-operative Limited**
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn : Ms Rajeswary Doraisamy

AJAX Inspection Services Pte Ltd
120 Lower Delta Road
#08-08, Cendex Centre
Singapore 169208
Tel: +65 6255 0808
Fax: +65 6849 9155
info@ajaxinspection.com

Invoice No – AV06849
Company Reg No -201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/0912556-002 ✓
OUR REF : AVS2016-07561/SA
TP VEHICLE NO : FBG1135C ✓
CLAIM TYPE : PRE-REPAIR SURVEY
DATE OF SURVEY : 20 September 2016

No.	Description	Amount (S\$)
1	Professional fee	50.00
Total		50.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Rajeswary D/o Doraisamy

Assign Date:	20/09/2016	Survey Date:	20/09/2016	Our Ref:	AVS2016-07561/SA
Accident Date:	21/08/2016	TP Policy No:	TBA	Your Ref:	MT/0912556-002
Place of Survey:	Global Motorsports 53 Ubi Avenue 1, Paya Ubi Industrial Park #01-12 Singapore 408934	Claim Type:	Third Party		

Description of Vehicle:

Veh. No:	FBG1135C	Make/Model:	Suzuki GSR750AL2
Colour:	Black	Engine No:	R749112258
Engine Capacity:	749cc	Chassis No:	JS1C5112100101658
Odometer:	1731	Reg. Date:	28/03/2012

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	NA
Handbrake:	NA	Footbrake:	NA	Paint work:	Good
Tyre Make:	Pirelli				
Front Tyre Size:	120/70/17	Front Side:	6mm		
Rear Tyre Size:	180/70/17	Rear Side:	6mm		

Description of Damage:

The vehicle sustained damage on the rear portion.

The exhaust, box compartment, cowling, balancer and fork assy were among the items affected.

Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than S\$5,500.00 and could take approximately five (5) working days to complete.

All the stated damage are subject to consistency of the mentioned accident.



Adjuster:

Sani
Motor Appraiser

Date

COMPLETED 11/09/2016

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Condex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AV52016 07561/SA

Your Ref: MT/0912556-002

Pre-repair survey - 20/09/2016



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R


①

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2016-07561/SA
Your Ref: MT/0912556-002

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6253 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067K

2


AJAX

Inspection Services Pte Ltd

Our Ref: AVS2016-07561/SA

Your Ref: MT/0912556-002

Re-survey items - 13/10/2016



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

3

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2016-07561/SA

Your Ref: MT/0912556-002

Re-survey items



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

④

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2016-07561/SA

Your Ref: MT/0912556-002

Re-survey items

Post repair survey - 18/11/2016




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

5

307c-f



INVOICE

TO : RUDY ASMARA BIN ABDUL SAMAD
C/O: GLOBAL MOTORSPORT
53 UBI AVE 1 #01-12 PAYA UBI IND
PARK
SINGAPORE 408934

Invoice No.: 10/FBG1135/GM/587
Date: 31 OCTOBER 2016

PARTICULARS

Vehicle Registration No.: FBG 1135 C
Date of Loss: 21 AUGUST 2016
Date of Assessment: 14 OCTOBER 2016

SERVICES

1. Assessment with report Photographs - Including films, developing, storage and Transport.

FEES

\$400.00

TOTAL \$400.00

SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of
the cheque.

AEON AUTO CONSULTANTS LLP



AUTOMOBILE ASSESSMENT REPORT

TO: RUDY ASMARA BIN ABDUL SAMAD
C/O: GLOBAL MOTORSPORT
53 UBI AVE 1 #01-12 PAYA UBI IND PARK
SINGAPORE 408934

Our Reference: 10/FBG1135/GM/587
Date: 31 OCTOBER 2016

ASSESSMENT OF VEHICLE NO. FBG 1135 C DATE OF LOSS: 21/08/2016

We have carried out a physical assessment of FBG1135C at **GLOBAL MOTORSPORT**, 53 Ubi Ave 1 #01-12 Paya Ubi Ind Park, Singapore 408934, according to your instruction on **14 OCTOBER 2016** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: FBG 1135 C
Make & Model: SUZUKI GSR750AL2
Year of Registration: 2012
Engine Capacity: 749
Chassis No.: JS1C5112100101658
Engine No.: R749112258
Colour: BLACK

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front

Make/Size/Thread: PIRELLI 120/70 17R - 70%

Rear

Make/Size/Thread: PIRELLI 180/55 17R - 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT to REAR portion.

5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$ 8,774.89
Adjusted Amount: \$ 8,374.89 (Lump Sum of \$6,000.00)
Estimated Repair Days: 10 days


Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.



ASSESSMENT REPORT FOR VEHICLE NO. FBG 1135 C

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	SIDE MIRROR LH	Cracked	105.30	105.30 ✓
1	HANDLE BAR	Bent	185.00	185.00 ✓
2	HANDLE BAR GRIP L/R	Cut	104.00	104.00 ✓
2	HANDLE BAR BALANCER L/R	Bent	106.00	106.00 ✓
2	HANDLE BAR UPPER CLAMP L/R	Bent	96.00	96.00 ✓
1	HEAD LAMP	Cracked	520.00	520.00 ✗
1	HEAD LAMP STAY	Cracked	120.00	120.00 ✗
1	CLUTCH LEVER	Bent	65.00	65.00 ✓
1	FRONT SIGN LAMP LH	Cracked	72.90	72.90 ✓
1	STEERING STEM ASSY	Bent	280.00	280.00 ✗
1	STEERING STEM RACE BEARING	Jammed	110.00	110.00 ✗
1	FRONT FORK ASSY	Bent	720.00	720.00 ✗
1	FRONT WHEEL SHAFT	Bent	48.00	48.00 ✓
1	FRONT WHEEL RIM	Bent	850.00	850.00 ✓
1	FUEL TANK	Bent	670.00	670.00 ✗
1	SIDE BODY COWLING LH	Cracked	280.00	280.00 ✓
1	FRONT MUDGUARD	Cracked	245.00	245.00 ✓
1	ENGINE LOWER COWLING	Cracked	320.00	320.00 ✓
1	REAR SEAT COWLING	Cracked	420.00	420.00 ✓
1	SIDE FRAME RUBBER PROTECTOR	Bent	40.00	40.00 ✓
1	TAIL LAMP	Cracked	154.00	154.00 ✗
1	TAIL LAMP TOP GARNISH	Cracked	28.00	28.00 ✗

ASSESSMENT REPORT FOR VEHICLE NO. FBG 1135 C

1	REAR MUDGUARD	Cracked	180.00	180.00 ✓
1	REAR SIGNAL LAMP LH	Cracked	75.20	75.20 ✓
1	TAIL BOX BRACKET	Bent	210.00	210.00 ✓
2	TAIL BOX L/R	Cracked	650.00	650.00 ✓
1	REAR FOOT REST PADDAL LH	Bent	78.00	78.00 ✓
1	REAR FOOT REST BRACKET LH	Bent	190.00	190.00 ✓
1	FOOT GEAR SELECTOR LEVER	Bent	132.00	132.00 ✓
1	FRONT FOOT REST PADDAL LH	Bent	79.00	79.00 ✓
1	FRONT FOOT REST BRACKET LH	Bent	210.00	210.00 ✓
			7,343.40	7,343.40
Less 15% discount			1,101.51	1,101.51
Parts Total:			6,241.89	6,241.89

SPECIAL NETT ITEMS

1	FRONT FORK OIL	Necessary	18.00	18.00 ✓
1	FRONT FORK OIL SEAL AND DUST COVER SET	Necessary	60.00	60.00 X
1	FRONT TYRE	Cut	180.00	180.00 70%
1	ARROW EXHAUST PIPE ASSY	Cracked	750.00	750.00 X
1	REAR NUMBER PLATE	Bent	25.00	25.00 ✓
Special Nett Total :			1,033.00	1,033.00

4741.4
 15%

 4030.18

ASSESSMENT REPORT FOR VEHICLE NO. FBG 1135 C

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	Check wiring system and light.	150.00	100.00 ✓
2	To check, align and balance chassis main frame.	500.00	300.00
3	Labour Charges.	550.00	450.00 300
4	Re-painting.	300.00	250.00 ✓
Labour Total :		1,500.00	1,100.00
TOTAL (PARTS & LABOUR) \$		8,774.89	8,374.89

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is **\$6,000.00** (SINGAPORE DOLLARS SIX THOUSAND ONLY)



Amas Ong
Automobile Assessor



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TAN KOK QUAN PARTNERSHIP		Ref : CS/LAW19011739/Usd3e2	
1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881		Date : 16-07-2019	
		Code : L021	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SFN 330C	Veh. Inspected	FBG 1135C
Policy No.		Coverage (\$)	0.00
Claim No.	TWK/AR/1253.18/ntuc/ml/PI+PD	Excess (\$)	0.00
Assign From	MICHELLE LIEW	Assign Date	17/06/2019
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI GSR750AL2	c.c	749
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JS1C5112100101658	Colour	BLACK
Odometer	119661	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70Z R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/70Z R17	PIRELLI	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	21/08/2016	Inspection Date	10/07/2019
Survey held at	GLOBAL MOTOR PTE LTD 53 PAYA UBI INDUSTRIAL #01-12 UBI AVE 1 SINGAPORE 408934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 1135C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE MIRROR LH	REPLACED	105.30	105.30
1	HANDLE BAR	REPLACED	185.00	185.00
2	HANDLE BAR GRIP L/R	REPLACED	104.00	104.00
2	HANDLE BAR BALANCER L/R	REPLACED	106.00	106.00
2	HANDLE BAR UPPER CLAMP L/R	REPLACED	96.00	96.00
1	HEAD LAMP	CAN'T SEE DAMAGE	520.00	-
1	HEAD LAMP STAY	CAN'T SEE DAMAGE	120.00	-
1	CLUTCH LEVER	REPLACED	65.00	65.00
1	FRONT SIGN LAMP LH	REPLACED	72.90	72.90
1	STEERING STEM ASSY	CAN'T SEE DAMAGE	280.00	-
1	STEERING STEM RACE BEARING	CAN'T SEE DAMAGE	110.00	-
1	FRONT FORK ASSY	CAN'T SEE DAMAGE	720.00	-
1	FRONT WHEEL SHAFT	REPLACED	48.00	48.00
1	FRONT WHEEL RIM	REPLACED	850.00	850.00
1	FUEL TANK	CAN'T SEE DAMAGE	670.00	-
1	SIDE BODY COWLING LH	REPLACED	280.00	280.00
1	FRONT MUDGUARD	REPLACED	245.00	245.00
1	ENGINE LOWER COWLING	REPLACED	320.00	320.00
1	REAR SEAT COWLING	REPLACED	420.00	420.00
1	SIDE FRAME RUBBER PROTECTOR	REPLACED	40.00	40.00
1	TAIL LAMP	CAN'T SEE DAMAGE	154.00	-
1	TAIL LAMP TOP GARNISH	CAN'T SEE DAMAGE	28.00	-
1	REAR MUDGUARD	REPLACED	180.00	180.00
1	REAR SIGNAL LAMP LH	REPLACED	75.20	75.20
1	TAIL BOX BRACKET	REPLACED	210.00	210.00

Report Ref No. CS/LAW19011739/Usd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAIL BOX L/R	REPLACED	650.00	650.00
1	REAR FOOT REST PADDAL LH	REPLACED	78.00	78.00
1	REAR FOOT REST BRACKET LH	REPLACED	190.00	190.00
1	FOOT GEAR SELECTOR LEVER	REPLACED	132.00	132.00
1	FRONT FOOT REST PADDAL LH	REPLACED	79.00	79.00
1	FRONT FOOT REST BRACKET LH	REPLACED	210.00	210.00
	LESS 15% DISCOUNT		-1,101.51	-711.21
			6,241.89	4,030.19
	SPECIAL NETT ITEMS			
1	FRONT FORK OIL (SN)	NOT NECESSARY	18.00	-
1	SET FRONT FORK OIL SEAL AND DUST COVER (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE (SN) (70%)	CUT	180.00	126.00
1	ARROW EXHAUST PIPE ASSY (SN)	NOT CHANGED	750.00	-
1	REAR NUMBER PLATE (SN)	REPLACED	25.00	25.00
			1,033.00	151.00
	LABOUR			
	CHECK WIRING SYSTEM AND LIGHT.	NOT NECESSARY	150.00	-
	TO CHECK, ALIGN AND BALANCE CHASSIS MAIN FRAME.)		500.00	300.00
	LABOUR CHARGES.)		550.00	-
	RE-PAINTING.		300.00	250.00
			1,500.00	550.00
	GRAND TOTAL		8,774.89	4,731.19
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS/LAW19011739/Usd3e2

CHUA KANG SENG
Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinatAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.