

ASS. REC. BY:

REF: CS/ICS K011746/K19d3^{S2}

Special instruction:

Surveyor: Kainn

ASSIGNMENT (Office)

From (Person): Desmond Lee

of ECICS

Date/Time: 2.7.19 11:59 AM

Estimated Cost:

Bill to:

OD (TP) WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHA 69924

Insured:

SDW 797R

at Workshop m/s Confortdesign

Tel: 6214 8355

of 521 Lowlands Way

Policy No:

Claim No: DMPC 19001694

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 29.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2.7.19 11:59 AM

Person Contacted: Lim

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 69924 - NS/NC 18218055/K19bn2 D.O.A - 03/10/2018
	SDW 797R - X
07/7/19 SA	10:59am revised to Desmond Lee via Message.

08/11/13

REF:

Surveyor: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 6992Y Yr Regn: 28 Sep 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 238456 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU603564863Gen. Cond: Good / ~~Ex~~ / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DonatiFront 7 mm Rear 7 mmR/Bal. 7 mmL/Bal. 7 mmD.O.A. 29/6/19 D.O.I. 2/7/19Survey held at CPHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/7/19 Chnd P/P \$813.28 / 20% Cred \$244.43, 75% ECZCS P/P

RECEIVED 8 JUL 2019

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)Survey Fee: 350

Transportation:

S - RS: \$1

Photos:

813.28

Catherine Chong (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Tuesday, 2 July, 2019 11:25 AM
To: assignments
Subject: FW: Our Claims Ref No: DMPC1900169H/DL // SHA6992Y with your insured SDW797R
Attachments: img-701105641-0001.pdf
Importance: High

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Tuesday, 2 July 2019 11:24 AM
To: Lim Kwok Eng <limke@cdge.com.sg>; motorsurvey <motorsurvey@ecics.com.sg>; SUR <sur@lkkauto.com>
Cc: Ng Nyuk Phin <ngnp@cdge.com.sg>; Roger How Keen Meng <rogerhow@cdge.com.sg>
Subject: Our Claims Ref No: DMPC1900169H/DL // SHA6992Y with your insured SDW797R
Importance: High

Dear LKK

Please assist with the PRI.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond.Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Lim Kwok Eng [<mailto:limke@cdge.com.sg>]
Sent: Tuesday, 2 July 2019 11:16 AM
To: motorsurvey
Cc: Ng Nyuk Phin; Roger How Keen Meng
Subject: Re: SHA6992Y with your insured SDW797R

Hi Desmond,

We agree LKK to survey, thanks.

Best Regards
Lim Kwok Eng
Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd
Tel. 6214-8355 / 6214-8156

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Tuesday, 2 July 2019 10:30 AM
To: Lim Kwok Eng; motorsurvey
Cc: Ng Nyuk Phin; Roger How Keen Meng
Subject: RE: SHA6992Y with your insured SDW797R

Without prejudice

Dear Mr Lim

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards
Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond.Lee@ecics.com.sg

Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Lim Kwok Eng [<mailto:limke@cdge.com.sg>]
Sent: Monday, 1 July 2019 11:10 AM
To: motorsurvey
Cc: Ng Nyuk Phin; Roger How Keen Meng
Subject: SHA6992Y with your insured SDW797R

To Officer In Charge

Pls arrange surveyor, refer attachment

Best Regards
Lim Kwok Eng
Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd
Tel. 6214-8355 / 6214-8156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of

the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Jul 2019

Preliminary Advice

Insured Vehicle No	: SDW797R	Accident Date	: 29/06/2019
TP Vehicle No	: SHA6992Y	Assignment Date	: 03/07/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 2.00
Date of Inspection	: 02/07/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,237.71
Revised Amount	:S\$	813.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	813.28

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/07/2019 07:11
Date Of Accident	29/06/2019 11:00
Exact Location Of Accident	BRAS BASAH RD X NORTH BRIDGE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA6992Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN KAY JOO
NRIC No	S1566830Z
Date Of Birth	29/10/1962
Occupation	OUTDOOR
Date Of Driving Pass	29/10/1962
Driving Experience	56 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91871262
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	536 09-2559 ANG MO KIO AVE 10
Postcode	560536
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SDW797R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT RHT

No. Of Passenger (Including Driver)

SKETCH PLAN

A: RHA 6992Y

B: SDW 797R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/6/19 at about 11:00 hrs, I was driving straight at above said location with a male pax onboard. Suddenly veh B cut into my lane and it right front portion hit & grazed onto the left rear portion of my taxi. Both of us then alighted to take photo. No injury at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199393821P
Policyholder's Signature

Driver's Signature

Reporting Centre Personnel's Signature

29/6/19

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 199303821P

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: **Loke Wei Yieng**
NRIC/FIN No.:





> Back to OneMotoring




Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHA6992Y
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZRS065687
Chassis No.:	JTDKB3FU603564863
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	28 Sep 2017
First Registration Date:	28 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$35,265.00
COE Rebate Amount:	\$27,477.00
Total Rebate Amount:	\$31,227.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jul 2019

OK





COMFORT DELGRO

Date/Time: 01.07.2019 10:28 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305307525

OWNER: COMFORT TRANSPORTATION PTE LTD
AS: 7010045
OWNER NO: 383 SIN MING DRIVE
RESS: Singapore SINGAPORE 575717
(R) 65508755 (O)

ECICS


REGN NO: SHA6992Y	MILEAGE
MAKE: TOYOTA	FUEL E 1/2 F
MODEL: PRIUS HYBRID(G4)	DATE/TIME IN 29.06.2019 11:45
YR OF MANUF: 28.09.2017	TARGET DATE
CHASSIS CODE: JTDKB3FU603564863	COMPLETION DATE/TIME

OUNT CARD NO.

JOB DESCRIPTION

Accident Date: 29.06.2019
NATURE: 3P 29.06.2019

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge ment Slip

Exit Pass

No.:

SHA6992Y

LKE

Vehicle No.:

SHA6992Y

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 6992Y

1/7/2019 10:18

MAKE :

MODEL : TOYOTA PRIUS

Like

ECIES

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR FENDER, LH <i>X rep</i>			\$ 836.70
REAR FENDER SHEILD (LH) <i>X su</i>			\$ 134.20
REAR TYRE RIM ,LH <i>X su</i>			\$ 1,555.00
<i>rear fender (LH) X rep</i>			
<i>rear (LH) wheel cover</i>			
SUB TOTAL		<i>\$177.70 \$177.70</i>	\$ 2,525.90
LESS 25%			\$ 631.48
DISCOUNTED TOTAL			\$ 1,894.43
REAR DOOR COMFORT & APPS STICKER <i>✓</i>			\$ 80.00
LABOUR CHARGE			
Panel Beating			<i>200</i> \$ 400.00
Spray Painting Charge			\$ 600.00 <i>800</i>
Tuff Kote			\$ 50.00 <i>X 17</i>
Rear Wheel Alignment			\$ 80.00 <i>X 2</i>
TOTAL LABOUR			\$ 1,130.00
ESTIMATE TOTAL			\$ 3,104.43 <i>3237.70</i>


Kali (UCL)

2/7/19 1505h

2 by,

PIP

Alfa Repor photo



This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No 305307525
Date : 06.07.19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM


To : LKK Fax :
Attn : Mr KALVIN ANG
Vehicle Reg No. SHA6992Y CTPL 29.06.19


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ECICS SDW797R
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$213.28
(b) Labour Charges	\$600.00
Total for Part-By-Part Repair Cost	\$813.28
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Kaha
Date : 8/7/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305307525
REGN NO : SHA6992Y
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 28.09.2017
DATE/TIME IN : 29.06.2019 11:45
ACCIDENT DATE : 29.06.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0302-2057-G PRIG4 CAP WHEEL 1 L 177.70 25.00 133.27

0002 28-01-0103-2013-A I40V3 APP LOGO REAR DOOR 1 N 80.00 2.50- 80.00

SUB-TOTAL : 213.27

JOB NATURE

0000 L PANEL BEATING 200.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA 400.00

SUB-TOTAL : 600.00

TOTAL : 813.27

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019 10:58 Edit Reg		02 Jul 2019 00:00 Edit Adj Rpt	S\$813.27 Edit Estimates	S\$813.27 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: NOEMAIL@NOEMAIL.COM		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA6992Y	Date of Loss:	29/06/2019 11:00 - :59 [21 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SDW797R	Policy No. (Claimant):	
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 12/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*SHA6992Y

[SDW797R]

TP

COMFORT TRANSPORTATION PTE LTD

Jun 29 2019 11:00AM

[-]


ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
































Assessment Reports

1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/07/19 10:59	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/07/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/07/19 14:05	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
23	08/07/19 14:05	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
24	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	08/07/19 14:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19011746/K1QD3S2

Date: 12/07/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHA6992Y	Insured Vehicle No :	SDW797R
Date of Loss:	29/06/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA6992Y	Engine No:	2ZRS065687
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU603564863
Reg. Date:	28/09/2017 (Man. Year: 2017)	Odometer:	238456 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,107.70	213.27	1,894.43	89.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	600.00	530.00	46.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,237.70	813.27	2,424.43	74.88
+ GST 7.00/7.00% (S\$)	226.64	56.93	169.71	74.88
Nett Amount (S\$)	3,464.34	870.20	2,594.14	74.88

INSPECTION

Date of Assignment:	02/07/2019	
Date Inspected:	02/07/2019	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$813.28

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2019)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA6992Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER, LH	Repair	836.70 FL	*- FL
2	1		*REAR FENDER SHIELD (LH)	Serviceable	134.20 FL	*- FL
3	1		*REAR TYRE RIM, LH	Serviceable	1,555.00 FL	*- FL
4	1		*REAR DOOR (LH)(NPA)	Repair	0.00 FL	*- FL
5	1		*REAR WHEEL COVER (LH)	Missing	177.70 FL	*177.70 FL
6	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,783.60	257.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	675.90	44.43
Total Parts (\$\$)	2,107.70	213.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	400.00	200.00
2	SPRAY PAINTING CHARGE.	New	600.00	400.00
3	TUFF KOTE.	New	50.00	0.00
4	REAR WHEEL ALIGNMENT.	New	80.00	0.00
Gross Labour Cost (S\$)			1,130.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >