

NATIONAL Assessment Centre Services

* Date In: 03/07/19	Job description	Date & Time Completed	Done by
Ref No: NA/INC19011752/63	SAS e-filing		
Veh No: SJM9807T	E-mail (within 8hrs. AIC 2hrs)		
DOA: 02/07/19 1830	i-Motor Claim Form	MT/1051662-001	
TP / Reporting Only	i-Motor W/O (Within: OD 2hrs. TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: SCR291014	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case : to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co. ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury :

Date/Time	Actions

Claimant's Particulars :-	Invoice Preparation Checklist	Amt (\$)	Amt (\$)
		1st Bill	Add Bill
Driver/Owner:	1) AR : Accident Reporting (\$30);		
Contact No:	2) DA : Damage Assessment (\$100); INC (\$80)		
Damaged Portion:	3) TF : Towing Fee \$40/\$45		
QC Checked by (Engr-In-Charge):	4) FT : Follow-Through Survey \$120		
Auditors' Comments :-	5) FT : Follow-Through Survey (Resurvey) \$30		
Cat 1:	For claiming against INC Only (wef 10 Jan 2005)		
Cat 2 / 3:	6) TR : Re-inspection \$75		
	7) N1 : Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	OD*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11) : TP (Non INC) against INC \$20		
	9) N12: Idac Mobile \$30		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2019 10:12
Date Of Accident	02/07/2019 18:30
Exact Location Of Accident	LORNIE VIADUCT TWDS BRADDELL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM9807T
Insured/Policyholder	
Name Of Registered Owner	TAY WEE KIAT
NRIC No	S9604373B
Email Address	A.SILVERTON@LIVE.COM
Mobile Phone No	(LOCAL) +65-98197790
Alternative Phone No	OTHERS-98197790

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107282892
Cover Note Number	

Driver

Name of Driver	TAY WEE KIAT
NRIC No	S9604373B
Date Of Birth	04/02/1996
Occupation	INDOOR
Date Of Driving Pass	21/02/2019
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98197790
Fax Number	
Contact Number	OTHERS-98197790
Email Address	A.SILVERTON@LIVE.COM

Address	BLK 3 UPPER ALJUNIED LANE
	#04-50
Postcode	360003
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR2910H
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE KOK YAN
NRIC/Passport Number	
Contact Number	81382283
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


03/07/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

03/07/19

SKETCH PLAN



A - SM9807T
B - SGR2910H
C - UNKNOWN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS DRIVING HOME FROM WORK, TOOK LORNIE HIGHWAY EXIT. AS I TOOK THE RIGHT LANE OF THE SLIP ROAD OUT, THE CAR STEERED TOO CLOSE/MUCH TO THE LEFT, RESULTING IN THE COLLISION. THERE WAS NO INTENTION TO FILTER.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ARMED FORCES
IDENTITY CARD

Name
TAY WEE KIAT

NRIC No
S9604373B

This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Manpower Base or any Police Station.

For LKK/NAC Use Only

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

NRIC No: **S9604373B**

TAY WEE KIAT

Birth Date: **04 Feb 1996**
Issue Date: **21 Jan 2019**

002894347B

OCMALFOSGP0102451903116

NRIC No/Colour
S9604373B/ PINK

Race
CHINESE

Date Of Birth
04/02/1996

Service Status
NSF

Address
**Blk 3 UPPER ALJUNIED LANE
#04-50 SINGAPORE 360003**

Blood Group
B (+)

Country Of Birth
SINGAPORE

Military Rank Status
ENLISTEE

Sex
M

For LKK/NAC Use Only

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg	EFFECTIVE DATE
Class 3		21 Jan 2019

NP 428A

Licence No: **S9604373B**

a.silverton@live.com

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	02/07/2019 18:30							
Vehicle No.(For Motor)	SJM9807T	Certificate Number								
Search										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5107282892		TAY WEE KIAT	S9604373B	GPC	drive CLASSIC	SJM9807T	SJM9807T	30/01/2019	29/01/2020
Continue										

Claim Handling

Accident MT/1051662

Policy No.	5107282892	Vehicle No.	SJM9807T	GST Registration No.
Certificate No.				
Policyholder Name	TAY WEE KIAT			Policyholder NRIC
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading
Contact No.(Mobile)	98197790	Contact No.(Office)	0	Contact No.(Home)
Email Address		Special Remark		eCode
KFK	☐ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason
NCD Protection	No	NCD Entitlement(%)	0	Private Hire

▼ Accident Details

Report Date	03/07/2019 11:14	Accident Report Within 24 hrs	Yes	Accident Type
Date of Accident	02/07/2019	Time of Accident hh:mm	18:30	Country of Accident
Reporting Centre		Orange Force		ICM No.
Accident Location	LORNIE VIADUCT TWDS BRADDELL RD			

▼ Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00	
OD Standard Excess		TP Standard Excess	0.00	
YIED OD Excess		YIED TP Excess	0.00	Driver is Covered?
Additional Excess				
Total OD Excess Applicable		Total TP Excess Applicable	0.00	

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 3 #04-50	Address 2	UPPER ALJUNIED LANE	Address 3
Address 4	SINGAPORE 360003	Address Type	Singapore address	Post Code
Unit No.	04-50	Related Policy Number	5107282892	

▼ OI Driver Info

Driver Name	TAY WEE KIAT	Driver Type	Main Driver	
Unnamed driver Name		Driver NRIC	S9604373B	Driver DOB
Register Date of Driver License	21/01/2019	Driver Age	29	Driving Experience
Contact No.(Mobile)	98197790	Contact No.(Office)	0	Contact No.(Home)
Address 1	BLK 3	Address 2	UPPER ALJUNIED LANE	Address 3
Address 4	SINGAPORE 360003	Address Type	Singapore address	Post Code
Unit No.	#04-50			
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Com.

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 OD-MD

New

Claim Type *	OD-MD	Insured Name	TAY WE
Contact No.(Mobile)	98197790	Contact No. (Home)	628537
Email Address	silvertan@live.com	Vehicle Number	SJM980
Claim Description	SJM9807T / SGR2910H ON 2 Jul 2019		
Preferred Workshop		Insured Liability	Fully at Fault
Workshop No. Finalisation	Yes	Preferred Repair Option	Income to assign workshop
Date Registered		GIA report	Received
		Claim Close Date	03/07/2019 11:18

Report Taken By

ROSLINDA

Workshop
Repairer

Print AK letter

Save

Submit

Attachment

Accident No. MT/1051662 Claim No. 001
 Last Doc. Received ☒ Yes ☐ No Upload Date 03/07/2019 00:00

Path *	Category *	Confidential
Choose File No file chosen	Clear Please Select	NO
Choose File No file chosen	Clear Please Select	NO
Choose File No file chosen	Clear Please Select	NO
Choose File No file chosen	Clear Please Select	NO
Choose File No file chosen	Clear Please Select	NO
Choose File No file chosen	Clear Please Select	NO
Choose File No file chosen	Clear Please Select	NO

Message Read

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Des.
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:18	NRIC/ Driving License	Normal	NRIC/ Driving
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:18	SAS	Normal	SAS
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:18	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Jul 2019 11:17	Photos	Normal	Photos

Video List

Uploaded By/Date

Folder Date

File Name

Display in New Window

Scan and uploading



ASSIGNMENT (IDAC)

COE Expired : 21 Jan 2024

By CSO - Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motor Car ()
 - b) Motorcycle ()
 - c) Bicycle ()
- 2) Vehicle hit ??
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govn Property ()
(E.g. signboard, barrier, tree etc)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other ()
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case
 - a) Stolen ()
 - b) Damage found when recovered ()
- 8) Fire
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SJM 980TT Yr Regn: 22 Jan 2009
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover / M102 / Truck / Trailer or
 Make & Model: Honda Fit 1.3 G A CC: 1339
 Colour: White Transmission Type: Auto / Manual
 Eng/No: Sp. Reading: 125596
 C/No: GE6 1101027
 Gen. Cond: Good / Fair / Poor / Burnt or
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/55 R15
 R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>3</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>3</u> mm

Parallel Import: Yes / No
 Towed-In: Yes / No
 Repair Type: LS / I.B.I
 Towing Required: Yes / No
 No of Repair Days: 9
 Vehicle in Idac: Yes / No
 D.O.I: 3/7/2009
 Time: 2.45pm

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govn Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started

Time Completed

1) CSO

2) ASS

3) Entire Operation Completed Time

MOTOR CAR (Frt)

Front Portion

Vehicle No: **SJM 980TT**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	CRA		
1006	991325	Frt Bumper Bracket	KEC	6	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	DIS	2	
1009	991318	Frt Bumper Beam	DD		
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Tow Eye Cover	MIS		
1013	991363	Frt Bumper Grille	DS		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover	BT		
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	BR		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BT		
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray	DD		

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel	Buc		
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	CRA		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	CT		
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CRA		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy	JM		
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy	JM		
1136	990247	Sticker			
		LH Headlamp Lower Bracket	CRA		
		Frt LH Door	SCR		
		" " " Wing Mirror	BR		
		" " " Window Glass	CUT		

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ALLIANCE

(1) Replace (✓) (2) Repair (X) (3) Check (X)
(4) Not Consistent (NC)

2 of 2

Vehicle No:

SJM 980 TT

[illegible]

Assessor: _____

Original copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4373B
Vehicle Details	
Vehicle No.:	SJM9807T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A4112412
Chassis No.:	GE61101027
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,329.00
Original Registration Date:	22 Jan 2009
First Registration Date:	22 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$9,838.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$11,833.00
Total Rebate Amount:	\$11,833.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jul 2019

OK

Claim Handling

▼ Accident MT/1051662

Task Transfer Exit

LOS SAL SUB

Policy No.	5107282892	Vehicle No.	SJM9807T	GST Registration No.	
Certificate No.					
Policyholder Name	TAY WEE KIAT			Policyholder NRIC	S9604373B
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	98197790	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No ▼
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

▼ Accident Details

Report Date	03/07/2019 11:14	Accident Report Within 24 hrs	Yes	Accident Type	Side Swipe
Date of Accident	02/07/2019	Time of Accident hh:mm	18:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	LORNIE VIADUCT TWDS BRADDELL RD				

▼ Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess		TP Standard Excess	0.00		
YIED OD Excess		YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess					
Total OD Excess Applicable		Total TP Excess Applicable	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 3 #04-50	Address 2	UPPER ALJUNIED LANE	Address 3	JOO SENG GREEN
Address 4	SINGAPORE 360003	Address Type	Singapore address	Post Code	360003
Unit No.	04-50	Related Policy Number	5107282892		

▼ OI Driver Info

Driver Name	TAY WEE KIAT	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S9604373B	Driver DOB	04/02/1996
Register Date of Driver License	21/01/2019	Driver Age	23	Driving Experience	0
Contact No.(Mobile)	98197790	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 3	Address 2	UPPER ALJUNIED LANE	Address 3	JOO SENG GREEN
Address 4	SINGAPORE 360003	Address Type	Singapore address	Post Code	360003
Unit No.	#04-50				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No
Modification History	03/07/2019 15:31 s069588 Modify Driver DOB(04/02/1990-->04/02/1996) 03/07/2019 15:31 s069588 Modify Driver Age(29-->23)		

▼ Investigation

Claim 001 OD-MD

▼ Claim Case Officer Yap Chee Ling

Claim Type	OD-MD	Insured Name	TAY WEE KIAT	Insured NRIC	S9604373B
Contact No.(Mobile)	98197790	Contact No. (Home)	62853705	Contact No. (Office)	
Email Address	a.silverton@live.com	OI Vehicle Number	SJM9807T	TP Vehicle Number	SGR2910H
Claim Description	SJM9807T / SGR2910H ON 2 Jul 2019			Name of Preferred Workshop	
Preferred Workshop	Yes	Preferred Repair Option	income to assign workshop	Insured Liability report	Fully at resolved
Date Registered	03/07/2019 11:18	Claim Close Date		Date Received	03/07/2019 15:1
Report Taken By	ROSLINDA	Workshop Repairer		Total Loss but Repaired	

[Print AK letter](#)OD Excess
Collected by
Workshop[Modification History](#)

Special Claim Creation Approval

Approval Reason

Remarks

damage assessment

[Attachment](#)

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	FIT	Engine Capacity
Date of Registration	22/01/2009	Classis No.	GE61101027	
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA	
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No	
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)

NO OF REPAIR:09 DAYS:AIRCON SUCTION PIPE-UNCONFIRM,AIR DUCT-UNCONFIRM,FRT LH WHEEL RIM-REPLACE,LH HEADLAMP LOWER BRACKET-REPLACE,FRT LH TIE ROD-UNC

Remark

Remark for
Supplementary

Damage Listing

No.	Part No.	Description	Qty *	Repair Code *
1	16000101	BUMPER (FRONT)	1	Replace
2	16002401	BUMPER CLIPS (FRONT)	6	Replace
3	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace
4	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace
5	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace
6	16006701	BUMPER TOWING COVER (FRONT)	1	Replace
7	16003201	BUMPER GRILLE (FRONT)	1	Replace
8	27100101	GRILLE (FRONT)	1	Unconfirm
9	27100801	GRILLE EMBLEM (FRONT)	1	Unconfirm
10	112023	AIR CON CONDENSER	1	Replace
11	112060	AIR CON FAN	1	Unconfirm
12	112044	AIR CON DISCHARGE PIPE	1	Unconfirm
13	344001	RADIATOR	1	Unconfirm
14	344005	RADIATOR COWLING	1	Unconfirm
15	344008	RADIATOR FAN	1	Unconfirm
16	141001	BATTERY	1	Unconfirm
17	141002	BATTERY BRACKET	1	Replace
18	41300101	SUPPORT PANEL (FRONT)	1	Replace
19	27700101	HEAD LAMP (LEFT)	1	Replace
20	27700102	HEAD LAMP (RIGHT)	1	Unconfirm
21	43600101	TYRE (FRONT LEFT)	1	Unconfirm
22	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace
23	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Unconfirm
24	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm
25	25400102	FENDER (FRONT LEFT)	1	Replace
26	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace
27	36300102	SEAT BELT (FRONT RIGHT)	1	Replace
28	36300101	SEAT BELT (FRONT LEFT)	1	Replace

Find a Part				
root	29	23300201	DOOR (FRONT LEFT)	1 Repair
Not Applicable	30	23304102	DOOR MIRROR (FRONT LEFT)	1 Replace
ABS	31	23302001	DOOR GLASS (FRONT LEFT)	1 Replace
ABSORBER	32	30000101	KNUCKLE ARM (FRONT LEFT)	1 Unconfirm
ACCELERATOR	33	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1 Unconfirm
ACTUATOR	34	30500101	LOWER ARM (FRONT LEFT)	1 Replace
ADVERTISEMENT STICKER	35	23600101	DRIVE SHAFT (FRONT LEFT)	1 Replace
AIR BAG	36	401028	STEERING RACK & PINION	1 Unconfirm
AIR BLOWER	37	401021	STEERING CROSS MEMBER	1 Unconfirm
AIR BOX				
AIR CHAMBER BOX				
AIR CLEANER				
AIR COMPRESSOR				
AIR CON				
AIR CON (VAN)				
AIR COOLER				
AIR DISTRIBUTOR				
AIR FILTER				
AIR FLOW				
AIR GRILLE				
AIR HORN				
AIR INTAKE				
AIR RESONATOR BOX				
AIR THROTTLE BODY AND SENSOR				
ALARM				
ALTERNATOR				
ALUMINIUM PANEL - SIDE				
AMPLIFIER				
ANTENNA				
ANTI ROLL				
APRON				
ARCH				
ARM REST				
ASH TRAY				
AUTO CLUTCH				
AUTO COOLER PIPE				
AUTO CRUISE MOTOR				
AUTO TRANSMISSION				
AXLE				
BACK REST (M/C)				
BACK SEAT				
BALANCER				
BATTERY				
BEADING (M/C)				
BELT COVER (M/C)				
BELT TENSIONER				
BODY				
BODY (M/C)				

Save

Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SJM 9807 T Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Modern

Collection Date: 5/7/19 Time: 11:00 with Keys: Yes / No

Tow Truck No: YM 5128 T Tow Man: Keat NRIC: S7986726 H

Signature: [Signature] 84369169

For office use

Attended by: ROSKINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe
Deputy Vice President
Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



ISLAND TOWING SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

Co. Reg. 53269210A

Cash Sales/ Work Order

NO. 54689

Date: 02/07/19

M/S:

Car 56

Vehicle No: SJM 9807 Model: Honda Fit

From: Bladde Road Time Start: 1920

To: 53 Pkps Ubi Ave 1 Time End:

Remarks:

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 120/-

Received By

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to you vehicle whilst being transported.