

ASS. REC. BY:

REF: CSMSG 19011764/AGT83ⁿ² Special Instruction:Supervisor: Adrian

ASSIGNMENT (Office)

From (Person): Christina Wong of MSG Date/Time: 3/7/2019 @10:48

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 397IX Insured: SKP 28575at Workshop m/s Chew Motor Tel: 66431311of Kaki Bukit Auto bay.Policy No: 80910120 Claim No: S98481

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 1/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle-IN/OUT

| Date/Time | Action/Instruction () Estimate |
|-----------|------------------------------------|
| | SMJ 397IX - X |
| | SKP 28575 - X |
| | |
| | lump sum \$22001- (Red: 9709; 81%) |
| | 4days |

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMJ397IX Yr Regn: 6 / 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios c.c. 1897

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY9305112027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 02/07/19

Survey held at Chew Motor

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|----------------------|----------------------|
| | <u>TP MSLG.</u> |
| RECEIVED 03 SEP 2019 | |
| | <u>MV:</u> |
| | <u>PV:</u> |
| | <u>Nett:</u> |

| Date/Time, File Pass to? | Date/Time, File Return to? | Part Prices Check: | | Survey Fee: | Date: |
|--------------------------|----------------------------|--------------------|-----|-------------------|------------|
| 1) | 2) | IN | OUT | Basic & Add. | <u>200</u> |
| 3) | 4) | | | <u>S + RS, SI</u> | <u>11</u> |
| 5) | 6) | | | Photos | |
| Prel Report: | | | | Others | |
| Final Report: | | | | TOTAL | <u>211</u> |

View Sent Message

This mail is associated with :

***SMJ3971X (598481)**
[SKP2857S]

TP

NG ZAKINNAJIB @ ZAKINNAJIB BIN ABDUL MUKTI

Jul 1 2019 8:00AM

[HOONG JIA YIN SHEENA]

Chew Motor Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **03/07/2019 15:12 PM**.

To christina_wong@sg.msg-asia.com

Subject SMJ3971X (598481) [SKP2857S]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMJ 3971X on 02/07/2019
We are pending estimate from repairer.

Regards,
Denise

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|----------------------|---------------|------------------------------------------------------|---------|---------------|------------|-----------------------------------------------------------------|
| Main | 02 Jul 2019 16:28 | | 03 Jul 2019 10:48 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|
| Insured: | HOONG JIA YIN SHEENA, ID: S8410563E | | |
| Main Claimant: | NG ZAKINNAJIB @ ZAKINNAJIB BIN ABDUL MUKTI, ID: S8728966D | | |
| Vehicle Reg. No.: | SMJ3971X | Date of Loss: | 01/07/2019 08:00 - :59 [120 Months and 28 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 598481 | Policy/Cover Note No.: | 80410120 (Comprehensive) Coverage: 28/08/2018 - 27/08/2019 |
| Vehicle Reg. No. (Insured): | SKP2857S | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Chew Motor Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #01-11/41, Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67479241 / 65095545 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 04/07/2019] | | |
| Driver/Custodian (Insured): | CHIONH SEOK CHIN (), NRIC: S0151218H Email: | | |
| Adj Asg. Remarks: | on WP. (manual assigned) Liab: dispute (OI NR) TP Agree on SJE - assign LKK. Contact: Sukyi Chong @ 6747 9241. Manual assigned to LKK via email on 02/07/19. | | |

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 01/07/2019 17:20 |
| Date Of Accident | 01/07/2019 08:10 |
| Exact Location Of Accident | ANG MO KIO ST 63 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------------------------|
| Vehicle Registration Number | SMJ3971X |
| Insured/Policyholder | |
| Name Of Registered Owner | NG ZAKINNAJIB @ ZAKINNAJIB BIN ABDUL MUKTI |
| NRIC No | S8728966D |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-98769417 |
| Alternative Phone No | OFFICE-98769417 |

Vehicle Particulars

| | |
|------------------------------------------------------------------------------|-------------|
| Manufacturer | TOYOTA |
| Model | VIOS |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | MS004059 |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------------------|
| Name of Driver | SITI NUR'AIN BINTI MOHAMED SHARIFF |
| NRIC No | S8844341A |
| Date Of Birth | 18/11/1988 |
| Occupation | INDOOR |
| Date Of Driving Pass | 28/03/2016 |
| Driving Experience | 3 YEARS AND 3 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-97206671 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|-----------------------------------------------------|---------------------------------------|
| Address | BLK 477C UPPER SERANGOON VIEW #05-576 |
| Postcode | 533477 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | SPOUSE |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|-------------------------------------------|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG ANG MO KIO ST 63. SUDDENLY, VEHICLE B FROM THE OPPOSITE LANE MADE A RIGHT TURN WITHOUT CHECKING FOR TRAFFIC. I TRIED TO AVOID BUT COULD NOT STOP AND WE COLLIDED.

Attachment(s)

| | |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SKP2857S |
| Vehicle Make/Model/Colour | |
| Details Of Properties | VEHICLE B |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REMOVE SketchPlanForm_V3

NEW TFOCTEC

Sketch Plan #2 Pg. 1

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight along Ang mo rio st 63.
 Suddenly, vehicle B from the opposite lane made a
 right turn without checking for traffic.
 I tried to avoid but could not stop and we collided.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

NG ZAKINNAJIB @ ZAKINNAJIB BIN MUKTI

01/07/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP MS19.

Denise.

Accident date: 01/07/2019

Estimated repair cost for vehicle no: SMJ3971X TOYOTA VIOS 1.5 E M '09

CHASSIS: MR053HY9305112027

| S/n | Qty | Items | U/price | Amount |
|-----|-----|-----------------------------------------------|----------|---------------------|
| 1 | 1 | Front Bonnet <i>2nd</i> | | \$565.00 <i>X</i> |
| 2 | 2 | Front Bonnet Hinge <i>2nd</i> | \$55.00 | \$110.00 <i>X</i> |
| 3 | 2 | Front Head Lamp <i>LH could</i> | \$455.00 | \$910.00 <i>455</i> |
| 4 | 1 | Front Bumper <i>Debond</i> | | \$485.00 <i>✓</i> |
| 5 | 10 | Front Bumper Clip <i>New</i> | \$6.50 | \$65.00 <i>30.</i> |
| 6 | 1 | Front Bumper Emblem Logo <i>new</i> | | \$55.00 <i>✓</i> |
| 7 | 2 | Front Bumper Side Retainer <i>new</i> | \$65.00 | \$130.00 <i>✓</i> |
| 8 | 2 | Front Bumper Fog Lamp Cover <i>new</i> | \$68.00 | \$136.00 <i>+</i> |
| 9 | 1 | Front Bumper Number Plate <i>could</i> | | \$50.00 <i>✓</i> |
| 10 | 1 | Front Bumper Towing Cover <i>new</i> | | \$53.00 <i>X</i> |
| 11 | 1 | Front Bumper Center Support <i>could</i> | | \$185.00 <i>✓</i> |
| 12 | 1 | Front Bumper Center Lower Garnish <i>lt</i> | | \$138.50 <i>✓</i> |
| 13 | 2 | Front Bumper Bottom Cover <i>new</i> | \$155.00 | \$310.00 <i>+</i> |
| 14 | 1 | Front Bumper Reinforcement <i>Best</i> | | \$382.00 <i>✓</i> |
| 15 | 2 | Front Bumper Reinforcement Bracket <i>new</i> | \$202.00 | \$404.00 <i>+</i> |
| 16 | 1 | Front Bumper Grille <i>could</i> | | \$255.00 <i>✓</i> |
| 17 | 1 | Front Bumper Grille Chrome <i>lt</i> | | \$135.00 <i>✓</i> |
| 18 | 8 | Front Bumper Grille Clip <i>new</i> | \$6.50 | \$52.00 <i>20</i> |
| 19 | 1 | Front Support Panel <i>2nd</i> | | \$925.00 <i>+</i> |
| 20 | 1 | Front Air-Con Condenser <i>new</i> | | \$1,255.00 <i>+</i> |
| 21 | 1 | Front Radiator <i>new</i> | | \$1,819.00 <i>+</i> |
| 22 | 1 | Front Radiator Fan Motor <i>new</i> | | \$580.00 <i>+</i> |

23 1 Front Radiator Side Garnish LH. *Debond*

70.60 *✓*

24 1 Front Radiator Side Garnish Clips. *New*

30.15

Subtotal :-

\$8,879.00

2406.10

1804.57

Labour charges

To remove & refit front air-con condenser, radiator, fan motor
& top up gas

\$380.00 X

To check wiring

~~\$100.00~~ 30

Tuff kote

\$150.00 X

Panel beating

~~\$1,200.00~~ 450

Spray painting

~~\$1,200.00~~ 450

Subtotal :- \$3,030.00

Total:- \$11,909.00

total: 2734 57

c/s: 2.2K:

04 Days

2.2K

04 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011764/AGTD3N2

Date: 03/09/2019

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|----------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 80410120 |
| Claimant Vehicle No : | SMJ3971X | Insured Vehicle No : | SKP2857S |
| Date of Loss: | 01/07/2019 | Nature of Claim: | TP |
| | | Claim No: | 598481 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SMJ3971X | Engine No: | 1NZX903737 |
| Make & Model: | TOYOTA VIOS, 1.5 E (M) | Chassis No: | MR053HY9305112027 |
| Reg. Date: | 03/06/2009 (Man. Year: 2009) | Odometer: | 0 km |
| Colour: | Blue | | |
| Engine Capacity: | 1497 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55R16 | Rear Tyre Size: | 205/55R16 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 9,100.10 | 1,804.57 | 7,295.53 | 80.17 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,030.00 | 930.00 | 2,100.00 | 69.31 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,130.10 | 2,734.57 | 9,395.53 | 77.46 |
| Approved Total (Overridden) (S\$) | | 2,200.00 | | |
| (S\$) | 12,130.10 | 2,200.00 | 9,930.10 | 81.86 |
| + GST 7.00/7.00% (S\$) | 849.11 | 154.00 | 695.11 | 81.86 |
| Nett Amount (S\$) | 12,979.21 | 2,354.00 | 10,625.21 | 81.86 |

INSPECTION

| | | |
|---------------------|--------------------------|--------------------------------------------------------------------------------------------------------|
| Date of Assignment: | 03/07/2019 | |
| Date Inspected: | 02/07/2019 Inspected At: | Chew Motor Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #01-11/41, Autobay@Kaki Bukit Singapore 417883 |

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 03 Sep 2019) |
| Parts: | 143 | TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMJ3971X) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1 | 1 | | *FRONT BONNET | Not Necessary | 565.00 F | *- FL |
| 2 | 2 | | *FRONT BONNET HINGE | Not Necessary | 110.00 F | *- FL |
| 3 | 1 | | *FRONT HEAD LAMP | N/s Cracked | 910.00 F | *455.00 FL |
| 4 | 1 | | *FRONT BUMPER | Deformed | 485.00 F | *485.00 FL |
| 5 | 10 | | *FRONT BUMPER CLIP | Necessary | 65.00 F | *30.00 FL |
| 6 | 1 | | *FRONT BUMPER EMBLEM LOGO | Necessary | 55.00 F | *55.00 FL |
| 7 | 2 | | *FRONT BUMPER SIDE RETAINER | Necessary | 130.00 F | *130.00 FL |
| 8 | 2 | | *FRONT BUMPER FOG LAMP COVER | Not Necessary | 136.00 F | *- FL |
| 9 | 1 | | *FRONT BUMPER NUMBER PLATE | Cracked | 50.00 F | *50.00 FL |
| 10 | 1 | | *FRONT BUMPER TOWING COVER | Not Necessary | 53.00 F | *- FL |
| 11 | 1 | | *FRONT BUMPER CENTER SUPPORT | Cracked | 185.00 F | *185.00 FL |
| 12 | 1 | | *FRONT BUMPER CENTER LOWER GARNISH | Cut | 138.50 F | *138.50 FL |
| 13 | 2 | | *FRONT BUMPER BOTTOM COVER | Not Necessary | 310.00 F | *- FL |
| 14 | 1 | | *FRONT BUMPER REINFORCEMENT | Bent | 382.00 F | *382.00 FL |
| 15 | 2 | | *FRONT BUMPER REINFORCEMENT BRACKET | Not Necessary | 404.00 F | *- FL |
| 16 | 1 | | *FRONT BUMPER GRILLE | Cracked | 255.00 F | *255.00 FL |
| 17 | 1 | | *FRONT BUMPER GRILLE CHROME | Cut | 135.00 F | *135.00 FL |
| 18 | 8 | | *FRONT BUMPER GRILLE CLIP | Necessary | 52.00 F | *20.00 FL |
| 19 | 1 | | *FRONT SUPPORT PANEL | Not Necessary | 925.00 F | *- FL |
| 20 | 1 | | *FRONT AIR-CON CONDENSER | Not Necessary | 1,255.00 F | *- FL |
| 21 | 1 | | *FRONT RADIATOR | Not Necessary | 1,819.00 F | *- FL |
| 22 | 1 | | *FRONT RADIATOR FAN MOTOR | Not Necessary | 580.00 F | *- FL |
| 23 | 1 | | *FRONT RADIATOR SIDE GARNISH LH | Deformed | 70.60 F | *70.60 FL |
| 24 | 1 | | *FRONT RADIATOR SIDE GARNISH CLIPS | Necessary | 30.00 F | *15.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|-----------------------------------------------------------|-----------------|-----------------|
| Sub Total (\$\$) | 9,100.10 | 2,406.10 |
| - List Item Discount on L Items 0.00/25.00% (\$\$) | 0.00 | 601.53 |
| Total Parts (\$\$) | 9,100.10 | 1,804.57 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|------------------------------------------------------------------------------|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE & REFIT FRONT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS | New | 380.00 | 0.00 |
| 2 | TO CHECK WIRING | New | 100.00 | 30.00 |
| 3 | TUFF KOTE | New | 150.00 | 0.00 |
| 4 | PANEL BEATING | New | 1,200.00 | 450.00 |
| 5 | SPRAY PAINTING | New | 1,200.00 | 450.00 |
| Gross Labour Cost (\$\$) | | | 3,030.00 | 930.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >