

Surveyor

REF: CSI/MSG19011765/Egd352

Special Instruction:

LE85000f

From (Person): Ashik of MS16 Date/Time: 3/7/2019

Estimated Cost: Bill to:

Third Parties:

Claimant: Owner

Surveyor: Autamax

Workshop: Eng Soon

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FT4846Z

Insured: GBA 9759G

at Workshop m/s Eng Soon

Tel: 67606271

of Blk H Yeo Tee Ind Est 393-J

Policy No:

Claim No: 587055

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8/3/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 9 days)

Date/Time: 04/7/19 Submit Final Fig 850, 3 days (Red \$ 4150 / 83%; Original 9 days)

Date/Time	Action/Instruction
	FT4846Z-X
	GBA 9759G-X
* Note:	MV-1600 (cost)
	PV-386 (Vins 422 (cost))
	NV-1244 NVs 61178

RECEIVED 05 JUL 2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

150

1) Date/Time 05/7/19 File Pass to [Signature]

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

Nivitha (LKK Auto)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 3 July 2019 10:16 AM
To: assignments
Subject: FW: Our ref: 587075 (Paper survey)
Attachments: OI report.pdf; third party report.pdf; survey report.pdf

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>
Sent: Wednesday, 3 July 2019 9:48 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Our ref: 587075 (Paper survey)

Dear Shiau Chan,

Please assist to conduct paper survey.

Kindly check on the market value & parts price accordingly.

We will send you the survey photos separately.

Thank you.

Ashik Madi

Executive, Claims Services (Motor)

D: +65 6594 2548 | F: +65 225 7402 | ashik_madi@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any

person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2019 11:27
Date Of Accident	08/03/2019 08:30
Exact Location Of Accident	813 BT BATOK WEST AVE 5 ESSO SERVICE STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FT4846Z
Insured/Policyholder	
Name Of Registered Owner	WOO KUM TUCK
NRIC No	S1508124D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81397307
Alternative Phone No	OFFICE-81397307

Vehicle Particulars

Manufacturer	YAMAHA
Model	MOTOR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5056318716-06
Cover Note Number	

Driver

Name of Driver	WOO KUM TUCK
NRIC No	S1508124D
Date Of Birth	19/09/1961
Occupation	INDOOR
Date Of Driving Pass	24/12/1984
Driving Experience	34 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81397307
Fax Number	
Contact Number	OFFICE-81397307
Email Address	NOEMAIL

Address	BLK 129 BT BATOK WEST AVE 6 #02-382
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHEN MY VEHICLE WAS STATIONARY PARKED AT 813 BT BATOK WEST AVE 5 ESSO SERVICE STATION. I WENT TO THE TOILET, ABOUT 15MINS LATER WHEN I RETURNED BACK TO MY VEHICLE. I SAW MY VEHICLE DROP DOWN ON THE FLOOR, A DRIVER PULL UP. THEN HE TOLD ME WHEN REVERSING HAD ACCIDENTALLY KNOCK DOWN MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA9759G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JACK CHAN HUAN YEE
NRIC/Passport Number	G3165833R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAĆ BUKIT BATOK (VAC)
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

GBA
9759.6

FT. 4846Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8124D
Vehicle Details	
Vehicle No.:	FT4846Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	Y125
Primary Colour:	Red
Manufacturing Year:	2001
Engine No.:	E101E029215
Chassis No.:	KE1029215
Maximum Power Output:	-
Open Market Value:	\$2,775.00
Original Registration Date:	31 May 2001
First Registration Date:	31 May 2001
Transfer Count:	6
Actual ARF Paid:	\$417.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$2,026.00
COE Rebate Amount:	\$386.00
Total Rebate Amount:	\$386.00
Message	
<p>Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.</p> <p>This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.</p> <p>This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.</p> <p>For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.</p>	


The information contained herein is correct as at 03 Jul 2019

MV-1600

Adm by Marcus

OK

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2019 16:44
Date Of Accident	08/03/2019 08:40
Exact Location Of Accident	INSIDE ESSO PETROL STATION BUKIT BATOK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA9759G
Insured/Policyholder	
Name Of Registered Owner	GARDENIA FOODS (S) PTE LTD
Co Reg No	NA
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-98331208

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FUSO LORRY
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29069129 MKF
Cover Note Number	

Driver

Name of Driver	JACK CHAN HUAN YEE
Passport No/FIN	G3165833R
Date Of Birth	05/04/1986
Occupation	OUTDOOR
Date Of Driving Pass	03/08/2017
Driving Experience	1 YEAR AND 7 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-88268689
Fax Number	
Contact Number	OFFICE-98331208
EMail Address	WFA6691@GMAIL.COM
Address	224 PANDAN LOOP SINGAPORE
Postcode	128411
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : NA Gender: : Male

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	NA
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

8/3/2019
15:41 pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am a driver from Gardenia Road. I parked my Lorry ~~and~~ to unloading the bread at ESSO Petrol station at Bukit Batok. And I ~~had~~ 'touch' the motorcycle behind me when I reverse to get out there accidentally.

There is a car in front of me. And the motorcycle ~~is~~ is parked on double ~~the~~ yellow line behind of my Lorry.

The motorcycle's side mirror is broken and the mudguard is broken too.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

2/7/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

[Signature]

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Billing To: Wod Kum Tuck
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP18030008

Date: 21 June 2019

Vehicle no: FT4846Z

Model : YAMAHA Y125

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 13 March 2019 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 780.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 780.00

Notes :



2. All cheque payment should be "crossed" and made payable to "Automax Survey".
Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP18030008

Date: 21 June 2019

Wod Kum Tuck
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY

ACCIDENT OCCURED ON 08 March 2019

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 13 March 2019
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
FT4846Z

1. VEHICLE PARTICULARS

Registration No : FT4846Z

Engine No : E101E029215

Model : YAMAHA Y125

Mileage : n.a km

Year / Capacity : May 2001 / 125 cc

Colour : Multi colour

Chassis No : KE1029215

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT :	70/90/R17	Pirelli	9.00 mm	Sport
REAR :	70/90/R17	Pirelli	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the ALL portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 09 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : FT4846Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

List Items

2 pcs	Side lamp assy X NN	electronically shocked	\$ 150.00	\$ 150.00
1 pc	Headlamp assy with casing X NN	electronically shocked	\$ 435.00	\$ 255.00
1 pc	Front mudguard	deformed	\$ 108.00	\$ 108.00 45/
1 pc	Rim X NN	bent/distorted	\$ 450.00	\$ 450.00
1 set	Front fork cover X NN	grazed/deformed	\$ 94.00	\$ 94.00
2 pcs	Front fork tube X NN	bent/distorted	\$ 222.00	\$ 222.00
2 pcs	Front fork oil seal X NN	grazed/deformed	\$ 104.00	\$ 104.00
1 pc	Handle bar	bent/distorted	\$ 208.00	\$ 208.00 65/
1 set	Handle bar grip X NN	bent/distorted	\$ 88.00	\$ 88.00
2 pcs	Handle bar balance X NF	grazed/deformed	\$ 168.00	\$ 168.00
1 pc	Master cylinder assy X NN	grazed/deformed	\$ 228.00	\$ 228.00
1 set	Ignition switch assy X NN	shocked	\$ 435.00	\$ 435.00
1 pc	Meter assy X NN	electronically shocked	\$ 1,758.00	\$ 1,758.00
1 pc	Meter casing (LH handle body) / DR	grazed/deformed	\$ 456.00	\$ 456.00 180/
1 pc	Horn switch X NN	grazed/deformed	\$ 70.00	\$ 70.00
1 pc	Starter switch X NN	grazed/deformed	\$ 92.00	\$ 92.00
1 pc	Side mirror assy RH X NN LH / DR	grazed/deformed	\$ 90.00	\$ 90.00 25/
1 pc	Main stand X NN	bent/distorted	\$ 128.00	\$ 128.00
1 pc	Front wheel shaft X NN	bent/distorted	\$ 68.00	\$ 68.00
2 pcs	Front side cover RH X NN LH / DR	grazed/deformed	\$ 340.00	\$ 340.00 34/
1 pc	Brake pedal X NN	bent/distorted	\$ 65.00	\$ 65.00
1 pc	Front fork bracket X NN	bent/distorted	\$ 115.00	\$ 115.00
1 pc	Steering cone X NN	bent/distorted	\$ 145.90	\$ 145.90
1 pc	Steering cone bearing	bent/distorted	\$ 85.00	\$ 85.00 80/
1 pc	Body frame assy X NN	bent - repair	\$ 1,880.00	\$ -

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------	------------------------------

List Items

1 pc	Shift gear pedal	distorted	\$ 68.00	\$ 68.00
1 pc	Throttle handle	distorted	\$ 62.00	\$ 62.00
1 pc	Brake lever	distorted	\$ 52.00	\$ 52.00
1 pc	Clutch lever	distorted	\$ 52.00	\$ 52.00
1 pc	Inner cover	grazed/deformed	\$ 118.00	\$ 118.00

	Parts Sub-Total	\$ 7,749.90	\$ 5,869.90
Discount	10.00%	\$ 774.99	\$ 586.99
		\$ 6,974.91	\$ 5,282.91

Vehicle Number : FT4846Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------	------------------------------

Special Nett Items

1 pc	Number plate	Necessary	\$ 35.00	\$ 35.00
2 blts	Fork oil	Necessary	\$ 60.00	\$ 60.00
2 blts	Brake oil	Necessary	\$ 60.00	\$ 60.00
1 pc	Meter cable	grazed/loose	\$ 65.00	\$ 65.00
1 pc	Throttle cable	grazed/loose	\$ 65.00	\$ 65.00
1 set	Wiring harness	open cicruit	\$ 250.00	\$ 250.00
1 pc	Horn assy	open cicruit	\$ 65.00	\$ 65.00
1 pc	Tyre	deformed	\$ 200.00	\$ 200.00
1 pc	Brake pad	Necessary	\$ 25.00	\$ 25.00
1 pc	Brake disc	wrapped	\$ 183.00	\$ 183.00
1 pc	Front basket	wrapped	\$ 88.00	\$ 88.00
1 pc	Front brake caliper	damaged	\$ 250.00	\$ 250.00
1 set	Rear box with bracket	distorted	\$ 288.00	\$ 288.00
1 pc	ERP assy	Necessary	\$ 58.00	\$ 58.00

Special Nett Sub-Total	\$ 1,692.00	\$ 1,692.00
------------------------	-------------	-------------

Spare Parts Total	\$ 8,666.91	\$ 6,974.91
-------------------	-------------	-------------

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

Spare Parts Total c/f \$ 8,666.91 \$ 6,974.91

1	Labour charges to repair and panel beat body frame structure cutting/welding and replacing the above mentioned parts.	\$ 1,800.00	\$ 1,600.00 300
2	Transport	\$ 60.00	\$ 60.00 30
3	To replace wiring harness system incl checking	\$ 240.00	\$ 220.00 30
4	To tuff coat affected areas	\$ 180.00	\$ 150.00 X
5	To respray affected areas	\$ 1,400.00	\$ 1,200.00 200

Total \$ 12,346.91 \$ 10,204.91 560

12873.41

The repairer has agreed to undertake the repair under a Sum Basis. We have further adjusted the amount to Sum Repair of:

\$ 5,000.00


Fong Kok Heng
Qualified Appraiser



3 days repair

P-485.10

NI- 15

L- 560

1060.10

L/S- 848.08

= 850



Your Ref: 587075

Date: 08th July 2019

Our Ref: CS1/MSG19011765/Eqd3s2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FT 4846Z
INSURED VEHICLE: GBA 9759G ACCIDENT DATE: 08/03/2019**

We thank you for your instruction on 03/07/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FT 4846Z from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles FT 4846Z and GBA 9759G.
- c) Colour damaged vehicle photographs of FT 4846Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FT 4846Z
Make & Model	: Yamaha Y125
Year of Registration	: 2001
Chassis Number	: KE1029215
Engine Capacity	: 125 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FT 4846Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	SIDE LAMP ASSY	NOT NECESSARY	150.00	-
1	HEADLAMP ASSY WITH CASING	NOT NECESSARY	435.00	-
1	FRONT MUDGUARD	DEFORMED	108.00	45.00
1	RIM	NOT NECESSARY	450.00	-
1	SET FRONT FORK COVER	NOT NECESSARY	94.00	-
2	FRONT FORK TUBE	NOT NECESSARY	222.00	-
2	FRONT FORK OIL SEAL	NOT NECESSARY	104.00	-
1	HANDLE BAR	BENT / DISTORTED	208.00	65.00
1	SET HANDLE BAR GRIP	NOT NECESSARY	88.00	-
2	HANDLE BAR BALANCE	NOT FITTED	168.00	-
1	MASTER CYLINDER ASSY	NOT NECESSARY	228.00	-
1	SET IGNITION SWITCH ASSY	NOT NECESSARY	435.00	-
1	METER ASSY	NOT NECESSARY	1,758.00	-
1	METER CASING (LH HANDLE HOUSING)	BROKEN	456.00	180.00
1	HORN SWITCH	NOT NECESSARY	70.00	-
1	STARTER SWITCH	NOT NECESSARY	92.00	-
1	SIDE MIRROR ASSY	O/S NOT NECESSARY / N/S BROKEN	90.00	25.00
1	MAIN STAND	NOT NECESSARY	128.00	-
1	FRONT WHEEL SHAFT	NOT NECESSARY	68.00	-
1	FRONT SIDE COVER	O/S NOT NECESSARY / N/S BROKEN	340.00	34.00
1	BRAKE PEDAL	NOT NECESSARY	65.00	-
1	FRONT FORK BRACKET	NOT NECESSARY	115.00	-
1	STEERING CONE	NOT NECESSARY	145.90	-
1	STEERING CONE BEARING	BENT / DISTORTED	85.00	80.00
1	BODY FRAME ASSY	NOT NECESSARY	1,880.00	-
1	SHIFT GEAR PEDAL	NOT NECESSARY	68.00	-
1	THROTTLE HANDLE	NOT NECESSARY	62.00	-
1	BRAKE LEVER	NOT NECESSARY	52.00	-
1	CLUTCH LEVER	DISTORTED	52.00	30.00
1	INNER COVER (HANDLE BAR OUTER COVER)	GRAZED / DEFORMED	118.00	80.00

Report Ref No. CS1/MSG19011765/Eqd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-833.49	-53.90
			7,501.41	485.10
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN)	NECESSARY	35.00	15.00
2	BLTS FORK OIL (SN)	NOT NECESSARY	60.00	-
2	BLTS BRAKE OIL (SN)	NOT NECESSARY	60.00	-
1	METER CABLE (SN)	NOT NECESSARY	65.00	-
1	THROTTLE CABLE (SN)	NOT NECESSARY	65.00	-
1	SET WIRING HARNESS (SN)	NOT NECESSARY	250.00	-
1	HORN ASSY (SN)	NOT NECESSARY	65.00	-
1	TYRE (SN)	NOT NECESSARY	200.00	-
1	BRAKE PAD (SN)	NOT NECESSARY	25.00	-
1	BRAKE DISC (SN)	NOT NECESSARY	183.00	-
1	FRONT BASKET (SN)	NOT NECESSARY	88.00	-
1	FRONT BRAKE CALIPER (SN)	NOT NECESSARY	250.00	-
1	SET REAR BOX WITH BRACKET (SN)	NOT NECESSARY	288.00	-
1	ERP ASSY (SN)	NOT NECESSARY	58.00	-
			1,692.00	15.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPAIR AND PANEL BEAT BODY FRAME STRUCTURE CUTTING / WELDING AND REPLACING THE ABOVE MENTIONED PARTS.		1,800.00	300.00
	TRANSPORT.		60.00	30.00
	TO REPLACE WIRING HARNESS SYSTEM INCL CHECKING.		240.00	30.00
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	180.00	-
	TO RESPRAY AFFECTED AREAS.		1,400.00	200.00
			3,680.00	560.00
	GRAND TOTAL		12,873.41	1,060.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			850.00

Report Ref No. CS1/MSG19011765/Eqd3s2

MARKET VALUE: \$1,600.00 (EST)-LTA REIMBURSEMENT VALUE: \$422.00(EST)=NETT VALUE: \$1,178.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.