



Your Ref: 587075

Date: 08th July 2019

Our Ref: CS1/MSG19011765/Eqd3s2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FT 4846Z
INSURED VEHICLE: GBA 9759G ACCIDENT DATE: 08/03/2019**

We thank you for your instruction on 03/07/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FT 4846Z from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles FT 4846Z and GBA 9759G.
- c) Colour damaged vehicle photographs of FT 4846Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FT 4846Z
Make & Model	: Yamaha Y125
Year of Registration	: 2001
Chassis Number	: KE1029215
Engine Capacity	: 125 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.