

ASSIGNMENT

From:

Date: 5/7/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 7714P

at Workshop m/s Volkswagen

of 1 Kampong Ampet.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

5/7/2019 11am Owner Waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLW 7714P

Yr Regn:

28 Feb 2018

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf G.C 999

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

34400

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

www 888 Au 8 Jw 082 823

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05-07-19

Survey held at

WS

UAM

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

1)



: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7421E
Vehicle Details	
Vehicle No.:	SLW7714P
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF TSI TL
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CHZ579336
Chassis No.:	WVWZZZAUZJW082823
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$18,520.00
Original Registration Date:	28 Feb 2018
First Registration Date:	28 Feb 2018
Transfer Count:	1
Actual ARF Paid:	\$18,520.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2028
PARF Rebate Amount:	\$13,890.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$33,029.00
Total Rebate Amount:	\$46,919.00

The information contained herein is correct as at 05 Jul 2019

OK