

INSURANCE

INS. CASE OWNER:

S.T

CC 4/AXA1901

1796 K2P639

LKK
IDAC:

Surveyor:

Kalvin.

DOI:

ASSIGNMENT

3/7/19

Date / Time:

3/7/19

Registered in Merimes:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKG 2212A

Name of Insured:

TAN KIM MINH

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

30/6/14

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN KIM KIM

Driver Tel No.:

(VA: YES / NO)

Claim No.:

SAmo28FA/124929

Policy No.:

GA4176071

Make / Model:

LEXUS

Place of Accident:

PATBESO M RD

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SHA 81037



INSRS:
WSP:
Tel:
Liability:
RMKS:

WSP
WSP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHA 81037 - X

SKG 2212A - X

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handling Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Assessed)

BOLA S/N No.:

27

If MO or B 28, Ass. Lia:

Repair Cost:

SS

963.00

Loss of Rental (LOR):

SS

221.34

(2 days)

X 112.67

Loss of Use (LOU):

SS

15

x 2 days

Loss of Income (LOI):

SS

100.00

(50 x 2 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

1291.83

Global Sum SS:

1290.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1290.00

Name 1:

ComfortDesign Engineering Pte Ltd

UG/10/19

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COMFORT

Date/Time: 02.07.2019 18:05

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO: 305308210

CITYCAB PTE LTD

7010070

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65551188

(D)

(P)

UNIT CARD NO:

REGN NO.

SHA8103J

MILEAGE

MAKE

HYUNDAI

FUEL

E 1/2 F

MODEL

I-40

DATE/TIME IN 02.07.2019 12:15

YR OF MANU

02.04.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMFU068297


COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 30.06.2019

NATURE: 3P 30.06.2019

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Lodgement Slip

Exit Pass

No.

SHA8103J

LKE

Vehicle No.:

SHA8103J

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

DATE 2/7/2019 15:58

Lee

$$AXA$$

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Reflector Lamp (LH) ✓			\$ 30.60
	Rear Fender (LH) ✕			\$ 2,171.40
	Rear Fender Inner Lining (LH) ✕			\$ 169.30
	Rear Windscreen Moulding ✕			\$ 28.30
	Rear Wheel Hub Cap, LH ✕			\$ 107.10
	SUB TOTAL			\$ 3,741.90
	LESS 20%			\$ 748.38
	DISCOUNTED TOTAL			\$ 2,993.52
	Rear Bumper Rubber Mat ✓			\$ 50.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Windscreen Sealant ✕			\$ 46.00
				\$ 231.70
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 80.00
	Rear Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,510.00
	ESTIMATE TOTAL			\$ 4,735.22

Kali 11/11/19
3/7/19 1045L.
2 Pgs
415 After Repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No 305308210
Date : 09.07.19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 308969
Fax: 6546 8156



FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. SH8103J CCPL

Fax :

30.06.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA — SKG2212A
 2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$900.00
Final Lumpsum Repair cost \$900.00
 3. Estimated normal period for repairs: 2 working days.
 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
 5. Thank you for your assistance.

Signature :
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156
- We confirm the estimates and finalized amount

Signature :
Name : KALVIN ANG
Date : 10/7/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Final Amount Subject to Insurance Approval

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8103J

DATE 2/7/2019 15:58

MAKE :

MODEL : HYUNDAI i40

Like

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Reflector Lamp (LH)			\$ 30.60
	Rear Fender (LH)			\$ 2,171.40
	Rear Fender Inner Lining (LH)			\$ 169.30
	Rear Windscreen Moulding			\$ 28.30
	Rear Wheel Hub Cap, LH			\$ 107.10
	SUB TOTAL			\$ 3,741.90
	LESS 20%			\$ 748.38
	DISCOUNTED TOTAL			\$ 2,993.52
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Windscreen Sealant			\$ 46.00
				\$ 231.70
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 80.00
	Rear Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,510.00
	ESTIMATE TOTAL			\$ 4,735.22

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

<< Service Request Details

Claim

S9M015FA

Reference

None 

Loss Date

June 30, 2019

Report Date

Jul 1, 2019 1:29:53 PM

Request Date

July 3, 2019

Due Date

July 10, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Kalin P: Lim

T: 10.10.19

V: 14

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHA8103J

Model

I40

Service Address

...

Primary Contact/Insured

TAN KIM MING

40 JALAN ARNAP, 249346, Singapore

K.M.TAN@HOTMAIL.COM

Claim Handler

KHOR Saw Theng

6568804754

sawtheng.khor@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Lim Kwok Eng <limke@cdge.com.sg>
Sent: Tuesday, 2 July, 2019 6:57 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Ng Nyuk Phin; Roger How Keen Meng
Subject: SHA8103J with your insured SKG2212A
Attachments: img-702183359-0001.pdf

Categories: Namrata

To Officer In Charge

Pls arrange surveyor, refer attachment

Best Regards

Lim Kwok Eng

Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8355 / 6214-8156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]



<TP - IA UPLOADED> - S9M01SFA [ACCIDENT INVOLVING SKG 2212A(OI) & SHA 8103J(TP) ON 30/06/2019]

Type

🔍 Question

Message

Liability: 100%. Insured rear-ended third party. TP- IA had been uploaded in Smartclaims. The total quantum is < \$5,000.00. We will proceed to negotiate settlement with third party. Thank you, Hsiao Tong - 10 July 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/07/2019

Survey Details:

Date of loss	30-Jun-19
Date of appointment	3-Jul-19
Date of survey	3-Jul-19
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHA 8103J
Make and Model	HYUNDAI I40
Date of registration	2/4/2015
Excess	
Market Value	\$0
Part Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 4,735.22
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 670.18
Check items (estimate)	\$ 528.16
Labour	\$ 430.00
Total	\$ 1,628.34
Lump Sum(if applicable)	\$ -
Number of days for repair	2



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R


51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: 100%. Insured rear-ended third party. TP - IA been uploaded in Smartclaims. The total quantum is < \$5,000.00. We will proceed to negotiate settlement with third party.

Mandate:

Liability(TP)	100%	
Proposed repair cost	TBA	
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
Proposed Total	TBA	



Hsiao Tong (LKKAuto)

From: William Tan Thoo Seng <williamtan@cdge.com.sg>
Sent: Monday, 5 August 2019 3:11 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: Your Ref: CC19060804/ SHA8103J/ WT(st) *Our Ref: CC4/ASM19011796/K1pb3 [ACCIDENT INVOLVING SKG 2212A(AXA) & SHA 8103J ON 30/06/2019]

Without Prejudice.

Dear Hsiao Tong

Purely for the purpose of an amicable settlement, we accept your global offer.

Kindly forward your D.V.

Thank you.

Best Regards
William Tan
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148737 | Fax : 62141843

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Monday, 5 August 2019 3:00 PM
To: William Tan Thoo Seng <williamtan@cdge.com.sg>; Catherine Koh Mui Gek <catherinekoh@cdge.com.sg>
Subject: Your Ref: CC19060804/ SHA8103J/ WT(st) *Our Ref: CC4/ASM19011796/K1pb3 [ACCIDENT INVOLVING SKG 2212A(AXA) & SHA 8103J ON 30/06/2019]

Your Ref: **CC19060804/ SHA8103J/ WT(st)**
Our Ref: CC4/ASM19011796/K1pb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SKG 2212A(AXA) & SHA 8103J ON 30/06/2019

We refer to the above matter.

We propose settlement at a global sum of \$1,290.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 10 July 2019 10:36 AM
To: K.M.TAN@HOTMAIL.COM
Subject: ACCIDENT INVOLVING SKG 2212A(AXA) AND SHA 8103J ALONG/AT PATERSON RD TURNING INTO ORCHARD BOULEVARD ON 30/06/2019

10 JULY 2019

MR TAN KIM MING

Dear Sir/ Mdm

OUR REF : CC4/ASM19011796/K1pb3 // S9M01SFA

YOUR REF : SKG 2212A

ACCIDENT INVOLVING SKG 2212A(AXA) AND SHA 8103J ALONG/AT PATERSON RD TURNING INTO ORCHARD BOULEVARD ON 30/06/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from COMFORTDELGRO ENGINEERING PTE LTD acting on behalf of the owner of SHA 8103J against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour as it is a head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or chewht@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGI 40 SHA8103J , SKG2212A
PATERSON RD TOWARDS ORCHARD BLVD

ON 30-Jun-19 15:20

I / We

RAVI KUMAR S/O KASS... (Hirer) NRIC No.: SXXXX606D

and/or

MOHD ZULKIFLI BIN OS... (Relief) NRIC No.: SXXXX599B

Taxi Number

SHA8103J

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

02-Jul-2019

Name of Hirer
Hirer NRICRAVI KUMAR S/O KASSIM
SXXXX606D

Signature :



Address

426D YISHUN AVENUE 11 #08-104
764426

Contact No.

91454912

Name of Relief
Relief NRICMOHD ZULKIFLI BIN OSMAN
SXXXX599B

Signature :



Address

173 YISHUN AVE 7 #03-813
760173

Contact No.

90678784



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKG 2212A (Insd veh)	Model: HYUNDAI : I40
	SHA 8103J (TP veh)	
Date of Accident/ Time:	30/06/2019	

Repair Estimate	: \$	5,066.69	
Final Repair Cost	: \$		
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	1,290.00	
Payee Name : COMFORTDELGRO ENGINEERING PTE LTD			
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:		Agreed Liability _____ (%)
B)	For GIA Registered Workshop:		BOLA Applicable <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No BOLA Scenario No: <u>27</u>
	BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp Name of Representative: <u>COMFORTDELGRO ENGINEERING PTE LTD</u> Date: <u>26-8-19</u>  <u>AWK</u>	Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>COMFORTDELGRO ENGINEERING PTE LTD</u> Date: <u>26-8-19</u> 
Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date:	

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

TAX INVOICE

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01
SINGAPORE 068811

CONTACT NO: 63387288

VEHICLE NO
SHA81031

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
02.04.2015

CHASSIS CODE
KMHCB41UMFU068297

NO/DATE

91454636 11.07.2019

JOB NO.
305308210

ODOMETER READING

JOB TYPE

Description : 3P 30.06.2019

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt.	900.00
Add GST @ 7.000 %	63.00
Total Invoice amount	963.00

Issued by : KATHIRKINTAN 11.07.2019 15:09:09
Repair Type : CPSO/57/57
Payment Type/Term : /Credit 30 days

WE HEREBY CERTIFY ALL REPAIRS AND SERVICES WERE COMPLETED AND THE VEHICLE WAS RETURNED TO THE CUSTOMER IN GOOD CONDITION. THE CUSTOMER HAS BEEN ADVISED OF THE REPAIRS AND SERVICES AND HAS ACCEPTED THE INVOICE. THE CUSTOMER HAS BEEN ADVISED OF THE REPAIRS AND SERVICES AND HAS ACCEPTED THE INVOICE. THE CUSTOMER HAS BEEN ADVISED OF THE REPAIRS AND SERVICES AND HAS ACCEPTED THE INVOICE.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CC19060804



Date: 10 July 2019

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 30/06/2019 @ 15:20 hrs
ALONG PATERSON RD TOWARDS ORCHARD BLVD
INVOLVING SKG2212A

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA8103J** (the "Taxi"). The Taxi was hired to **RAVI KUMAR S/O KASSIM IC NO S2548606D** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$110.67** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

[illegible]

Enquire Vehicle Insurance Details

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKG2212A	30 Jun 2019 / 15:20:00	Successful	A12	AXA INSURANCE PTE LTD

Previous

OK

SHA8103

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19011796/K1pb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG		Date : 03-09-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKG 2212A	Veh. Inspected	SHA 8103J
Policy No.	GA417607/1	Coverage (\$)	0.00
Claim No.	S9M01SFA	Excess (\$)	0.00
Assign From		Assign Date	03/07/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMFU068297	Colour	YELLOW
Odometer	615347	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/06/2019	Inspection Date	03/07/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8103J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	553.00	553.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30 (CONSISTENT)	SERVICEABLE	160.60	-
10	REAR BUMPER CLIP (CONSISTENT)	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60 (CONSISTENT)	SERVICEABLE	71.20	-
1	REAR BUMPER REFLECTOR LAMP (LH) (CONSISTENT)	CRACKED	30.60	30.60
1	REAR FENDER (LH) (CONSISTENT)	SERVICEABLE	2,171.40	-
1	REAR FENDER INNER LINING (LH) (CONSISTENT)	SERVICEABLE	169.30	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	28.30	-
1	REAR WHEEL HUB CAP ,LH (CONSISTENT)	SERVICEABLE	107.10	-
	LESS 20% DISCOUNT		-748.38	-121.12
			2,993.52	484.48
SPECIAL NETT ITEMS				
1	REAR BUMPER RUBBER MAT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	135.70	135.70
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	46.00	-
			231.70	185.70
LABOUR				
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING CHARGE.		600.00	200.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.	NOT NECESSARY	150.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR .		80.00	40.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			1,510.00	440.00
GRAND TOTAL			4,735.22	1,110.18

Report Ref No. CC4/ASM19011796/K1pb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00
---	--	--	--------

Report Ref No. CC4/ASM19011796/K1pb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9M015FA	Vehicle Information	
Reference	CC4/ASM19011796/K10b3u2	Incident Vehicle Registration #	S9A8103J
Loss Date	30 June 2019	Make	TPVO HYUNDAI
Report Date	1 Jul 2019 1:29:53 PM	Model	I40
Request Date	3 July 2019	Service Address	
Due Date			
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)	Primary Contact/Insured	
Type of Loss	Third Party Vehicle Damage	TAN KIM MING	
Services	Pending verification - Direct Settlement	40 JALAN ARNAP, 249346, Singapore	
		K.M.TAN@HOTMAIL.COM	
		Claim Handler	
		KHOR Saw Theng	
		6568804754	
		sawtheng.khor@axa.com.sg	

Actions

Next Step

Wait for Approve Invoice

Add Evidence

Additional Instructions















- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

Upload Document

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (0).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 RENTAL MILEAGE.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LKXInspection (5).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LKXAdjustment1a (7).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LETTER TO Q1.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LKX Resurvey Photos.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 LKX Survey Photos.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 TP - IA 01 100719.pdf	Forms / Claim Documents	Assessment	LKX AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 TP ESTIMATE_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 TP-IA 8103.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	4 July 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 SKG2212A INSD GUA.PDF	Reports & Statement	GUA Report	DHINWAR Namrata	3 July 2019
 TP PSI EMAIL FROM WORKSHOP WITH ESTIMATE.msg	Letters and Correspondence	Workshop	DHINWAR Namrata	3 July 2019
 GA417607 Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	DHAKAL Raghav	1 July 2019
 GA417607 Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	DHAKAL Raghav	1 July 2019