

INS. CASE OWNER:

CC6 / AIG 19011797 / A da3

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

2/7/19

Date / Time:

2/7/19

Registered in Merimen:

3/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SSP 9304L

Claim No.:

Name of Insured:

Orange Cars

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II:SS

D.O.A:

1/7/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

GBC 8878S



INSRS:

WSP:

Tel:

Liability:

RMKS:

Eunos Motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

14/8/19 - FILE PAS TO HMC TO WISE

GBC 8878S : X ; SSP 9304L : X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 5100.00

Loss of Rental (LOR):

(w/65)

S\$ 270.40

(

6 days)

x \$120

Loss of Use (LOU):

S\$ -

(\$

x days)

Loss of Income (LOI):

S\$ -

(\$

x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$ 5870.40

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5870.40

Name 1:

Eunos Motor Service

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

14/8/19

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

TP AIG.

43 - \$5100 (Red \$ 6702.50 / 571)

MV : 371C

PV : 17.1K

Nett: 19.91C

Veh No: GBC8878S Yr Regn: 2014 / Jan.
 Type: M.Car / M.Cycle / Bus / Van / Loan / Taxi / Primo Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2982

Colour: Blue A/C: Insured / Std / Nil / NA

Sp. Reading 264933 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTFAT35Y20K202720

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155 R15

R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>06</u> mm	R/Bal.	<u>06</u> mm
L/Bal.	<u>06</u> mm	L/Bal.	<u>06</u> mm
D.O.A.		D.O.I.	<u>02/07/19</u>

Survey held at Eunos Motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

0199E.

Date/Time, File Pass to?	Date/Time, File Return to?
1) _____	2) _____
3) _____	4) _____
5) _____	6) _____
Prel. Report:	
Final Report:	

Part Prices Check:

IN OUT

Survey Fee:

Date:

Basic & Add.
 S + RS, S
 Photos
 Others
 TOTAL

GBC 85785 Toyota Dyna

JTFA135Y20K201720

Date

No

Rear Tail gate Dented.

105530

✓

" " Lock LH/RT - 4 189 MM

375.00

X

" " Emblem - Toyota Nec

175.00

✓

" " " 70km

30.00

15(SN)

" " " 32 13 Pax } Nec

30.00

15(SN)

" " " Dyna Nec

38.00

✓

Rear Tail gate Aluminum Panel MM

164.00

X

" " End Panel Dented.

384.00

✓

Tail Lamp LH Smashed.

169.70

✓

Tail Lamp panel LH Bent.

56.10

✓

Rear LH side gate LH Repair

1555.10

X

" side gate Lock LH Bent. LH Bent

128.00

✓

Rear Tail gate Retainer 43842 LH

76.00

3P

" " " stop rubber 43442 Missing

68.00

✓

Rear Number Plate Panel Bent.

159.10

✓

Rear spare Tyre Carrier Assy Damaged

312.00

✓

Rear LH chassis member Repair

924.00

X

Rear step Bracket (Side Case) Bent

122.00

✓

Rear side gate panel Repair

185.00

X

Rear Floor Centre panel Repair

945.00

X

Reverse sensor Damaged

350.00

200(SN)

Radiator Dented.

1637.00

✓

Fan Blade LH

192.70

✓

Engine Mounting 2x 4123 toln

246.00

✓

Rear Box Mounting toln

117.00

✓

Rear Number Plate Bent

500.00

30(SN)

4550.00

Less 25%

2387.50

4897.90

S.N: 260.

7162.50

Ln 25%: 3673.42

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Company
Owner ID:	0199E
Vehicle Details	
Vehicle No.:	GBC8878S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	1KD2359320
Chassis No.:	JTFAT35Y20K202720
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	23 Jan 2014
First Registration Date:	23 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
PARF Eligibility	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details	
COE Expiry Date:	22 Jan 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,532.00
COE Rebate Amount:	\$17,081.00
Total Rebate Amount:	\$17,081.00

The information contained herein is correct as at 03 Jul 2019

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A

3.18% P.A \$0 Admin Fees At GV
Finance, 2 Years Warranty,
Monthly From \$558.
GV Credit Pte Ltd StarAd

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 [View Our Cars](#)

Browse by Category [Save Search](#) [Print](#) Sort by Date Posted 20 results/page

6 vehicles **Search** Dyna [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Dyna Any Any 2013 Any Any Any Available



☐ **Toyota Dyna 150 3.0M** **\$34,800** **\$9,680 /yr** **05-Feb-2013** **2,982 cc** **-** **Truck** **Available**

Fuel Type: Diesel

Previous Owner Was Sure To Keep Vehicle Well Maintain, Clean, Freezer And Fridge, Loan Available, Trade In Welcome, Please Call, Thank You.;

ABWIN (1994) Pte Ltd

[Posted: 01-Jun-2013](#) [Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna](#)



☐ **Toyota Dyna 150 3.0M** **\$36,800** **\$9,750 /yr** **12-Apr-2013** **2,982 cc** **-** **Truck** **Available**

Fuel Type: Diesel

Low Cost Maintenance, Reliable Truck, Truck In Very Good Condition. Doorstep Viewing Can Be Arrange.;

ABWIN (1994) Pte Ltd

[Posted: 01-Jun-2013](#) [Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna](#)



☐ **Land Rover Range Rover Evoque Dynamic SDR** **\$101,999** **\$16,400 /yr** **07-Jun-2013** **1,999 cc** **-** **SUV** **Available**

1 Owner And Agent Unit! Highly Sought After Dynamic High Spec Models, Firenze Red Exterior Color Options Offset The Sport Themed And 2 Tone Interior Perforated Leather Seats, All-conditions Terrain Response Sys. Enable You To Handle It Well Under Any Road Cond...

Car Buyers Automotive Pte Ltd

[Posted: 14-Jun-2013](#) [Tags: 2013 Land Rover Range, 2013 Land Rover Range, Land Rover Range, Land Rover Range, Land Rover Range, Land Rover Range, Land Rover Range, Land Rover Range](#)



☐ **Toyota Dyna 150 3.0M** **\$34,800** **\$8,810 /yr** **14-Jun-2013** **2,982 cc** **-** **Truck** **Available**

Fuel Type: Diesel

1 Owner! Underutilised Vehicle With Low Mileage! Loan Up To 100% Available! Guaranteed Best Condition In The Market With No Repairs Needed! Best Deal For Short Term Drive! Full Cash Welcome! High Trade In Value. Call Our Friendly Sales Consultant To View This Beau...

Car (5) Pte Ltd

[Posted: 26-Jun-2013](#) [Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna](#)



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle

STA

Buying a pre-owned car, but
Unsure of its Condition?
Get STA Car Evaluation



☐ **Toyota Dyna 150 3.0M** **\$38,800** **\$5,790 /yr** **19-Jun-2013** **2,982 cc** **130,000 km** **Truck** **Available**

Fuel Type: Diesel

Powerful Engine And Gearbox In Excellent Condition! All Wear And Tear Replaced! Interior In Excellent Condition! Seats Have Been Newly Wrapped. As Good As New! Super Cold Aircon! High Loan Available! Call Our Friendly Salesman To Arrange For A Viewing O...

KSL Automotive Pte Ltd

[Posted: 29-Jun-2013](#) [Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna](#)



☐ **Toyota Dyna 150 3.0M** **\$36,800** **\$9,170 /yr** **08-Jul-2013** **2,982 cc** **-** **Truck** **Available**

Fuel Type: Diesel

Superb Condition 10FT Lorry With Canopy. New Paint Job Done, Wear And Tear All Done Up. 100% LOAN Available, High Trade In Guaranteed. 6 Months Warranty. See To Believe, Call For More Information.;

Qifei Auto Pte Ltd

[Posted: 01-Jul-2013](#) [Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna](#)

Jia Le (LKK Auto)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Friday, 26 July 2019 4:44 PM
To: Jia Le (LKK Auto)
Subject: RE: [MANDATE REQUEST] RE: Your ref: 2557761268SG [ACCIDENT INVOLVING VEHICLES SJP9304L AND GBC8878S ON 01/07/2019]

Dear Jia Le,

Please proceed as recommendation.

Kindly request for Rental agreement from Third party's repairer.

Thank you

Kind regards
Norsiah

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606
Norsiah.MdNoor@aig.com | www.aig.com.sg



Celebrating 100 Years:
Visit 100.aig to learn more.

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jia Le (LKK Auto) [<mailto:JiaLe@lkkauto.com>]
Sent: Friday, July 26, 2019 4:06 PM
To: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Subject: [EXTERNAL] [MANDATE REQUEST] RE: Your ref: 2557761268SG [ACCIDENT INVOLVING VEHICLES SJP9304L AND GBC8878S ON 01/07/2019]

This message is from an external sender; be cautious with links and attachments.

AIG Ref: 2557761268SG

Dear Sirs/Madam,

ACCIDENT INVOLVING SJP 9304L(OI) AND GBC 8878S(TP) ON 01/07/2019

We refer to the above matter.

Mandate summary and the relevant documents had been uploaded in Merimen.

For your approval please.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jia Le (LKK Auto)

Sent: Friday, 26 July 2019 3:06 PM

To: Md Noor, Norsiah

Subject: Your ref: 2557761268SG [ACCIDENT INVOLVING VEHICLES SJP9304L AND GBC8878S ON 01/07/2019]

AIG Ref: **2557761268SG**

LKK Ref: CC6/AIG19011797/Ada3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJP 9304L(OI) AND GBC 8878S(TP) ON 01/07/2019

We refer to the above matter.

It is head to rear collision. Liability is not in our driver's favour.

We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "EUNOS MOTOR SERVICE" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 11,802.50	\$ 5,100.00
2. Loss of Rental (6days x \$120.00) (w/GST)	\$ 770.40	\$ 770.40 (6days x \$120.00) (w/GST)
Total	\$ 12,572.90	\$ 5,870.40

**06days recommendation for repair.

All the relevant documents had been uploaded in Merimen.

Kindly let us have your approval.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Neptune Mechanical Engg Pte Ltd ("the third party claimant")
of 31K 3016, Bedok North Avenue 4, #02-05, Eastah 489947 (address),
owner of GBC 88785 (vehicle no.) hereby authorize
Eunos Motor Service

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") ^(Property Damage Claim) for my vehicle no. GBC 88785 that was
damaged pursuant to the accident which occurred on 1/7/19 (date) along
Sims Avenue (location)
Involving vehicle no/s GBC 88785 & SSP 9304L ("the accident").

Property Damage Claim

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

The property damage claim should be without prejudice to my claim for personal injury
and related damages.

Date this 26 day of July (month) 20 19 (year)



Signed by "the third party claimant"

Signed by "the workshop"

The terms of this Discharge Voucher are without
prejudice to, and reserves, the claimant's claim
for property damage/personal injury, in respect
of this accident, which the claimant has or may have.

RELEASE VOUCHER
(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

We/I, Eunos Motor Service ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd., LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 5,100.00 (repair costs), S\$ 770.40 (loss of use/rental) S\$ - (search fees) (the Property Damage) for vehicle no. GBL 88785 that was damaged pursuant to the accident which occurred on 1/7/19 (date) along Sims Avenue (location) involving vehicle no./r GBL 88785 & SJF 93042 and without prejudice to any personal injury claim related to this accident.

This is pursuant to the inspection conducted on 2/7/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Naptime Mechanical ("third party claimant") of vehicle no. GBL 88785 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

for only the Property Damage

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBL 88785 (vehicle no.) as a result of the accident.

for only the Property Damage

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 day of Aug (month) 20 19 (year)



LWP

Signed by AIG appointed surveyor

EUNOS MOTOR SERVICE

Chopped & Signed by "the workshop"

The terms of this Discharge Voucher are without prejudice to, and reserves, the claimant's claim for property damage/personal injury, in respect of this accident, which the claimant has or may have.

INVOICE

Specialise in Motor Car Repairs, Servicing,
Car Air-Conditioners, Car Spray Painting,
Knocking of Mudguards & Car Bodies.

友諾士汽車修理
EUNOS MOTOR SERVICE

Nº 42641

N.B. Prepare for ROV Inspection.

Blk 1, Kaki Bukit Ave 6 #01-64
Singapore 417883
Tel: 67472033, 67480107, 67473418
Fax: 67415197
Reg. No. 336791/00C

M/S. AIG ASIA PACIFIC INSUR. PTE LTD.,

Owner: Neptune Mechanical Engrg Pte Ltd., Policy No: 2019-V0106629
Date 26th. July '19
x ~~Forward Order No.~~

Vehicle No: GBC8878S Toyota Dyna

Ref. Our D/O No. _____

ITEM NO	QUANTITY	DESCRIPTION	Price Per Unit	AMOUNT \$
		Re: Accident involving vehicle GBC8878S and SJP9304L along Sims Drive 1.7.19 11.45 Being Lump Sum Repair by LKK AUTO CONSULTANTS PTE LTD., ADRIAN LING WAI PING (inclusive of parts and labour charges		\$5100.00
(S. Dollars: <u>Five Thousand One Hundred Only</u>			TOTAL >	\$5100.00

for EUNOS MOTOR SERVICE

Received By _____

E. & O. E.

AUTHORIZED SIGNATURE _____

Cheques to be made payable to Eunost Motor Service and marked A/C payee.

N.B. Early Remittance will be much appreciated.
No official receipt will be issued for all cheque payment unless requested.



長江企業私人有限公司
CHIANG KANG ENTERPRISES CO. (PTE.) LTD.

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246, 6294 9170 Fax: 6298 3864

Official Receipt

No. 4657

Date 6/7/19

Received from NEPTUNE MECHANICAL ENGINEERING PTE LTD
the sum of Dollars SEVEN HUNDRED SEVENTY AND CENTS FOUR ONLY

being payment of Rental of Wmry @ 24583m from 1/7/19 to 6/7/19

Chiang Kang Enterprises Co. (Pte) Ltd

S\$ 770.40

Cash/Cheque No.

Authorised Signature



長江企業(私人)有限公司
CHIANG KANG ENTERPRISES CO. (PTE.) LTD.

No. 4 Petain Road, Petain Court Singapore 208086
Tel: 6298 1936, 6294 0246, 6294 9170 Fax: 6298 3864

GST NO: 19-8304039-K

TAX INVOICE

Neptune Mechanical Engineering Pte Ltd
Blk 3016 bedok North Avenue 4 #02-05 Eastech
Singapore 489947
Attn : Accounts Dept

NO: 103/2019

Date: 6/7/2019

Terms:

Being rental of :

GZ4583M Toyota Dyna 1.5 tons Canopy Truck

from 01/07/19 to 6/7/19, 6 days.....

Name Of Driver : YIU YONG SENG

\$ 720.00

\$ 50.40

TOTAL

\$ 770.40

Singapore Dollars : Seven Hundred Seventy And Cents Forty Only



CHIANG KANG ENTERPRISES CO (PTE) LTD



長江企業(私人)有限公司

Chiang Kang Enterprises Co. (Pte.) Ltd.



1995 - 2003

TAX INVOICE

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246 Fax: 6298 3864

RENTAL OF CARS, VANS, PICK-UPS & LORRIES

出租: 汽車、廣告車、必甲與輕重型羅厘

GST Reg.No. 19-8304039-K

HIRER'S PARTICULARSIf Different From
Section 1

I/We Nepdane Mechanical Supply Pk Ltd
of Blk 3016, Block North Avenue 7
#02-05, Eastah S 489947 Tel: _____

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from CHIANG KANG ENTERPRISES CO. (PTE.) LTD. hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

a) THIRD PARTY ONLY MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$1500/= to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.

b) COMPREHENSIVE MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$2000/= for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.

c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle. whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the terms and conditions of Hire, hereinafter mentioned and printed at the back hereof:

Vehicle Regn No. 車輛註冊號碼 <u>G2 4583 M</u>		Rental Agreement 合同號碼 No. <u>A</u>	
Section 1 Hire's And/Or Driver's Particulars 租車者/駕駛員個人記錄		租出日期及時間 Date & Time OUT <u>1/7/19 - 4:00 PM.</u>	
姓名 Name: <u>YU YONG SENG</u>		交車日期及時間 Date & Time IN <u>6/7/19 - 9 AM</u>	
地址 Address: <u>Blk 724, Pasir Ris St 72</u>		Chargeable	Rates Amount
<u>#09-141</u>	S <u>510724</u>	天 Days <u>6</u> @ \$ <u>120</u>	<u>720</u>
居民證/護照號碼 I/C No./Passport No:	駕駛執照號碼 Driving Licence No: <u>50487666J</u>	星期 Weeks @ \$	
居民證/護照種類 Type of I/C/Passport:	Pass 日期 Pass Date:	月 Month @ \$	
出生日期 Date of Birth:	發出地 Place of Issue:	ADD 7% GST <u>50.40</u>	
三號保險底金 \$1500/=		一號保險底金 \$2000/=	
a) Third Party Only Policy Excess \$1500/=		b) Comprehensive Policy Excess \$2000/=	
車輛必須歸還車主於 Vehicle Must Be Returned To Owner's Office By:		送車/費 Delivery Fees	
備註與付款記錄 Remarks & Payment Records		總計 Total Charge	<u>\$ 770.40</u>
按金 Security Deposit			
總金額 Total Payable			
來銀 Amount Paid			
收車費用 Collection Fees/Misc.			
IMPORTANT! For Singapore Use only!		超過/小時 Extra Hours @ \$	
出車油箱 Fuel Tank OUT	E <input type="checkbox"/> W <input type="checkbox"/> M <input type="checkbox"/> F	出車油箱 Fuel Tank IN	E <input type="checkbox"/> W <input type="checkbox"/> M <input type="checkbox"/> F
車牌號碼 Vehicle No:	1)	起 From:	至 To:
車牌號碼 Vehicle No:	2)	起 From:	至 To:
工具 Tools	輪胎 Spare Tyre	裝飾品 Accessories	加額費用 Total Additional Charges
車輛發出人 Vehicle Issued By:	車輛接收人 Vehicle Collected By:		
NOTE: 註 租車者或司機必須付所有停車及違反交通法例負起一切的責任。 HIRER AND/OR DRIVER IS LIABLE FOR ALL PARKING AND TRAFFIC VIOLATIONS.		總計 Grand Total	

租車者不准載沙或石灰
HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE

我/我們同意以上及後頁租車公司所列的條款與條件。

I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.

日期
Date:

1/7/19

租車者簽名

Signature of Hirer:

Yong Seng

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2019 Edit Reg		02 Jul 2019 00:00 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ORANGE CARS , Co. Reg. No.: 53314768M								
Main Claimant:	NEPTUNE MECHANICAL ENGINEERING PTE LTD , Co. Reg. No.: 199400199E								
Vehicle Reg. No.:	GBC8878S	Date of Loss:	01/07/2019 11:00 - :59 [65 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2557761268SG	Policy/Cover Note No.:	0999994461 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJP9304L	Policy No. (Claimant):	2019-V0106629						
		Excess:							
Repairer:	Eunos Motor Service (HQ) 1 Kaki Bukit Ave 6, #01-64 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 2033								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC8878S (2557761268SG)

[SJP9304L]

TP



















































NEPTUNE MECHANICAL ENGINEERING PTE LTD




























Jul 1 2019 11:00AM

[ORANGE CARS]

Eunos Motor Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1		Edit		
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	26/07/19 16:02	Adjuster Immediate Advice												1		Load HTM		
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	25/07/19 09:20	Front View												1		Load JPG		
2	25/07/19 09:20	Front View												1		Load JPG		
3	25/07/19 09:20	Front View												1		Load JPG		
4	25/07/19 09:20	Front View												1		Load JPG		
5	25/07/19 09:20	Front View												1		Load JPG		
6	25/07/19 09:20	Front View												1		Load JPG		
7	25/07/19 09:20	Front View												1		Load JPG		
8	25/07/19 09:20	Front View												1		Load JPG		
9	25/07/19 09:20	Front View												1		Load JPG		
10	25/07/19 09:20	Front View												1		Load JPG		
11	25/07/19 09:20	Front View												1		Load JPG		
12	25/07/19 09:20	Front View												1		Load JPG		
13	25/07/19 09:20	Front View												1		Load JPG		
14	25/07/19 09:20	Front View												1		Load JPG		
15	25/07/19 09:20	Front View												1		Load JPG		
16	25/07/19 09:20	Front View												1		Load JPG		
17	25/07/19 09:20	Front View												1		Load JPG		
18	25/07/19 09:20	Front View												1		Load JPG		
19	25/07/19 09:20	Front View												1		Load JPG		
20	25/07/19 09:20	Front View												1		Load JPG		
21	25/07/19 09:20	Front View												1		Load JPG		
22	25/07/19 09:20	Front View												1		Load JPG		
23	25/07/19 09:20	Front View												1		Load JPG		
24	25/07/19 09:20	Front View												1		Load JPG		
25	25/07/19 09:20	Front View												1		Load JPG		
26	25/07/19 09:20	Front View												1		Load JPG		
27	25/07/19 09:20	Front View												1		Load JPG		
28	25/07/19 09:20	Front View												1		Load JPG		
29	25/07/19 09:20	Front View												1		Load JPG		
30	25/07/19 09:20	Front View												1		Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	25/07/19 09:20	Front View	 Load JPG	<input checked="" type="checkbox"/>
32	25/07/19 09:20	Front View	 Load JPG	<input checked="" type="checkbox"/>
33	25/07/19 09:20	Front View	 Load JPG	<input checked="" type="checkbox"/>
34	25/07/19 09:20	Front View	 Load JPG	<input checked="" type="checkbox"/>
35	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	25/07/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
82	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
83	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
84	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
85	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
86	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
87	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
88	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
89	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
90	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
91	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
92	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
93	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
94	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
95	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
96	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
97	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
98	25/07/19 09:20	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/19 09:21	TP GIA REPORT		
2	26/07/19 14:53	WORKSHOP INVOICE		
3	26/07/19 14:57	TP ESTIMATE - MARKED		
4	14/08/19 08:52	MANDATE APPROVAL EMAIL		
5	05/09/19 08:06	RENTAL RECEIPT		
6	05/09/19 08:06	AUTHORISATION TO ACT FORM		
7	05/09/19 08:06	Release Voucher		
8	05/09/19 08:08	LETTER TO OI		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/07/19 15:21	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJP9304L (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBC8878S (TP veh)		
Date of Accident:	01/07/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		12,002.50
Final Repair Cost	:	\$		5,100.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	770.40	6 days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	5,870.40	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Eunos Motor Service	:	\$ 5,870.40
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

05 Sep
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011797/ADA3Q2

Date: 05/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994461

Claimant Vehicle No: GBC8878S

Insured Vehicle No:

SJP9304L

Date of Loss: 01/07/2019

Nature of Claim:

TP

Claim No: 2557761268SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC8878S

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2359320

Reg. Date: 23/01/2014 (Man. Year: 2013)

Chassis No: JTFAT35Y20K202720

Colour: Blue

Odometer: 264933 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

155 R12

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,162.50	3,933.42	3,229.08	45.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	2,450.00	2,390.00	49.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,002.50	6,383.42	5,619.08	46.82
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	12,002.50	5,100.00	6,902.50	57.51
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
Nett Liability (S\$)		5,870.40		

INSPECTION

Date of Assignment: 02/07/2019

Date Inspected: 02/07/2019 Inspected At:

Eunos Motor Service (HQ)
1 Kaki Bukit Ave 6, #01-64 AutoBay @
Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,055.30 FL	*1,055.30 FL
2	2		*REAR TAILGATE LOCK LH/RH	Not Necessary	378.00 FL	*- FL
3	1		*REAR TAILGATE EMBLEM TOYOTA	Necessary	175.00 FL	*175.00 FL
4	1		*REAR TAILGATE EMBLEM 70KM	Necessary	22.50 FS	*15.00 FS
5	1		*REAR TAILGATE EMBLEM 13PAX	Necessary	22.50 FS	*15.00 FS
6	1		*REAR TAILGATE EMBLEM DYNA	Necessary	38.00 FL	*38.00 FL
7	1		*REAR TAILGATE ALUMINIUM PANEL	Not Necessary	164.00 FL	*- FL
8	1		*REAR TAILGATE END PANEL	Dented	384.00 FL	*384.00 FL
9	1		*TAIL LAMP LH	Smashed	169.70 FL	*169.70 FL
10	1		*TAIL LAMP PANEL LH	Bent	56.10 FL	*56.10 FL
11	1		*REAR LH SIDE GATE LH	Repair	1,555.10 FL	*- FL
12	1		*REAR SIDE GATE LOCK LH	Bent	128.00 FL	*128.00 FL
13	1		*REAR TAIL GATE RETAINER	N/S Bent	76.00 FL	*38.00 FL
14	2		*REAR TAIL GATE STEP RUBBER	Missing	68.00 FL	*68.00 FL
15	1		*REAR NUMBER PLATE PANEL	Bent	159.10 FL	*159.10 FL
16	1		*REAR SPARE TYRE CARRIER ASSY	Damaged	312.00 FL	*312.00 FL
17	1		*REAR LH CHASSIS MEMBER	Repair	924.00 FL	*- FL
18	1		*REAR STEP BRACKET (STAIN-CASE)	Bent	122.00 FL	*122.00 FL
19	1		*REAR SIDE GATE PANEL	Repair	188.00 FL	*- FL
20	1		*REAR FLOOR CENTRE PANEL	Repair	945.00 FL	*- FL
21	1		*REVERSE SENSOR	Damaged	262.50 FS	*200.00 FS
22	1		*RADIATOR	Dented	1,637.00 FL	*1,637.00 FL
23	1		*FAN BLADE	Cut	192.70 FL	*192.70 FL
24	2		*ENGINE MOUNTING	Torn	246.00 FL	*246.00 FL
25	1		*GEAR BOX MOUNTING	Torn	117.00 FL	*117.00 FL
26	1		*REAR NUMBER PLATE	Bent	37.50 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	9,435.00	5,157.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,272.50	1,224.48
Total Parts (\$\$)	7,162.50	3,933.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR CHASSIS	New	1,200.00	800.00
2	DISMANTLE TAIL GATE	New	800.00	0.00
3	TO REMOVE REVERSE SENSOR	New	80.00	50.00
4	TO DISMANTLE RADIATOR	New	180.00	120.00
5	TO REPAIR UNDERCARRIAGE	New	180.00	0.00
6	TO ADJUST ALIGNMENT	New	180.00	0.00
7	TO CHECK WIRING	New	120.00	30.00
8	TO SPRAY PAINTING AFFECTED ACCIDENT PARTS	New	650.00	400.00
9	TO KNOCK ,STRAIGHTEN ALL NECESSARY PARTS ,INCLUDING CHANGING & REPAIRING OF ALL DAMAGED PARTS	New	800.00	600.00
10	TO REMOVE REAR DECK TO FACILITATE REPAIR TO REAR CHASSIS MEMBER	New	650.00	450.00
Gross Labour Cost (\$\$)			4,840.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >