

ASS. REC. BY:

REF: CS/TP 19011800 / KVd3m2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Gabriel wea

of TP

Date/Time: 3.7.19 2.11p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT 50997

Insured: SHN 7925K

at Workshop m/s King's Auto

Tel: 64578629

of BIK 176 SSM MING Drive #02-10

Policy No: MCOM0015

Claim No: MCT19070034

Sum Insured: Excess:

Make of Veh:

(Client's Record)

D.O.A. 1.7.2019

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 3.7.19 2.17p.m

Person Contacted: Anne

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 50997 - CC4 / AIG 16010852 / U=6292 120A - 29/10/2016
	SHN 7925K - CC4 / TP 19003231 / G665 120A - 28/11/2018

23/8/19 @ 204pm Anne will email us. est

3/9 11/21 @ 1150c Confirm (Recd 1077.58, 5370)

ASS. REC. BY: Kenneth

REF Ti

ASSIGNMENT

From: _____ Date: 4.7.2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJT 5099J
 at Workshop n/s Kng's Auto
 of BK 176 Sg Minig Drive #02-10

Insured:

Policy No:

Claims No:

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 88k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or NoLump Sum: 20 % ? Vol Yes or NoCA / REV / REP. / 24 HRS may

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJT 5099J Yr Regn: 15/10, 09

Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toy Uio c.c. 1497Colour: M. Green A/C: Insured / Std / NI / NASp. Reading: 218879 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR0531449305131066Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: Yoko 185/60R15R: Kumho

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 1/7/19Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Est not ready

RECEIVED 05 SEP 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 5/9 - typistReport Format: merimanLump Sum / I.B.I. (\$) 1150/-Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

G + HOS, 3H

Photos

Others

TOTAL

25011261

Veron Chen (LKKAUTO)

From: Gabriel Wee <Gabriel@iii.com.sg>
Sent: Thursday, 5 September 2019 10:32 AM
To: Veron Chen (LKKAUTO); Motor Claim - III; SUR
Cc: Manivel Priyadarshini
Subject: RE: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS-TP SJT 5099J

Dear Veron,

III CLAIM NUMBER: MCT19070034

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: 05 September, 2019 10:03 AM
To: Motor Claim - III <motorclaim@iii.com.sg>; SUR <sur@lkkauto.com>; Gabriel Wee <Gabriel@iii.com.sg>
Cc: Manivel Priyadarshini <manivel@iii.com.sg>
Subject: RE: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS-TP SJT 5099J

Dear Gabriel,

Please provides claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 3 July 2019 3:24 PM
To: 'Motor Claim - III' <motorclaim@iii.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Manivel Priyadarshini' <manivel@iii.com.sg>
Subject: RE: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS

Dear Sir / Mdm,

- Thank you for the assignment.

Please be informed vehicle in the workshop, repairer arrange on 4/7/19.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Wednesday, 3 July, 2019 3:11 PM

To: Kuru & Co <kurulegal@yahoo.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Manivel Priyadarshini <manivel@iii.com.sg>

Subject: RE: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJT5099J and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]

Sent: 03 July, 2019 10:57 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **LKK Auto Consultants Pte Ltd/Kenneth**

Please arrange for your surveyor to survey our client's vehicle at the following address:

KING'S AUTO AIR-CONDITIONING SERVICE

**Blk 176 Sin Ming Drive
#02-10 Sin Ming Autocare
Singapore 575721
Contact: 6457 8629**

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Tuesday, 2 July 2019, 4:27:39 pm SGT, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]
Sent: 02 July, 2019 2:15 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS

Dear Sirs

ACCIDENT INVOLVING SJT 5099J & SHA 7925K ON 01.07.2019

ALONG CARPARK OF BLK 643 HOUGANG AVENUE 8

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **SG Rent & Drive Pte Ltd**, whose vehicle registration number **SJT 5099J** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 3 July, 2019 3:11 PM
To: Kuru & Co; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: Our Ref: L19.0850.at//Your Ref: SHA 7925K//PRS
Attachments: img-702140723.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJT5099J and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

p: Anne
T: 317pm
r: in
T: ✓

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: 03 July, 2019 10:57 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Our Ref: L19.0850.at//Your Ref: SHA 7925K//PRS

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **LKK Auto Consultants Pte Ltd/Kenneth**

Please arrange for your surveyor to survey our client's vehicle at the following address:

KING'S AUTO AIR-CONDITIONING SERVICE
Blk 176 Sin Ming Drive
#02-10 Sin Ming Autocare
Singapore 575721
Contact: 6457 8629

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Tuesday, 2 July 2019, 4:27:39 pm SGT, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: 02 July, 2019 2:15 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: L.19.0850.at//Your Ref: SHA 7925K//PRS

Dear Sirs

ACCIDENT INVOLVING SJT 5099J & SHA 7925K ON 01.07.2019

ALONG CARPARK OF BLK 643 HOUGANG AVENUE 8

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **SG Rent & Drive Pte Ltd**, whose vehicle registration number **SJT 5099J** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	6696W

Vehicle Details

Vehicle No.:	SJT5099J
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZX972347
Chassis No.:	MR053HY9305131066
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	15 Oct 2009
First Registration Date:	15 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$12,717.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2019
PARF Rebate Amount:	\$6,358.00

Intended COE Rebate Details

COE Expiry Date:	14 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,201.00
COE Rebate Amount:	\$444.00
Total Rebate Amount:	\$6,802.00

The information contained herein is correct as at 05 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2019 12:16
Date Of Accident	01/07/2019 20:40
Exact Location Of Accident	OUTSIDE OF CARPARK NEAR BLK 643 HOUGANG AVENUE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT5099J
Insured/Policyholder	
Name Of Registered Owner	SG RENT & DRIVE PTE LTD
Co Reg No	201806696W
Email Address	ADRIELPNG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82285690
Alternative Phone No	OFFICE-82285690

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5110046293
Cover Note Number	

Driver

Name of Driver	PNG JUN HAO, ADRIEL
NRIC No	S9329710E
Date Of Birth	18/08/1993
Occupation	OUTDOOR
Date Of Driving Pass	28/11/2012
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82285690
Fax Number	
Contact Number	
Email Address	ADRIELPNG@GMAIL.COM

Address	BLK 49 WHAMPOA SOUTH #04-08
Postcode	330049
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7925K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	HWANG TENG HUI
NRIC/Passport Number	S0018967G
Contact Number	87529295
Address	BLK 224 SERANGOON AVENUE 4 #09-159
Postcode	550224
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was looking for a parking lot. I saw a parking lot on my left. After I check no vehicle was coming, I proceed to do my reverse parking. While doing so, I was being hit by vehicle B.

Vehicle B was on the opposite side of the road.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

02 JUL 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC/PIN No.:
admin.vac@vicom.com.sg

KING'S AUTO AIR-CONDITIONING SERVICE

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721
 TEL: 6457-8629 FAX: 6451-7651

DATE 28th Aug 2019
 OUR REF SJT5099J
 TO SG Rent & Drive Pte Ltd
 210 Turf Club Road, The Grandstand Car Mall
 Lot A12/A27
 Singapore 287995

Fax: 62564315
 King's Auto

Not Authorised

11 Sep 8/15 of

2 days

RE Quotation For Toyota Vios

Quantity	Item	Unit Price (\$)	Amount (\$)	
1	Rear RH Lamp		305.38	✓
1	Rear RH Lamp Inner Panel		115.35	x
1	Rear Bumper		447.98	✓
1/2	Rear Bumper RH Retainers	o/s 101.56	203.12	✓
1/2	Rear Bumper RH Lower Retainers	o/s 34.34	68.68	✓
1	Rear Bumper Reflector		91.09	✓
set	Rear Bumper Clips		38.50	✓
1	Rear Parking Sensors		380.00	2000
			1,650.10	
		LESS 25% DISCOUNT	412.53	
		SUBTOTAL	1,237.58	

FOR LABOUR CHARGES

Quantity	Item	Unit Price (\$)	Amount (\$)	
	Panel Beating		400.00	2000
	Spray Painting		600.00	2000
	Wiring		50.00	200
	To apply anti rust coat		80.00	x
	Labour to replace parking sensors		60.00	500
		SUBTOTAL	1,190.00	

GRAND TOTAL FOR THIS QUOTATION 2,427.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19011800/KVD3N2

Date: 06/09/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SJT5099J	Insured Vehicle No :	SHA7925K
Date of Loss:	01/07/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT5099J	Engine No:	1NZX972347
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305131066
Reg. Date:	15/10/2009 (Man. Year: 2009)	Odometer:	218879 km
Colour:	Metallic Green		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Kumho 9 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,237.57	964.14	273.43	22.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	470.00	720.00	60.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,427.57	1,434.14	993.43	40.92
Approved Total (Overridden) (\$\$)		1,150.00		
Nett Amount (\$\$)	2,427.57	1,150.00	1,277.57	52.63

INSPECTION

Date of Assignment:	03/07/2019	
Date Inspected:	04/07/2019	Inspected At:
		King's Auto Air-conditioning (HQ)
		Blk 176 Sin Ming Dr #02-10 Singapore
		575721
		Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT5099J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH LAMP	Cut	305.38 FL	*305.38 FL
2	1		*REAR RH LAMP INNER PANEL	Repair	115.35 FL	*- FL
3	1		*REAR BUMPER	Bent	447.98 FL	*447.98 FL
4	1		*REAR BUMPER RH RETAINERS	O/s Distorted	203.12 FL	*101.56 FL
5	1		*REAR BUMPER RH LOWER RETAINERS	O/s Cracked	68.68 FL	*34.34 FL
6	1		*REAR BUMPER REFLECTOR	Mtg Cracked	91.09 FL	*91.09 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	38.50 FL	*38.50 FL
8	1		*REAR PARKING SENSORS	Shorted	285.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,555.10	1,218.85
- List Item Discount on L Items 25.00/25.00% (S\$)	317.53	254.71
Total Parts (S\$)	1,237.57	964.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	600.00	200.00
3	WIRING	New	50.00	20.00
4	TO APPLY ANTI RUST COAT	New	80.00	0.00
5	LABOUR TO REPLACE PARKING SENSORS	New	60.00	50.00
Gross Labour Cost (S\$)			1,190.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >