

# SK AUTOMOBILE PTE LTD

Roc.No. 201500047H

23 Kaki Bukit Ave 4 #03-01 Vicom Inspection Centre  
(South Wing) Singapore 415933  
Tel: 67895155 Fax : 67835155

Date: 03/07/19

To: AXA Insurance Pte Ltd

By Fax & Email

Attn: Motor Claims Department.

Re: Accident involving motor vehicle nos. XD 9058U and SKB 688A  
Along AVE > MCE After Buona Vista on 28/06/19


We refer to the above matter.

Under the new practice directions, we the repairers of motor vehicle no XD 9058U  
Hereby give you the insurer of motor vehicle no SKB 688A 2 working days.  
Whether you are appointing your own surveyors to conduct a pre-repair inspection on our  
customers vehicle.

If we do not hear from you after 2 working days, we shall carry out to appoint our own surveyors on  
behalf of our said customer to conduct the said pre-repair inspection and proceed to repair the said  
vehicle thereafter.

Thank You.

Regards



Huey Lee

E-mail: admin@skauto.com.sg

## FOR SURVEYOR

Please initial here after completion of pre-repair  
inspection. Thank you.

Appointed Surveyor: \_\_\_\_\_  
(Name & Signature)

Date & Time of Inspection: \_\_\_\_\_

**\*\*8 Kaki Bukit Ave 4 #08-46**

**Premier@Kaki Bukit**

**Singapore 415875**

**\*\* Pls contact: Xiong - 8121 0478**

Operations address: 23 Kaki Bukit Ave 4, #03-01 (South Wing) Singapore 415933  
Tel: +65 6789-5155 Fax: +65 6783-5155