



Your Ref: D16/4276/SMRT/JW

Date: 26th Sep 2019

Our Ref: CS1/FCI19011817/Atd3e2

M/s First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YL 7011M
INSURED VEHICLE: SHB 597P
ACCIDENT DATE: 01/04/2016

We thank you for your instruction on 01/07/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YL 7011M from M/s Par Automotive Consultancy.
- b) Final Repair Bill of YL 7011M from M/s N-51 Automotive Pte Ltd.
- c) Singapore Accident Statement and Police Report of Vehicles YL 7011M and SHB 597P.
- d) Colour damaged vehicle photographs of YL 7011M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
Registration Number : YL 7011M
Make & Model : Isuzu FSR33P
Chassis Number : JALFSR33P47000012
Year of Registration : 2004
2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.